

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG16004424/KWB3S2-1
Date: 31/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 100624659
Claimant Vehicle No : SGJ6777S **Insured Vehicle No :** SGF1853J
 Date of Loss: 06/03/2016 Nature of Claim: TP Claim No: 1079069098SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGJ6777S**
 Make & Model: SUBARU LEGACY, 2.0I SEDAN (A) Engine No: EJ20D904506
 Reg. Date: 07/07/2010 (Man. Year: 2009) Chassis No: JF1BM5KC2AG003543
 Colour: Metallic Pearl White Odometer: 129324 km
 Engine Capacity: 1994 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R18 Rear Tyre Size: 225/45R18
 Front Left Side: Continental 8 mm Rear Left Side: Continental 8 mm
 Front Right Side: Continental 8 mm Rear Right Side: Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,310.30	2,264.80	1,045.50	31.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,316.00	2,894.00	6,422.00	68.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,626.30	5,158.80	7,467.50	59.14
+ GST 7.00/7.00% (S\$)	883.84	361.12	522.72	59.14
Nett Amount (S\$)	13,510.14	5,519.92	7,990.22	59.14
+ Car Rental (8.0 x S\$120.00/day + 7.00% GST) (S\$)		1,027.20		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,549.12		

INSPECTION

Date of Assignment: 11/03/2016
 Date Inspected: 11/03/2016 Inspected At: Motor Image Enterprises Pte Ltd (Toa Payoh)
 19 Lorong 8 Toa Payoh
 Singapore 319255
 Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG**Manager:** VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SPARE WHEEL PAN	Repair	414.00 FL	*- FL
2	1		*REAR END PANEL	Bent	288.00 FL	*288.00 FL
3	1		*CABLE AY TRK	Serviceable	18.00 FL	*- FL
4	1		*REAR BOOT COMPLETE	Bent	648.00 FL	*648.00 FL
5	1		*REAR BOOT STRIKER	Distorted	54.00 FL	*54.00 FL
6	1		*REAR BOOT WEATHERSTRIP	Distorted / Dented	119.00 FL	*119.00 FL
7	1		*REAR BUMPER	Bent	594.00 FL	*594.00 FL
8	1		*REAR BUMPER SIDE BRACKET RHS	Distorted	18.00 FL	*18.00 FL
9	1		*REAR BUMPER SIDE BRACKET LHS	Serviceable	18.00 FL	*- FL
10	1		*REAR BUMPER BEAM	Bent	216.00 FL	*216.00 FL
11	1		*COVER HOOK R FHI SD	Missing	15.00 FL	*15.00 FL
12	1		*REAR RHS FENDER LINER	Serviceable	72.00 FL	*- FL
13	1		*LH REAR MUDGUARD	Serviceable	72.00 FL	*- FL
14	1		*PLATE AIR FLAP RRH	Serviceable	11.00 FL	*- FL
15	1		*PLATE AIR FLAP RLH	Serviceable	11.00 FL	*- FL
16	1		*WINDOW GL ASSY R	Serviceable	1,080.00 FL	*- FL
17	1		*REAR WINDSCREEN UPPER DAM RUBBER	Not Necessary	12.00 FL	*- FL
18	1		*REAR WINDSCREEN LOWER	Not Necessary	12.00 FL	*- FL
19	1		*REAR WINDSCREEN MOULDING	Not Necessary	51.00 FL	*- FL
20	1		*REAR RHS REFLECTOR	Mtg Cracked	30.00 FL	*30.00 FL
21	1		*LH REFLECTOR	Mtg Cracked	22.00 FL	*22.00 FL
22	1		*REAR BOOT INNER GARNISH	Serviceable	180.00 FL	*- FL
23	1		*REAR BOOT EMBLEM	Necessary	96.00 FL	*96.00 FL
24	1		*REAR BOOT LETTERING - LEGACY	Necessary	65.00 FL	*65.00 FL
25	1		*REAR BOOT LETTERING SUBARU / AWD	Necessary	108.00 FL	*108.00 FL
26	1		*SUNDRISE	Necessary	100.00 FS	*30.00 FS
27	2		*POINT REVERSE SENSOR	Dented / Shorted	300.00 FS	*300.00 FS
28	1		*GASKET RM	Necessary	16.00 FL	*16.00 FL
29	1		*TAIL PIPE CUTTER	Dented	51.00 FL	*51.00 FL
30	1		*LH MUFFLER	Bent	760.00 FL	*760.00 FL
31	1		*REAR BUMPER CORNER BRACKET RHS	Cracked	28.80 FL	*28.80 FL
32	1		*REAR BUMPER CORNER BRACKET LHS	Cracked	28.80 FL	*28.80 FL
33	1		*REAR RH TAILLAMP	Cracked	449.00 FL	*449.00 FL
34	1		*COVER	Missing	29.00 FL	*29.00 FL
35	1		*REAR END PANEL TRIM	Dented	144.00 FL	*144.00 FL
36	1		*REAR NUMBER PLATE	Necessary	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,175.60	4,154.60
- List Item Discount on L Items 50.00/50.00% (\$\$)	2,865.30	1,889.80
Total Parts (\$\$)	3,310.30	2,264.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE & REPAIR REAR BUMPER, BUMPER BEAM, REAR BOOT, END PANEL & FENDER.	New	2,940.00	700.00
2	RESPRAY REAR BUMPER, BUMPER BEAM, REAR END PANEL, REAR BOOT, REAR FENDER.	New	3,920.00	1,200.00
3	TO CONDUCT LIGHTING TEST.	New	100.00	28.00
4	TO CONDUCT WATER SEEPAGE TEST.	New	100.00	0.00
5	TO REMOVE & REFIX REAR BOOT GARNISH, CARPET & TRIMS TO FACILITATE REPAIR.	New	342.00	342.00
6	TO REMOVE & INSTALL REAR WINDSCREEN.	New	300.00	0.00
7	TO TRANSFER REAR BOOTLID MECHANISM.	New	150.00	150.00
8	TO REFIX & RE-ALIGN EXHAUST.	New	150.00	0.00
9	CONDUCT PROTECTANT COATING ON REAR PORTION PANEL.	New	500.00	250.00
10	CONDUCT ANTI-RUST COATING ON REAR PORTION PANEL.	New	590.00	0.00
11	TO REPLACE & RE-ALIGN EXHAUST SYSTEM.	New	224.00	224.00
Gross Labour Cost (S\$)			9,316.00	2,894.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >