

AXA  
LKK - Kenneth



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Repair Estimates

SJY 765 B

*Not within  
L1 Sy B?  
4 days*

<b>Parts</b>	(a) Cost / List Price Items	\$	<u>3,498.00</u>
	Plus/Less <u>-25%</u>	\$	<u>874.50</u>
	<b>Total of Cost / List</b>	\$	<u><u>2,623.50</u></u>
	(b) Nett Price Items		_____
	Less _____		_____
	<b>Total of Nett Item</b>		_____
	(c) Special Nett Items	\$	<u>200.00</u>
<b>Total Parts Cost</b>		\$	<u><u>2,823.50</u></u>
<b>Labour</b>		\$	<u>2,860.00</u>
<b>Total</b>		\$	<u><u>5,683.50</u></u>

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 7/13/18 at 2pm

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : Le Date: 7/13/18



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Spare Parts

Vehicle No. : SJY 765 B  
 Make & Model : TOYOTA VIOS  
 Chassis No : MR053HY9305170412

Submit By : Carmen Lim  
 Year Manufacture : 2010  
 Engine No. : \_\_\_\_\_

### Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor <i>Shon</i>	2	\$200.00	S.N	✓
2	Rear bumper <i>Ry</i>	1	\$475.00		✓
3	Rear bumper clip <i>na</i>	10	\$45.00		✓
4	Rear bumper side retainer LH <i>Dis</i>	1	\$105.00		✓
5	Rear bumper side retainer RH <i>su</i>	1	\$105.00		X
6	Rear bumper bracket LH	1	\$85.00		?
7	Rear bumper bracket RH <i>R</i>	1	\$85.00		X
8	Rear bumper reflector LH <i>CR</i>	1	\$100.00		✓
9	Rear bumper reflector RH <i>su</i>	1	\$100.00		X
10	Bootlid <i>R</i>	1	\$750.00		X
11	Bootlid emblem <i>na</i>	1	\$55.00		X
12	Wording "VISO" <i>na</i>	1	\$50.00		X
13	Wording "E" <i>na</i>	1	\$45.00		X
14	Tail end panel <i>Ry</i>	1	\$660.00		✓
15	Tail end panel garnish <i>su</i>	1	\$220.00		X
16	Tail end panel garnish clip <i>na</i>	8	\$40.00		X
17	Boot weatherstrip <i>su</i>	1	\$218.00		✓
18	Tail lamp LH <i>su</i>	1	\$360.00		X
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Labour

Vehicle No. : SJY 765 B Submit By : Carmen Lim  
 Make & Model : TOYOTA VIOS Year of Manufacture : 2010

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER,BOOTLID,END PANEL, SPARE TYRE WELL PANEL)	\$1,200.00	600
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER,BOOTLID,END PANEL, SPARE TYRE WELL PANEL)	\$1,000.00	600
3	To check wiring	\$50.00	200
4	To remove & refit reverse sensor	\$120.00	500
5	To tuff coat	\$100.00	300
6	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	600
7	To transfer boot mechanism to new boot <i>rr</i>	\$120.00	X
8	To conduct water leakage tests to ensure proper air and sealing	\$120.00	200

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.