

AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A
 #01-09 AMK AUTOPOINT Singapore 568047
 Tel: 6483 1244 Fax: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST Reg No: M9-0009639-E

TP INSURER: India International Insurance Pte Ltd (HQ)
 UNKNOWN

SURVEYOR COPY

Singapore

Claimant Insurer: Tokio Marine Insurance Singapore Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	02/05/2018
Vehicle Reg. No.:	SJK6635C	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	JAYANDRAN WALTER MUTHU		
Make/Model:	KIA CERATO, 1.6 (M)	Vehicle Reg. Date:	30/10/2008
Vehicle Colour:	BLUE	Chassis No:	KNAFE227295614504
Engine No:	G4FC8H008244		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	7 ✓		

Description of Accident/Loss REFER TO THE SKETCH PLAN BY DRIVER

Remarks: CAR NOT IN - TO BE ARRANGE
 Present Location: AH LIM MOTOR COMPANY (AMK)

Not Notified
11/2/18 87
Recovery After Painting

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

COST OF CLAIMS

Parts	5,490.00
Miscellaneous Items	
Labour	10.00
Paintwork Labour	4,050.00
Towing	0.00

Gross Total (S\$)	9,550.00
+ GST 7.00% (S\$)	668.50
Nett Amount (S\$)	10,218.50

This claim is handled by: ZILA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 May 2018)

Parts: 143 KIA CERATO 1.6 (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Ah Lim Motor Company/SJK6635C/07/05/2018 15:52

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount
1	1		*FRONT BONNET	R	10.00	0.00	*835.00 FL X
2	10		*FRONT BONNET INSULATOR CLIPS	na	10.00	0.00	*20.00 FL X
3	1		*FRONT BONNET INNER LOCK	R	10.00	0.00	*75.00 FL Y
4	1		*FRONT BONNET TOP OUTER CTR CHROME	Oct	10.00	0.00	*130.00 FL L
5	1		*FRONT GRILLE ASSY	cm	10.00	0.00	*209.00 FL L
3	6		*FRONT GRILLE CLIPS	na	10.00	0.00	*18.00 FL L
7	2		*HEADLAMP LH & RH <i>n/s m/c p/s</i>		10.00	0.00	*824.00 FL L
3	2		*HEADLAMP LOWER BEAM LH & RH	R	10.00	0.00	*20.00 FL X
9	1		*FRONT BUMPER	Bu	10.00	0.00	*430.00 FL L
10	2		*FRONT BUMPER SIDE RETAINER LH & RH	sn	10.00	0.00	*16.00 FL X
11	1		*FRONT BUMPER LOWER GRILLE	DR	10.00	0.00	*60.00 FL L
12	1		*FRONT BUMPER SPONGE		10.00	0.00	*101.00 FL ?
13	1		*FRONT BUMPER REINFORCEMENT		10.00	0.00	*263.00 FL ?
14	2		*FRONT BUMPER REINFORCEMENT BRACKET	R	10.00	0.00	*16.00 FL A
15	12		*FRONT BUMPER CLIPS	na	10.00	0.00	*36.00 FL L
16	2		*FOGLAMP	sn	10.00	0.00	*344.00 FL X
17	1		*RADIATOR SUPPORT PANEL COMPLETE - CHECK PRICE		10.00	0.00	*- FL ?
18	1		*AIR CON CONDENSER ASSY - CHECK PRICE	sn	10.00	0.00	*- FL X
19	1		*REAR BOOT	R	10.00	0.00	*745.00 FL X
20	1		*REAR BOOT EMBLEM	na	10.00	0.00	*55.00 FL X
21	1		*REAR BOOT LOGO (EX) RH	na	10.00	0.00	*32.00 FL X
22	1		*REAR BOOT LOGO (CERATO) LH - CHECK PRICE	na	10.00	0.00	*- FL X
23	1		*REAR BOOT LOGO (CYCLE CARRIAGE) RH - CHECK PRICE	na	10.00	0.00	*- FL X
24	8		*REAR BOOT INSULATOR CLIPS	na	10.00	0.00	*24.00 FL X
25	1		*TAILAMP RH	cm	10.00	0.00	*278.00 FL L
26	3		*TAILAMP CLIPS - CHECK PRICE	na	10.00	0.00	*- FL X
27	1		*TAILAMP PANEL RH - CHECK PRICE	R	10.00	0.00	*- FL X
28	1		*REAR BUMPER	Bu	10.00	0.00	*466.00 FL L
29	1		*REAR BUMPER SIDE RETAINERS RH	DR	10.00	0.00	*23.00 FL L
30	12		*REAR BUMPER CLIPS	na	10.00	0.00	*36.00 FL L
31	1		*REAR BUMPER REINFORCEMENT WITH BRACKET		10.00	0.00	*454.00 FL ?
32	1		*REAR END PANEL		10.00	0.00	*290.00 FL ?
33	1		*REAR END PANEL TOP GARNISH - CHECK PRICE	sn	10.00	0.00	*- FL X
34	1		*RADIATOR COOLANT	na	0	0.00	*35.00 FS X
35	1		*REVERSE CAMERA - CHECK PRICE	sn	0	0.00	*- FS X
36	1		*REVERSE SENSOR		0	0.00	*200.00 FS ?
37	1		*NUMBER PLATE	B	0	0.00	*35.00 FS L

* = Franchise part. S = SpcNett. L = ListItemDisc.

Sub Total (\$\$) 6,070.00
 - List Item Discount on L Items (\$\$) 580.00

Total Parts (\$\$) 5,490.00

Ah Lim Motor Company/SJK6635C/07/05/2018 15:52. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			

No Qty Particulars

Amount

1	1	OD/TP Case (Insurer)	10.00
---	---	----------------------	-------

Sub Total (S\$)	10.00
-----------------	-------

Estimates on Labour

No	Particulars	Lab.Type	Amount
----	-------------	----------	--------

Labour Items

1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	201 40.00
2	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES; RADIATOR AND HOSES; VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	New	nn 120.00
3	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD RADIATOR SUPPORT PANEL;FRONT BUMPER REINFORCEMENT WITH BRACKET.TO KNOCK & REPAIR FRONT FENDER LH & RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	350 800.00
4	TO SPRAY FRONT BONNET;FRONT BUMPER;FRONT BUMPER REINFORCEMENT & BRACKET;FRONT FENDER LH & RHRADIA SUPPORT PANEL.	New	400 800.00
5	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	201 40.00
3	TO REMOVE & REINSTALL/REPLACE REAR REVERSE CAMERA.	New	nn 501 120.00
7	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	New	501 80.00
3	TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	New	nn 150.00
9	TO REALIGN; DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.	New	nn 100.00
10	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD TAILAMP PANEL RH;END PANEL;REAR BUMPER REINFORCEMENT & BRACKET.TO KNOCK & REPAIR REAR FENDER RH;REAR CHASSIS FRAME RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	500 900.00
11	TO SPRAY REAR BOOT;REAR BUMPER;REAR BUMPER REINFORCEMENT & BRACKET;END PANEL;TAILAMP PANEL RH;REAR FENDER RH;REAR CHASSIS FRAME RH.	New	600 900.00

Gross Labour Cost (S\$)	4,050.00
-------------------------	----------

Ah Lim Motor Company/SJK6635C/07/05/2018 15:52. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >