



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-05 SUNTEC TOWER FIVE
SINGAPORE 038985

Ref: CS3/EG18008394/Gea3s2

Date: 12-05-2020



Code: EGI

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	XE 8886Y	Veh. Inspected	SJT 9813M
Policy No.	DMCV17S017673	Coverage (\$)	0.00
Claim No.	XE8886Y/SL/sa	Excess (\$)	0.00
Assign From	SITI A'THIKAH	Assign Date	09/05/2018

2. Vehicle Particulars & Condition

Make & Model	KIA FORTE	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	KNAFU411LA5135514	Colour	GREY
Odometer	182354 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	CONTINENTAL	6 mm
L/H Front Tyre	195/65 R15	CONTINENTAL	6 mm
R/H Rear Tyre	195/65 R15	CONTINENTAL	6 mm
L/H Rear Tyre	195/65 R15	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/05/2018	Inspect Date / Time	09/05/2018 (11:30 AM)
Survey held at	BOON AUTOMOBILE SERVICE BLK 5033 ANG MO KIO IND PK 2 #01-267 SINGAPORE 569536		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$8,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
--	-----------------------