

ASS. REC. BY:

REF: CS /SPF18008399/TI.rbez Special Instruction:

Survivor

Tawfik

ASSIGNMENT (Office)

From (Person): Abdul Rahman of SPF Date/Time: 07/05/2018

Estimated Cost: Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLS 8787T Insured: YN 6680C

at Workshop m/s D's Graffiti Concepts Tel: 8608 3456

of 25 Kala Bulat Rd 4 #06-26

Policy No: Claim No: AEMD/105/009/2018/057

Sum Insured: Excess:

Make of Veh: D.O.A. 11-04-2018
(Client's Record)CA / REV / REP. / REV 24 HRS Wp 51 Paya Ubi #01-04 C 1:30pm
Indu Park
Dave. H.O.D. Endorsement:

Date/Time: 08/05/2018 9:29am Person Contacted: Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SLS 8787T - X
	YN 6680C - CS/SPF18008395/b
	Dismantle: 16/5/2018
	Submit L/S \$10,900.00 @ 5 days

DCA: 110413



SINGAPORE POLICE FORCE

SPF Accidents Claims Section
Automotive Engg & Mgmt Div
Police Logistics Department
No. 1 Mount Pleasant Road
Block 8 Old Police Academy
#02-12 Singapore 298333

Your Ref : SLS8787T

Our Ref : AEMD/105/009/2018/057

Date : 7 May 2018

Tel: 64784840

Fax: 64784848

M/s LKK Auto Consultants Pte Ltd
Paya Ubi Industrial Park
51 Ubi Avenue 1 #01/02-25
Singapore 408933

Via Fax only: 62564315

Dear Sir/Madam,

RTA ON 11 APRIL 2018 INVOLVING GOVT VEH YN6680C AND OTHER VEH SLS8787T

We refer to the above matter.

- 2 Please arrange for a Pre Repair Inspection of vehicle no. SLS8787T at M/s D's Graffiti Concepts Pte Ltd of 25 Kaki Bukit Road 4 #06-26 Synergy@KB, Singapore 417800.
- 3 For appointment please contact Mr Dave at Tel: 86083456.
- 4 Estimates were not provided by the workshop.
- 5 Thank you.

Yours sincerely,

Abdul Rahman
Accident Claims Officer
for Assistant Director

A FORCE FOR THE NATION

VEN: SLS 8787T

DOI: 8/5/18

1. Rear bumper o/s - R X -
2. Upper side panel o/s - R -
3. Rear signal light o/s - CR ✓ 220.00
4. Rear bumper clipset - nec ✓ 90

Sticker wrap cut - car wrap 8,000.00

Painting 1,400.00

Paint Protector 3,000.00

Labour 1000.00

13,620.00

TCU in

mm

11/5/18

L/S 108,00/2

Repair days 5



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF18008399/T1rbe2

ACCIDENT CLAIM SECTION
(SINGAPORE POLICE FORCE) 1 MOUNT
PLEASANT ROAD BLK 8 OLD POLICE ACADEMY
SINGAPORE 298333

Date : 06-09-2018



ATTN : ABDUL RAHMAN

Code : SPF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 6680C	Veh. Inspected	SLS 8787T
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/057	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	07/05/2018

2. Vehicle Particulars & Condition

Make & Model	MCLAREN	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	SBM11AAD6CW000621	Colour	GOLD
Odometer	37216	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/35 R19	PIRELLI	6 mm
L/H Front Tyre	235/35 R19	PIRELLI	6 mm
R/H Rear Tyre	305/30 R20	PIRELLI	6 mm
L/H Rear Tyre	305/30 R20	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	11/04/2018	Inspection Date	08/05/2018
Survey held at	D'S GRAFFITI CONCEPTS - 25 KAKI BUKIT RD 4 #08-26		
Repairer	-		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 8787T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER O/S (NPA)	TO REPAIR SEE LABOUR	-	-
1	UPPER SIDE PANEL O/S (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR SIGNAL LIGHT O/S	CRACKED	220.00	220.00
1	SET REAR BUMPER CLIP	NECESSARY	90.00	90.00
			310.00	310.00
	<u>LABOUR</u>			
	STICKER WRAP CUT - CAR WRAP.		8,000.00	8,000.00
	PAINTING.		1,400.00	1,400.00
	PAINT PROTECTOR.		3,000.00	3,000.00
	LABOUR. INCLUSIVE OF THE REPAIR OF REAR BUMPER O/S AND UPPER SIDE PANEL O/S.		1,000.00	1,000.00
			13,400.00	13,400.00
GRAND TOTAL			13,710.00	13,710.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				10,900.00

Report Ref No. CS/SPF18008399/T1rbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.