

ASS. REC. BY:

REF: CS/MSG18008445/R/Hb 91

Special Instruction:

MINOR

Rasul

ASSIGNMENT (Office)

Merimen

From (Person): Kwok Woon Choo of MSGH Date/Time: 08052018 11:30am

Estimated Cost: Bill to:

☒ DD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLP 8434C Insured:

at Workshop in/s Autoprice Tel: 8383 3190

of 305 Alexandra Rd

Policy No: MSD/YPCD/17-001639-00 Claim No:

Sum Insured: Excess: \$ 1500-00

Make of Veh: D.O.A. 04052018
(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 08052018 12:14pm Person Contacted: Guo Xiang Vehicle: ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SLP 8434C - X
9/5/18	Report thru Merimen; seek mandate
10/5/18	Woon Choo authorise repair, Inform Guo Xiang to proceed by email & call
	confirm \$5418.50 @ 5 days
	(Red: \$6775.50, 56%)

(09/11/13)

Surveyor: Rame

REF:

0399N

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MVTo Inspect Vehicle No: SLP 8434Cat Workshop m/s AutoFRANCE

of _____

Insured: msk

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 1500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: 112K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA ☒ REV ☐ REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLP 8434C Yr Regn: 2017 / JunType: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or _____

Make: TOYOTA CHR 1.8 HB c.c. 1757Colour: WHITE A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: 29649 T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: 24X102017594Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim orTyre Size: F: 225/50 R18

R: _____

BS / ☒ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIE / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 04/05/18 D.O.I. 08/05/18Survey held at: AutoFRANCEDes. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop orFRt o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 02 JUL 2018

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

_____ \$ + RS. _____ \$

) Photos

) Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 May 2018		08 May 2018 11:30 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	HITACHI CAPITAL ASIA PACIFIC PTE. LTD., Co. Reg. No.: 199400399N								
Vehicle Reg. No.:	SLP8434C	Date of Loss:	04/05/2018 13:00 - :59 [16 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD	Policy/Cover Note No.:	MSD/VPCD/17-001639-00 (Comprehensive) Coverage: 20/06/2017 - 19/06/2018						
		Excess:	S\$1,500.00						
Repairer:	AutoFrance (HQ) 305 Alexandra Road, #02-01, 159942 Alexandra - Tel: 64777331								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Kwok Woon Choo - 6643 1330]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 09/05/2018]								
Driver/Custodian:	NEO KOK SERN (41 / Male), NRIC: S77105711, Tel: +6591178988								
Adj Asg. Remarks:	Survey by today. REVERT CASE.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

08

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Kwok Woon Choo

Date: 09 May 2018

Preliminary Advice

Vehicle No	: SLP8434C	Accident Date	: 04/05/2018
Make	: TOYOTA C-HR	Policy No.	: MSD/VPCP/17-001639
Assignment Date	: 08/05/2018	Excess	: S\$1,500.00
Date of Inspection	: 08/05/2018	Est. Duration of Repair	: 5.00
Inspection At	: AUTOFRANCE (HQ) 305 ALEXANDRA ROAD, #02-01 SINGAPORE 159942		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,161.00
Revised Amount	:S\$	5,176.50
Check Items (Estimated)	:S\$	1,586.50
Total	:S\$	6,763.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	112,000.00
COE / PARF Rebate	:S\$	53,230.00
Salvage Value	:S\$	
Margin for Repair	:S\$	58,770.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

Print Received Message

This mail is associated with :

***SLP8434C (MSC/V/18-000638)**
OD
May 4 2018 12:00AM
[HITACHI CAPITAL ASIA PACIFIC PTE. LTD.]
AutoFrance

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 10/05/2018 15:30 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$5176.50) - SLP8434C - Claim Handler: Kwok Woon Choo

Approved:5176.50:a if c; check items to be confirmed

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Thursday, May 10, 2018 3:53 PM
To: wong.guo.xiang@simedarby.com.sg
Cc: SUR
Subject: SLP 8434C MSIG OD

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLP 8434C (excess \$1,500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Kwok Woon Choo

Date: 27 Jun 2018

Preliminary Advice

Vehicle No	: SLP8434C	Accident Date	: 04/05/2018
Make	: TOYOTA C-HR	Policy No.	: MSD/VPCP/17-001639
Assignment Date	: 08/05/2018	Excess	: S\$1,500.00
Date of Inspection	: 08/05/2018	Est. Duration of Repair	: 5.00
Inspection At	: AUTOFRANCE (HQ) 305 ALEXANDRA ROAD, #02-01 SINGAPORE 159942		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,194.00 (Include supplementary \$33)
Revised Amount	:S\$	5,418.50
Check Items (Estimated)	:S\$	
Total	:S\$	5,418.50
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	112,000.00
COE / PARF Rebate	:S\$	53,230.00
Salvage Value	:S\$	
Margin for Repair	:S\$	58,770.00

Remarks

- (X) The vehicle is economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0399N
Vehicle Details	
Vehicle No.:	SLP8434C
Vehicle to be Exported:	No
Intended De-registration Date:	09 May 2018
Vehicle Make:	TOYOTA
Vehicle Model:	C-HR 1.8 HYBRID G AUTO 5DR
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	2ZR8048434
Chassis No.:	ZYX102017594
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$31,848.00
Original Registration Date:	20 Jun 2017
First Registration Date:	20 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$6,588.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jun 2027
PARF Rebate Amount:	\$4,941.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jun 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,001.00
COE Rebate Amount:	\$48,289.00
Total Rebate Amount:	\$53,230.00

The information contained herein is correct as at 09 May 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	07/05/2018 09:05
Date Of Accident	04/05/2018 13:30
Exact Location Of Accident	ALONG AMK AVE 5
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLP8434C
Insured/Policyholder	
Name Of Registered Owner	HITACHI CAPITAL ASIA PACIFIC PTE. LTD.
Co Reg No	199400399N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67341222
Vehicle Particulars	
Manufacturer	TOYOTA
Model	C-HR-1.8 HYBRID S/G (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MSD/VPCD/17-001639-00
Cover Note Number	
Driver	
Name of Driver	NEO KOK SERN
NRIC No	S7710571I
Date Of Birth	05/04/1977
Occupation	INDOOR
Date Of Driving Pass	01/02/2007
Driving Experience	11 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91178988
Fax Number	
Contact Number	
Email Address	LINUS.NEO@YAHOO.COM

Address	BLK 577 HOUGANG AVE 4 #04 - 668
Postcode	530577
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - LEASING
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : TAN BEE KHIM GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO THE ATTACH STATEMENT & SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG9028B
Vehicle Make/Model/Colour	TRUCK
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/TIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Ayrk Ave 5 approaching the junction towards Haydon Ave 4. The light was green and as I was approaching the junction, I stopped for incoming traffic. When the traffic was cleared, I proceeded to turn right to Haydon Ave 4. Then I realise that there is an incoming lorry GBG 9028B approaching from opposite side & both vehicle collided.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

648000C_V000100010001_001

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SLP8434C		
Vehicle Type:	R11 - Private Hire (Self-Drive) Station Wagon/Jeep/Land Rover		
Vehicle Attachment 1:	No Attachment		
Vehicle Scheme:	Normal		
Vehicle Make:	TOYOTA		
Vehicle Model:	C-HR 1.8 HYBRID G AUTO 5DR		
Chassis No.:	ZYG102017594		
Propellant:	Petrol-Electric		
Engine No.:	2ZR8048434		
Motor No.:	20A317208996		
Engine Capacity:	1797 cc		
Power Rating:	53.0 kW		
Maximum Power Output:	90.0 kW (120 bhp)		
Maximum Laden Weight:	1715 kg		
Unladen Weight:	1440 kg		
Year Of Manufacture:	2017		
Original Registration Date:	20 Jun 2017		
Lifespan Expiry Date:	-		
COE Category:	B - Car above 1600cc or 97kW (130bhp)		
Quota Premium:	\$53,001.00		
COE Expiry Date:	19 Jun 2027		
Road Tax Expiry Date:	19 Jun 2018		
PARF Eligibility Expiry Date:	19 Jun 2027		
Inspection Due Date:	19 Jun 2020		
Intended Transfer Date:	08 May 2018		
CO2 Emission:	91.00 (g/km)		
CEV/VES Rebate Utilised Amount:	\$30,000.00		
CO Emission:	-		
HC Emission:	-		
NOx Emission:	-		
PM Emission:	-		
The current road tax expiry is 19 Jun 2018, You may renew the road tax from 20 Mar 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 19 Jun 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 20 Jun 2018 to 19 Dec 2018)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	487.00	-	487.00
Total Amount Payable:			512.00
Amount Payable (From 20 Jun 2018 to 19 Jun 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	974.00	-	974.00
Total Amount Payable:			999.00

You may print this page for reference.

OK

Print

Vantage Automotive Limited

305 Alexandra Road S'pore 159942

Date : 04.01.2018

RE: VEHICLE REPAIR QUOTATION

Insurance Company	:	MSIG INSURANCE (S) PTE LTD
Vehicle Reg No	:	SLP8434C
Date of Accident	:	04.05.2018
Tyre of Claim	:	OD CLAIM
Model	:	TOYOTA C-HR 1.8 HYBRID G
Chassis No	:	ZYX102017594

We are please to submit our estimate of repairs to the above mention vehicle.

	Parts	Labour
FRT BUMPER	\$ 250.00	700 / 275
COVER, FRONT BUMPER, LOWER	\$ 200.00	DE / 220
GRILLE, RADIATOR, INNER	\$ 70.00	CR4 / 77
RETAINER, FRONT BUMPER SIDE, RH	\$ 55.00	re / 60.50
RETAINER, FRONT BUMPER SIDE, LH	\$ 55.00	X su
ABSORBER, FRONT BUMPER, LOWER	\$ 40.00	? su
ABSORBER, FRONT BUMPER ENERGY	\$ 40.00	CR4 / 44
STAY, FRONT BUMPER SIDE, RH	\$ 30.00	re / 33
STAY, FRONT BUMPER SIDE, LH	\$ 30.00	X su
COVER, FRONT BUMPER HOLE, RH	\$ 55.00	DI / 60.50
COVER, FRONT BUMPER HOLE, LH	\$ 55.00	X su
REINFORCEMENT, FRONT BUMPER	\$ 190.00	? BT / 209
REINFORCEMENT, FRONT BUMPER, NO.2	\$ 130.00	PA / 143
BRACKET SUB-ASSY, FRONT SIDE MEMBER, RH	\$ 100.00	? su c x
BRACKET SUB-ASSY, FRONT SIDE MEMBER, LH	\$ 100.00	X
COVER, FOG LAMP, RH	\$ 70.00	X } 48
COVER, FOG LAMP, LH	\$ 70.00	X }
GRILLE, RADIATOR	\$ 200.00	? su
SEAL, HOOD TO RADIATOR GRILLE	\$ 20.00	cut / 22
GRILLE, RADIATOR, INSIDE	\$ 95.00	? su
HOOD SUB-ASSY	\$ 350.00	X su
FENDER SUB-ASSY, FRONT RH	\$ 230.00	? su
PROTECTOR, FRONT FENDER SIDE PANEL, RH	\$ 55.00	su X
LINER, FRONT FENDER, RH	\$ 100.00	? su
BONNET HINGE LH	\$ 35.00	X
BONNET HINGE RH	\$ 35.00	? BT / 38.50
HEADLAMP ASSY, RH	\$ 2,200.00	CR4 / 2420
HEADLAMP ASSY, LH	\$ 2,200.00	X 9
LAMP ASSY, FOG, RH	\$ 180.00	? }
LAMP ASSY, FOG, LH	\$ 180.00	X }
WIPER WASHER TANK	\$ 80.00	? }

FRT PARKING SENSOR
FRT RHS FENDER MOULDING
FRT LHS FENDER MOULDING

\$ 150.00 *ms* *165*
\$ 80.00 *sun* *88*
\$ 80.00 *Xm*

Sub Total Parts = \$ 7,810.00
Add 10% = \$ 781.00
Total Parts = \$ 8,591.00

1	SUNDRIES <i>ms</i>	<i>X</i>	\$	100.00 <i>20</i>
2	REPLACE / REPAIR FRT BUMPER, FRT BONNET, FRT SUPPORT PANEL, FRT LHS FENDER, FRT RHS FENDER	<i>X</i>	\$	1,200.00 <i>500</i>
3	RESpray FRT BUMPER, FRT BONNET, FRT LHS FENDER, FRT RHS FENDER, FRT SUPPORT PANEL		\$	1,000.00 <i>700</i>
4	WIRING CONNECTION & CHECK		\$	100.00 <i>30</i>
5	REMOVE & REPLACE FRT HEADLAMP INCLUDING REALIGN HEADLAMP BEAM LEVEL		\$	80.00 <i>40</i>
6	REMOVE & REFIX A/C CONDENSER INCLUDING PRESSURE TEST, CHECK LEAKAGE & TOP UP GAS		\$	120.00 <i>Xm</i>
7	REMOVE & REFIX RADIATOR INCLUDING PRESSURE TEST, CHECK LEAK & AIR BLEEDING		\$	80.00 <i>Xm</i>
8	TUFF KOTE @ \$40 PER PANEL		\$	120.00 <i>40</i>
9	SEALANT FOR FRT BONNET		\$	90.00 <i>X</i>
10	TO CONDUCT CHASSIS ALIGNMENT & MEASUREMENT		\$	<i>250</i> 380.00 <i>Xm</i>
11	TO CONDUCT ECU COMPUTER DIAGNOSTIC INCLUDING CLEAR FAULT CODES		\$	<i>200</i> 300.00

Total (Labour) \$ 3,570.00
Sub Total : \$ 12,161.00
GST 7% \$ 851.27
Grand Total : \$ 13,012.27

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

WONG GUO XIANG (64777409 / 83833190)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
5 days
P/P
08/05/18 @1250
Revert
EXCESS: 1500
2 Resurvey by paint
23/5/18

Business Registration No. 53055563L GST Registration No. M2-0000551-1
305 Alexandra Road Singapore 159942
Tel: 64777409 Fax: 64777398



RO Number: B9 41021

NO.	Supplementary / Check Items Parts	Part Number	Price
1	REINFORCEMENT, FRONT BUMPER	52131-10080	\$ 209.00
2	FRT BUMPER CENTRE SENSOR BRACKET * 2	89348-F4020-C1	\$ 33.00
			\$ 242.00

Price

Labour Charges:		
		Total Parts And Labour \$ 242.00

Raised By Technician	Approved By	Acknowledge By	Resurvey by	BO Parts: Yes / No
	<p><u>LK/CSA to Consult</u> the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>	<p><u>Parts Assistant</u></p>		<p>ETA: _____</p>

VANTAGE AUTOMOTIVE LIMITED

(A Simie Darby Motors Company)

Co. Regs. No. 192600045M GST Regs. No. M2-0000551-1

305, Alexandra Road
Vantage Automotive Centre
Singapore 119942

Service Booking: 6477 7368
Vantage 24-Hour Assist: 6473 8588
Fax: 6477 7300

**SERVICE TAX INVOICE**

RE-PRINT

REPAIR ORDER NO. b9 41021	Date In 11/05/2018 Payment Term 30 Days From Invoice Customer Service Advisor Wong Guo Xiang	Invoice Number Invoice Date Invoice By Wong Guo Xiang	Page No. 1 of 2
CUSTOMER INFORMATION Neo Kok Sern Blk 577 Hougang Avenue 4 #04-66B Singapore 530577		INVOICE TO 24748 MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay #24-01 Hong Leong Building Singapore 048581	
REGISTRATION No. SLP8434C	CHASSIS No. ZYX102017594	STOCK No. 526475	REGISTRATION DATE 20/06/2017
MODEL TOYOTA C-HR		MILEAGE 1	

CODE	DESCRIPTION	UNITS	NETT
	SUNDRIES	1	20.00 ✓
	REPLACE/REPAIR FRT BUMPER, FRT BONNET, FRT RHS FENDER	1	500.00 ✓
	RESPRAY FRT BUMPER, FRT BONNET, FRT RHS FENDER	1	700.00 ✓
	WIRING CONNECTION & CHECK	1	30.00 ✓
	REMOVE & REPLACE FRT HEADLAMP INCLUDING REALIGN HEADLAMP BEAM LEVEL	1	40.00 ✓
	TUFF KOTE @ \$40 PER PANEL	1	40.00 ✓
	TO CONDUCT ECU COMPUTER DIAGNOSTIC INCLUDING CLEAR FAULT CODE	1	200.00 ✓
Sub-Total :			1,530.00

CODE	DESCRIPTION	UNITS	NETT
N T52119-10916	FRT BUMPER	1	275.00 ✓
N T52535-10040	RETAINER, FRT BUMPER SIDE RH	1	60.50 ✓
N T89341-0W010-A0	FRT PARKING SENSOR RH	1	165.00 ✓
N T52129-10010	COVER, FRONT BUMPER, LOWER	1	220.00 ✓
N T53114-10030	GRILLE, RADIATOR, INNER	1	77.00 ✓
N T52611-10030	ABSORBER, FRT BUMPER ENERGY	1	44.00 ✓
N T42145-10060	STAY, FRT BUMPER SIDE, RH	1	33.00 ✓
N T52127-10050	COVER, FRT BUMPER HOLE, RH	1	60.50 ✓
N T52132-10050	REINFORCEMENT FRT BUMPER, NO.2	1	143.00 ✓
N T53395-10030	SEAL, HOOD TO RAD GRILLE	1	22.00 ✓
N T53351-10010	BONNET HINGE RH	1	38.50 ✓
N T81110-10890	HEADLAMP ASSY, RH	1	2,420.00 ✓
N T75601-10010	FRT RHS FENDER MOULDING	1	88.00 ✓
N 152131-10080	FRT BUMPER REINFORCEMENT	1	209.00 ✓
N T89348-F4020-C1	FRT BUMPER CENTRE SENSOR BRACKET	2	33.00 ✓
Sub-Total :			3,888.50

Attending CSO : Wong
Should you require further explanation, please reach me at 64777409

VANTAGE AUTOMOTIVE LIMITED

(A Sime Darby Motors Company)

Co. Regs. No. 192600045M GST Regs. No. M2-0000551-1

 305 Alexandra Road

Vantage Automotive Centre

Singapore 159942

 Service Booking: 6477 7368

Vantage 24-hour Assalt: 6473 8588

Fax: 6477 7300

**SERVICE TAX INVOICE**

RE-PRINT

REPAIR ORDER NO. b9 41021	Date IN 11/05/2018 Payment Term 30 Days From Invoice Customer Service Advisor Wong Guo Xiang	Invoice Number Invoice Date Invoice By Wong Guo Xiang	Page No. 2 of 2
-------------------------------------	--	---	------------------------

Service Packages	0.00	Total Labour/Parts/Service Package Charges	S\$	5,418.50
Labour Charges	1,530.00	Less Insurance Excess	S\$	0.00
Parts Charges	3,888.50	GST @ 7%	S\$	379.30
Lubricant/Misc	0.00	Invoice Total Amounts	S\$	5,797.80
		Less Deposit/Voucher	S\$	0.00
Computer generated invoice. No signature is required.		Amount Payable	S\$	5,797.80
All amounts are in Singapore Dollars. Work was carried out subject to the Company's Terms and Conditions of Service. No complaints will be entertained unless reported within seven (7) days of the date of this invoice. For credit purchases, interest @1% per month will be debited on overdue amounts.				

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 May 2018		08 May 2018 11:30 Edit Adj Rpt	S\$5,418.50 Edit Estimates	S\$5,418.50 View Rpt		Pending for Survey Report Cancel Case






























Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	HITACHI CAPITAL ASIA PACIFIC PTE. LTD., Co. Reg. No.: 199400399N								
Vehicle Reg. No.:	SLP8434C	Date of Loss:	04/05/2018 00:00 - :59 [10 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / MSC/V/18-000638	Policy/Cover Note No.:	MSD/VPCP/17-001639 (Comprehensive) Coverage: 20/06/2017 - 19/06/2018						
		Excess:	S\$1,500.00						
Repairer:	AutoFrance (HQ) 305 Alexandra Road, #02-01, 159942 Alexandra - Tel: 64777331								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Kwok Woon Choo - 6643 1330]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL ... [Final Rpt due 07/06/2018]								
Driver/Custodian:	NEO KOK SERN (41 / Male), NRIC: S77105711, Tel: +6591178988								
Adj Asg. Remarks:	Survey by today. REVERT CASE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (02/07/2018): Alert - Adj Mandate Approved (S\$5418.50) - SLP8434C - Claim Handler: Kwok Woon C... MSIG_SG (28/06/2018): Alert - Adj Mandate Maintained - SLP8434C - Claim Handler: Kwok Woon Choo MSIG_SG (10/05/2018): Alert - Adj Mandate Approved (S\$5176.50) - SLP8434C - Claim Handler: Kwok Woon C... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									





































Claim Documents

*SLP8434C (MSC/V/18-000638)
 OD
 May 4 2018 12:00AM
 [HITACHI CAPITAL ASIA PACIFIC PTE. LTD.]
 AutoFrance

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)





View [View in Browser](#)

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Vantage Automotive Limited (Ubi)	Thumbnail	Print	
1	07/05/18 09:23	Accident Statement	 Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	09/05/18 11:15	Adjuster Immediate Advice	 Load HTM		
2	27/06/18 18:58	Adjuster Immediate Advice	 Load HTM		
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Vantage Automotive Limited (Ubi)	Thumbnail	Print	
1	07/05/18 09:17	Accident Photo <small>[Linked Accident Report Documents]</small>	 Load JPG <input checked="" type="checkbox"/>		
2	07/05/18 09:17	Accident Photo <small>[Linked Accident Report Documents]</small>	 Load JPG <input checked="" type="checkbox"/>		
3	07/05/18 09:17	Accident Photo <small>[Linked Accident Report Documents]</small>	 Load JPG <input checked="" type="checkbox"/>		
4	07/05/18 09:17	Accident Photo <small>[Linked Accident Report Documents]</small>	 Load JPG <input checked="" type="checkbox"/>		
5	07/05/18 09:23	Accident Photo <small>[Linked Accident Report Documents]</small>	 Load JPG <input checked="" type="checkbox"/>		
6	07/05/18 09:23	Accident Photo <small>[Linked Accident Report Documents]</small>	 Load JPG <input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	09/05/18 11:27	General View	 Load JPG <input checked="" type="checkbox"/>		
2	09/05/18 11:27	General View	 Load JPG <input checked="" type="checkbox"/>		
3	09/05/18 11:27	General View	 Load JPG <input checked="" type="checkbox"/>		
4	09/05/18 11:27	General View	 Load JPG <input checked="" type="checkbox"/>		
5	09/05/18 11:27	General View	 Load JPG <input checked="" type="checkbox"/>		
6	09/05/18 11:27	General View	 Load JPG <input checked="" type="checkbox"/>		
7	09/05/18 11:27	General View	 Load JPG <input checked="" type="checkbox"/>		
8	09/05/18 11:27	General View	 Load JPG <input checked="" type="checkbox"/>		
9	09/05/18 11:27	General View	 Load JPG <input checked="" type="checkbox"/>		
10	09/05/18 11:27	General View	 Load JPG <input checked="" type="checkbox"/>		
11	09/05/18 11:27	General View	 Load JPG <input checked="" type="checkbox"/>		
12	09/05/18 11:27	General View	 Load JPG <input checked="" type="checkbox"/>		
13	09/05/18 11:27	General View	 Load JPG <input checked="" type="checkbox"/>		
14	09/05/18 11:27	General View	 Load JPG <input checked="" type="checkbox"/>		
15	09/05/18 11:27	General View	 Load JPG <input checked="" type="checkbox"/>		
16	09/05/18 11:27	General View	 Load JPG <input checked="" type="checkbox"/>		
17	09/05/18 11:27	General View	 Load JPG <input checked="" type="checkbox"/>		
18	09/05/18 11:27	General View	 Load JPG <input checked="" type="checkbox"/>		
19	09/05/18 11:27	General View	 Load JPG <input checked="" type="checkbox"/>		
20	09/05/18 11:27	General View	 Load JPG <input checked="" type="checkbox"/>		
21	09/05/18 11:27	General View	Load JPG <input checked="" type="checkbox"/>		
22	09/05/18 11:27	General View	Load JPG <input checked="" type="checkbox"/>		
23	09/05/18 11:27	General View	Load JPG <input checked="" type="checkbox"/>		
24	09/05/18 11:27	General View	Load JPG <input checked="" type="checkbox"/>		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Vantage Automotive Limited (Ubi)	Thumbnail	Print
25	09/05/18 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
26	09/05/18 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
27	09/05/18 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
28	09/05/18 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
29	09/05/18 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
30	09/05/18 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
31	09/05/18 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
32	09/05/18 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
33	09/05/18 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
34	09/05/18 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
35	09/05/18 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
36	09/05/18 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
37	09/05/18 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
38	09/05/18 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
39	09/05/18 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
40	09/05/18 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
41	09/05/18 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
42	09/05/18 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
43	09/05/18 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
44	09/05/18 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
45	27/06/18 19:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	27/06/18 19:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	27/06/18 19:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	27/06/18 19:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	27/06/18 19:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	27/06/18 19:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	27/06/18 19:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	27/06/18 19:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	27/06/18 19:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	27/06/18 19:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	27/06/18 19:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	27/06/18 19:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/05/18 10:18	E-MAIL FR AUTO FRANCE TO ARRANGE OD SURVEY	 Load PDF	
2	08/05/18 10:46	PARF_COE Rebate Enquiry.html - SLP8434C	 Load HTML	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/05/18 11:23	SLP 8434C ESTIMATE	 Load PDF	
2	29/06/18 14:29	SLP 8434C SUPPLEMENTARY+FINAL EST	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Vantage Automotive Limited (Ubi)	Thumbnail	Print
1	07/05/18 09:23	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Vantage Automotive Limited (Ubi)	Thumbnail	Print
1	07/05/18 09:17	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	07/05/18 09:17	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Vantage Automotive Limited (Ubl)	Thumbnail	Print
3	07/05/18 09:17	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	07/05/18 09:17	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	07/05/18 09:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	07/05/18 09:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Vantage Automotive Limited (Ubl)	Thumbnail	Print
1	07/05/18 09:13	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	07/05/18 09:13	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18008405/R1RBQ2

Date: 06/07/2018

REFERENCE

Insured/Claimant: HITACHI CAPITAL ASIA PACIFIC PTE. LTD.

Policy No: MSD/VPCP/17-001639

Date of Loss: 04/05/2018

Nature of Claim: OD

Claim No: MSC/V/18-000638

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLP8434C

Make & Model: TOYOTA C-HR, 1.8 HYBRID S/G (A)

Reg. Date: 20/06/2017 (Man. Year: 2017)

Colour: White

Engine Capacity: 1797 cc

Market Value/New Car Price: S\$112,000.00

Sum Insured (S\$): Market Value/New Car Price

Engine No: 2ZR8048434

Chassis No: ZYX102017594

Odometer: 29649 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R18

Front Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Tyre Size: 225/50 R18

Rear Left Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,933.00	3,908.50	5,024.50	56.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,470.00	1,510.00	1,960.00	56.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,403.00	5,418.50	6,984.50	56.31
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	10,903.00	3,918.50	6,984.50	64.06
+ GST 7.00/7.00% (S\$)	763.21	274.30	488.91	64.06
Nett Amount (S\$)	11,666.21	4,192.80	7,473.41	64.06

INSPECTION

Date of Assignment: 08/05/2018

Date Inspected: 08/05/2018 Inspected At:

AutoFrance (HQ)
305 Alexandra Road, #02-01
Singapore 159942

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jul 2018)
Parts:	M1-SUV	TOYOTA C-HR 1.8 HYBRID S/G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP8434C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRT BUMPER (WCP)	Torn	250.00 F	*250.00 F
2	1	*COVER ,FRONT BUMPER ,LOWER (WCP)	Deformed	200.00 F	*200.00 F
3	1	*GRILLE ,RADIATOR ,INNER (WCP)	Cracked	70.00 F	*70.00 F
4	1	*RETAINER ,FRONT BUMPER SIDE ,RH (WCP)	Necessary	55.00 F	*55.00 F
5	1	*RETAINER ,FRONT BUMPER SIDE ,LH (WCP)	Serviceable	55.00 F	*- F
6	1	*ABSORBER ,FRONT BUMPER ,LOWER (WCP)	Serviceable	40.00 F	*- F
7	1	*ABSORBER ,FRONT BUMPER ,ENERGY (WCP)	Cracked	40.00 F	*40.00 F
8	1	*STAY ,FRONT BUMPER SIDE ,RH (WCP)	Necessary	30.00 F	*30.00 F
9	1	*STAY ,FRONT BUMPER SIDE ,LH (WCP)	Serviceable	30.00 F	*- F
10	1	*COVER ,FRONT BUMPE HOLE ,RH (WCP)	Distorted	55.00 F	*55.00 F
11	1	*COVER ,FRONT BUMPE HOLE ,LH (WCP)	Serviceable	55.00 F	*- F
12	1	*REINFORCEMENT ,FRONT BUMPER (WCP)	Bent	190.00 F	*190.00 F
13	1	*REINFORCEMENT ,FRONT BUMPER ,NO.2 (WCP)	Bent	130.00 F	*130.00 F
14	1	*BRACKET SUB-ASSY ,FRONT SIDE MEMBER ,RH (WCP)	Serviceable	100.00 F	*- F
15	1	*BRACKET SUB-ASSY ,FRONT SIDE MEMBER ,LH (WCP)	Serviceable	100.00 F	*- F
16	1	*COVER ,FOG LAMP, RH (WCP)	Serviceable	70.00 F	*- F
17	1	*COVER ,FOG LAMP, LH (WCP)	Serviceable	70.00 F	*- F
18	1	*GRILLE ,RADIATOR (WCP)	Serviceable	200.00 F	*- F
19	1	*SEAL ,HOOD TO RADIATOR GRILLE (WCP)	Cut	20.00 F	*20.00 F
20	1	*GRILLE ,RADIATOR ,INSIDE (WCP)	Serviceable	95.00 F	*- F
21	1	*HOOD SUB-ASSY (WCP)	Serviceable	350.00 F	*- F
22	1	*FENDER SUB-ASSY ,FRONT RH (WCP)	Serviceable	230.00 F	*- F
23	1	*RPOTECTOR ,FRONT FENDER SIDE PANEL ,RH (WCP)	Serviceable	55.00 F	*- F
24	1	*LINER ,FRONT FENDER ,RH (WCP)	Serviceable	100.00 F	*- F
25	1	*BONNET HINGE LH (WCP)	Serviceable	35.00 F	*- F
26	1	*BONNET HINGE RH (WCP)	Bent	35.00 F	*35.00 F
27	1	*HEADLAMP ASSY ,RH (WCP)	Cracked	2,200.00 F	*2,200.00 F
28	1	*HEADLAMP ASSY ,LH (WCP)	Serviceable	2,200.00 F	*- F
29	1	*LAMP ASSY ,FOG,RH (WCP)	Serviceable	180.00 F	*- F
30	1	*LAMP ASSY ,FOG,LH (WCP)	Serviceable	180.00 F	*- F
31	1	*WIPER WASHER TANK (WCP)	Serviceable	80.00 F	*- F
32	1	*FRT PARKING SENSOR (WCP)	Missing	150.00 F	*150.00 F
33	1	*FRT RHS FENDER MOULDING (WCP)	Scratched	80.00 F	*80.00 F
34	1	*FRT LHS FENDER MOULDING (WCP)	Serviceable	80.00 F	*- F
35	1	*SUNDRIES	Necessary	100.00 FS	*20.00 FS
36	1	*REINFORCEMENT ,FRONT BUMPER (WCP)	Repeated	190.00 F	*- F
37	1	*FRT BUMPER CENTRE SENSOR BRACKET (WCP)	Necessary	30.00 F	*30.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$) 8,130.00 3,555.00

+ Margin on L,N Items 10.00/10.00% (\$\$) 803.00 353.50

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					8,933.00	3,908.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE /REPAIR FRT BUMPER ,FRT BONNET ,FRT SUPPORT PANEL ,FRT LHS FENDER ,FRT RHS FENDER	New	1,200.00	500.00
2	RESPRAY FRT BUMPER ,FRT BONNET ,FRT LHS FENDER ,FRT RHS FENDER ,FRT SUPPORT PANEL	New	1,000.00	700.00
3	WIRING CONNECTION & CHECK	New	100.00	30.00
4	REMOVE & REPLACE FRT HEADLAMP INCLUDING REALIGN HEADLAMP BEAM LEVEL	New	80.00	40.00
5	REMOVE & REFIX A/C CONDENSER INCLUDING PRESSURE TEST ,CHECK LEAKAGE & TOP UP GAS	New	120.00	0.00
6	REMOVE & REFIX RADIATOR INCLUDING PRESSURE TEST ,CHECK LEAK & AIR BLEEDING	New	80.00	0.00
7	TUFF KOTE	New	120.00	40.00
8	SEALANT FOR FRT BONNET	New	90.00	0.00
9	TO CONDUCT CHASSIS ALIGNMENT & MEASUREMENT	New	380.00	0.00
10	TO CONDUCT ECU COMPUTER DIAGNOSTIC INCLUDING CLEAR FAULT CODES	New	300.00	200.00
Gross Labour Cost (\$\$)			3,470.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >