



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBJ 4763D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	R.H. PANNIER CO	* CHECK	998.40	-
1	L.H. PANNIER CO	CUT	998.40	998.40
1	BRACKET BOTTOM	* CHECK	140.50	-
1	BRACKET BOTTOM	* CHECK	140.50	-
1	PLATE HOLDER	CRACKED	121.70	121.70
1	MUDFLAP	MISSING	77.70	77.70
1	NUMBER PLATE HO	BENT	26.70	26.70
1	FLASHER LIGHT F	* CHECK	59.40	-
1	FLASHER LIGHT F	* CHECK	59.40	-
2	SPACER @\$17.50	NECESSARY	35.00	35.00
5	QUICK FASTENING @\$4.30	NECESSARY	21.50	21.50
5	QUICK FASTENING @\$4.30	NECESSARY	21.50	21.50
2	SCREW TCEIF M5X @\$2.40	NECESSARY	4.80	4.80
9	SCREW @\$1.00	NECESSARY	9.00	9.00
1	SCREW	NECESSARY	1.00	1.00
10	SCREW @\$6.90	NECESSARY	69.00	69.00
1	BRACKET, REFLEC	MISSING	20.00	20.00
1	REFLEX, REFLECTO	MISSING	7.20	7.20
1	TAIL GUARD BOTT	* CHECK	296.40	-
1	TAIL GUARD BOTT	* CHECK	296.40	-
1	REAR WHEEL RIM	* CHECK	2,433.60	-
1	VALVE, TUBELESS	* CHECK	12.80	-
1	NUT	* CHECK	62.10	-
1	WASHER 48.5X65X	* CHECK	3.40	-
1	SPACER	* CHECK	94.90	-
1	GEARBOX POSITIO	* CHECK	234.00	-
1	REAR WHEEL SPIN	* CHECK	1,474.80	-
1	LEVA FRIZIONE B	* CHECK	209.80	-
2	PLUG @\$13.70	NECESSARY	27.40	27.40
1	REAR-VIEW MIRRO	CUT	234.00	234.00
1	HUB	* CHECK	1,145.10	-

Report Ref No. CS/FCI18008417/T1sbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	STEERING CROWN	* CHECK	858.00	-
1	STEERING HEAD	* CHECK	624.00	-
1	HANDLEBAR	* CHECK	299.60	-
2	SEAL RING @\$10.80	* CHECK	21.60	-
2	BEARING, CONICA @\$100.10	* CHECK	200.20	-
1	R.H. FORK LEG A	* CHECK	4,648.80	-
1	L.H. FORK LED A	* CHECK	4,648.80	-
1	FRONT WHEEL RIM	* CHECK	2,508.50	-
1	FRONT WHEEL SPI	* CHECK	262.30	-
1	VALVE, TUBELESS	* CHECK	27.90	-
1	MATT CARB, FRONT	CRACKED	730.90	730.90
1	CARBON REAR MUD	* CHECK	569.50	-
1	HEADLIGHT	CUT	1,244.90	1,244.90
1	LEFT COVER	CUT	11.00	11.00
1	COWLING	CUT	932.90	932.90
1	WINDSHIELD	CUT	468.00	468.00
1	HALF-FAIRING FR	CUT	25.00	25.00
1	FAIRING, RH	* CHECK	135.00	-
1	FAIRING, LH	* CHECK	135.00	-
1	GEARCHANGE LEVE	BENT	111.40	111.40
1	BUSH	DEFORMED	5.30	5.30
2	RUBBER PAD @\$5.30	DEFORMED	10.60	10.60
1	PIN PEDAL	NECESSARY	9.40	9.40
1	COVER, RADIATOR	* CHECK	374.40	-
1	CAP L.H. RED	CUT	202.80	202.80
1	CAP R.H. RED	* CHECK	202.80	-
			28,605.00	5,427.10
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	CRACKED	40.00	40.00
1	FRONT NUMBER PLATE (SN) (NPA)	NECESSARY	-	-
			40.00	40.00

Report Ref No. CS/FCI18008417/T1sbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR TO REPLACE DAMAGED PARTS CAUS.		5,600.00	4,000.00
			5,600.00	4,000.00
	GRAND TOTAL		34,245.00	9,467.10
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$23,177.90 NETT)				9,467.10

Report Ref No. CS/FCI18008417/T1sbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.