

ASS. REC. BY:

REF: CS/AWA18008418/Krbnz2 Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

How Lee Fong

of

AWA

Date/Time:

08052018 1121am

Estimated Cost:

Bill to:

OD / ~~EP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 64A

Insured:

FBL 9315X

at Workshop m/s

Trans Cab

Tel:

6287 6666

of

No. 2 Amik St 63

Policy No:

AWMCSB 0028831700

Claim No:

NSV1800783 / TKL

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 01-052018

CA / REV / REP. / REV 24 HRS wpt

H.O.D. Endorsement:

Date/Time:

08052018 11:30am

Person Contacted:

Candy

Vehicle: ~~IN~~ / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD 64A - CS / FCL12008287 / Rylk3
	FBL 93151 - X

D.A. : 200412

ASS. REC. BY:

REF:

AWA/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop mv's

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

1.31

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S/HO 64 A

Yr Regn:

08.15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Perant Carade c.c 1995

Colour:

White/Red

A/C: Insured / Std / NI / NA

Sp. Reading

266875

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VI-1ABL15AUC 282221

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoper / Jammed / Leaked / Burnt or

Brake: Inoper / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

Rear

R/Bal.

6

mm

R/Bal.

9

mm

L/Bal.

4

mm

L/Bal.

9

mm

D.O.A.

1/3/18

D.O.I.

2/5/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S 191

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

9/3 File pass to Corhouse

9041.05 (Red. 63, 119, 12, 872)

RECEIVED 15 OCT 2018

Date/Time, File Pass to?

☐

Prell. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS \$

Photos

Others

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)

Report Format :

TP

Lump Sum / I.B.I. (\$)

9,041.05

350

TOTAL

Catherine Chong (LKK Auto)

From: Hew, LeeFong <LeeFong.Hew@awac.com> on behalf of Motorsurvey <Motorsurvey@awac.com>
Sent: Tuesday, 8 May, 2018 11:21 AM
To: 'assignments'
Cc: 'SUR'; 'Candy Kong'
Subject: TP Survey assignment for SHD 64A - DOA: 01/05/2018 Our ref: NSV1800283/TKL

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us **do** have consensus in the appointment of **Mr Kenneth Kong** as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3 rd Party Vehicle	:	SHD 64 A
Insured Vehicle	:	FBL 9315 X (Accident Not Reported)
Policy Number	:	AVMCSB0028831700
Name of Workshop	:	Trans-Cab Services Pte Ltd
Contact Number	:	6287 6666
Person to Contact	:	Candy Kong
Estimated Cost of repairs	:	\$ 72,160.17

Regards,
Claims Division

Copy to Trans-Cab Services Pte Ltd via Email

Note -

- (x)
1. This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
 2. **Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.**
 3. Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
 4. Please do not construe this appointment of surveyor and our above request as an admission of liability.

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail

(and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, GmbH or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 3878K

Vehicle Details

Vehicle No.: SHD64A

Vehicle to be Exported: Yes

Intended De-registration Date: 02 May 2018

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour: Red

Manufacturing Year: 2015

Engine No.: M9R8839C002780

Chassis No.: VF1ABL15AUC282221

Maximum Power Output: 127.0 kW (170 bhp)

Open Market Value: \$19,998.00

Original Registration Date: 03 Aug 2015

First Registration Date: 03 Aug 2015

Transfer Count: 0

Actual ARF Paid: \$19,998.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 02 Aug 2023

PARF Rebate Amount: \$14,998.00

Intended COE Rebate Details

COE Expiry Date: 02 Aug 2023

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$50,236.00

COE Rebate Amount: \$32,967.00

Total Rebate Amount: \$47,965.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 May 2018.

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/05/2018 15:35
Date Of Accident	01/05/2018 13:40
Exact Location Of Accident	CROSS JUNCTION RAFFLES BLVD AND NICOLL HIGHWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD64A
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD

Are you claiming under your own insurance policy for repair to your vehicle?	NO
--	----

If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520\
Cover Note Number	

Driver

Name of Driver	KOH HAN ZHONG
NRIC No	S1815768C
Date Of Birth	11/05/1967
Occupation	OUTDOOR
Date Of Driving Pass	06/01/1990
Driving Experience	28 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93263672
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 698B HOUGANG STREET 61
#05-322
Postcode 532698
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name HOGANG N.P.C
Police Station Address ROAD: 60 HOUGANG AVE 9 SINGAPORE 538775 , POSTCODE: 538775 ,
COUNTRY: SINGAPORE
Police Station Contact TEL NO: - FAX NO:
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO THE POLICE REPORT- T/20180501/2113

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

Details of Witness 1

Name MR KOH
Phone Number 94372008
Email Address

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBL9315X
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category MOTORCYCLE
Name of Driver
NRIC/Passport Number
Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SHB8636H
Vehicle Make/Model/Colour SILVER CAB
Details Of Properties
Vehicle Category TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name KOH HAN ZHONG

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHD64A

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

Cross Junction of Raffles Boulevard and Nicoll Highway



A = SHD64A
B = FBL 9315X
C = SHB 8636H

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report - T/20180501/2113

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180501/2113

1 of 4

Report No. T/20180501/2113

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 01/05/2018 22:56	Vide Report No.:	Station Diary No.: 134
--	------------------	---------------------------

Informant's Particulars

Name of Informant: KOH HAN ZHONG	Address: APT BLK 698B HOUGANG STREET 61 #05-322 SINGAPORE 532698		
ID Type / ID No.: NRIC NO / S1815768C	Contact No.:	Mobile: 93263672	
Nationality: SINGAPORE CITIZEN	Home/Office:	Email:	
Sex: Male	Age: 50	Date of Birth: 11/05/1967	Type of Informant: Driver
Race: Chinese	Language:		Institution / School Name:
Occupation: Taxi driver	Driving Licence Information: Class: 2B,2A,2,3		Date of Expiry:

General Information of the Accident

General Information of the Accident				
Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 01/05/2018 13:40	Type of Location: X-Junction
Location: Along Road 1 RAFFLES BOULEVARD NICOLL HIGHWAY Junction of Raffles Boulevard and Nicoll High way				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control: Traffic Light - Working	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBL9315X	Motorcycle				Seriously Damaged	0
SHB8636H	Car					0
SHD64A	Car					0

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180501/2113

2 of 4

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

Report No. T/20180501/2113

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	YUS	ID No.	NIL
Related Vehicle	FBL9315X (Motorcycle)	Contact No.	90684023
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	TAN	ID No.	NIL
Related Vehicle	SHB8636H (Car)	Contact No.	88666718
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	KOH HAN ZHONG	ID No.	S1815768C
Related Vehicle	SHD64A (Car)	Contact No.	93263672
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

Brief Details.

On 01/05/2018 at about 1340hrs, I was travelling on Raffles Boulevard in my vehicle. I then came to a traffic junction of Raffles Boulevard and Nicoll Highway, where everything was intact and in order. I was on the 3rd lane where vehicles can either turn right or proceed straight, I then saw a taxi SHB8636H changing lane abruptly into the 4th lane, the act caused a motorcycle FBL9315X which was travelling on the 4th lane to collide into the side of SHB8636H. The impact of the collision made the rider of FBL9315X to lose control and in turn, FBL9315X hit onto the front left bumper of my vehicle. The rider of FBL9315X then landed directly in front of my vehicle which I had to apply emergency brakes to prevent further accident.

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180501/2113

3 of 4

Report No. T/20180501/2113

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

CONTINUATION OF REPORT

I managed to stop in time hence there was no collision between my vehicle and the rider of FBL9315X. All drivers/rider then alighted to exchange particulars and took photos of the accident.

No one required immediate medical attention as such no police or ambulance was at scene. I did not feel well after the accident as such I proceeded to Central 24Hr Clinic (Hougang) and I received MC from 01/05/2018 to 03/05/2018.

I wish to state that I do not have an in-car CCTV installed in my vehicle and reference to the accident, one witness Mr Koh HP: 94372008 came forward to state that he witnessed the accident and would be making a report on his own. Mr Koh further revealed that he might have the CCTV footage which captured the accident.

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180501/2113

4 of 4

Report No. T/20180501/2113

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Sgt 2 ASHLEY TOH

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

01/05/2018 22:56

Officer In Charge Of Case:

TP / G1A /

Staff Sgt TANG SIEW PING

Contact No: 65476430

SN 085

Authentication Stamp:

NP166

Singapore Police Force

Classification Of Case:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 64A**AAD1805-012**

Not Authored
Resony Bepain *89041.05*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 64A

VF1ABL15AUC282221

RENAULT

LATITUDE

1.5.2018

ALLIED WORLD**PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>CM</i> 1,259.42 ✓
2	1	BUMPER SPOILER FRT	\$	<i>Dis</i> 181.75 ✓
3	1	BUMPER ABSORBER FRT	\$	<i>CM</i> 394.68 ✓
4	1	BUMPER RETAINER FRT LH	\$	<i>Dis</i> 151.41 ✓
5	1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88 X
6	1	BUMPER RETAINER FRT RH	\$	<i>R</i> 150.77 X
7	1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88 X
8	1	BUMPER UNDERTRAY FRT	\$	<i>Se</i> 472.83 ✓
9	1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80 X
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Dis</i> 207.21 ✓
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.21 X
12	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08 X
13	1	TOW COVER FRT	\$	<i>Sn</i> 28.61 ✓
14	1	RADIATOR GRILLE	\$	<i>Sn</i> 1,707.78 X
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Sn</i> 225.36 X
16	1	RADIATOR GRILLE FRAME	\$	<i>Sn</i> 1,353.75 X
17	1	FRAME FULL SUPPORT PANEL	\$	<i>Sn</i> 615.90 X
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79 X
19	1	FRONT BRACE PANEL	\$	<i>R</i> 177.22 X
20	1	HORN	\$	<i>Sn</i> 314.17 ✓
21	1	HORN BRACKET	\$	<i>R</i> 40.45 X
22	1	HEADLAMP LH	\$	<i>mg CM</i> 1,184.43 ✓
23	1	HEADLAMP RH	\$	<i>Sn</i> 1,184.43 X
24	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15 ✓
25	1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15 X
26	1	BONNET	\$	<i>R</i> 1,941.63 X
27	1	BONNET INSULATOR	\$	<i>Sn</i> 405.73 X
28	1	BONNET STRUT LH	\$	<i>Sn</i> 88.61 X

Trans-cab Auto Services Pte Ltd

AAD1805-012

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 64A

29	1	BONNET STRUT RH	\$	SH 88.61	}
30	1	BONNET HINGE LH	\$	SH 348.31	
31	1	BONNET HINGE RH	\$	SH 348.31	
32	1	BONNET LOCK	\$	SH 305.48	
33	1	BONNET CABLE	\$	SH 119.19	
34	1	BONNET CABLE COVER	\$	SH 161.03	
35	1	BONNET SEAL OUTER	\$	SH 92.36	
36	1	BONNET SEAL INNER	\$	SH 157.28	}
37	1	FENDER PANEL FRT LH	\$	SH 783.83	
38	1	WHEELARCH FRT LH	\$	CM 278.84	}
39	1	FENDER BRACKET LOWER LH	\$	SH 15.79	
40	1	FENDER INSULATOR LH	\$	SH 130.84	}
41	1	FENDER INSULATOR RH	\$	SH 130.84	
42	1	WIPER RESERVOIR	\$	SH 348.25	}
43	1	WIPER RESERVOIR NECK	\$	SH 136.11	
44	1	WIPER RESERVOIR MOTOR	\$	SH 270.06	}
45	1	AIR CLEANER LOWER	\$	CM 271.26	
46	1	AIR CLEANER HOSE	\$	SH 76.14	}
47	1	BASE BATTERY TRAY	\$	SH 363.40	
48	1	AIR CLEANER BOX	\$	SH 464.20	}
49	1	TURBO DUCT	\$	SH 1,027.80	
50	1	A/C HEATER VALVE	\$	SH 484.50	}
51	1	SUBFRAME OUTER FRT	\$	SH 2,652.45	
52	1	SUBFRAME BRACKET OUTER LH	\$	SH 92.36	}
53	1	ENGINE UNDERTRAY	\$	SH 564.98	
54	1	A/C CONDENSER	\$	SH 2,020.37	}
55	1	A/C CONDENSER GARNISH LH UPPER	\$	SH 39.67	
56	1	A/C CONDENSER GARNISH RH UPPER	\$	SH 39.67	
57	1	A/C CONDENSER GARNISH LH	\$	SH 58.81	
58	1	A/C CONDENSER GARNISH RH	\$	SH 59.60	
59	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	SH 208.39	
60	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	SH 658.72	
61	1	A/C PIPE COMPRESSOR	\$	SH 334.29	}
62	1	A/C PIPE	\$	SH 658.72	
63	1	A/C COMPRESSOR	\$	SH 2,684.61	}
77	1	AIR COOLER	\$	SH 792.60	
78	1	AIR INTERCOOLER HOSE (LONG)	\$	SH 1,014.13	
79	1	AIR INTERCOOLER HOSE (Short)	\$	SH 375.14	}

Trans-cab Auto Services Pte Ltd**AAD1805-012**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 64A

80	1	TRANSMISSION COOLER	\$	Su	1,219.30	
81	1	TRANSMISSION COOLER PAD	\$	Su	17.96	
82	1	RADIATOR	\$	Su	1,202.20	
83	2	RADIATOR STUD UPPER	\$	Su	14.41	
84	2	RADIATOR BUSH UPPER	\$	Su	50.12	
85	2	RADIATOR MTG LOWER	\$	Su	55.85	
86	1	RADAIATOR FAN COWLING	\$	Su	820.54	
87	1	RADIATOR FAN MOTOR LH	\$	Su	967.36	
88	1	RADIATOR FAN MOTOR RH	\$	Su	1,479.46	
89	1	RADIATOR TANK	\$	Su	324.62	
90	1	RADIATOR HOSE UPPER	\$	Su	240.56	
91	1	RADIATOR HOSE LOWER	\$	Su	491.18	
92	1	RADIATOR TANK HOSE	\$	Su	61.18	
93	1	AUTO COMPUTER	\$	my car	5,032.17	
94	1	INJECTION COMPUTER	\$	SVC my car	4,706.30	
95	1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	n	5,154.52	X
96	1	STEERING PUMP ELECTRIC L70Y	\$	Su	2,306.90	X
97	1	STEERING PINION RACK L70Y	\$	n	4,413.11	X

TOTAL	\$	61,330.75
10%	\$	6,133.07
	\$	55,197.67

Specical Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	na	52.00	X
2	1SET	BUMPER CLIP FRT	\$	na	66.00	
3	1	BUMPER BRACKET CLIP FRT LH	\$	na	12.00	
4	1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	
5	1	BUMPER BRACKET CLIP FRT RH	\$	na	12.00	
6	1	BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	
7	1	TOW COVER FRT	\$	Su	14.50	X
8	1SET	RADAIATOR GRILLE SCREW	\$	na	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00	
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	

Trans-cab Auto Services Pte Ltd

AAD1805-012

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 64A

21	1	Windscreen moulding	\$	<i>nn</i> 100.00 <i>X</i>
22	1SET	Front licence plate with holder	\$	<i>nn</i> 80.00 <i>X</i>

TOTAL	\$	562.50
TOTAL PARTS	\$	55,760.17

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	<i>400/</i> 5,400.00
Towing Fees.	\$	120.00 <i>50/</i>
To apply paint protection system (PPS) maintain and enhancement	\$	<i>nn</i> 380.00 <i>X</i>
Putty and spray painting of the affected portion.	\$	6,000.00 <i>440/</i>
To rust-proofing of the affected areas.	\$	<i>nn</i> 170.00 <i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>20/</i>
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>nn</i> 380.00 <i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00 <i>X</i>

Trans-cab Auto Services Pte Ltd

AAD1805-012

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 64A

To lift-up engine with gear box and refit.	\$	~ 440.00 X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	~ 440.00 X
To remove and refit air bag system and reset.	\$	~ 480.00 X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	~ 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	~ 380.00 X
To replace, refix and top up coolant for radiator	\$	~ 170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	~ 170.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	~ 170.00 X

TOTAL	\$	16,400.00
--------------	-----------	------------------

Over All Total	\$	72,160.17
-----------------------	-----------	------------------

Repair Days (PART-BY-PART)~~20 DAYS~~

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA18008418/Krbn2

(SINGAPORE BRANCH)

60 ANSON ROAD #08-01 (8th FLOOR)

MAPLETREE ANSON

SINGAPORE 079914

Date : 24-10-2018



Code : AWA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBL 9315X	Veh. Inspected	SHD 64A
Policy No.	AVMCSB0028831700	Coverage (\$)	0.00
Claim No.	NSV1800283/TKL	Excess (\$)	0.00
Assign From	HEW LEE FONG	Assign Date	08/05/2018

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	VF1ABL15AUC282221	Colour	WHITE / RED
Odometer	266875	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	4 mm
L/H Front Tyre	215/60 R16	GITI	4 mm
R/H Rear Tyre	215/60 R16	GITI	9 mm
L/H Rear Tyre	215/60 R16	GITI	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	01/05/2018	Inspection Date	08/05/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 64A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER FRT	CRACKED	1,259.42	1,259.42
1	BUMPER SPOILER FRT	DISTORTED	181.75	181.75
1	BUMPER ABSORBER FRT	CRACKED	394.68	394.68
1	BUMPER RETAINER FRT LH	DISTORTED	151.41	151.41
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER RETAINER FRT RH	TO REPAIR SEE LABOUR	150.77	-
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE LH	DISTORTED	207.21	207.21
1	BUMPER FOG LAMP GRILLE RH	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	TOW COVER FRT	SERVICEABLE	28.61	-
1	RADIATOR GRILLE	SERVICEABLE	1,707.78	-
1	RADIATOR GRILLE BADGE "RENAULT"	SERVICEABLE	225.36	-
1	RADIATOR GRILLE FRAME	SERVICEABLE	1,353.75	-
1	FRAME FULL SUPPORT PANEL	SERVICEABLE	615.90	-
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	89.79	-
1	FRONT BRACE PANEL	TO REPAIR SEE LABOUR	177.22	-
1	HORN	SERVICEABLE	314.17	-
1	HORN BRACKET	TO REPAIR SEE LABOUR	40.45	-
1	HEADLAMP LH	MTG CRACKED	1,184.43	1,184.43
1	HEADLAMP RH	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT LH	TO REPAIR SEE LABOUR	152.15	-
1	HEADLAMP PANEL FRT RH	TO REPAIR SEE LABOUR	152.15	-
1	BONNET	TO REPAIR SEE LABOUR	1,941.63	-
1	BONNET INSULATOR	SERVICEABLE	405.73	-
1	BONNET STRUT LH	SERVICEABLE	88.61	-

Report Ref No. CS/AWA18008418/Krbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET STRUT RH	SERVICEABLE	88.61	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET LOCK	TO REPAIR SEE LABOUR	305.48	-
1	BONNET CABLE	SERVICEABLE	119.19	-
1	BONNET CABLE COVER	SERVICEABLE	161.03	-
1	BONNET SEAL OUTER	SERVICEABLE	92.36	-
1	BONNET SEAL INNER	SERVICEABLE	157.28	-
1	FENDER PANEL FRT LH	TO REPAIR SEE LABOUR	783.83	-
1	WHEELARCH FRT LH	CRACKED	278.84	278.84
1	FENDER BRACKET LOWER LH	SERVICEABLE	15.79	-
1	FENDER INSULATOR LH	SERVICEABLE	130.84	-
1	FENDER INSULATOR RH	SERVICEABLE	130.84	-
1	WIPER RESERVOIR	SERVICEABLE	348.25	-
1	WIPER RESERVOIR NECK	SERVICEABLE	136.11	-
1	WIPER RESERVOIR MOTOR	SERVICEABLE	270.06	-
1	AIR CLEANER LOWER	CRACKED	271.26	271.26
1	AIR CLEANER HOSE	SERVICEABLE	76.14	-
1	BASE BATTERY TRAY	SERVICEABLE	363.40	-
1	AIR CLEANER BOX	SERVICEABLE	464.20	-
1	TURBO DUCT	SERVICEABLE	1,027.80	-
1	A/C HEATER VALVE	SERVICEABLE	484.50	-
1	SUBFRAME OUTER FRT	SERVICEABLE	2,652.45	-
1	SUBFRAME BRACKET OUTER LH	TO REPAIR SEE LABOUR	92.36	-
1	ENGINE UNDERTRAY	SERVICEABLE	564.98	-
1	A/C CONDENSER	SERVICEABLE	2,020.37	-
1	A/C CONDENSER GARNISH LH UPPER	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH RH UPPER	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH LH	SERVICEABLE	58.81	-
1	A/C CONDENSER GARNISH RH	SERVICEABLE	59.60	-
1	A/C PIPE CONDENSER TO COMPRESSOR	SERVICEABLE	208.39	-
1	A/C PIPE CONDENSER TO EXPENSION VALVE	SERVICEABLE	658.72	-
1	A/C PIPE COMPRESSOR	SERVICEABLE	334.29	-

Report Ref No. CS/AWA18008418/Krnb2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	A/C PIPE	SERVICEABLE	658.72	-
1	A/C COMPRESSOR	SERVICEABLE	2,684.61	-
1	AIR COOLER	SERVICEABLE	792.60	-
1	AIR INTERCOOLER HOSE (LONG)	SERVICEABLE	1,014.13	-
1	AIR INTERCOOLER HOSE (SHORT)	SERVICEABLE	375.14	-
1	TRANSMISSION COOLER	SERVICEABLE	1,219.30	-
1	TRANSMISSION COOLER PAD	SERVICEABLE	17.96	-
1	RADIATOR	SERVICEABLE	1,202.20	-
2	RADIATOR STUD UPPER	SERVICEABLE	14.41	-
2	RADIATOR BUSH UPPER	SERVICEABLE	50.12	-
2	RADIATOR MTG LOWER	SERVICEABLE	55.85	-
1	RADIATOR FAN COWLING	SERVICEABLE	820.54	-
1	RADIATOR FAN MOTOR LH	SERVICEABLE	967.36	-
1	RADIATOR FAN MOTOR RH	SERVICEABLE	1,479.46	-
1	RADIATOR TANK	SERVICEABLE	324.62	-
1	RADIATOR HOSE UPPER	SERVICEABLE	240.56	-
1	RADIATOR HOSE LOWER	SERVICEABLE	491.18	-
1	RADIATOR TANK HOSE	SERVICEABLE	61.18	-
1	AUTO COMPUTER	MTG CRACKED	5,032.17	5,032.17
1	INJECTION COMPUTER	SERVICEABLE	4,706.30	-
1	RHD HYDRAULIC POWER (ROCK & PINION)	TO REPAIR SEE LABOUR	5,154.52	-
1	STEERING PUMP ELECTRIC L70Y	SERVICEABLE	2,306.90	-
1	STEERING PINION RACK L70Y	TO REPAIR SEE LABOUR	4,413.11	-
	LESS 10% DISCOUNT		-6,133.09	-896.12
			55,197.67	8,065.05
	<u>SPECIAL NETT ITEMS</u>			
1	SET RADIATOR GRILLE FRAME CLIP (SN)	NOT NECESSARY	52.00	-
1	SET BUMPER CLIP FRT (SN)	NECESSARY	66.00	66.00
1	BUMPER BRACKET CLIP FRT LH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN)	NOT NECESSARY	10.50	-
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	10.50	-
1	TOW COVER FRT (SN)	SERVICEABLE	14.50	-
1	SET RADIATOR GRILLE SCREW (SN)	NOT NECESSARY	16.00	-

Report Ref No. CS/AWA18008418/Krbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET BUMPER GRILE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	NOT NECESSARY	80.00	-
			562.50	66.00
	LABOUR			
	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR INTERCOOLER.	NOT NECESSARY	170.00	-
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.}		5,400.00	400.00
	INCLUSIVE OF THE REPAIR OF BUMPER RETAINER FRT RH,BUMPER BEAM FRT,FRAME FULL SUPPORT BRACKET,FRONT BRACE PANEL,HORN BRACKET,HEADLAMP PANEL FRT LH,HEADLAMP PANEL FRT RH,BONNET,BONNET HINGE LH,BONNET HINGE RH,BONNET LOCK,FENDER PANEL FRT LH,SUBFRAME BRACKET OUTER LH,RHD HYDRAULIC POWER (ROCK & PINION) AND STEERING PINION RACK L70Y. }		-	-
	TOWING FEES.		120.00	50.00
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	440.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK/	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO LIFT-UP ENGINE WITH GEAR BOX AND REFIT,	NOT NECESSARY	440.00	-

Report Ref No. CS/AWA18008418/Krbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND RENEW POWER STEERING PUMP,OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	NOT NECESSARY	440.00	-
	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET.	NOT NECESSARY	480.00	-
	TO DROP DIESEL TANK,PIPES,HOSES TO FACILITATE BODYWORK REPAIR,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR CONDENSER.	NOT NECESSARY	380.00	-
	TO REPLACE,REFIX AND TOP UP COOLANT FOR RADIATOR.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			16,400.00	910.00
	GRAND TOTAL		72,160.17	9,041.05
RECOMMENDED COST OF REPAIRS				9,041.05

Report Ref No. CS/AWA18008418/Krbn2

KSC
KONG SENG CHEONG
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.