



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	1 2006 TOYOTA WISH 1.8 (SGK5613H)
Date of Loss	May 4, 2018
Time of Loss	15.45
Loss Description	SGK5613H (INSD) HIT REAR OF CB7501D (TP)
Comment	

Workshop Details

Total Rebate Amount	39456
Nett Loss Amount	-\$39,456.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (OD)
Days of work completion *	20



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SGK5613H

Purchase Date

mm/dd/yyyy



Registration State

SINGAPORE

Registration Date *

08/17/2006



Mileage

225061

Age of Vehicle

11

Driver Details

CATEGORY

POLICY
INFORMATION

ASSESSMENT INFORMATION

Manufacturing
Year

2006

2006

Make

TOYOTA

TOYOTA

Model

WISH 1.8

WISH 1.8 A

CATEGORY

FNOL
INFORMATIONPOST SURVEY
INFORMATION

Driver Name

TAN TEE YEOW

Date of Birth

August 15, 1959

mm/dd/yyyy



Age

59

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		
Type of Paint		
Chassis No	ZNE100306260	ZNE100306260
Engine No	1ZZ2569872	1ZZ2569872
Engine Capacity		1794
Sum Insured	0	0
Market Value	0	0

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	38	
Driver License #	S1353697Z	
License Type	3	
License Issue Date	January 30, 1980	mm/dd/yyyy 
License Expiration Date	January 1, 2050	mm/dd/yyyy 
Address	Singapore	
Address type	Personal Correspondence	

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Unknown	
Marital status	Unknown	
Identification #	S1353697Z	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

05/19/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

750

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

195/65R15

Rear Tyre Size

195/65R15

Front left side

MICHELIN6mm

Rear left side

MICHELIN6mm

Front right side

MICHELIN6mm

Rear right side

MICHELIN6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary Parts																
Add Approve Deny Submit All																
EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE	
	1	1			FRONT BONNET			Buckled	160				160	Reviewing		
	2	1			FRONT BONNET HINGE LH			Bent	22				22	Reviewing		
	3	1			FRONT BONNET HINGE RH			Bent	22				22	Reviewing		
	4	1			FRONT BONNET INSULATOR			Deformed	140				140	Reviewing		
	5	10			FRONT BONNET INSULATOR CLIPS			Necessary	1.5				15	Reviewing		
	6	1			FRONT BONNET CHROME MOULDING			Broken	90				90	Reviewing		
	7	1			FRONT BONNET RUBBER			Twisted	15				15	Reviewing		
	8	1			FRONT BONNET INNER LOCK			Bent	30				30	Reviewing		
	9	1			FRONT BONNET LOCK CABLE			Serviceable	0	0	0	0	0	Deny		
	10	1			FRONT BONNET STAND HOLDER			Missing	5				5	Reviewing		
	11	1			FRONT GRILLE			Cracked	45				45	Reviewing		
	12	6			FRONT GRILLE CLIPS			Necessary	1.5				9	Reviewing		
	13	1			HEADLAMP LH			Cracked	355				355	Reviewing		
	14	1			HEADLAMP RH			Cracked	355				355	Reviewing		

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		15	4			HEADLAMP CLIPS			Necessary	1,5				6	Reviewing	
		16	1			FRONT BUMPER			Cracked	165				165	Reviewing	
		17	1			FRONT BUMPER SIDE RETAINERS LH			Necessary	22				22	Reviewing	
		18	1			FRONT BUMPER SIDE RETAINERS RH			Necessary	22				22	Reviewing	
		19	15			FRONT BUMPER CLIPS			Necessary	1				15	Reviewing	
		20	1			FRONT BUMPER LOWER AIR GRILLE			Serviceable	0	0	0	0	0	Deny	
		21	1			FRONT BUMPER REINFORCEMENT			Serviceable	0	0	0	0	0	Deny	
		22	1			FRONT BUMPER REINFORCEMENT BRACKET LH			Serviceable	0	0	0	0	0	Deny	
		23	1			FRONT BUMPER REINFORCEMENT BRACKET RH			Serviceable	0	0	0	0	0	Deny	
		24	1			FRONT BUMPER SPONGE			Serviceable	0	0	0	0	0	Deny	
		25	1			ENGINE UNDER COVER LH			Cracked	55				55	Reviewing	
		26	1			ENGINE UNDER COVER RH			Cracked	55				55	Reviewing	
		27	10			ENGINE UNDER COVER CLIPS			Necessary	1				10	Reviewing	
		28	1			FRONT FENDER LH			Buckled	185				185	Reviewing	
		29	1			FRONT FENDER COWLING LH			Deformed	60				60	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		30	8			FRONT FENDER COWLING CLIPS			Necessary	1				8	Reviewing	
		31	1			FRONT FENDER RH			Buckled	185				185	Reviewing	
		32	1			FRONT FENDER COWLING RH			Serviceable	0	0	0	0	0	Deny	
		33	8			FRONT FENDER COWLING CLIPS			Necessary	1				8	Reviewing	
		34	1			FRONT FENDER SIGNAL LAMP RH			Serviceable	0	0	0	0	0	Deny	
		35	1			RADIATOR SUPPORT PANEL			Bent	250				250	Reviewing	
		36	1			RADIATOR SUPPORT PANEL TOP GARNISH			Cut	65				65	Reviewing	
		37	8			RADIATOR SUPPORT PANEL TOP GARNISH CLIPS			Necessary	1.8				14.4	Reviewing	
		38	1			BRACE PANEL			Bent	35				35	Reviewing	
		39	1			AIR CON CONDENSER			Bent	450				450	Reviewing	
		40	1			AIR CON CONDENSER PIPE (FROM COND TO COMP)			Bent	110				110	Reviewing	
		41	1			AIR CON CONDENSER PIPE (FROM COND TO VALVE)			Serviceable	0	0	0	0	0	Deny	
		42	1			AIR CON CONDENSER PIPE (FROM COMP TO VALVE)			Serviceable	0	0	0	0	0	Deny	
		43	1			RADIATOR ASSY			Bent	450				450	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		44	1			RADIATOR FAN MOTOR			Serviceable	0	0	0	0	0	Deny	
		45	1			RADIATOR FAN BLADE			Serviceable	0	0	0	0	0	Deny	
		46	1			RADIATOR FAN COWLING			Deformed	68				68	Reviewing	
		47	1			RADIATOR AIR GUIDE LH			Deformed	30				30	Reviewing	
		48	1			RADIATOR AIR GUIDE RH			Deformed	30				30	Reviewing	
		49	1			RADIATOR SPARE TANK			Serviceable	0	0	0	0	0	Deny	
		50	1			RADIATOR TOP BRACKET LH			Bent	18				18	Reviewing	
		51	1			RADIATOR TOP BRACKET RH			Bent	18				18	Reviewing	
		52	1			RADIATOR TOP BUSH LH			Bent	12				12	Reviewing	
		53	1			RADIATOR TOP BUSH RH			Bent	12				12	Reviewing	
		54	1			RADIATOR BOTTOM BUSH LH			Bent	15				15	Reviewing	
		55	1			RADIATOR BOTTOM BUSH RH			Bent	15				15	Reviewing	
		56	1			RADIATOR TOP HOSE			Twisted	25				25	Reviewing	
		57	1			RADIATOR BOTTOM HOSE			Serviceable	0	0	0	0	0	Deny	
		58	2			HORN			Serviceable	0	0	0	0	0	Deny	
		59	1			AIR FILTER BOX ASSY			Serviceable	0	0	0	0	0	Deny	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		60	1			AIR DUCT			Serviceable	0	0	0	0	0	Deny	
		61	1			FUSE RELAY BOX HOUSING TOP			Serviceable	0	0	0	0	0	Deny	
		62	1			FUSE RELAY BOX HOUSING BOTTOM			Serviceable	0	0	0	0	0	Deny	
		63	1			BATTERY TRAY			Serviceable	0	0	0	0	0	Deny	
		64	1			BATTERY TOP BRACKET			Serviceable	0	0	0	0	0	Deny	
		65	2			BATTERY ROD X 2			Serviceable	0	0	0	0	0	Deny	
		66	1			INTAKE FANFOLD			Serviceable	0	0	0	0	0	Deny	
		67	1			ENGINE MOUNTING FRONT			Serviceable	0	0	0	0	0	Deny	
		68	1			ENGINE MOUNTING RH			Serviceable	0	0	0	0	0	Deny	
		69	1			ENGINE MOUNTING REAR			Serviceable	0	0	0	0	0	Deny	
		70	1			GEARBOX MOUNTING LH			Serviceable	0	0	0	0	0	Deny	
		71	1			ABS PUMP			Serviceable	0	0	0	0	0	Deny	

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	30	0	0	Reviewing		

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
 	2		TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	100	0	0	Reviewing		
 	3		TO REPLACE INTAKE MANIFOLD	0	0	0	Deny		
 	4		TO REMOVE & REPLACE ENGINE MOUNTING & GEAR BOX MOUNTING	0	0	0	Deny		
 	5		TO REPLACE ABS PUMP	0	0	0	Deny		
 	6		LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	0	0	0	Deny		
 	7		TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL. TO KNOCK & REPAIR FRONT CHASSIS LH & RH, FRONT WHEELHOUSE PANEL LH & RH, FRONT DOOR LH & RH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1200	0	0	Reviewing		
 	8		TO SPRAY FRONT BONNET,FRONT BUMPER,FRONT FENDER LH & RH,FRONT DOOR LH & RH, RADIATOR SUPPORT PANEL, FRONT CHASSIS LH & RH, FRONT WHEELHOUSE PANEL LH & RH, FRONT DOOR PILLAR LH	1200	0	0	Reviewing		

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
 	1	RADIATOR SUPPORT COVER	Reviewing	20	(DEFORMED) SUPP 1 - 17/05/2018	
 	2	AIR CON CONDENSER MOUNTING X 2	Reviewing	10	(BENT)SUPP 1 - 17/05/2018	
 	3	HEADLAMP TOP PANEL LH / RH	Reviewing	100	(BENT) SUPP 1 - 17/05/2018	
 	4	TO CHANGE AIR CON VALVE SOCKET & REPAIR	Reviewing	30	SUPP 1 - 17/05/2018	
 	5	DAYS OF REPAIR : 8 DAYS	Reviewing			
 	6	COOLANT	Reviewing	30	NECESSARY	
 	7	BATTERY	Reviewing	180	DAMAGED	

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		8	NUMBER PLATE	Reviewing	35	CUT	
		9	BRAKE OIL	Deny	0	NOT NECESSARY	
		10	GRILLE STOPPER LH / RH-2PCS	Reviewing	14	NECESSARY (SUPPLEMENTARY)	

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Claim Amount \$5,875.40 Claim Amount \$5,875.40

CATEGORY	ESTIMATE	REVISED AMOUNT
Spare Parts	\$3,676.40	\$3,676.40
Labour	\$2,530.00	\$2,530.00
Miscellaneous	\$419.00	\$419.00
Excess	-\$750.00	-\$750.00

Submit for Review