

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. TIB 1158E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FLAP	DEFORMED	1,820.79	1,820.79
1	FRONT STRUCTURE METAL	DEFORMED	1,653.92	1,653.92
1	FRONT BUMPER RH	CRACKED	594.15	594.15
1	FRONT BUMPER CENTER	CRACKED	1,493.59	1,493.59
1	FRONT BUMPER LH	CRACKED	594.15	594.15
1	SIGNAL LAMP	CRACKED	128.33	128.33
1	FRONT OUTER LAMP	CRACKED	204.51	204.51
1	FRONT MOULDING	TO REPAIR SEE LABOUR	2,433.64	-
1	FRONT HEADLAMP HOUSING LH	TO REPAIR SEE LABOUR	736.46	-
1	FRONT HEADLAMP HOUSING RH	TO REPAIR SEE LABOUR	736.46	-
	LESS 10% DISCOUNT		-	-648.94
			10,396.00	5,840.50
	<u>SPECIAL NETT ITEMS</u>			
1	SMRT STICKER (S) (SN)	NECESSARY	75.00	75.00
			75.00	75.00
	<u>LABOUR</u>			
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF FRONT MOULDING , FRONT HEADLAMP HOUSING LH AND FRONT HEADLAMP HOUSING RH.		1,590.00	1,325.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		616.00	528.00
			2,206.00	1,853.00
	GRAND TOTAL		12,677.00	7,768.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,600.00

Report Ref No. CS/GAI18008561/Svbe2

Report Ref No. CS/GAI18008561/Svbe2



A handwritten signature in black ink, appearing to read 'Ho Leong Chuan' with a stylized flourish at the end.

HO LEONG CHUAN
Automotive Assessor