

Repairer's (Price-denominated Standard List)

Code: (Unsubmitted, no print-code for SHD3089J)

Notes: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Info: Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*BOOT LID *	Dented	1,681.40 FL	*1,681.40 FL ✓
1		*BOOT LID RUBBER *	Necessary	115.80 FL	*115.80 FL ✓
2		*BOOT LID HINGE (LH/RH)	Not Necessary	356.20 FL	*-FL ✓
1		*BOOT LID LOCK UPPER *	Bent	137.90 FL	*137.90 FL ✓
1		*BOOT LID LOCK LOWER	Repair	31.70 FL	*-FL ✓
1		*BOOT LID H EMBLEM *	Necessary	27.20 FL	*27.20 FL ✓
1		*BOOT LID CRDI PLATE *	Necessary	41.00 FL	*41.00 FL ✓
2		*BOOT LID LAMP (LH/RH) *	Cracked	1,113.60 FL	*1,113.60 FL ✓
1		*BOOT LID TRIMBOARD *	Torn	172.70 FL	*172.70 FL ✓
10		*BOOT LID TRIMBOARD CLIPS *	Necessary	11.00 FL	*11.00 FL ✓
1		*BOOTLID MOULDING	Not Necessary	85.00 FL	*-FL ✓
1		*BOOTLID I40 EMBLEM	Not Necessary	41.00 FL	*-FL ✓
1		*BOOTLID LOWER GARNISH	Not Necessary	398.00 FL	*-FL ✓
1		*REAR BUMPER 50%	Dented	603.60 FL	*603.60 FL ✓
1		*REAR BUMPER REINFORCEMENT	Not Necessary	504.35 FL	*-FL ✓
2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Not Necessary	360.00 FL	*-FL ✓
10		*REAR BUMPER CLIP 50%	Necessary	22.00 FL	*22.00 FL ✓
2		*REAR BUMPER BRACKET	Not Necessary	98.00 FL	*-FL ✓
1		*REAR BUMPER SPONGE	Not Necessary	143.40 FL	*-FL ✓
1		*REAR BUMPER UNDER COVER *	Distorted	225.00 FL	*225.00 FL ✓
2		*TAIL LAMP (LH/RH) *	Cracked	1,131.20 FL	*1,131.20 FL ✓
1		*TAIL LAMP QUARTER PANEL (RH)	Not Necessary	97.90 FL	*-FL ✓
1		*REAR PANEL	Repair	592.30 FL	*-FL ✓
1		*REAR PANEL GARNISH	Serviceable	57.70 FL	*-FL ✓
1		*REAR PANEL LOWER PANEL	Repair	495.50 FL	*-FL ✓
2		*EXHAUST PIPE INSULATOR	Not Necessary	117.10 FL	*-FL ✓
2		*EXHAUST SILENCER	Not Necessary	1,908.00 FL	*-FL ✓
2		*EXHAUST PIPE HANGER	Not Necessary	117.10 FL	*-FL ✓
1		*EXHAUST PIPE CENTRE	Not Necessary	1,150.30 FL	*-FL ✓
2		*REAR FENDER WITH HOUSING (LH/RH)	Buckled	9,473.60 FL	*9,473.60 FL ✓
2		*REAR FENDER INNER LINING (LH/RH)	Serviceable	328.80 FL	*-FL ✓
1		*REAR FENDER AIR-DUCT,RH	Serviceable	51.60 FL	*-FL ✓
1		*REAR WINDSCREEN MOULDING	Necessary	60.00 FL	*60.00 FL ✓
1		*REAR DOOR (LH)	Buckled	1,351.10 FL	*1,351.10 FL ✓
1		*REAR DOOR RUBBER (LH)	Deformed	280.50 FL	*280.50 FL ✓
1		*REAR DOOR OUTER MOULDING (LH)	Serviceable	212.15 FL	*-FL ✓
7		*REAR DOOR GEAR/REGULATOR (LH)	Not Necessary	785.50 FL	*-FL ✓
8		*REAR DOOR POWER MOTOR (LH)	Not Necessary	530.50 FL	*-FL ✓
9		*REAR DOOR LOCK ASSY	Damaged	321.85 FL	*321.85 FL ✓
0		*REAR DOOR HINGE UPPER (LH)	Not Necessary	53.40 FL	*-FL ✓
1		*REAR DOOR HINGE LOWER (LH)	Not Necessary	53.40 FL	*-FL ✓
2		*REAR DOOR CHECK (LH)	Not Necessary	66.50 FL	*-FL ✓

o.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
3	1		*REAR DOOR TRIM BOARD (LH)	Mounting Cracked	892.55 FL	*892.55 FL
4	1		*DOOR CENTRE PILLAR OUTER (LH)	Dented	1,786.20 FL	*1,786.20 FL
5	1		*ROCKER PANEL OUTER GARNISH (LH)	Cut	483.60 FL	*483.60 FL
6	2		*REAR TYRE RIM (LH/RH)	Not Necessary	703.80 FL	*-FL
7	2		*REAR WHEEL HUP-CAP (LH/RH)	Cut	301.40 FL	*301.40 FL
8	2		*REAR WHEEL BEARING ING & HUB	Damaged	802.80 FL	*802.80 FL
9	2		*REAR TRAILING ARM (LH/RH)	Distorted	240.00 FL	*240.00 FL
10	2		*REAR ASSIST (LH/RH)	Distorted	240.00 FL	*240.00 FL
11	2		*REAR SHOCK ABSORBER (LH/RH)	Distorted	684.40 FL	*684.40 FL
12	2		*REAR SHOCK ABSORBER MOUNTING (LH/RH)	Necessary	115.40 FL	*115.40 FL
13	1		*REAR CROSSMEMBER	Distorted	1,190.00 FL	*1,190.00 FL
14	1		*STABILIZER BAR	Distorted	204.60 FL	*204.60 FL
15	2		*STABILIZER LINK	Distorted	136.30 FL	*136.30 FL
16	2		*REAR UPPER ARM (LH/RH)	Distorted	671.50 FL	*671.50 FL
17	2		*REAR LOWER ARM (LH/RH)	Distorted	408.70 FL	*408.70 FL
18	2		*REAR KNUCKLE ARM (LH/RH)	Distorted	1,149.60 FL	*1,149.60 FL
19	1		*BOOT LID COMFORT LOGO & TEL NO STICKER	Necessary	30.00 FS	*30.00 FS
20	1		*REAR BUMPER REVERSE SENSOR	Shorted	135.70 FS	*135.70 FS
21	1		*REAR BUMPER RUBBER MAT 50%	Necessary	50.00 FS	*50.00 FS
22	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
23	1		*REAR DOOR COMFORT DELGRO & APPS STICKER (LH)	Necessary	80.00 FS	*80.00 FS
24	2		*REAR TYRE (LH/RH)	Serviceable	432.00 FS	*-FS
F=Franchise part, S=Spec/Net, L=List Item/Disc						
				Sub Total (\$\$)	36,189.40	26,418.20
				- List Item Discount on L Items 20.00/20.00% (\$\$)	7,083.14	5,215.30
				Total Parts (\$\$)	29,106.26	21,202.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING * 300/-	New	1,600.00	1,200.00 ✓
2	SPRAY PAINTING CHARGE * - \$ 300/-	New	1,200.00	800.00 ✓
3	WIRING CHARGE *	New	50.00	30.00 ✓
4	TUFF KOTE	New	80.00	40.00
5	TOWING CHARGE	New	50.00	-
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	100.00	80.00
7	REMOVE/REFIX REAR WINDSCREEN GLASS	New	100.00	80.00
8	REMOVE/REFIX UNDERCARRIAGE (RR)	New	190.00	150.00
9	TRANSFER OF DOOR	New	100.00	60.00
10	REAR WHEEL ALIGNMENT	New	120.00	60.00
11	REMOVE/REFIX REVERSE SENSOR *	New	120.00	40.00 ✓
Gross Labour Cost (\$\$)			3,710.00	2,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

* 10 days 2 days.