

ASST. REC. BY:

REF:

CS/MSG180088608/Kvbez

Special Instruction:

Survivor

Kenneth

ASSIGNMENT (Office)

Merimen

From (Person): Jasmine Lok

of

MSG1

Date/Time: 10052018 451pm

Estimated Cost:

Bill to:

OD / TH / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBG 9028B

Insured:

SLP 8434C

at Workshop m/s

Guan Motor

Tel:

of

176 Sin Ming Drive #02-03

Policy No:

MISD / VPCP / 17 - 001639

Claim No:

M8C / V/18 - 000638

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

04052018

CA / REV / REP. / REV 24 HRS Wpl

H.O.D. Endorsement:

Date/Time: 10052018

Person Contacted:

Heng

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

GBG 9028B - x

SLP 8434C - CS / MSG18003405 / R/b

DA: 040518

11/5/18

Informed Jasmine pending workshop est by merimen

L/L & 82501 email

ASS. REC. BY:

REF: MSG/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

OK 7 days

Res.: Yes or No

Lump Sum:

1.8% %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

G B G 9028

Yr Regn:

11, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

To Dyna

c.c

2982

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

11784

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFA 7 35720K 209425

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

195 R15 X8

R:

155 R12 X8 (D)

BS/DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

9

mm

Rear

R/Bal.

P P

mm

L/Bal.

P

mm

L/Bal.

P P

mm

D.O.A.

4/5/18

D.O.I.

9/5/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

ols body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

10/5

File pass to Corium, error rectify

10/8

@ Flat 86 re-tax 8508.60

17/8/18

@ 11am Final fig \$ 8508.60 confirmed with Ah Guan (Red 3082.05, 22.9)

17/9/18

@ 2:15pm Informed Ah Guan to hold back

18/9/18

@ 5:37pm Informed Ah Guan fig confirmed

RECEIVED 19 SEP 2018

RECEIVED 19 SEP 2018

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

19/9- typist

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Days Of Repair:

7

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format:

Meimen

Lump Sum / I.B.I. (\$

8508.60

200

10

210

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 May 2018		10 May 2018 16:51 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N		
Main Claimant:	HIGHLAND ENGINEERING CONSTRUCTION PTE LTD, Co. Reg. No.: 201703009R		
Vehicle Reg. No.:	GBG9028B	Date of Loss:	04/05/2018 00:00 - :59 [5 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/18-000638	Policy/Cover Note No.:	MSD/VPCP/17-001639 (Comprehensive) Coverage: 20/06/2017 - 19/06/2018
Vehicle Reg. No. (Insured):	SLP8434C	Policy No. (Claimant):	
		Excess:	
Repairer:	Guan Motor Works (HQ) 176 Sin Ming Drive #02-03 Sin Ming Autocare, 575721 Sin Ming - Tel: 64536111		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 11/05/2018]		
Adj Asg. Remarks:	ON WP Third party nominated LKK (Mr Kenneth Kong) as SJE to survey.		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***GBG9028B (MSC/V/18-000638)**
[SLP8434C]

TP

HIGHLAND ENGINEERING CONSTRUCTION PTE LTD

May 4 2018 12:00AM

[HITACHI CAPITAL ASIA PACIFIC PTE LTD]

Guan Motor Works

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **11/05/2018 10:15 AM**.

To MSIG_JLKK

Subject TP SURVEY GBG 9028B

Dear Jasmine,

Please be informed that we have inspected the vehicle GBG 9028B on 9/5/2018.

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/05/2018 11:29
Date Of Accident	04/05/2018 13:30
Exact Location Of Accident	BUANGKOK GREEN
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG9028B
Insured/Policyholder	
Name Of Registered Owner	HIGHLAND ENGINEERING CONSTRUCTION PTE LTD
Co Reg No	201703009R
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90896452
Alternative Phone No	OFFICE-90896452

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150-3.0 D 1KD (M)
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5097923035
Cover Note Number	

Driver

Name of Driver	CHANDRASEKHARAN JAYACHANDRAN
Work Permit No	G8093305W
Date Of Birth	10/05/1986
Occupation	OUTDOOR
Date Of Driving Pass	03/02/2012
Driving Experience	6 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90896452
Fax Number	(LOCAL) +65-90896452
Contact Number	
Email Address	NOEMAIL

Address	SUNGEI TENGAH LODGE, 500 OLD CHOA CHU KANG ROAD
Postcode	698924
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - EMPLOYEE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED FILE

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP8434C
Vehicle Make/Model/Colour	TOYOTA C-HR
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NEO KOP SERN
NRIC/Passport Number	S7710571I
Contact Number	91178988
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8 Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



A car going Green light.

Bangkok View

A - LORRY-GIBB 902E.

B- (AY-SLP-8439)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 04-05-2018 at 1.30pm It was green light and
I was going ^{straight} towards byangkak green. SLP 8434C
Car suddenly turn right and hit my lorry. GBS 9028 B

DECLARATION

I/We declare the foregoing  are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature _____
(if driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To check damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Date:

09-05-2018

REPAIR ESTIMATE FOR TOYOTA DYNA 150 - 3.0 D 1KD (M) - GBG 9028

B

1 pc.	Front bumper	\$ <i>Pr</i> 727.10	✓
1 pc.	Front bumper RH inner bracket	<i>Pr</i> 292.10	✓
1 pc.	RH Headlamp	<i>Gr</i> 1,460.10	✓
1 set.	Front grille centre "TOYOTA" logo	<i>Nr</i> 97.10	X
1 pc.	Front RH corner panel	<i>R</i> 285.10	X
1 pc.	Front RH door	<i>Pr</i> 1,450.45	✓
1 pc.	Front RH door front pillar outer	<i>R</i> 485.10	X
1 pc.	Front RH door inner lock	<i>Pr</i> 509.00	✓
1 pc.	Front RH door hinge (Top & Bottom)	<i>R</i> 148.20	X
1 pc.	Front RH door check	<i>Sm</i> 145.00	X
1 pc.	Front RH door weatherstrip	<i>Sm</i> 169.40	X
1 pc.	Front RH door inner trim board	<i>CM</i> 600 728.10	X
1 set.	Front RH door inner trim board clips	<i>Nr</i> 50.00	✓
1 pc.	Front RH door glass regulator	<i>Pr</i> 395.00	✓
1 pc.	Front RH door glass regulator motor	<i>Tr</i> 509.00	✓
1 pc.	Front RH step panel	<i>R</i> 435.10	X
1 pc.	Front RH step garnish	<i>Nd/Gr</i> 282.00	✓
1 pc.	Front RH mudguard	<i>Nd/Gr</i> 195.10	✓
1 pc.	Radiator spare tank	<i>Rn</i> 403.00	X
1 pc.	Front RH wheel rim	<i>Rd</i> 440.00	✓
1 pc.	Front RH shock absorber	<i>Pr</i> 210.95	✓
1 pc.	Front RH knuckle arm	<i>Pr</i> 654.00	✓
1 pc.	Front RH wheel hub & bearing	<i>Pr</i> 563.00	✓
1 pc.	Front RH lower arm	<i>Dir</i> 393.10	✓
1 pc.	Rear RH side gate front rubber stopper	<i>Mr</i> 75.00	✓
1 pc.	Rear RH lower rubber stopper bracket	<i>R</i> 123.10	X
1 set.	Rear RH lower rubber stopper	<i>Mr</i> 69.10	✓

\$ 11,294.20

Less 25%

2,823.55

\$ 8,470.65

\$ 8,470.65

Front Tyre R/H *Gr* 280/SW *Pr* 180 *Pr* 162SW

1.	Labour charges for remove/refit, cutting/welding and replacement of damages.	\$ 1,000.00	600
2.	To putty and spray spray paintings charges	1,300.00	900
3.	To check electrical wirings and lightings	40.00	200
4.	To remove, refit front RH door's fittings	80.00	600
5.	To remove, refit front RH under carriages.	250.00	1600
6.	To conduct computerize wheel alignment test.	80.00	600
7.	To supply and apply anti rust treatment	90.00	300

TOTAL (Parts and Labour) \$ 11,310.65

11,590.65

Not Authorized
\$ 8508.60
Running After Party
Today

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 08102600E

TO KENNETH

9 days

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

09-05-2018

GBG 9028

REPAIR ESTIMATE FOR TOYOTA DYNA 150 - 3.0 D 1KD-(M)

B

1 pc.	Front bumper	S	727.10	? 52101-37985
1 pc.	Front bumper RH inner bracket		292.10	
1 pc.	RH Headlamp	1145.80	1,460.10	? 81110-37660
1 set.	Front grille centre "TOYOTA" logo		97.10	
1 pc.	Front RH corner panel		285.10	
1 pc.	Front RH door		1,450.45	
1 pc.	Front RH door front pillar outer		485.10	? 69310-37090
1 pc.	Front RH door inner lock		509.00	
1 pc.	Front RH door hinge (Top & Bottom)		148.20	
1 pc.	Front RH door check		145.00	
1 pc.	Front RH door weatherstrip		169.40	
1 pc.	Front RH door inner trim board		728.10	? 61610-37090
1 set.	Front RH door inner trim board clips		50.00	
1 pc.	Front RH door glass regulator		395.00	
1 pc.	Front RH door glass regulator motor		509.00	
1 pc.	Front RH step panel		435.10	
1 pc.	Front RH step garnish		282.00	
1 pc.	Front RH mudguard		195.10	
1 pc.	Radiator spare tank		403.00	
1 pc.	Front RH wheel rim		440.00	-100%
1 pc.	Front RH shock absorber		210.95	
1 pc.	Front RH knuckle arm		654.00	? 43201-25080
1 pc.	Front RH wheel hub & bearing		563.00	
1 pc.	Front RH lower arm		393.10	
1 pc.	Rear RH side gate front rubber stopper		75.00	
1 pc.	Rear RH lower rubber stopper bracket		123.10	
1 set.	Rear RH lower rubber stopper		69.10	
		S	11,294.20	
	Less 25%		2,823.55	
		S	8,470.65	S 8,470.65

Front Tyre R/H 250/SW

1. Labour charges for remove/refit, cutting/welding and replacement of damages. S 1,000.00
2. To putty and spray spray paintings charges 1,300.00
3. To check electrical wirings and lightings 40.00
4. To remove, refit front RH door's fittings 80.00
5. To remove, refit front RH under carriages. 250.00
6. To conduct computerize wheel alignment test. 80.00
7. To supply and apply anti rust treatment 90.00

TOTAL (Parts and Labour) S 11,310.65

WORK ORDER: R040021

License: GBG9028B

Year: 08

Date 10.5.18 13:52

Toyota : Dyna : KDY/LY(220,230,250,260) Independent Front Suspension Models : 2006.9- : KDY231R-TLMKY

Front : Left

Actual	Before	Specified Range
0°30'	-0°30'	-0°15' 1°15'
		2°25' 3°55'
0°06'	0°06'	0°07' 0°12'
12°46'	12°46'	
12°16'	12°16'	

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
2°08'	-2°08'	-0°15' 1°15'
		2°25' 3°55'
0°01'	0°01'	0°07' 0°12'
14°33'	14°34'	
12°25'	12°25'	

Front

	Actual	Before	Specified Range
Cross Camber	1°38'	1°39'	-0°30' 0°30'
Cross Caster			-0°30' 0°30'
Cross SAI	-1°47'	-1°48'	-0°30' 0°30'
Total Toe	0°07'	0°07'	0°14' 0°24'
Cross Turn Diff.			

Rear : Left

Actual	Before	Specified Range
-0°13'	-0°13'	
-0°13'	-0°13'	

Camber
Toe

Actual	Before	Specified Range
-0°05'	-0°05'	
0°10'	0°10'	

Rear

	Actual	Before	Specified Range
Cross Camber	-0°08'	-0°08'	
Total Toe	-0°03'	-0°03'	
Thrust Angle	-0°12'	-0°12'	

License: GBG9028B ✓
 Year: 08
 Date 17.5.18 10:27

Toyota 2006- Dyna KDY231R-TLMKY

Front : Left			Front : Right		
Actual	Before	Specified Range	Actual	Before	Specified Range
-0°56'		-0°15' 1°15'	-0°21'		-0°15' 1°15'
		2°25' 3°55'			2°25' 3°55'
0°01'		0°07' 0°12'	-0°01'	0°07'	0°07' 0°12'
13°20'	12°18'		13°03'	11°57'	
12°24'	12°24'		12°43'	12°43'	
			Included Angle		
			Turning Angle Diff.		

Front		
	Actual	Before Specified Range
Cross Camber	-0°36'	-0°40' -0°30' 0°30'
Cross Caster		-0°30' 0°30'
Cross SAI		-0°30' 0°30'
Total Toe	0°00'	0°03' 0°14' 0°24'
Cross Turn Diff.		

Rear : Left			Rear : Right		
Actual	Before	Specified Range	Actual	Before	Specified Range
-0°16'	-0°17'		0°00'	0°02'	
0°12'	0°13'		-0°15'	-0°17'	

Rear		
	Actual	Before Specified Range
Cross Camber	-0°17'	-0°18'
Total Toe	-0°03'	-0°04'
Thrust Angle	0°14'	0°15'

Claim Documents

*GBG9028B (MSC/V/18-000638)
[SLP8434C]

TP

HIGHLAND ENGINEERING CONSTRUCTION PTE LTD

May 4 2018 12:00AM

[HITACHI CAPITAL ASIA PACIFIC PTE LTD]

Guan Motor Works

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	08/05/18 15:39	Accident Statement From:OD - Reg. No: SLP8434C, Claimant: HITACHI CAPITAL ASIA PACIFIC PTE. LTD.		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/05/18 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
2	11/05/18 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
3	11/05/18 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
4	11/05/18 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
5	11/05/18 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
6	11/05/18 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
7	11/05/18 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
8	11/05/18 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
9	11/05/18 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
10	11/05/18 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
11	11/05/18 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
12	11/05/18 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
13	11/05/18 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
14	11/05/18 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
15	11/05/18 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
16	11/05/18 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
17	11/05/18 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
18	11/05/18 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
19	11/05/18 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
20	11/05/18 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
21	11/05/18 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
22	11/05/18 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
23	11/05/18 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
24	11/05/18 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
25	19/09/18 08:40	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
26	19/09/18 08:40	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
27	19/09/18 08:40	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
28	19/09/18 08:40	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
29	19/09/18 08:40	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
30	19/09/18 08:40	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
31	19/09/18 08:40	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
32	19/09/18 08:40	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
33	19/09/18 08:40	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
34	19/09/18 08:40	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
35	19/09/18 08:40	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
36	19/09/18 08:40	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
37	19/09/18 08:40	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
38	19/09/18 08:40	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
39	19/09/18 08:40	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
40	19/09/18 08:40	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	08/05/18 15:30	TP PRI & ACCDT REPORT		Load PDF	
2	08/05/18 15:42	E-FILE REPORT (GBG9028B)		Load PDF	
3	10/05/18 14:46	TP REPLY & NOMINATED OUR COMMON SJE - LKK		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18008603/KVBE2

Date: 20/09/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VPCP/17-001639
Claimant Vehicle No :	GBG9028B	Insured Vehicle No :	SLP8434C
Date of Loss:	04/05/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-000638

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG9028B		
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Engine No:	1KD2761722
Reg. Date:	29/11/2017 (Man. Year: 2017)	Chassis No:	JTFAT35Y20K209425
Colour:	Silver	Odometer:	11784 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	155 R12X8 (D)
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 8/8 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,750.65	6,678.60	2,072.05	23.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,840.00	1,830.00	1,010.00	35.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	11,590.65	8,508.60	3,082.05	26.59

INSPECTION

Date of Assignment:	10/05/2018	
Date Inspected:	09/05/2018 Inspected At:	Guan Motor Works (HQ) 176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721
Estimated Period of Repair:	7.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 20 Sep 2018)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG9028B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	727.10 FL	*727.10 FL
2	1		*FRONT BUMPER RH INNER BRACKET	Bent	292.10 FL	*292.10 FL
3	1		*RH HEADLAMP	Cut	1,460.10 FL	*1,145.80 FL
4	1		*SET FRONT GRILLE CENTRE TOYOTA LOGO	Not Necessary	97.10 FL	*- FL
5	1		*FRONT RH CORNER PANEL	Repair	285.10 FL	*- FL
6	1		*FRONT RH DOOR	Bent	1,450.45 FL	*1,450.45 FL
7	1		*FRONT RH DOOR FRONT PILLAR OUTER	Repair	485.10 FL	*- FL
8	1		*FRONT RH DOOR INNER LOCK	Dented	509.00 FL	*509.00 FL
9	1		*FRONT RH DOOR HINGE (TOP & BOTTOM)	Repair	148.20 FL	*- FL
10	1		*FRONT RH DOOR CHECK	Serviceable	145.00 FL	*- FL
11	1		*FRONT RH DOOR WEATHERSTRIP	Serviceable	169.40 FL	*- FL
12	1		*FRONT RH DOOR INNER TRIM BOARD	Cracked	728.10 FL	*728.10 FL
13	1		*SET FRONT RH DOOR INNER TRIM BOARD CLIPS	Necessary	50.00 FL	*50.00 FL
14	1		*FRONT RH DOOR GLASS REGULATOR	Bent	395.00 FL	*395.00 FL
15	1		*FRONT RH DOOR GLASS REGULATOR MOTOR	Torn	509.00 FL	*509.00 FL
16	1		*FRONT RH STEP PANEL	Repair	435.10 FL	*- FL
17	1		*FRONT RH STEP GARNISH	Dented / Cut	282.00 FL	*282.00 FL
18	1		*FRONT RH MUDGUARD	Dented / Cut	195.10 FL	*195.10 FL
19	1		*RADIATOR SPARE TANK	Serviceable	403.00 FL	*- FL
20	1		*FRONT RH WHEEL RIM	Dented	440.00 FL	*440.00 FL
21	1		*FRONT RH SHOCK ABSORBER	Bent	210.95 FL	*210.95 FL
22	1		*FRONT RH KNUCKLE ARM	Bent	654.00 FL	*654.00 FL
23	1		*FRONT RH WHEEL HUB & BEARING	Bent	563.00 FL	*563.00 FL
24	1		*FRONT RH LOWER ARM	Distorted	393.10 FL	*393.10 FL
25	1		*REAR RH SIDE GATE FRONT RUBBER STOPPER	Missing	75.00 FL	*75.00 FL
26	1		*REAR RH LOWER RUBBER STOPPER BRACKET	Repair	123.10 FL	*- FL
27	1		*SET REAR RH LOWER RUBBER STOPPER	Missing	69.10 FL	*69.10 FL
28	1		*FRONT TYRE R/H (\$180) (90%)	Cut	280.00 FS	*162.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,574.20	8,850.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,823.55	2,172.20
Total Parts (\$\$)	8,750.65	6,678.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES FOR REMOVE / REFIT, CUTTING / WELDING AND REPLACEMENT OF DAMAGES	New	1,000.00	600.00
2	TO PUTTY AND SPRAY PAINTINGS CHARGES	New	1,300.00	900.00
3	TO CHECK ELECTRICAL WIRINGS AND LIGHTINGS	New	40.00	20.00
4	TO REMOVE, REFIT FRONT RH DOORS FITTINGS	New	80.00	60.00
5	TO REMOVE, REFIT FRONT RH UNDER CARRIAGES	New	250.00	160.00
6	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT TEST	New	80.00	60.00
7	TO SUPPLY AND APPLY ANTI RUST TREATMENT	New	90.00	30.00
Gross Labour Cost (S\$)			2,840.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 May 2018		10 May 2018 16:51 Edit Adj Rpt	S\$8,508.60 Edit Estimates	S\$8,508.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD , Co. Reg. No.: 199400399N								
Main Claimant:	HIGHLAND ENGINEERING CONSTRUCTION PTE LTD , Co. Reg. No.: 201703009R								
Vehicle Reg. No.:	GBG9028B	Date of Loss:	04/05/2018 00:00 - :59 [5 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/18-000638	Policy/Cover Note No.:	MSD/VPCP/17-001639 (Comprehensive) Coverage: 20/06/2017 - 19/06/2018						
Vehicle Reg. No. (Insured):	SLP8434C	Policy No. (Claimant):							
		Excess:							
Repairer:	Guan Motor Works (HQ) 176 Sin Ming Drive #02-03 Sin Ming Autocare, 575721 Sin Ming - Tel: 64536111								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Imm.Advice due 11/05/2018]								
Adj Asg. Remarks:	ON WP Third party nominated LKK (Mr Kenneth Kong) as SJE to survey.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									