

ASS. REC. BY:

REF:

CS/m6618008611/Kqbnz

Special Instruction:

Surveyor

ASSIGNMENT (Office) r

Melmien

From (Person):

Elaine Ngu

of

mslh

Date/Time:

08/05/2018 4:03pm

Estimated Cost:

Bill to:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLT 7692J

Insured:

GBA 1620A

at Workshop m/s

NGS Motorsport

Tel:

96953547

of

Bk 10 Amk Ind Park 2A #05-18

Policy No:

29076799 MKT

Claim No:

557624

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

03052018

CA / REV / REP. / REV 24 HRS "Up"

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Evelyn.

Vehicle IN / ☒ OUT

Date/Time

Action/Instruction (✓) Estimate

SLT 7692J - X

GBA 1620A - CS/INC 09020794 / Tip

DCA: 190509

15/5/18 @ 4.51pm revised to Elaine Ngu via Melmian.

14/6 L1 Sy 823 at email (red 83002.22, 577.)

ASS. REC. BY:

REF: MSG/Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 815K

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 045 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 8/18

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

15 Feb 1951 to Catherine

Date/Time, File Pass to?

11/16/18

Date/Time, File Return to?

2)

Report Format: MEP-7PLump Sum / I.B.I: (\$) 2300☐ : Prel. Report☐ : Final ReportDays Of Repair: 5Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)Survey Fee: 150Transportation: 10

S - RS. \$

Photos

Others

TOTAL

160Veh No: SLT 7692JYr Regn: 08, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: ToyPrius

c.c.

1998Colour: 2. Red

A/C:

Insured / Std / NI / NA

Sp. Reading: 313776

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: JTEGH23B500025892Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD / R/Rim or

Tyre Size: F: 195/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 1 mm

Rear

R/Bal. 3 mmL/Bal. 1 mmL/Bal. 3 mmD.O.A. 3/5/18D.O.I. 14/5/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 14 JUN 2018

14/6/2018

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 May 2018		08 May 2018 16:03 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	MCT RENTALS PTE LTD , Co. Reg. No.: 201800101W								
Main Claimant:	SM CAR RENTAL PTE LTD , Co. Reg. No.: 201700552G								
Vehicle Reg. No.:	SLT7692J	Date of Loss:	03/05/2018 13:00 - :59 [116 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 557624	Policy/Cover Note No.:	29076799MKF (Third Party Only) Coverage: 01/04/2018 - 31/03/2019						
Vehicle Reg. No. (Insured):	GBA1620A	Policy No. (Claimant):							
		Excess:							
Repairer:	Ngs Motorsport Pte Ltd (HQ) Blk 10 Ang Mo Kio Ind Pk 2A, #05-18 AMK AutoPoint, 568047 Ang Mo Kio - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 09/05/2018]								
Adj Asg. Remarks:	TP AGREE SJE AS LKK. PLS KINDLY ARRANGE								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Joseph Inhouse

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 15 May 2018

Preliminary Advice

Insured Vehicle No	: GBA1620A	Accident Date	: 03/05/2018
TP Vehicle No	: SLT7692J	Assignment Date	: 08/05/2018
Make	: TOYOTA PICNIC	Est. Duration of Repair	: 5.00
Date of Inspection	: 14/05/2018		
Inspection At	: NGS MOTORSPORT PTE LTD (HQ) BLK 10 ANG MO KIO IND PK 2A, #05-18 AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,302.22
Revised Amount	:S\$	3,368.89
Check Items (Estimated)	:S\$	806.64
Total	:S\$	4,175.53

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0552G
Vehicle Details	
Vehicle No.:	SLT7692J
Vehicle to be Exported:	No
Intended De-registration Date:	15 May 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PICNIC AUTO W/O ROOF RACK
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	1AZ5794738
Chassis No.:	JTEGH23B500025892
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$24,659.00
Original Registration Date:	28 Aug 2008
First Registration Date:	28 Aug 2008
Transfer Count:	4
Actual ARF Paid:	\$24,659.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Aug 2018
PARF Rebate Amount:	\$12,329.00
Intended COE Rebate Details	
COE Expiry Date:	27 Aug 2018
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$14,235.00
COE Rebate Amount:	\$401.00
Total Rebate Amount:	\$12,730.00

The information contained herein is correct as at 15 May 2018

OK

NGS MOTORSPORT PTE LTD

Blk 10 Ang Mo Kio Industrial Park 2A #02-01 AMK AutoPoint Singapore 568047

Tel :9695 5547 Fax: 6481 5727 e-mail : evelynnngstrading@gmail.com

Reg No: 201812604N

Our Ref: MS20180404/SLT7692J

MSIG

Attn: Motor Claims Dept

Dear Sir,

RE: ACCIDENT ON 03/05/2018 @13:00HRS

VEH NO.: SLT7692J & GBA1620A

CLAIMS AGAINST GBA1620A

We submit herewith our direct claim estimate quotation as follow:-

Replacement parts:

- | | |
|---|---------------------------|
| 1 | RR Boot Lock |
| 1 | RR Boot Lid |
| 1 | Garnish, RR Boot Lid |
| 2 | Lamp, Boot Lid RH/LH |
| 2 | Reflexor, RR Bumper RH/LH |
| 1 | RR Bumper |
| 1 | End Panel |
| 1 | Garnish, End Panel |
| 1 | Compartment Panel |
| 2 | Taillamp RH/LH |

nd	\$	213.31	—
B	\$	1,388.50	—
wap	\$	333.87	—
Ln	\$	179.10	X
Ln	\$	48.97	X
Bu	\$	461.57	—
A	\$	356.81	X
Ln	\$	212.04	X
A	\$	673.98	X
Ln	\$	226.88	X

\$ 4,095.03

Less 25% \$ 1,023.76

\$ 3,071.27

- | | | |
|---|---------------------|--------|
| 1 | RR Boot Clips 20pcs | S.Nett |
| 1 | Parking Camera | S.Nett |
| 1 | Reverse Sensor | S.Nett |
| 1 | Enblem Bagde | S.Nett |
| 1 | LOGO "TOYOTA" | S.Nett |
| 1 | LOGO "PINIC" | S.Nett |

na	\$	5.00	— 50.00
Ln	\$	380.00	X
cm	\$	280.00	—
na	\$	72.45	—
na	\$	48.42	—
na	\$	45.08	—

\$ 600.00 500

To remove all damaged part with all necessary component/attachment

Straighten chassis member, repair/reshape dented body panel..

Replace damaged part. Refit into position.

To spray paint replace/repair body part.

Check wiring & light function

\$ 750.00 600

\$ 50.00 200

\$ 5,302.22

5347.22

Any other parts which necessitate repair or renewal will incur additional charged.

Please contact our Ms Evelyn @HP96955547 to arrange for survey. Thank you

Yours faithfully,

NGS MOTORSPORT PTE LTD

EVELYN NG

LKK Auto Consultancy hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18008611/KQBN2

Date: 18/06/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29076799MKF
Claimant Vehicle No :	SLT7692J	Insured Vehicle No :	GBA1620A
Date of Loss:	03/05/2018	Nature of Claim:	TP
		Claim No:	557624

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT7692J	Engine No:	1AZ5794738
Make & Model:	TOYOTA PICNIC, 2.0 W/O ROOF RACK (A)	Chassis No:	JTEGH23B500025892
Reg. Date:	28/08/2008 (Man. Year: 2008)	Odometer:	313776 km
Colour:	Metallic Red		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R16	Rear Tyre Size:	195/60 R16
Front Left Side:	Bridgestone 1 mm	Rear Left Side:	Bridgestone 3 mm
Front Right Side:	Bridgestone 1 mm	Rear Right Side:	Bridgestone 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,947.22	2,293.89	1,653.33	41.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	1,120.00	280.00	20.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,347.22	3,413.89	1,933.33	36.16
Approved Total (Overridden) (S\$)		2,300.00		
Nett Amount (S\$)	5,347.22	2,300.00	3,047.22	56.99

INSPECTION

Date of Assignment:	08/05/2018	
Date Inspected:	14/05/2018 Inspected At:	Ngs Motorsport Pte Ltd (HQ) Blk 10 Ang Mo Kio Ind Pk 2A, #05-18 AMK AutoPoint Singapore 568047
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jun 2018)
Parts:	M1-MPV	TOYOTA PICNIC 2.0 W/O ROOF RACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT7692J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR BOOT LOCK	Dented	213.31 FL	*213.31 FL
2	1		*RR BOOT LID	Bent	1,388.50 FL	*1,388.50 FL
3	1		*GARNISH,RR BOOT LID	Warped	333.87 FL	*333.87 FL
4	2		*LAMP,BOOT LID RH/LH	Serviceable	179.10 FL	*. FL
5	2		*REFLECTOR,RR BUMPER RH/LH	Serviceable	48.97 FL	*. FL
6	1		*RR BUMPER	Buckled	461.57 FL	*461.57 FL
7	1		*END PANEL	Repair	356.81 FL	*. FL
8	1		*GARNISH,END PANEL	Serviceable	212.04 FL	*. FL
9	1		*COMPARTMENT PANEL	Repair	673.98 FL	*. FL
10	2		*TAILLAMP RH/LH	Serviceable	226.88 FL	*. FL
11	20		*RR BOOT CLIPS	Necessary	50.00 FS	*50.00 FS
12	1		*PARKING CAMERA	Serviceable	380.00 FS	*. FS
13	1		*REVERSE SENSOR	Cracked	280.00 FS	*280.00 FS
14	1		*EMBLEM BADGE	Necessary	72.45 FS	*72.45 FS
15	1		*LOGO TOYOTA	Necessary	48.42 FS	*48.42 FS
16	1		*LOGO PINIC	Necessary	45.08 FS	*45.08 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,970.98	2,893.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,023.76	599.31
Total Parts (\$\$)	3,947.22	2,293.89

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items**There are no new miscellaneous items selected.****Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL DAMAGED PART WITH ALL NECESSARY COMPONENT/ATTACHMENT.STRAIGHTEN CHASSIS MEMBER,REPAIR/RESHAPE DENTED BODY PANEL.REPLACE DAMAGED PART.REFIT INTO POSITION	New	600.00	500.00
2	TO SPRAY PAINT REPLACE/REPAIR BODY PART	New	750.00	600.00
3	CHECK WIRING & LIGHT FUNCTION	New	50.00	20.00
Gross Labour Cost (S\$)			1,400.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >