

22/03/2017

ASS. BY: BY:

REF: CS/MSG/17017290/BS-6-1

Special Instruction:

Surveyor:

Wilson

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

MSLH

Date/Time:

08/05/2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKM 40555

Insured:

FX 8663L

at Workshop m/s

N-51 Automated

Tel:

of

2 KDA Bukit Air 2 #01-17

Policy No:

MSD/VMT/17-983224-WTI

Claim No:

MSC/V/17-001365

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

03/09/2017

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement:

Date/Time:

08/05/2017 10:17am

Person Contacted:

Elynn

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate	Don't finalize
	SKM 40555 - X	
	FX 8663L - NOH/MSG/15015132/Y-D.O.A. 30/3/2015	...
	Dismantle Part: 07/09/2017	
	After repair: 11/09/2017	
03-10-17 330pm Email to Katherine Wong thru Melimen.		

21/05/18 (\$8,016.52 4x \$2,550/-) 4 days? Reduc - 68%

Labour 4 days
17/5/18


21/5/2018

RECEIVED 21 MAY 2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Sep 2017		06 Sep 2017 08:37 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	RAJESH KUMAR S/O RAMPARCH, ID: S7234458H, Tel: +6591620176, Email: NOEMAIL								
Main Claimant:	Karthigaisamy Srihar Selvan, ID: S8260462F								
Vehicle Reg. No.:	SKM4055S	Date of Loss:	03/09/2017 10:00 - :59 [105 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/17-001365	Policy/Cover Note No.:	MSD/VMT/17-983224-WTT (Comprehensive) Coverage: 31/05/2017 - 30/05/2018						
Vehicle Reg. No. (Insured):	FX8663L	Policy No. (Claimant):	Excess:						
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Final Rpt due 10/05/2018]								
Driver/Custodian (Insured):	RAJESH KUMAR S/O RAMPARCH (44 / Male), NRIC: S7234458H, Tel: +6591620176								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
MSIG_SG (08/05/2018): Report Send Back Alerts - SKM4055S (TP)									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
REAR BOOTLID	1	buckled	610.70	610.70 R X
REAR BOOTLID '1.8' EMBLEM	1	necessary	16.40	16.40
REAR BOOTLID 'H' LOGO EMBLEM	1	necessary	25.70	25.70 } nec ✓
REAR BOOTLID 'I-VTEC' EMBLEM	1	necessary	33.70	33.70
REAR BOOTLID HINGES L/R	2	repair	93.40	0.00
REAR BOOTLID INNER UPHOLSTERY TRIM GARNISH	1	deformed	133.70	133.70 SVC X
REAR BOOTLID MECHANISM LOCK	1	bent	187.00	187.00 BT ✓
REAR BOOTLID REFLECTOR LAMP BACK RUBBER SEAL L/R	2	necessary	29.80	29.80 SVC X
REAR BOOTLID REFLECTOR LAMP L/R	2 1	fractured LH	404.40	202.20 404.40 CR ✓ Δ
REAR BOOTLID RUBBER GUIDE STOPPER L/R	2	deformed	21.00	21.00 SVC X
REAR BOOTLID RUBBER PROTECTOR L/R	2	deformed	29.00	29.00 SVC
REAR BOOTLID WEATHERSTRIP	1	deformed	91.10	91.10 de ✓
REAR BUMPER	1	squashed	638.00	638.00 de ✓
REAR BUMPER RH LOWER GARNISH	1	reuse	19.50	0.00 X
REAR BUMPER SIDE RETAINER L/R	2	necessary	28.20	28.20 nec ✓
REAR END PANEL	1	buckled	300.50	300.50 R X
REAR END PANEL INNER TOP GARNISH	1	fractured	58.40	58.40 ✓
REAR FENDER INNER UPHOLSTERY TRIM GARNISH L/R	2	deformed	291.80	291.80 SVC X
REAR NUMBER PLATE GARNISH	1	warped	121.60	121.60 SVC X
REAR NUMBER PLATE LAMP L/R	2	fractured	52.00	52.00 SVC X X Δ
REAR SPARE TYRE INNER UPHOLSTERY TOP COVER	1	deformed	316.00	316.00 SVC X
REAR TAILLAMP BACK RUBBER SEAL L/R	2	necessary	29.80	29.80 nec ✓
REAR TAILLAMP L/R	1 2	fractured LH	617.40	308.70 617.40 CR ✓ Δ
REAR TAILLAMP LOWER BRACKET L/R	2	bent	27.80	27.80 R X
Subtotal before discount			S\$ 4,176.90	S\$ 4,064.00 2514.80
Percentage discount 20% and 20%			S\$ 835.38	S\$ 812.80 502.96
Sub-total 1			S\$ 3,341.52	S\$ 3,251.20 2011.86
REAR BOOTLID INNER UPHOLSTERY TRIM GARNISH CLIPS - SET	1	necessary	50.00	50.00 NN X
REAR BOOTLID REVERSE CAMERA	1	shorted	800.00	800.00 R X
REAR BUMPER CLIPS - SET	2	necessary	100.00	35 100.00 nec ✓ Δ
REAR BUMPER REVERSE SENSOR - SET	1	shorted	350.00	200 350.00 SC ✓
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	necessary	30.00	30.00 NN X
REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R - SET	2	necessary	100.00	100.00 NN X
REAR NUMBER PLATE	1	reuse	25.00	0.00 X
REAR NUMBER PLATE GARNISH CLIPS - SET	1	necessary	30.00	30.00 nec ✓
REAR NUMBER PLATE HOLDER	1	fractured	50.00	50.00 NN X
REAR TAILLAMP CLIPS L/R - SET	1	necessary	30.00	30.00 nec ✓
Subtotal before discount			S\$ 1,565.00	S\$ 1,540.00 360.00
Sub-total 2			S\$ 1,565.00	S\$ 1,540.00 360.00
Parts-total			S\$ 4,906.52	S\$ 4,791.20 2371.86

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

100.00 60.00 ✓ 40/-

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

140.00 60.00 ✓ 40/-

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

1,400.00 1,200.00 400/-

To remove and reinstall exhaust pipe.

150.00 0.00 X

To provide labour, workmanship to change the above damaged bodyparts, repair, reconstruct and re-align body structure, body alignments and damaged consistent to the accident.

1,200.00 1,100.00 500/-

To apply anti-rust chemical on repaired and replaced panel.

120.00 60.00 X

Labour Total	SS 3,110.00	SS 2,480.00	1020.00
Parts & Labour Total	SS 8,016.52	SS 7,271.20	3391.86

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : SS 6,200.00 and the recommended number of working days for the repairs is within 7 day(s).


B J Loi (1 Eng., MIMI, AIRTE)
Automotive Appraiser

Labour 4 days

17/5/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Sep 2017		06 Sep 2017 08:37 Edit Adj Rpt	S\$2,550.00 Edit Estimates	S\$2,550.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	RAJESH KUMAR S/O RAMPARCH, ID: S7234458H, Tel: +6591620176, Email: NOEMAIL		
Main Claimant:	Karthigaisamy Srithar Selvan, ID: S8260462F		
Vehicle Reg. No.:	SKM4055S	Date of Loss:	03/09/2017 10:00 - :59 [105 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/17-001365	Policy/Cover Note No.:	MSD/VMT/17-983224-WTT (Comprehensive) Coverage: 31/05/2017 - 30/05/2018
Vehicle Reg. No. (Insured):	FX8663L	Policy No. (Claimant):	
		Excess:	
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Final Rpt due 10/05/2018]		
Driver/Custodian (Insured):	RAJESH KUMAR S/O RAMPARCH (44 / Male), NRIC: S7234458H, Tel: +6591620176		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (08/05/2018): Report Send Back Alerts - SKM4055S (TP)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKM4055S (MSC/V/17-001365)**
[FX8663L]

TP

Karthigaisamy Srithar Selvan
Sep 3 2017 10:00AM
[RAJESH KUMAR S/O RAMPARCH]
N-51 Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports

1 per page ▼

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	05/09/17 16:44	Accident Statement From: SC - Reg. No: FX8663L, Claimant: RAJESH KUMAR S/O RAMPARCH	Load HTM	

Photos/Images

3 per page ▼

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/10/17 15:27	General View	Load JPG	
2	03/10/17 15:27	General View	Load JPG	
3	03/10/17 15:27	General View	Load JPG	
4	03/10/17 15:27	General View	Load JPG	
5	03/10/17 15:27	General View	Load JPG	
6	03/10/17 15:27	General View	Load JPG	
7	03/10/17 15:27	General View	Load JPG	
8	03/10/17 15:27	General View	Load JPG	
9	03/10/17 15:27	General View	Load JPG	
10	03/10/17 15:27	General View	Load JPG	
11	03/10/17 15:27	General View	Load JPG	
12	03/10/17 15:27	General View	Load JPG	
13	03/10/17 15:27	General View	Load JPG	
14	03/10/17 15:27	General View	Load JPG	
15	03/10/17 15:27	General View	Load JPG	
16	03/10/17 15:27	Odometer Reading	Load JPG	
17	03/10/17 15:27	General View	Load JPG	
18	03/10/17 15:27	Chassis Number	Load JPG	
19	03/10/17 15:28	Photographs of Damaged Parts	Load JPG	
20	03/10/17 15:28	Photographs of Damaged Parts	Load JPG	
21	03/10/17 15:28	Photographs of Damaged Parts	Load JPG	
22	03/10/17 15:28	Photographs of Damaged Parts	Load JPG	
23	03/10/17 15:28	Photographs of Damaged Parts	Load JPG	
24	03/10/17 15:28	Photographs of Damaged Parts	Load JPG	
25	03/10/17 15:28	Photographs of Damaged Parts	Load JPG	
26	03/10/17 15:28	Photographs of Damaged Parts	Load JPG	
27	03/10/17 15:28	Photographs of Damaged Parts	Load JPG	
28	03/10/17 15:28	Photographs of Damaged Parts	Load JPG	
29	03/10/17 15:28	Photographs of Damaged Parts	Load JPG	
30	03/10/17 15:28	Photographs of Damaged Parts	Load JPG	
31	03/10/17 15:28	Photographs of Damaged Parts	Load JPG	

Assessment Reports			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	03/10/17 15:28	Photographs of Damaged Parts	 Load JPG	✓
33	03/10/17 15:28	Photographs of Damaged Parts	 Load JPG	✓
34	03/10/17 15:28	Photographs of Damaged Parts	 Load JPG	✓
35	03/10/17 15:28	Photographs of Damaged Parts	 Load JPG	✓
36	03/10/17 15:28	Photographs of Damaged Parts	 Load JPG	✓
37	03/10/17 15:28	Photographs of Damaged Parts	 Load JPG	✓
38	03/10/17 15:28	Photographs of Damaged Parts	 Load JPG	✓
39	03/10/17 15:28	Photographs of Damaged Parts	 Load JPG	✓
40	03/10/17 15:28	Photographs of Damaged Parts	 Load JPG	✓
41	03/10/17 15:28	Photographs of Damaged Parts	 Load JPG	✓
42	03/10/17 15:28	Photographs of Damaged Parts	 Load JPG	✓
43	03/10/17 15:28	Photographs of Damaged Parts	 Load JPG	✓
44	03/10/17 15:28	Photographs of Damaged Parts	 Load JPG	✓
45	03/10/17 15:28	Photographs of Damaged Parts	 Load JPG	✓
46	03/10/17 15:28	Photographs of Damaged Parts	 Load JPG	✓
47	03/10/17 15:28	Photographs of Damaged Parts	 Load JPG	✓
48	03/10/17 15:28	Photographs of Damaged Parts	 Load JPG	✓
49	03/10/17 15:28	Photographs of Damaged Parts	 Load JPG	✓
50	03/10/17 15:28	Photographs of Damaged Parts	 Load JPG	✓
51	03/10/17 15:28	Photographs of Damaged Parts	 Load JPG	✓
52	03/10/17 15:28	Photographs of Damaged Parts	 Load JPG	✓
53	03/10/17 15:28	Photographs of Damaged Parts	 Load JPG	✓
54	03/10/17 15:28	Photographs of Damaged Parts	 Load JPG	✓
55	03/10/17 15:28	Photographs of Damaged Parts	 Load JPG	✓
56	03/10/17 15:28	Photographs of Damaged Parts	 Load JPG	✓
57	03/10/17 15:28	Photographs of Damaged Parts	 Load JPG	✓
58	03/10/17 15:28	Photographs of Damaged Parts	 Load JPG	✓
59	03/10/17 15:28	Photographs of Damaged Parts	 Load JPG	✓
60	03/10/17 15:28	Photographs of Damaged Parts	 Load JPG	✓
61	03/10/17 15:28	Photographs of Damaged Parts	 Load JPG	✓
62	03/10/17 15:28	Photo After Spray	 Load JPG	✓
63	03/10/17 15:28	Photo After Spray	 Load JPG	✓
64	03/10/17 15:28	Photo After Spray	 Load JPG	✓
65	03/10/17 15:28	Photo After Spray	 Load JPG	✓
66	03/10/17 15:28	Photo After Spray	 Load JPG	✓
67	03/10/17 15:28	Photo After Spray	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	05/09/17 16:44	SKM4055S E FILE REPORT From: SC - Reg. No: FX8663L, Claimant: RAJESH KUMAR S/O RAMPARCH	 Load PDF	
2	06/09/17 08:37	Rejection Email on SJE to TP	 Load PDF	
3	06/09/17 09:09	PRI Details	 Load PDF	
4	08/05/18 12:59	SURVEY REPORT	 Load PDF	
5	08/05/18 12:59	SURVEY PHOTO 1	 Load PDF	
6	08/05/18 12:59	SURVEY PHOTO 2	 Load PDF	
7	08/05/18 12:59	SURVEY PHOTO 3	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/05/18 13:50	PRS INVOICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17017290/BSBS2-12
Date: 25/05/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VMT/17-983224-WTT
Claimant Vehicle No : SKM4055S **Insured Vehicle No :** FX8663L
Date of Loss: 03/09/2017 **Nature of Claim:** TP **Claim No:** MSC/V/17-001365

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKM4055S**
 Make & Model: HONDA CIVIC, 1.8 L (A) Engine No: R18A14003786
 Reg. Date: 17/11/2008 (Man. Year: 2008) Chassis No: JHMF16309S200567
 Colour: Silver Odometer: 197627 km
 Engine Capacity: 1799 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45R17 Rear Tyre Size: 215/45R17
 Front Left Side: Goodyear 4 mm Rear Left Side: Goodyear 4 mm
 Front Right Side: Goodyear 4 mm Rear Right Side: Goodyear 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,906.52	1,590.36	3,316.16	67.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,110.00	980.00	2,130.00	68.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,016.52	2,570.36	5,446.16	67.94
Approved Total (Overridden) (S\$)		2,550.00		
(S\$)	8,016.52	2,550.00	5,466.52	68.19
+ GST 7.00/7.00% (S\$)	561.16	178.50	382.66	68.19
Nett Amount (S\$)	8,577.68	2,728.50	5,849.18	68.19

INSPECTION

Date of Assignment: 06/09/2017
 Date Inspected: 06/09/2017 Inspected At: N-51 Automotive Pte Ltd (HQ)
 BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB
 Singapore 417921
 Estimated Period of Repair: 4.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printprt&caseid=634519&extid=249673&CFID=34392390&CFTOKEN=6

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 May 2018)
Parts:	143	HONDA CIVIC 1.8 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKM4055S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BOOTLID	Repair	610.70 FL	*- FL
2	1	*REAR BOOTLID 1.8 EMBLEM	Necessary	16.40 FL	*16.40 FL
3	1	*REAR BOOTLID H LOGO EMBLEM	Necessary	25.70 FL	*25.70 FL
4	1	*REAR BOOTLID I-VTEC EMBLEM	Necessary	33.70 FL	*33.70 FL
5	2	*REAR BOOTLID HINGES L/R	Repair	93.40 FL	*- FL
6	1	*REAR BOOTLID INNER UPHOLSTERY TRIM GARNISH	Serviceable	133.70 FL	*- FL
7	1	*REAR BOOTLID MECHANISM LOCK	Bent	187.00 FL	*187.00 FL
8	2	*REAR BOOTLID REFLECTOR LAMP BACK RUBBER SEAL L/R	Serviceable	29.80 FL	*- FL
9	1	*REAR BOOTLID REFLECTOR LAMP L/R	N/s Cracked	404.40 FL	*202.20 FL
10	2	*REAR BOOTLID RUBBER GUIDE STOPPER L/R	Serviceable	21.00 FL	*- FL
11	2	*REAR BOOTLID RUBBER PROTECTOR L/R	Serviceable	29.00 FL	*- FL
12	1	*REAR BOOTLID WEATHERSTRIP	Deformed	91.10 FL	*91.10 FL
13	1	*REAR BUMPER	Deformed	638.00 FL	*638.00 FL
14	1	*REAR BUMPER RH LOWER GARNISH	Reuse	19.50 FL	*- FL
15	2	*REAR BUMPER SIDE RETAINER L/R	Necessary	28.20 FL	*28.20 FL
16	1	*REAR END PANEL	Repair	300.50 FL	*- FL
17	1	*REAR END PANEL INNER TOP GARNISH	Fractured	58.40 FL	*58.40 FL
18	2	*REAR FENDER INNER UPHOLSTERY TRIM GARNISH L/R	Serviceable	291.80 FL	*- FL
19	1	*REAR NUMBER PLATE GARNISH	Serviceable	121.60 FL	*- FL
20	2	*REAR NUMBER PLATE LAMP L/R	Serviceable	52.00 FL	*- FL
21	1	*REAR SPARE TYRE INNER UPHOLSTERY TOP COVER	Serviceable	316.00 FL	*- FL
22	2	*REAR TAILLAMP BACK RUBBER SEAL L/R	Necessary	29.80 FL	*29.80 FL
23	1	*REAR TAILLAMP L/R	N/s Cracked	617.40 FL	*308.70 FL
24	2	*REAR TAILLAMP LOWER BRACKET L/R	Repair	27.80 FL	*- FL
25	1	*SET REAR BOOTLID INNER UPHOLSTERY TRIM GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
26	1	*REAR BOOTLID REVERSE CAMERA	Repair	800.00 FS	*- FS
27	2	*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*35.00 FS
28	1	*SET REAR BUMPER REVERSE SENSOR	Short Circuit	350.00 FS	*200.00 FS
29	1	*SET REAR END PANEL INNER TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
30	2	*SET REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R	Not Necessary	100.00 FS	*- FS
31	1	*REAR NUMBER PLATE	Reuse	25.00 FS	*- FS
32	1	*SET REAR NUMBER PLATE GARNISH CLIPS	Necessary	30.00 FS	*30.00 FS
33	1	*REAR NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
34	1	*SET REAR TAILLAMP CLIPS L/R	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,741.90	1,914.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	835.38	323.84
Total Parts (\$\$)	4,906.52	1,590.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR.	New	100.00	40.00
2	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)	New	140.00	40.00
3	TO RE-SPRAY PAINTING ON THE REAR BOOTLID, REAR END PANEL, REAR FENDER (L/R), SPARE TYRE PANEL AND REAR BUMPER.	New	1,400.00	400.00
4	TO REMOVE AND REINSTALL EXHAUST PIPE.	New	150.00	0.00
5	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.	New	1,200.00	500.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.	New	120.00	0.00

Gross Labour Cost (S\$)**3,110.00****980.00**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >