

INS. CASE OWNER:

CC3 / CTI1800 8647, Sub 112

LKK:
IDAC:

Surveyor:

YWK

DOI:

ASSIGNMENT

11/5/18

Date / Time:

11/5/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJM 850XD

Name of Insured:

BASHEER AHMED JUMAD AHMED

Insured Tel No.:

HP:

98581503

Excess Sec II :SS

D.O.A:

2/5/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

SNM801238207

Policy No.:

DMPCLN 3037561700

Make / Model:

MISAW

Place of Accident:

PIE

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SJM 850XD

SHL 4398R

SHF 300H



INSRS:

WSP:

Tel:

Liability:

RMKS:

01



INSRS:

WSP:

Tel:

Liability:

RMKS:

SMRT

TP



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

23/5/18
TH

SHL 4398R -x

SJM 850XD -x

3 vehicle chain collision OI last

RECEIVED 11 SEP 2018

STAGE	DATE / PIC
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	
After call ltr to OI:	
Documentation Check List:	Handler Typist
Notification ltr (if non-pickup)	
After call ltr to OI:	
Authorisation To Act:	
Release Voucher:	
Final Repair Bill:	
Car Rental Invoice:	
Towing Invoice	
UTA / GIA:	
Medical Bill:	
PIR:	
Mandate/Reject Instruction:	
LOD	
Payment Breakdown Form:	
Post-Repair Photos:	
Others:	

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	SS	() days	Reduction: %
FINAL SETTLEMENT		Date/Time: 31/8/18	Confirm with Lee Gek
Final Liability:	%	100	(Agreed / Assessed) BOLA S/N No.: 28
Repair Cost:	SS	11000.00	
Loss of Rental (LOR):	SS	1335.36	(12 days) x 111.28
Loss of Use (LOU):	SS	(\$) x days	
Loss of Income (LOI):	SS	(\$) x days	
LOR only	☐	LOU only	☐
LOR + LOU	☐	LOR + LOI	☐
[Tick only one]			
GIA/LTA Search	SS	7.00	
Medical:	SS		
Disbursement:	SS		(e.g. Tow/ Independent)
Legal Cost	SS		
Total:	SS	12342.36	Global Sum SS: 12340.00
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	SS	12340.00	Name 1: SMRT TAXIS PTE LTD
Payee 2: (Strike if N.A.)	SS		Name 2:
Payee 3: (Strike if N.A.)	SS		Name 3:

COPY SENT

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

a

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No.

54C 4398R

Yr Regn:

6/11/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

C.C. 1798

Colour

Maroon

A/C: Insured / Std / NI / NA

Sp. Reading

423089

T/Radio: Insured / Std / NI / NA

Eng/No:

JTDKN364705720318

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size:

F: 195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

7/5/18

D.O.I.

7/5/18

Survey held at

SMART

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

LIS - \$11000 (Red: \$22737.82/67%)

TAX 105/18/2041

LKK
Ching Tai Ping

SYM 85020

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Report Format:

Lump Sum / I.B.I. (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : GC3/CTI18008647/Sub3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 11-05-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJM 8502D	Veh. Inspected	SHC 4398R
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	11/05/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	07/05/2018	Inspection Date	09/05/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTI18008647/Sub3

Date: 11.05.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC4398R


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 09.05.2018 at the premises of M/s SMRT Automotive Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	23,849.88
Revised Estimate Amount	: S\$	6,279.07
"Check" Items Amount	: S\$	13,958.42
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Front & Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 7 days

Yours faithfully,

SEBASTIAN YEANG
Licensed Appraiser

Shu Pei (LKKAUTO)

From: Lucas Lee <luccs.lee@sg.cntaiping.com>
Sent: Friday, 11 May 2018 4:02 PM
To: Shu Pei (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving SJM8502D (OI : CTI - SNM18D02338C02) and SHC4398R (TP : LKK REF - CC3/CTI18008647/Sub3) on 07.05.2018
Attachments: leeSZ_SNM18D02338C02-SJM8502D-LKKDirectSettlementAccidentLtr_CLCR95.903.pdf; MCHM18059904-SJM8502D.pdf

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Sharon Han

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175
Email: luccs.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Friday, 11 May, 2018 3:06 PM
To: Claims Dept of CTI
Cc: Sharon Han; Angie Foo; Admin A; Thin Thin (LKKAUTO)
Subject: Direct Settlement - Accident Involving SJM8502D (OI : CTI - TBA) and SHC4398R (TP : LKK REF - CC3/CTI18008647/Sub3) on 07.05.2018

WITHOUT PREJUDICE

Dear Sharon,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHC 4398R at M/s SMRT Automotive Services Pte Ltd.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair
- Preliminary advice

Our case handler in-charge is Thin Thin and she can be contacted at DID: 6841 2360.

Thank You.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Tel: 6389 6111 Fax: 6222 1033

Website: www.sg.cntaiping.com

Co. Reg. No. 200208384E

Our Reference: **SNM18D02338/C02/2**

Date : **11 MAY 2018**

via Ordinary & Registered Mail

**BASHEER AHMED JUNAID AHMED
BLK 8 JALAN BUKIT HO SWEE
#03-94 BUKIT HO SWEE VIEW
SINGAPORE 161008**

Dear Sir / Madam

**ACCIDENT INVOLVING SJM8502D AND SHC4398R ON 07 MAY 2018
ALONG PIE BEFORE KALLANG EXIT**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHC4398R**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,

Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : THIN THIN

Ref : CC3/CTI18008647/SUB3

Contact No : 68412360

via Email : THINTHIN@LKKAUTO.COM

CC : Agent - (AN0584A) - HUANG GUOQING, TERRY

F01/LKKDS-2013

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHC4398R
Vehicle to be Exported:	No
Intended De-registration Date:	11 May 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2013
Engine No.:	2ZR5935466
Chassis No.:	JTDKN36U905720518
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,120.00
Original Registration Date:	06 Jan 2014
First Registration Date:	06 Jan 2014
Transfer Count:	0
Actual ARF Paid:	\$8,368.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Jan 2022
PARF Rebate Amount:	\$6,276.00
Intended COE Rebate Details	
COE Expiry Date:	05 Jan 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$60,888.00
COE Rebate Amount:	\$27,784.00
Total Rebate Amount:	\$34,060.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 11 May 2018

OK

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4398R
 Ref. No : TAX/05/18/2041
 Reg. Date : 06/01/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : WONG BOON HUI
 Type of Accident : CHAIN COLLISION
 Date / Time of Accident : 07/05/2018 04:00:00 PM
 Accident Reported Date / Time : 08/05/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 07/05/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095952
 Special Instruction to ARC, if any :
 TOWED \$40 / SJM8502D
 Prepared Date : 08/05/2018 01:28:00 PM



Sebastian
 9/5/18.
 - Lump Sum Repair.
 - Question Mark Item Photo
 - Photo After Paint

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U90-5720518

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,521.00	0.00
Total Spray Painting Charges	: 2,628.00	0.00
Total Material Charges	: 17,578.68	17,578.68
Other Charges	: 2,122.20	0.00
TOTAL	: 23,849.88	0.00
Lum Sum Total	: 23,850.00	0.00
No. of Repair Days	: 10.00	0.00
Prepared / Adjusted By	:	<i>7 days</i>
Arc / Surveyor Sign Off Date	: 08/05/2018 02:49:04 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 08/05/2018 02:46:13 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 5/8/2018 2:52:12 PM

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	338.00	0.00 200
TO REPAIR FRONT PORTION	1,183.00	0.00 600
Total Labour	1,521.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00	0.00 ?
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO REPSRAY FRONT HOOD	378.00	0.00 200
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00 50
TO RESPRAY FRONT FENDER LH	378.00	0.00 200
TO RESPRAY FRONT FENDER RH	378.00	0.00 X
TO RESPRAY FRONT DOOR LH	378.00	0.00 200
Total Spray Painting & Panel Beating	2,628.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0.00 30
TO TOP UP A/C GAS	120.00	0.00 ?
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	742.20	0.00 ✓
TO REMOVE AND REFIT WIRE HARDESS	250.00	0.00 ?
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	120.00	0.00 60
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
TO CHECK & RESET SYSTEM FUNCTION	250.00	0.00 120
Total Other Costs	2,122.20	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace <i>R</i>	No
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace <i>?</i>	No
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace <i>?</i>	No
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace <i>?</i>	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace <i>?</i>	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace <i>✓</i>	No
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace <i>✓</i>	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace <i>?</i>	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace <i>?</i>	No
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace <i>✓ CRK</i>	No
52161-16010			BUMPER CLIPS	10	1.61	25.00	12.07	Replace	Replace <i>✓ NUC</i>	No
52611-47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Replace <i>✓ CRK</i>	No
52021-47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Replace <i>✓ DP</i>	No
57014-47030			ARM SUB-ASSY, FR BUMPER LH	1	250.40	25.00	187.80	Replace	Replace <i>✓ BT</i>	No
57013-47030			ARM SUB-ASSY, FR BUMPER RH	1	250.40	25.00	187.80	Replace	Replace <i>?</i>	No
52114-47140			BRACKET, FR BUMPER	1	110.40	25.00	82.80	Replace	Replace <i>?</i>	No
			NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace <i>✓</i>	No <i>CRK</i>
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace <i>✓ CRK</i>	No
52128-47903			COVER, FR BUMPER HOLE LH	1	18.50	25.00	13.87	Replace	Replace <i>✓ Defect</i>	No
52618-47050		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	25.00	95.77	Replace	Replace <i>?</i>	No
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.32	Replace	Replace <i>✓ CRK</i>	No
81220-12230		6505438	FOG LAMP LH	1	280.10	10.00	252.09	Replace	Replace <i>?</i>	No
81529-47060			BRACKET, FR TURN CENTER LH	1	58.20	25.00	43.65	Replace	Replace <i>?</i>	No
81529-47050			BRACKET, FR TURN LOWER LH	1	26.00	25.00	19.50	Replace	Replace <i>?</i>	No
81529-47040			BRACKET, FR TURN UPPER LH	1	24.40	25.00	18.30	Replace	Replace <i>?</i>	No
81521-47050			LENS & BODY, FR TURN LH	1	511.80	10.00	460.62	Replace	Replace <i>?</i>	No
52116-47040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Replace <i>?</i>	No
52115-47040		6505515	BUMPER SUPPORT F/RH	1	76.40	25.00	57.30	Replace	Replace <i>?</i>	No
82113-47180			WIRE, ENGINE ROOM, NO.3	1	242.00	10.00	217.80	Replace	Replace <i>?</i>	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
53301-47060		6505555	HOOD PANEL	1	748.10	25.00	561.07	Replace	Replace	No ✓ OT
53420-47070			HOOD HINGE LH	1	55.90	25.00	41.92	Replace	Replace	No ✓ BT
53410-47070			HOOD HINGE RH	1	55.90	25.00	41.92	Replace	Replace	No ✓ BT
53395-47020			HOOD END PANEL SEAL	1	35.50	25.00	26.62	Replace	Replace	No ✓ NSC
53341-47020			HOOD PANEL INSULATOR	1	390.50	25.00	292.87	Replace	Replace	No X
53510-47102			HOOD LOCK	1	128.90	25.00	96.67	Replace	Replace	No ✓ BT
53630-47050			CABLE ASSY, HOOD	1	52.20	25.00	39.15	Replace	Replace	No ?
53614-47030			CLAMP, HOOD LOCK	1	5.90	25.00	4.42	Replace	Replace	No ?
55708-47101			WIPER GARNISH	1	614.00	25.00	460.50	Replace	Replace	No ?
55084-47011			WIPER GARNISH COVER, LH	1	23.80	25.00	17.85	Replace	Replace	No ?
55083-47011			WIPER GARNISH COVER, RH	1	23.80	25.00	17.85	Replace	Replace	No ?
53201-47902			SUPPORT SUB-ASSY	1	1,460.40	25.00	1,095.30	Replace	Replace	No R
81170-47500		6505436	HEAD LAMP LH	1	945.20	10.00	850.68	Replace	Replace	No ✓ CRK
81130-47500		6505437	HEAD LAMP RH	1	945.20	10.00	850.68	Replace	Replace	No X
53289-47032			COVER, RADIATOR	1	122.80	25.00	92.10	Replace	Replace	No ?
75310-47010		6505638	EMBLEM FRONT	1	86.50	25.00	64.87	Replace	Replace	No ✓ NSC
53111-47040		6505573	GRILLE, RADIATOR	1	310.60	25.00	232.95	Replace	Replace	No ?
82111-47772			WIRE, ENGINE ROOM	1	5,567.10	10.00	5,010.39	Replace	Replace	No ?
88460-47150			A/C CONDENSER	1	1,181.90	25.00	886.42	Replace	Replace	No ?
	COMMO N		COOLANT	1	12.32	0.00	12.32	Replace	Replace	No ?
16400-37230		6505302	RADIATOR ASSY	1	1,496.90	25.00	1,122.67	Replace	Replace	No ?
57104-47020		6505507	RADIATOR LOWER SUPPORT	1	876.30	25.00	657.22	Replace	Replace	No ?
16535-20030			SUPPORT, RADIATOR,	1	18.50	25.00	13.87	Replace	Replace	No ?
16534-37010			SUPPORT, RADIATOR, LH	1	17.70	25.00	13.27	Replace	Replace	No ?
16533-28051			SUPPORT, RADIATOR, RH	1	54.50	25.00	40.87	Replace	Replace	No ?
16523-21050			CUSHION, RADIATOR	2	11.30	25.00	16.95	Replace	Replace	No ?
16571-37140		6505303	RADIATOR TOP HOSE NO 1	1	42.40	25.00	31.80	Replace	Replace	No ?
16267-37030			RADIATOR HOSE, BYPASS NO.3	1	37.20	25.00	27.90	Replace	Replace	No ?
16281-37030			RADIATOR HOSE, BYPASS NO.4	1	37.20	25.00	27.90	Replace	Replace	No ?
G9010-47031			RADIATOR ASSY, UPPER	1	679.60	25.00	509.70	Replace	Replace	No ?

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
G9225-47021			HOSE, INVERTER NO.1	1	80.00	25.00	60.00	Replace	Replace	No
G9229-47020			HOSE, INVERTER COOLING NO.5	1	125.30	25.00	93.97	Replace	Replace	No
G9214-47060			BRACKET, INVERTER, NO.1	1	31.40	25.00	23.55	Replace	Replace	No
G92A0-47010			TANK ASSY, INVERTER	1	364.30	25.00	273.22	Replace	Replace	No
53294-47030		6505561	DEFLECTOR, RADIATOR LH	1	77.00	25.00	57.75	Replace	Replace	No
16361-37010			FAN BLADE	1	158.60	25.00	118.95	Replace	Replace	No
16361-28360			FAN BLADE NO 2	1	204.20	25.00	153.15	Replace	Replace	No
16363-37010			FAN MOTOR NO 1	1	538.30	25.00	403.72	Replace	Replace	No
16363-37020			FAN MOTOR NO 2	1	538.30	25.00	403.72	Replace	Replace	No
16711-37040			FAN SHROUD	1	244.50	25.00	183.37	Replace	Replace	No
16712-37030			FAN SHROUD TOP	1	99.60	25.00	74.70	Replace	Replace	No
17700-38252			AIR CLEANER ASSY	1	929.90	25.00	697.42	Replace	Replace	No
53801-47050		6505557	FENDER FRT/RH	1	723.40	25.00	542.55	Replace	Replace	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No
53875-47030		6505553	FENDER LINER FRT/RH	1	171.70	25.00	128.77	Replace	Replace	No
53802-47050		6505558	FENDER FRT/LH	1	723.40	25.00	542.55	Replace	Replace	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No
53876-47030		6505554	FENDER LINER FRT/LH	1	171.70	25.00	128.77	Replace	Replace	No
53852-47020			FENDER LINER PAD, FR WHEEL. LH	1	49.30	25.00	36.97	Replace	Replace	No
67002-47070		6505529	DOOR FRT/LH	1	894.40	25.00	670.80	Replace	Replace	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace	No
TOTAL MATERIALS								21,973.51	21,973.35	
TOTAL MATERIALS(Discounted)							17,578.68	17,578.68		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									



Tow. 17-5-18 / 08:39

SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672



ADV: 17-5-18 / 12:34

+20 days 17-5-18 / 16:34

SMRT Accident Vehicle Repair Estimates

9-5-18 / 16:34

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre


Reg. No : SHC4398R
 Ref. No : TAX/05/18/2041
 Reg. Date : 06/01/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : WONG BOON HUI
 Type of Accident : CHAIN COLLISION
 Date / Time of Accident : 07/05/2018 04:00:00 PM
 Accident Reported Date / Time : 08/05/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Sebastian
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 07/05/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095952
 Special Instruction to ARC, if any :




TOWED \$40 / SJM8502D China LHS
 BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL
 SURVEYOR SEBASTIAN (LKK) & Email : sebastianyeang @lkkauto.com HP:90036121
 LUMPSUM REPAIR

Prepared Date : 08/05/2018 01:28:00 PM

Recording Camera



Radio Antenna



1st witness


R

Date

2-5-18

2nd witness

Date



Vehicle to Wega Date In: 10/5	Towing: Aug.
Time In: 1343	Driver:
Wega Job No: 05/0297	
Vehicle sent to SMRT Date In: 18.05.18	Towing:
Time In: 09:45	Driver: CP
Received by (SMRT):	

QC 18/5/18 13.10 Reject
 RR Bumper SC LHR Bender name Plate hybrid missing
 1G + 12 pins

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U90-5720518

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,521.00	1,000.00
Total Spray Painting Charges :	2,628.00	1,050.00
Total Material Charges :	15,146.57	7,728.11
Other Charges :	2,122.20	1,212.20
TOTAL :	21,417.77	10,990.31
Lum Sum Total :	21,400.00	11,000.00
No. of Repair Days :	10.00	9.00
Prepared / Adjusted By :		SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date :	08/05/2018 02:49:04 PM	09/05/2018 04:39:32 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 08/05/2018 02:46:13 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1805-046-2

Invoice No :

Quotation Date : 21/5

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 5/8/2018 2:52:12 PM

Section D:- Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	338.00	200.00 /
TO REPAIR FRONT PORTION	1,183.00	800.00 /
Total Labour	1,521.00	1,000.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00 /
TO RESPRAY BUMPER BEAM	180.00	0.00
TO REPSRAY FRONT BUMPER	378.00	200.00 /
TO REPSRAY FRONT HOOD	378.00	200.00 /
TO RESPRAY FRONT SUPPORT PANEL	180.00	50.00 /
TO RESPRAY FRONT FENDER LH	378.00	200.00 /
TO RESPRAY FRONT FENDER RH	378.00	0.00
TO RESPRAY FRONT DOOR LH	378.00	200.00 /
Total Spray Painting & Panel Beating	2,628.00	1,050.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	80.00 /
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30.00 /
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	30.00 /
TO TOP UP A/C GAS	120.00	120.00 /
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET) <i>Net</i>	742.20	742.20 /
TO REMOVE AND REFIT WIRE HARDESS	250.00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00 /
TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	120.00	60.00 /
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
TO CHECK & RESET SYSTEM FUNCTION	250.00	120.00 /
Total Other Costs	2,122.20	1,212.20

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	100.00	0.00	Replace	Repair	No <i>R</i>
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.28	Replace	Check	No <i>X</i>
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Check	No <i>X</i>
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Check	No <i>X</i>
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Check	No <i>X</i>
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No <i>X</i>
76891-47020		6505619	BUMPER LIP REAR	0	228.90	25.00	0.00	Replace	Not given	No <i>X</i>
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Check	No <i>X</i>
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Check	No <i>X</i>
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace	No <i>X</i>
52161-16010			BUMPER CLIPS	10	1.61	25.00	12.07	Replace	Replace	No <i>X</i>
52611-47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Replace	No <i>X</i>
52021-47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Replace	No <i>X</i>
57014-47030			ARM SUB-ASSY, FR BUMPER LH	1	250.40	25.00	187.80	Replace	Replace	No <i>X</i>
57013-47030			ARM SUB-ASSY, FR BUMPER RH	1	250.40	25.00	187.80	Replace	Check	No <i>X</i>
52114-47140			BRACKET, FR BUMPER	1	110.40	25.00	82.80	Replace	Replace	No <i>X</i>
			NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace	No <i>X</i>
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace	No <i>X</i>
52128-47903			COVER, FR BUMPER HOLE LH	1	18.50	25.00	13.87	Replace	Replace	No <i>X</i>
52618-47050		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	25.00	95.78	Replace	Check	No <i>X</i>
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.32	Replace	Replace	No <i>X</i>
81220-12230		6505438	FOG LAMP LH	1	280.10	10.00	252.09	Replace	Check	No <i>X</i>
81529-47060			BRACKET, FR TURN CENTER LH	1	58.20	25.00	43.65	Replace	Check	No <i>X</i>
81529-47050			BRACKET, FR TURN LOWER LH	1	26.00	25.00	19.50	Replace	Check	No <i>X</i>
81529-47040			BRACKET, FR TURN UPPER LH	1	24.40	25.00	18.30	Replace	Check	No <i>X</i>
81521-47050			LENS & BODY, FR TURN LH	1	511.80	10.00	460.62	Replace	Check	No <i>X</i>
52116-47040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Check	No <i>X</i>
52115-47040		6505515	BUMPER SUPPORT F/RH	1	76.40	25.00	57.30	Replace	Check	No <i>X</i>
82113-47180			WIRE, ENGINE ROOM, NO.3	1	242.00	10.00	217.80	Replace	Check	No <i>X</i>

1471-26

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
53301-47060		6505555	HOOD PANEL	1	748.10	25.00	561.07	Replace	Replace	No ✓
53420-47070			HOOD HINGE LH	1	55.90	25.00	41.92	Replace	Replace	No ✓
53410-47070			HOOD HINGE RH	1	55.90	25.00	41.92	Replace	Replace	No ✓
53395-47020			HOOD END PANEL SEAL	1	35.50	25.00	26.62	Replace	Replace	No ✓
53341-47020			HOOD PANEL INSULATOR	0	390.50	25.00	0.00	Replace	Not given	No X
53510-47102			HOOD LOCK	1	128.90	25.00	96.67	Replace	Replace	No ✓
53630-47050			CABLE ASSY, HOOD	1	52.20	25.00	39.15	Replace	Check	No X
53614-47030			CLAMP, HOOD LOCK	1	5.90	25.00	4.43	Replace	Check	No X
55708-47101			WIPER GARNISH	1	614.00	25.00	460.50	Replace	Check	No X
55084-47011			WIPER GARNISH COVER, LH	1	23.80	25.00	17.85	Replace	Replace S	No ✓
55083-47011			WIPER GARNISH COVER, RH	1	23.80	25.00	17.85	Replace	Check	No X
53201-47902			SUPPORT SUB-ASSY	1	1,460.40	25.00	1,095.30	Replace	Replace S	No ✓
81170-47500		6505436	HEAD LAMP LH	1	945.20	10.00	850.68	Replace	Replace	No ✓
81130-47500		6505437	HEAD LAMP RH	0	945.20	10.00	0.00	Replace	Not given	No X
53289-47032			COVER, RADIATOR	1	122.80	25.00	92.10	Replace	Check	No X
75310-47010		6505638	EMBLEM FRONT	1	86.50	25.00	64.87	Replace	Replace	No ✓
53111-47040		6505573	GRILLE, RADIATOR	1	310.60	25.00	232.95	Replace	Replace S	No ✓
82111-47772			WIRE, ENGINE ROOM	1	5,567.10	10.00	5,010.39	Replace	Check	No ✓
88460-47150			A/C CONDENSER	1	1,181.90	25.00	886.43	Replace	Replace S	No ✓
	COMMO N		COOLANT	1	12.32	0.00	12.32	Replace	Replace S	No ✓
16400-37230		6505302	RADIATOR ASSY	1	1,496.90	25.00	1,122.68	Replace	Replace S	No ✓
57104-47020		6505507	RADIATOR LOWER SUPPORT	1	876.30	25.00	657.23	Replace	Check	No X
16535-20030			SUPPORT, RADIATOR,	1	18.50	25.00	13.88	Replace	Check	No X
16534-37010			SUPPORT, RADIATOR, LH	1	17.70	25.00	13.28	Replace	Check	No X
16533-28051			SUPPORT, RADIATOR, RH	1	54.50	25.00	40.88	Replace	Check	No X
16523-21050			CUSHION, RADIATOR	2	11.30	25.00	16.95	Replace	Check	No X
16571-37140		6505303	RADIATOR TOP HOSE NO 1	1	42.40	25.00	31.80	Replace	Check	No X
16267-37030			RADIATOR HOSE, BYPASS NO.3	1	37.20	25.00	27.90	Replace	Check	No X
16281-37030			RADIATOR HOSE, BYPASS NO.4	1	37.20	25.00	27.90	Replace	Check	No X
G9010-47031			RADIATOR ASSY, UPPER	1	679.60	25.00	509.70	Replace	Replace S	No ✓
G9225-47021			HOSE, INVERTER NO.1	1	80.00	25.00	60.00	Replace	Check	No X

7560-98

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
G9229-47020			HOSE, INVERTER COOLING NO.5	1	125.30	25.00	93.98	Replace	Check	No X
G9214-47060			BRACKET, INVERTER, NO.1	1	31.40	25.00	23.55	Replace	Check	No X
G92A0-47010			TANK ASSY, INVERTER	1	364.30	25.00	273.23	Replace	Check	No X
53294-47030		6505561	DEFLECTOR, RADIATOR LH	1	77.00	25.00	57.75	Replace	Replace S	No /
16361-37010			FAN BLADE	1	158.60	25.00	118.95	Replace	Check	No X
16361-28360			FAN BLADE NO 2	1	204.20	25.00	153.15	Replace	Check	No X
16363-37010			FAN MOTOR NO 1	1	538.30	25.00	403.73	Replace	Replace S	No /
16363-37020			FAN MOTOR NO 2	1	538.30	25.00	403.73	Replace	Replace S	No /
16711-37040			FAN SHROUD	1	244.50	25.00	183.38	Replace	Replace S	No /
16712-37030			FAN SHROUD TOP	1	99.60	25.00	74.70	Replace	Replace S	No /
17700-38252			AIR CLEANER ASSY	1	929.90	25.00	697.43	Replace	Replace S	No /
53801-47050		6505557	FENDER FRT/RH	0	723.40	25.00	0.00	Replace	Not given	No X
75374-47051			NAME PLATE (HYBRID)	0	51.90	25.00	0.00	Replace	Not given	No X
53875-47030		6505553	FENDER LINER FRT/RH	0	171.70	25.00	0.00	Replace	Not given	No X
53802-47050		6505558	FENDER FRT/LH	1	723.40	25.00	542.55	Replace	Replace S	No /
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No /
53876-47030		6505554	FENDER LINER FRT/LH	1	171.70	25.00	128.77	Replace	Replace	No /
53852-47020			FENDER LINER PAD, FR WHEEL. LH	1	49.30	25.00	36.97	Replace	Replace	No /
67002-47070		6505529	DOOR FRT/LH	1	894.40	100.00	0.00	Replace	Repair	No R
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace	No /
TOTAL MATERIALS							18,933.28	9,660.14		
TOTAL MATERIALS(Discounted)							15,146.57	7,728.11		

Added Spare Parts / Material Usage After Surveyor Signed off

2627.93

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

9660.14 /
- 20%
7728.11 /
+ 1000.00 /
+ 2262.20 /

10,990.31 /

L/S \$11,000/- /
Sebastian
25/5/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CT118008647/Sub3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 13-09-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJM 8502D	Veh. Inspected	SHC 4398R
Policy No.	DMPCSN3037561700	Coverage (\$)	0.00
Claim No.	SNM18D02338C02	Excess (\$)	0.00
Assign From		Assign Date	09/05/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36U905720518	Colour	MAROON
Odometer	423089	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65R15	FALKEN	6 mm
L/H Front Tyre	195/65R15	FALKEN	6 mm
R/H Rear Tyre	195/65R15	FALKEN	6 mm
L/H Rear Tyre	195/65R15	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	07/05/2018	Inspection Date	09/05/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	9 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4398R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER FRT (DISC 25%)	CRACKED	482.00	361.50
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.07
1	BUMPER ENERGY ABSORBER FRT (DISC 25%)	CRACKED	78.80	59.10
1	BUMPER REINFORCEMENT FRT (DISC 25%)	DENTED	498.40	373.80
1	ARM SUB-ASSY ,FR BUMPER LH (DISC 25%)	BENT	250.40	187.80
1	BRACKET ,FR BUMPER (DISC 25%)	CRACKED	110.40	82.80
1	COVER ,FR BUMPER HOLE LH (DISC 25%)	DEFORMED	18.50	13.87
1	BUMPER GRILLE SUB-ASSY ,LOWER (DISC 25%)	CRACKED	311.10	233.32
1	HOOD PANEL (DISC 25%)	DENTED	748.10	561.07
1	HOOD HINGE LH (DISC 25%)	BENT	55.90	41.92
1	HOOD HINGE RH (DISC 25%)	BENT	55.90	41.92
1	HOOD END PANEL SEAL (DISC 25%)	NECESSARY	35.50	26.62
1	HOOD LOCK (DISC 25%)	BENT	128.90	96.67
1	WIPER GARNISH COVER ,LH (DISC 25%)	MISSING	23.80	17.85
1	SUPPORT SUB-ASSY (DISC 25%)	BENT	1,460.40	1,095.30
1	EMBLEM FRONT (DISC 25%)	NECESSARY	86.50	64.87
1	GRILLE ,RADIATOR (DISC 25%)	CRACKED	310.60	232.95
1	A/C CONDENSER (DISC 25%)	DENTED	1,181.90	886.43
1	RADIATOR ASSY (DISC 25%)	DENTED	1,496.90	1,122.68
1	RADIATOR ASSY ,UPPER (DISC 25%)	DENTED	679.60	509.70
1	DEFLECTOR ,RADIATOR LH (DISC 25%)	TORN	77.00	57.75
1	FAN MOTOR NO 1 (DISC 25%)	DAMAGED	538.30	403.73
1	FAN MOTOR NO 2 (DISC 25%)	DAMAGED	538.30	403.73
1	FAN SHROUD (DISC 25%)	CRACKED	244.50	183.38
1	FAN SHROUD TOP (DISC 25%)	TORN	99.60	74.70
1	AIR CLEANER ASSY (DISC 25%)	CRACKED	929.90	697.43
1	FENDER FRT/LH (DISC 25%)	DENTED	723.40	542.55
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.92
1	FENDER LINER FRT/LH (DISC 25%)	TORN	171.70	128.77
1	FENDER LINER PAD,FR WHEEL LH (DISC 25%)	MISSING	49.30	36.97
1	HEAD LAMP LH (DISC 10%)	CRACKED	945.20	850.68

Report Ref No. CC3/CT118008647/Sub3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ADVERTISEMENT STICKER (SN)	NECESSARY	742.20	742.20
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	NUMBER PLATE (SN)	CRACKED	15.00	15.00
1	NUMBER PLATE FRAME (SN)	CRACKED	12.00	12.00
1	COOLANT (SN)	NECESSARY	12.32	12.32
1	STICKER DECAL SMRT (DOOR) (SN)	NECESSARY	60.00	60.00
1	BUMPER REINFORCEMENT REAR	NOT NECESSARY	205.70	-
1	ARM SUB-ASSY ,RR BUMPER LH	NOT NECESSARY	139.60	-
1	ARM SUB-ASSY ,RR BUMPER RH	NOT NECESSARY	139.60	-
1	SENSOR REVERSE	NOT NECESSARY	180.00	-
1	BUMPER LIP REAR	NOT NECESSARY	228.90	-
1	BUMPER SIDE RETAINER RR/LH	NOT NECESSARY	94.80	-
1	BUMPER SIDE RETAINER RR/RH	NOT NECESSARY	94.80	-
1	ARM SUB-ASSY ,FR BUMPER RH	NOT NECESSARY	250.40	-
1	BUMPER ABSORBER LOWER	NOT NECESSARY	127.70	-
1	FOG LAMP LH	NOT NECESSARY	280.10	-
1	BRACKET ,FR TURN CENTER LH	NOT NECESSARY	58.20	-
1	BRACKET ,FR TURN LOWER LH	NOT NECESSARY	26.00	-
1	BRACKET ,FR TURN UPPER LH	NOT NECESSARY	24.40	-
1	LENS & BODY ,FR TURN LH	NOT NECESSARY	511.80	-
1	BUMPER SUPPORT F/LH	NOT NECESSARY	76.40	-
1	BUMPER SUPPORT F/RH	NOT NECESSARY	76.40	-
1	WIRE ,ENGINE ROOM ,NO .3	NOT NECESSARY	242.00	-
1	HOOD PANEL INSULATOR	NOT NECESSARY	390.50	-
1	CABLE ASSY ,HOOD	NOT NECESSARY	52.20	-
1	CLAMP ,HOOD LOCK	NOT NECESSARY	5.90	-
1	WIPER GARNISH	NOT NECESSARY	614.00	-
1	WIPER GARNISH COVER ,RH	NOT NECESSARY	23.80	-
1	HEAD LAMP RH	NOT NECESSARY	945.20	-
1	COVER ,RADIATOR	NOT NECESSARY	122.80	-
1	WIRE ,ENGINE ROOM	NOT NECESSARY	5,567.10	-
1	RADIATOR LOWER SUPPORT	NOT NECESSARY	876.30	-
1	SUPPORT RADIATOR	NOT NECESSARY	18.50	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SUPPORT RADIATOR ,LH	NOT NECESSARY	17.70	-
1	SUPPORT RADIATOR ,RH	NOT NECESSARY	54.50	-
2	CUSHION ,RADIATOR @\$11.30	NOT NECESSARY	22.60	-
1	RADIATOR TOP HOSE NO 1	NOT NECESSARY	42.40	-
1	RADIATOR HOSE ,BYPASS NO 3	NOT NECESSARY	37.20	-
1	RADIATOR HOSE ,BYPASS NO 4	NOT NECESSARY	37.20	-
1	HOSE INVERTER NO.1	NOT NECESSARY	80.00	-
1	HOSE INVERTER COOLING NO.5	NOT NECESSARY	125.30	-
1	BRACKET INVERTER NO.1	NOT NECESSARY	31.40	-
1	TANK ASSY ,INVERTER	NOT NECESSARY	364.30	-
1	FAN BLADE	NOT NECESSARY	158.60	-
1	FAN BLADE NO 2	NOT NECESSARY	204.20	-
1	FENDER FRT/RH	NOT NECESSARY	723.40	-
1	NAME PLATE (HYBRID)	NOT NECESSARY	51.90	-
1	FENDER LINER FRT/RH	NOT NECESSARY	171.70	-
1	BUMPER REAR	TO REPAIR SEE LABOUR	458.60	-
1	DOOR FRT/LH	TO REPAIR SEE LABOUR	894.40	-
			28,208.82	10,402.37
	LABOUR			
	PANEL BEATING & BODY WORK ,INCLUSIVE OF THE REPAIR OF BUMPER REAR AND DOOR FRT/LH.		1,521.00	1,000.00
	SPRAY PAINT.		2,628.00	1,050.00
	TOWING CHARGE.		80.00	80.00
	TO CHECK WIRING AND SYSTEM FUNCTION .		80.00	30.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		200.00	30.00
	TO TOP UP A/C GAS.		120.00	120.00
	TO REMOVE AND REFIT WIRE HARDESS.	NOT NECESSARY	250.00	-
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	30.00
	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER .		120.00	60.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM .	NOT NECESSARY	60.00	-

Report Ref No. CC3/CT118008647/Sub3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO CHECK & RESET SYSTEM FUNCTION.		250.00	120.00
			5,529.00	2,520.00
GRAND TOTAL			33,737.82	12,922.37
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				11,000.00

Report Ref No. CC3/CT118008647/Sub3n2

YEANG WAI KEEN

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.