

ASSIGNMENT

Form: _____ Date: _____
 Estimated Cost: _____
 OO / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. _____

At Workshop No. _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured _____


Excess _____

(Client's Record)

Make of Veh. _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value _____

IDAC Accident Report Consistent? Yes or No

GIA / PR Seen Consistent? Yes or No

Est. Repairs: 13 9 days Res. Yes or No

Lump Sum: 20 % 3 Val. Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted _____

Vehicle IN / OUT

Veh No. GBB 8921E Yr Regn 2010 August

Type M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make Fiat Doblo 1248

Colour White A/C Insured / Std / NI / NA

Sp Reading 139144 T/Mile Insured / Std / NI / NA

Eng/No. 199A20003660817

C/No. ZFA22300005727117

Gen. Cond. Good / Fair / Poor / Burnt

Steering In order / Jammed / Leaked / Burnt or

Brake In order / Jammed / Leaked / Burnt or

Mod. Oil / S/Rim / STD A/Rim or

Tyre Size F: 185/65 R15

R: - 11 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal S mm R/Bal S mm

L/Bal S mm L/Bal S mm

D.O.A. 08/05/2018 D.O.I. 14/05/2018

Survey held at EDGE Braddell

Des. of Damages Front / Rear / O/S / N/S / U/C / Rooftop or

Front y Rear

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction	S - S - 13 TUE	21 M 6
15/09/18	AXA YP 5718A.	9 W	22 M 7
	MV 18K	10 W	23 W 8
	LTA 6.8K	11 S	24 F 9
	HL 11.2K	12 S	25 F 10
	Invoice # 215 10,500/- - it's 13 days	13 S	26 S
	R (\$10,428.05 / 50%)	14 M - 0011	27 S
		15 T 2	28 M 11
		16 W 3	29 T 12
		17 T 4	30 W 13
		18 F 5	31
		19 S	
		20 S	

Date/Time File Pass to?



Preli. Report

Days Of Repair:

1)



Final Report

Resturvey No. of Trip:

Date/Time File Return to?

2)

Add Fee:



Site Insp. 1\$



Intervew 1\$



Tech. Insp. 1\$



Witness Insp. 1\$

Report Format:

Lump Sum / L.B.R. 1\$

Survey Fee

Transportation

1. 10 x 10 13

2. 10 x 10

3. 10 x 10

4. 10 x 10

5. 10 x 10

Spark Car Care
 ComfortDelgro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax: 62815767

Finalization Form

Bill To : AXA
 Attn to : LKK, BRYAN

Vehicle Number : GBB8921E
 Type Of Claim : TP

A. Spare parts \$ 11,875.15 ✓
 B. Supplementary \$ 1,044.19 ✓
 C. Nett Price \$ -
 D. Supp Nett Price \$ -
 E. S/Nett \$ 705.00 ✓

F. Total Parts \$ 12,332.41 ✓
 G. Total Labour \$ 3,240.00 ✓
 H. Total Repair \$ 15,572.41 ✓
 I. Excess _____
 P/P Total 15,572.41

Total Spare Parts Price		<u>\$ 12,919.34</u> ✓
Cost plus / List Down	<u>10%</u>	<u>1,291.93</u>
Total		<u>11,627.41</u> ✓

Total Nett Price		<u>\$ -</u>
Nett Price Less		<u>\$ -</u>
Total		<u>-</u>

LIMIT \$10,500.00

Lump Sum Les 20% \$ 3,114.48 13 days.
 Lump Sum Rounding \$ 12,457.92

Total Finalized

N.B. If we DO NOT receive your reply within 2 weeks, we shall treat the above finalized amount as confirmed & correct.

Remarks : Please confirm and revert by Fax or Email

Date In : _____ Total Repair Day _____
 Date Survey : _____ LOU/ Day _____
 Date Out : _____ Total LOU _____
 Sat/Sun/Ph. : _____ Rental/Day _____
 Authorized Repair Day _____ Total Rental _____

Submitted By / Date : _____ Confirmed By / Date : _____

Andy 8/6/1.8

Spark Car Care

Page 1

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : GBB8921E

Case Owner : WILLIAM

Make & Model : FIAT DOBLO 1.3MJTD

Year Manufacture : 2010

Chassis No : ZFA22300005727117

Engine No : 199A20003660817

Sales Order : _____

Supplier : _____

Order By : _____

Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Front number plate with casing <i>Crack</i>	1					
2	Front bumper <i>distorted</i>	1				\$ 35.00	✓
3	Front bumper fog lamp cover LH <i>HH</i>	1		\$ 755.66	✓		
4	Front bumper fog lamp cover RH <i>HH</i>	1		\$ 121.33	X		
5	Front bumper reinforcement <i>HH</i>	1		\$ 121.33	X		
6	Front grille <i>Crack</i>	1		\$ 1,112.10	X		
7	Front grille badge logo <i>Crack</i>	1		\$ 375.88	✓		
8	Headlamp LH <i>HH</i>	1		\$ 142.26	✓		
9	Headlamp RH <i>HH</i>	1		\$ 288.00	X		
10	Headlamp lower garnish LH <i>HH</i>	1		\$ 288.00	X		
11	Headlamp lower garnish RH <i>Crack</i>	1		\$ 184.34	X		
12	Rear number plate with casing <i>vt</i>	1		\$ 184.34	✓		
13	Rear bumper <i>Bnc</i>	1				\$ 35.00	✓
14	Rear bumper LH <i>distorted</i>	1		\$ 295.60	✓		
15	Rear bumper RH <i>Bnc</i>	1		\$ 405.00	✓		
16	Rear bumper reflector LH <i>HH</i>	1		\$ 405.00	X		
17	Rear bumper reflector RH <i>HH</i>	1		\$ 35.72	X		
18	Reverse sensors <i>Down</i>	2		\$ 35.72	X		
19	Taillamp LH <i>Scratched</i>	1				\$ 200.00	✓
20	Taillamp RH <i>broken</i>	1		\$ 332.72	✓		
21	Taillamp covering LH <i>Crack</i>	1		\$ 346.51	✓		
22	Taillamp covering RH <i>Crack</i>	1		\$ 337.50	✓		
23	Back door LH <i>Bnc</i>	1		\$ 337.50	✓		
24	Back door LH badge logo <i>Huc</i>	1		\$ 2,008.80	✓		
25	Back door LH upper hinge <i>vt</i>	1		\$ 30.00	✓		
26	Back door LH lower hinge <i>vt</i>	1		\$ 120.70	✓		
27	Back door LH check <i>vt</i>	1		\$ 120.70	✓		
28	Back door LH glass <i>shattered</i>	1		\$ 66.53	✓		
29	Back door LH glass sealant <i>Huc</i>	1		\$ 165.00	✓		
30	Back door LH glass inner seal <i>Huc</i>	1				\$ 40.00	✓
						\$ 30.00	✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

15/05/2018

11:02 AM

6024-70

SN 340

Spark Car Care

Page 2

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : GBB8921E

Case Owner : WILLIAM

Make & Model : FIAT DOBLO 1.3MJTD

Year Manufacture : 2010

Chassis No : ZFA22300005727117

Engine No : 199A20003660817

Sales Order : 0

Supplier : 0

Order By : 0

Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
31	Back door LH wiper arm <i>bt</i>	1		\$ 74.00	✓		
32	Back door LH wiper arm blade <i>SVL</i>	1		\$ 27.00	X		
33	Back door LH wiper motor <i>Dom</i>	1		\$ 547.68	✓		
34	Back door LH wiper arm cover <i>SVL</i>	1		\$ 20.25	X		
35	Back door LH trim board <i>Cut</i>	1		\$ 268.14	✓		
36	speed limit sticker - 70 km/h <i>HLC</i>	1					
37	Rear number plate lamp LH <i>NH</i>	1		\$ 56.44	X	\$ 15.00	✓
38	Rear number plate lamp RH <i>NH</i>	1		\$ 56.44	X		
39	Back door LH upper lock <i>NH</i>	1		\$ 166.36	X		
40	Back door LH upper lock cover <i>NH</i>	1		\$ 11.64	X		
41	Back door LH upper lock striker <i>bt</i>	1		\$ 42.45	✓		
42	Back door LH lower lock <i>bt</i>	1		\$ 163.30	✓		
43	Back door LH lower lock cover <i>NH</i>	1		\$ 11.64	X		
44	Back door LH lower lock striker <i>bt</i>	1		\$ 42.45	✓		
45	Back door RH <i>180 BNC</i>	1		\$ 1,888.19	✓		
46	Back door RH emblem - Mutijet <i>HLC</i>	1		\$ 76.73	✓		
47	Back door RH sticker - singtel <i>HLC</i>	1					
48	Back door RH upper hinge <i>bt</i>	1		\$ 120.70	✓	\$ 100.00	✓
49	Back door RH lower hinge <i>bt</i>	1		\$ 120.70	✓		
50	Back door RH check <i>bt</i>	1		\$ 66.53	✓		
51	Back door RH glass <i>3 hatin AL</i>	1		\$ 195.00	✓		
52	Back door RH glass sealant <i>HLC</i>	1					
53	Back door RH glass inner seal <i>HLC</i>	1				\$ 40.00	✓
54	Back door RH trim board <i>SVL</i>	1				\$ 30.00	✓
55	Back door RH upper lock <i>NH</i>	1		\$ 268.14	X		
56	Back door RH upper lock cover <i>NH</i>	1		\$ 166.36	X		
57	Back door RH upper lock striker <i>NH</i>	1		\$ 11.64	X		
58	Back door RH lower lock <i>bt</i>	1		\$ 42.45	X		
59	Back door RH lower lock cover <i>NH</i>	1		\$ 162.00	✓		
60	Back door RH lower lock striker <i>bt</i>	1		\$ 11.64	X		
				\$ 42.45	✓		

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

15/05/2018

3810.32

SW 185

11:02 AM

Spark Car Care

Page 3

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : GBB8921E Case Owner : WILLIAM
Make & Model : FIAT DOBLO 1.3MJTD Year Manufacture : 2010
Chassis No : ZFA22300005727117 Engine No : 199A20003660817
Sales Order : 0 Supplier : 0
Order By : 0 Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
61	Back door opening weatherstrip <i>deformed</i>	1		\$ 321.36	✓		
62	Back door top weatherstrip <i>deformed</i>	1		\$ 140.46	✓		
63	Back door weatherstrip <i>deformed</i>	1		\$ 292.38	✓		
64	Rear bumper reinforcement <i>st</i>	1		\$ 297.00	✓		
65	Rear end panel <i>bul</i>	1		\$ 651.43	✓		
66	Rear end panel top garnish <i>broken</i>	1		\$ 337.50	✓		
67	LH rear body panel (fender) <i>vaz</i>	1		\$ 2,217.73	X		
68	LH rear body panel sticker - Singtel <i>4N</i>	1					
69	LH rear body panel inner shield <i>4N</i>	1		\$ 128.60	X	\$ 180.00	✓
70	Back door lock RH <i>4N</i>	1		\$ 207.03	X		
71	0	0		4543.49		180	
72	0	0					
73	0	0					
74	0	0					
75	0	0					
76	0	0					
77	0	0					
78	0	0					
79	0	0					
80	0	0					
81	0	0					
82	0	0					
83	0	0					
84	0	0					
85	0	0					
86	0	0					
87	0	0					
88		0					
89		0					
90		0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

15/05/2018

2040-13

SN 180

11:02 AM

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Supplementary 1

Vehicle No : GBB8921E

Case Owner : WILLIAM

Make & Model : FIAT DOBLO 1.3MJTD

Year Manufacture : 2010

Chassis No : ZFA22300005727117

Engine No : 199A20003660817

Sales Order : 0

Supplier : 0

Order By : _____

Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Item	S/N	Disposition By Surveyor
1	Taillamp retainer LH <i>crack</i>	1		\$ 180.33	✓		
2	Taillamp retainer RH <i>crack</i>	1		\$ 180.33	✓		
3	Back door LH inside lock <i>broken</i>	1		\$ 61.16	✓		
4	Back door LH inside handle trim <i>crack</i>	1		\$ 61.16	✓		
5	Back door LH inside opening handle <i>crack</i>	1		\$ 58.37	✓		
6	Back door LH outer handle <i>crack</i>	1		\$ 502.84	✓		
7	0	1					
8	0	1					
9		1		1044.11			
10		1					
11		1					
12		1					
13		1					
14		1					
15		1		18914.24		705	
16		1		17022.82			
17		1					
18		1					
19		1					
20		1					
21		1					
22		1					
23		1					
24		1					
25		1					
26		1					
27		1					
28		1					
29		1					
30		1					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

1044-19

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

LabourVehicle No. : **GBB8921E**Make & Model : **FIAT DOBLO 1.3MJTD**

Case Owner

Year of Manufacture

: **WILLIAM**: **2010**

S/Nº	Labour Description	Estimated Price	Adjusted Price
1	To transfer back door LH parts and mechanisms to new door.	\$60.00	40/-
2	To transfer back door RH parts and mechanisms to new door.	\$60.00	40/-
3	To remove/replace back door LH glass.	\$60.00	40/-
4	To remove/replace back door RH glass.	\$60.00	40/-
5	To mount vehicle on black hawk floor bench in order to re-align chassis members or body structure.	\$250.00	180/-
6	To remove/refit fuel tank to facilitate repairs.		Nil
7	To remove/refit cargo compartment trims and garnish to facilitate repairs.	\$50.00	40/-
8	To remove/refit aircond parts, vacuum & recharge gas.	\$100.00	Nil
9	Labour charges to repair and panel beat the frt support panel and replace damaged parts.	\$500.00	400/-
10	Labour charges to repair and panel beat the LH rear body inner structure, RH taillamp panel, rear floor board panel, cutting/welding and replacing damaged parts.	\$1,400.00	1200/-
11	To check wiring functions and focus headlamps.	\$20.00	✓
12	To remove/replace reverse sensor to new rear bumper and check wiring functions.	\$80.00	40/-

photo

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

2024 0



205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:

Type of Claim : TPVehicle No. : GBB8921EMake & Model : FIAT DOBLO 1.3MJTDYear of Manufacture : 2010Chassis No. : ZFA22300005727117Ins Company : OAC VS AXAEngine No. : 199A20003660817Excess : -Policy No. : -Date of Accident : 08.05.2018Time of Accident : 08:30Suggested Days of Repair : -

In-house Vehicle Assessor

Repair EstimateCase Owner : WILLIAM

Signature : _____

Parts (a) Cost / List Price Items \$ 17,870.05Plus/Less 10% \$ 1,787.01Total of Cost / List \$ 16,083.05(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 705.00Total Parts Cost (Appendix A) \$ 16,788.05Labour (Appendix B) \$ 4,140.00Total Repair Cost \$ 20,928.05Contact No
Frt Counter Operation

63837103 - Patrick Tia

63837730 - Brenda Ng

63837466 - Rohani

braddell_cr@sparkcarcare.com

Workshop Operation

63837656 - Ngo Toh Wee

63837362 -

63838115 - William Wang

63838115 - Andrew Goh

braddell_operation@sparkcarcare.com

LKK Auto Consultants hence notify
the Premier of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

The above total will be subjected to 7% G.S.T.

Name of Surveyor : BryanCompany : LKK AutoSurvey conducted on : 14/05/2018 at 1145hrs.

Acknowledged by Repairer

Signature: _____

Date: _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 9 day(s)(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

Spark Car Care

Page 1

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : GBB8921ECase Owner : WILLIAMMake & Model : FIAT DOBLO 1.3MJTDYear Manufacture : 2010Chassis No : ZFA22300005727117Engine No : 199A20003660817

Sales Order : _____

Supplier : _____

Order By : _____

Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Front number plate with casing ✓	1				\$ 35.00	State ✓
2	Front bumper ✓	1		\$ 755.66			distorted
3	Front bumper fog lamp cover LH ✓	1		\$ 121.33			✓ P/N
4	Front bumper fog lamp cover RH ✓	1		\$ 121.33			SVL
5	Front bumper reinforcement ✓	1		\$ 1,112.10			✓ X
6	Front grille ✓	1		\$ 375.88			✓
7	Front grille badge logo ✓	1		\$ 142.28			State ✓
8	Headlamp LH ✓	1		\$ 288.00			✓ X
9	Headlamp RH ✓	1		\$ 288.00			✓ X
10	Headlamp lower garnish LH ✓	1		\$ 184.34			✓ X
11	Headlamp lower garnish RH ✓	1		\$ 184.34			✓ X
12	Rear number plate with casing ✓	1				\$ 35.00	bt
13	Rear bumper ✓	1		\$ 295.60			one
14	Rear bumper LH ✓	1		\$ 405.00			distorted
15	Rear bumper RH ✓	1		\$ 405.00			SVL
16	Rear bumper reflector LH ✓	1		\$ 35.72			SVL
17	Rear bumper reflector RH ✓	1		\$ 35.72			SVL
18	Reverse sensors ✓	2				\$ 200.00	Done
19	Taillamp LH ✓	1		\$ 332.72			broken
20	Taillamp RH ✓	1		\$ 346.51			✓
21	Taillamp covering LH ✓	1		\$ 337.50			cut
22	Taillamp covering RH ✓	1		\$ 337.50			cut
23	Back door LH ✓	1		\$ 2,008.80			one
24	Back door LH badge logo ✓	1		\$ 30.00			one
25	Back door LH upper hinge ✓	1		\$ 120.70			✓
26	Back door LH lower hinge ✓	1		\$ 120.70			✓
27	Back door LH check ✓	1		\$ 66.53			✓
28	Back door LH glass ✓	1		\$ 165.00			shattered
29	Back door LH glass sealant ✓	1				\$ 40.00	one
30	Back door LH glass inner seal ✓	1				\$ 30.00	one

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

Page 2

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : GBB8921E Case Owner : WILLIAM

Make & Model : FIAT DOBLO 1.3MJTD Year Manufacture : 2010

Chassis No : ZFA22300005727117 Engine No : 199A20003660817

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
31	Back door LH wiper arm ✓	1		\$ 74.00			Wt
32	Back door LH wiper arm blade X	1		\$ 27.00			Svc
33	Back door LH wiper motor 2 Den	1		\$ 547.68			2 ✓
34	Back door LH wiper arm cover X	1		\$ 20.25			Svc
35	Back door LH trim board 2 Lwt	1		\$ 268.14			2 ✓
36	speed limit sticker - 70 km/h ✓	1				\$ 15.00	hlc
37	Rear number plate lamp LH 2 NN	1		\$ 56.44			2 ✓
38	Rear number plate lamp RH 2 NH	1		\$ 56.44			2 ✓
39	Back door LH upper lock 2 NN	1		\$ 166.36			2 ✓
40	Back door LH upper lock cover 2 HH	1		\$ 11.64			2 ✓
41	Back door LH upper lock striker 2 NH	1		\$ 42.45			2 ✓
42	Back door LH lower lock 2 BT	1		\$ 163.30			2 ✓
43	Back door LH lower lock cover 2 NN	1		\$ 11.64			2 ✓
44	Back door LH lower lock striker 2 BT	1		\$ 42.45			2 ✓
45	Back door RH ✓	1		\$ 1,888.19			Bnc
46	Back door RH emblem - Mutijet —	1		\$ 76.73			hlc
47	Back door RH sticker - singtel ✓	1				\$ 100.00	hlc
48	Back door RH upper hinge 2 BT	1		\$ 120.70			2 ✓
49	Back door RH lower hinge 2 BT	1		\$ 120.70			2 ✓
50	Back door RH check 2 BT	1		\$ 66.53			2 ✓
51	Back door RH glass ✓	1		\$ 195.00			Shattered
52	Back door RH glass sealant ✓	1				\$ 40.00	hlc
53	Back door RH glass inner seal ✓	1				\$ 30.00	hlc
54	Back door RH trim board 2 Svc	1		\$ 268.14			2 ✓
55	Back door RH upper lock 2 NN	1		\$ 166.36			2 ✓
56	Back door RH upper lock cover 2 HH	1		\$ 11.64			2 ✓
57	Back door RH upper lock striker 2 NH	1		\$ 42.45			2 ✓
58	Back door RH lower lock 2 BT	1		\$ 162.00			2 ✓
59	Back door RH lower lock cover 2 HH	1		\$ 11.64			2 ✓
60	Back door RH lower lock striker 2 BT	1		\$ 42.45			2 ✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

Page 3

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare PartsVehicle No : GBB8921ECase Owner : WILLIAMMake & Model : FIAT DOBLO 1.3MJTDYear Manufacture : 2010Chassis No : ZFA22300005727117Engine No : 199A20003660817Sales Order : 0Supplier : 0Order By : 0Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
61	Back door opening weatherstrip ✓	1		\$ 321.36			deformed
62	Back door top weatherstrip ✓	1		\$ 140.46			deformed
63	Back door weatherstrip ✓	1		\$ 292.38			deformed
64	Rear bumper reinforcement ✓	1		\$ 297.00			HI
65	Rear end panel ✓	1		\$ 651.43			✓
66	Rear end panel top garnish ✓	1		\$ 337.50			✓
67	LH rear body panel (fender) X	1		\$ 2,217.73			repa-
68	LH rear body panel sticker - Singtel ✓	1				\$ 180.00	HI
69	LH rear body panel inner shield X	1		\$ 128.60			HI
70	Back door lock RH X	1		\$ 207.03			HI
71	0	0					
72	0	0					
73	0	0					
74	0	0					
75	0	0					
76	0	0					
77	0	0					
78	0	0					
79	0	0					
80	0	0					
81	0	0					
82	0	0					
83	0	0					
84	0	0					
85	0	0					
86	0	0					
87	0	0					
88		0					
89		0					
90		0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

VEHICLE NO.: **GBB8921E**
 MAKE: FIAT DOBLO 1.3MJTD
 MODEL:
 YEAR OF MAKE: 2010
 CHASSIS NO.: ZFA22300005727117

0

PAGE 1

COST / LIST

S/N	Parts Description	PART NUMBER	Qty	Remarks	
				COST	LIST
1	Taillamp retainer LH <i>Crack</i> ✓	735418918	1		
2	Taillamp retainer RH <i>Crack</i> ✓	735418900	1		
3	Back door LH inside lock <i>broken</i> ✓	46773091	1		
4	Back door LH inside handle trim <i>Crack</i> ✓	735274578	1		
5	Back door LH inside opening handle <i>Crack</i> ✓	735379973	1		
6	Back door LH outer handle <i>Crack</i> ✓	735402299	1		
7			1		
8			1		
9			1		
10	<i>18/05/2018</i>		1		
11	<i>Form</i>		1		
12	<i>to</i>		1		
13	<i>to</i>		1		
14	<i>to</i>		1		
15	<i>to</i>		1		
16	<i>to</i>		1		
17	<i>to</i>		1		
18	<i>to</i>		1		
19			1		
20			1		
21			1		
22			1		
23			1		
24			1		
25			1		
26			1		
27			1		
28			1		
29			1		
30			1		

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Labour

Vehicle No. : **GBB8921E**

Case Owner

: **WILLIAM**

Make & Model : **FIAT DOBLO 1.3MJTD**

Year of Manufacture

: **2010**

S/No	Labour Description	Estimated Price	Adjusted Price
1	To transfer back door LH parts and mechanisms to new door.	\$60.00	40/-
2	To transfer back door RH parts and mechanisms to new door.	\$60.00	40/-
3	To remove/replace back door LH glass.	\$60.00	40/-
4	To remove/replace back door RH glass.	\$60.00	40/-
5	To mount vehicle on black hawk floor bench in order to re-align chassis members or body structure.	\$250.00	180/-
6	To remove/refit fuel tank to facilitate repairs.		NH
7	To remove/refit cargo compartment trims and garnish to facilitate repairs.	\$50.00	40/-
8	To remove/refit aircond parts, vacuum & recharge gas.	\$100.00	NH
9	Labour charges to repair and panel beat the frt support panel and replace damaged parts.	\$500.00	400/-
10	Labour charges to repair and panel beat the LH rear body inner structure, RH taillamp panel, rear floor board panel, cutting/welding and replacing damaged parts.	\$1,400.00	1200/-
11	To check wiring functions and focus headlamps.	\$20.00	✓
12	To remove/replace reverse sensor to new rear bumper and check wiring functions.	\$80.00	40/-

photo

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

ComfortDelGro Engineering Pte Ltd

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

: WILLIAM
: 2010

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.



Auto
Consultants
Pte Ltd

Company Registration No. 199607196R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 16/5/2018

Survey Details:

Date of loss	8-May-18
Date of appointment	11-May-18
Date of survey	14-May-18
Location of survey	CDGE Braddell

Vehicle Details:

Claim Type:	Third party
Vehicle number	GBB 8921E
Make and Model	FIAT DOBLO 1.3MJTD
Date of registration	16-Aug-10
Excess	
Market Value	\$ 18,000.00
Parf Rebate	\$ 6,800.00
Nett Loss	\$ 11,200.00

Repair details:

Initial Estimate	\$ 20,928.05
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 7,978.93
Check items (estimate)	\$ 5,767.54
Labour	\$ 3,240.00
Total	\$ 16,986.47
Lump Sum(if applicable)	TBA

Number of days for repair	9 days
---------------------------	--------



Service Request Details

Claim

S8M00GDW

Reference

None 

Loss Date

May 8, 2018

Request Date

May 11, 2018

Due Date

May 18, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Andrew 6383 8115
Braddell
(IN)
Bryan.

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

GBB8921E-B

Make

TPVD FIAT

Service Address

Primary Contact/Insured

METEORITE LOGISTICS SERVICES PTE LTD
45 JALAN PEMIMPIN, #01-01, 577197, Singapore
62595104
AT2BSURE@GMAIL.COM

Claim Handler

NG Stacey
6568804351
stacey.ng@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)

New Message



Re:REMINDER FOR MANDATE

Type

🔗 Question

Message

pls proceed

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

3 VEH CHAIN COLLISION L INSURED VEHICLE 3RD AND LAST.
BOLA 28. (13 days reco for repair + 3 Saturdays + 3 Sundays + 1
PH

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 11,235.00	GST included
Loss of Rental	\$ -	
Loss of Use	\$ 1,080.00	\$60 x 18days
LTA search fees	\$ 2.00	
Proposed Total	\$ 12,317.00	

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	YP 5718A (Insd veh)	Model:	FIAT DOBLO
	GBB 8921E (TP veh)		
Date of Accident:	08/05/2018		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	23,398.57
Final Repair Cost	:	\$	11,235.00
Loss of Use	:	\$	1,080.00
Rental (if any)	:	\$	18 days at \$60.00 per day
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$
---------	---	----

	:	\$
Final Settlement Sum (GLOBAL SUM)	:	\$ 12,315.00

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ 100 _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	COMFORTDELGRO ENGINEERING PTE LTD	:	\$ 12,315.00

NUR SHAQILAH BTE ABDOL
WAHAB

08/02/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18008724/Dja3s2		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 08-02-2019		
ATTN: STACEY NG		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 5718A	Veh. Inspected	GBB 8921E	
Policy No.	GA325161/1	Coverage (\$)	0.00	
Claim No.	S8M00GDW	Excess (\$)	0.00	
Assign From	STACEY NG	Assign Date	11/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	FIAT DOBLO	c.c	1248	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	ZFA22300005727117	Colour	WHITE	
Odometer	139144	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65R15	FALKEN	5 mm	
L/H Front Tyre	185/65R15	FALKEN	5 mm	
R/H Rear Tyre	185/65R15	FALKEN	5 mm	
L/H Rear Tyre	185/65R15	FALKEN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/05/2018	Inspection Date	14/05/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 205 BRADDELL ROAD Blk C, 3rd Floor SINGAPORE 579701.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		13 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 8921E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (CONSISTENT)	DISTORTED	755.66	755.66
1	FRONT BUMPER FOG LAMP COVER LH (CONSISTENT)	NOT NECESSARY	121.33	-
1	FRONT BUMPER FOG LAMP COVER RH (CONSISTENT)	NOT NECESSARY	121.33	-
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	1,112.10	-
1	FRONT GRILLE (CONSISTENT)	CRACKED	375.88	375.88
1	FRONT GRILLE BADGE LOGO (CONSISTENT)	CUT	142.26	142.26
1	HEADLAMP LH (CONSISTENT)	NOT NECESSARY	288.00	-
1	HEADLAMP RH (CONSISTENT)	NOT NECESSARY	288.00	-
1	HEADLAMP LOWER GARNISH LH (CONSISTENT)	NOT NECESSARY	184.34	-
1	HEADLAMP LOWER GARNISH RH (CONSISTENT)	CRACKED	184.34	184.34
1	REAR BUMPER (CONSISTENT)	BUCKLED	295.60	295.60
1	REAR BUMPER LH (CONSISTENT)	DENTED	405.00	405.00
1	REAR BUMPER RH(CONSISTENT)	SERVICEABLE	405.00	-
1	REAR BUMPER REFLECTOR LH (CONSISTENT)	NOT NECESSARY	35.72	-
1	REAR BUMPER REFLECTOR RH (CONSISTENT)	NOT NECESSARY	35.72	-
1	TAILLAMP LH (CONSISTENT)	SCRATCHED	332.72	332.72
1	TAILLAMP RH (CONSISTENT)	BROKEN	346.51	346.51
1	TAILLAMP COVERING LH (CONSISTENT)	CUT	337.50	337.50
1	TAILLAMP COVERING RH (CONSISTENT)	CUT	337.50	337.50
1	BACK DOOR LH (CONSISTENT)	BUCKLED	2,008.80	2,008.80
1	BACK DOOR LH BADGE LOGO (CONSISTENT)	NECESSARY	30.00	30.00
1	BACK DOOR LH UPPER HINGE (CONSISTENT)	BENT	120.70	120.70
1	BACK DOOR LH LOWER HINGE (CONSISTENT)	BENT	120.70	120.70
1	BACK DOOR LH CHECK (CONSISTENT)	BENT	66.53	66.53
1	BACK DOOR LH GLASS (CONSISTENT)	SHATTERED	165.00	165.00
1	BACK DOOR LH WIPER ARM (CONSISTENT)	BENT	74.00	74.00
1	BACK DOOR LH WIPER ARM BLADE (CONSISTENT)	SERVICEABLE	27.00	-
1	BACK DOOR LH WIPER MOTOR (CONSISTENT)	DAMAGED	547.68	547.68
1	BACK DOOR LH WIPER ARM COVER (CONSISTENT)	SERVICEABLE	20.25	-
1	BACK DOOR LH TRIM BOARD (CONSISTENT)	CUT	268.14	268.14
1	REAR NUMBER PLATE LAMP LH (CONSISTENT)	NOT NECESSARY	56.44	-

Report Ref No. CC4/ASM18008724/Dja3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR NUMBER PLATE LAMP RH (CONSISTENT)	NOT NECESSARY	56.44	-
1	BACK DOOR LH UPPER LOCK (CONSISTENT)	NOT NECESSARY	166.36	-
1	BACK DOOR LH UPPER LOCK COVER (CONSISTENT)	NOT NECESSARY	11.64	-
1	BACK DOOR LH UPPER LOCK STRIKER (CONSISTENT)	BENT	42.45	42.45
1	BACK DOOR LH LOWER LOCK (CONSISTENT)	BENT	163.30	163.30
1	BACK DOOR LH LOWER LOCK COVER (CONSISTENT)	NOT NECESSARY	11.64	-
1	BACK DOOR LH LOWER LOCK STRIKER (CONSISTENT)	BENT	42.45	42.45
1	BACK DOOR RH (CONSISTENT)	BUCKLED	1,888.19	1,888.19
1	BACK DOOR RH EMBLEM - MUTIJET (CONSISTENT)	NECESSARY	76.73	76.73
1	BACK DOOR RH UPPER HINGE (CONSISTENT)	BENT	120.70	120.70
1	BACK DOOR RH LOWER HINGE (CONSISTENT)	BENT	120.70	120.70
1	BACK DOOR RH CHECK (CONSISTENT)	BENT	66.53	66.53
1	BACK DOOR RH GLASS (CONSISTENT)	SHATTERED	195.00	195.00
1	BACK DOOR RH TRIM BOARD (CONSISTENT)	SERVICEABLE	268.14	-
1	BACK DOOR RH UPPER LOCK (CONSISTENT)	NOT NECESSARY	166.36	-
1	BACK DOOR RH UPPER LOCK COVER (CONSISTENT)	NOT NECESSARY	11.64	-
1	BACK DOOR RH UPPER LOCK STRIKER (CONSISTENT)	NOT NECESSARY	42.45	-
1	BACK DOOR RH LOWER LOCK (CONSISTENT)	BENT	162.00	162.00
1	BACK DOOR RH LOWER LOCK COVER (CONSISTENT)	NOT NECESSARY	11.64	-
1	BACK DOOR RH LOWER LOCK STRIKER (CONSISTENT)	BENT	42.45	42.45
1	BACK DOOR OPENING WEATHERSTRIP (CONSISTENT)	DEFORMED	321.36	321.36
1	BACK DOOR TOP WEATHERSTRIP (CONSISTENT)	DEFORMED	140.46	140.46
1	BACK DOOR WEATHERSTRIP (CONSISTENT)	DEFORMED	292.38	292.38
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	297.00	297.00
1	REAR END PANEL (CONSISTENT)	BUCKLED	651.43	651.43
1	REAR END PANEL TOP GARNISH (CONSISTENT)	BROKEN	337.50	337.50
1	LH REAR BODY PANEL (FENDER) (CONSISTENT)	TO REPAIR SEE LABOUR	2,217.73	-
1	LH REAR BODY PANEL INNER SHIELD (CONSISTENT)	NOT NECESSARY	128.60	-
1	BACK DOOR LOCK RH (CONSISTENT)	NOT NECESSARY	207.03	-
1	TAILLAMP RETAINER LH (CONSISTENT)	CRACKED	180.33	180.33
1	TAILLAMP RETAINER RH (CONSISTENT)	CRACKED	180.33	180.33
1	BACK DOOR LH INSIDE LOCK (CONSISTENT)	BROKEN	61.16	61.16

Report Ref No. CC4/ASM18008724/Dja3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BACK DOOR LH INSIDE HANDLE TRIM (CONSISTENT)	CRACKED	61.16	61.16
1	BACK DOOR LH INSIDE OPENING HANDLE (CONSISTENT)	CUT	58.37	58.37
1	BACK DOOR LH OUTER HANDLE (CONSISTENT)	CUT	502.84	502.84
	LESS 10% DISCOUNT		-1,891.42	-1,291.93
			17,022.82	11,627.41
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE WITH CASING (SN) (CONSISTENT)	CRACKED	35.00	35.00
1	REAR NUMBER PLATE WITH CASING (SN) (CONSISTENT)	BENT	35.00	35.00
2	REVERSE SENSORS (SN) (CONSISTENT)	DAMAGED	200.00	200.00
1	BACK DOOR LH GLASS SEALANT (SN) (CONSISTENT)	NECESSARY	40.00	40.00
1	BACK DOOR LH GLASS INNER SEAL (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	SPEED LIMIT STICKER - 70KM/H (SN) (CONSISTENT)	NECESSARY	15.00	15.00
1	BACK DOOR RH STICKER - SINGTEL (SN) (CONSISTENT)	NECESSARY	100.00	100.00
1	BACK DOOR RH GLASS SEALANT (SN) (CONSISTENT)	NECESSARY	40.00	40.00
1	BACK DOOR RH GLASS INNER SEAL (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	LH REAR BODY PANEL STICKER - SINGTEL (SN) (CONSISTENT)	NECESSARY	180.00	180.00
			705.00	705.00
	<u>LABOUR</u>			
	TO TRANSFER BACK DOOR LH PARTS AND MECHANISMS TO NEW DOOR.		60.00	40.00
	TO TRANSFER BACK DOOR RH PARTS AND MECHANISMS TO NEW DOOR.		60.00	40.00
	TO REMOVE / REPLACE BACK DOOR LH GLASS.		60.00	40.00
	TO REMOVE / REPLACE BACK DOOR RH GLASS.		60.00	40.00
	TO MOUNT VEHICLE ON BLACK HAWK FLOOR BENCH IN ORDER TO RE-ALIGN CHASSIS MEMBERS OR BODY STRUCTURE.		250.00	180.00
	TO REMOVE / REFIT FUEL TANK TO FACILITATE REPAIRS. (NPA)	NOT NECESSARY	-	-
	TO REMOVE / REFIT CARGO COMPARTMENT TRIMS AND GARNISH TO FACILITATE REPAIRS.		50.00	40.00
	TO REMOVE / REFIT AIRCOND PARTS, VACUUM & RECHARGE GAS.	NOT NECESSARY	100.00	-

Report Ref No. CC4/ASM18008724/Dja3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR CHARGES TO REPAIR AND PANEL BEAT THE FRT SUPPORT PANEL AND REPLACE DAMAGED PARTS.		500.00	400.00
	LABOUR CHARGES TO REPAIR AND PANEL BEAT THE LH REAR BODY INNER STRUCTURE, RH TAILLAMP PANEL, REAR FLOOR BOARD PANEL, CUTTING WEDLING AND REPLACING DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF LH REAR BODY PANEL (FENDER).		1,400.00	1,200.00
	TO CHECK WIRING FUNCTIONING AND FOCUS HEADLAMPS.		20.00	20.00
	TO REMOVE / REPLACE REVERSE SENSOR TO NEW REAR BUMPER AND CHECK WIRING FUNCTIONS.		80.00	40.00
	TO PUTTY, APPLY PRIMER & SPRAY-PAINT THE FRONT BUMPER, FRONT SUPPORT PANEL, HEADLAMP LOWER GARNISH LH, HEADLAMP LOWER GARNISH RH AND AFFECTED AREAS.		500.00	400.00
	TO PUTTY, APPLY PRIMER & SPRAY-PAINT THE REAR BUMPER LH, REAR BUMPER RH, BACK DOOR LH, BACK DOOR RH, REAR END PANEL, LH REAR BODY PANEL, LH REAR BODY PANEL INNER STRUCTURE, RH TAILLAMP PANEL, LH TAILLAMP PANEL, REAR FLOORBOARD PANEL AND AFFECTED AREAS.		1,000.00	800.00
			4,140.00	3,240.00
GRAND TOTAL			21,867.82	15,572.41
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				10,500.00

Report Ref No. CC4/ASM18008724/Dja3s2

ANG BRYAN TANI

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.