

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

	GBF 6153 Y	Nos Norharke
arts (a) Cost / List Price Items	\$ 4,588.25	Mesony Bapaing
Plus/Less10%	\$ 458.83	- Praing
Total of Cost / List	\$ 4,129.43	
(b) Nett Price Items		
Less		LKK Auto Consultants hence notify
Total of Nett Item		the Repairer of the following: To resurvey before/after spray painting To display damaged part(s) during resurvey
(c) Special Nett Items	\$ 35.00	 Parts prices are subject to confirmation
tal Parts Cost	\$ 4,164.43	No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and
bour	\$ 1,510.00	is subject to final approval from Insurance Company Acknowledged by Repairer
4-1	\$ 5,674.43	Signature:
ne above total will be subjected to		_ Date:
e above total will be subjected to		
e above total will be subjected to Name of Surveyor		Menneth UK/c 19/3/18 at
Name of Surveyor Company Survey conducted on Remarks By Surveyor	7% G.S.T.	Henneth UKIC 19/5/18 at
Name of Surveyor Company Survey conducted on Remarks By Surveyor (a) The repair of this vehicle is	7% G.S.T.	Hennesh UK/c 19/3/18 at d until further notice.
Name of Surveyor Company Survey conducted on Remarks By Surveyor	7% G.S.T.	Henneth UKIC 19/5/18 at
Name of Surveyor Company Survey conducted on Remarks By Surveyor (a) The repair of this vehicle is	7% G.S.T.	Henneth UK/c 19/3/M at d until further notice. 03 day(s)
Name of Surveyor Company Survey conducted on Remarks By Surveyor (a) The repair of this vehicle is the survey of Recommended Days of Regions.	7% G.S.T. : : : : : : : : : : : : : : : : : :	Henneth UK/c 19/3/W at d until further notice. 03 day(s)



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle	No.	:
Make &	Model	:

Chassis No :

GBF 6153 Y

VOLK T6

WV1ZZZ7HZHH042387

Submit By

Year Manufacture

Carmen Lim

2016

Engine No. Cost / List

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
1	RH wing mirror (motor)	Ty	1	\$471.45		-
2	RH wing mirror (cover)	ns	1	\$43.00		
3	RH front door	B	1	\$2,582.05		_
4	RH front door hinge top	n	1	\$117.75		X
5	RH front door hinge bottom	n	1	\$241.05		X
6	RH front door weatherstip	Sn	1	\$27.85		X
7	RHF door glass outer moulding	Su.	1	\$94.85		<
8	RHF power window motor	F.	, 1	\$540.50		X
9	RHF power window regulator	Len	1	\$469.75		
10	RHF door company sticker	1	K 1	\$35.00	SN	
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						- 1 21 1
22						
23						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829 Company Reg No. 200005485N / GST No. 20-0005485-N



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

L	a	b	0	u	r

Vehicle No.	:	GBF 6153 Y	Submit By	:	Carmen Lim	
Make & Model	:	VOLK T6	Year of Manufacture:		2016	

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
	REPAIR AREA. (RH SIDE MIRROR ,RHF DOOR)	\$500.00	234
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		
	REPAIR AREA. (RH SIDE MIRROR ,RHF DOOR)	\$500.00	2501
3	To check wiring	\$50.00	201
4	To remove & refit Door trim, door glass, window regulator,		
	door lock to assist work load.	\$180.00	601
5	To do art work. (B://)	\$200.00	?
6	To tuff coat	\$80.00	301
	, , , , , , , , , , , , , , , , , , , ,		

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.