

ASS. REC. BY:

REF: CS/MSG18008811/Kvd3/12 Special Instruction:

Surveyor:
Merimen

ASSIGNMENT (Office)

From (Person): Eldine Ngu of MSIG Date/Time: 15/5/2018 @ 3:17pm

Estimated Cost: Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No: SJU 2868X Insured: GBC 1180 S

at Workshop m/s Alan's United Auto Tel: 6453 8686

of Blk 7, Sin Ming Ind. #01-76

Policy No: 28720181MKC Claim No: 558260

Sum Insured: Excess:

Make of Veh: D.O.A. 08/05/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS (wp) H.O.D. Endorsement:

Date/Time: 3:31pm @ 15/5/18 Person Contacted: Kenny Vehicle: IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	SJU 2868X - X
	GBC 1180S - X.
28/5/18	Send preli revised by merimen
7/6	11pm @ 1600 confirmed by email (Ref 843.20, 347)

ASS. REC. BY:

REF: MSG/Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: _____

at Workshop m/s Alan's

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: STU 2868X Yr Regn: 07, 13Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Subaru Impreza c.c. 1600Colour: M. Silver A/C: Insured / Std / NI / NASp. Reading: 81437 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JF1GJ3KC5CG004245Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD A/Rim orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 8/5/18Survey held at ✓

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 25/5/18Des. of Damages: 0/S / Rrt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/5 File pass to Catherine

RECEIVED 01 JUN 2018

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 7/6- typist

Report Format:

Lump Sum / I.B.I: (\$

merimen1600/pDays Of Repair: 4Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fixtures

Others

TOTAL

15010160

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 28 May 2018

Preliminary Advice

Insured Vehicle No	: GBC1180S		
TP Vehicle No	: SJU2868X	Accident Date	: 08/05/2018
Make	: SUBARU IMPREZA	Assignment Date	: 15/05/2018
Date of Inspection	: 25/05/2018	Est. Duration of Repair	: 4.00
Inspection At	: ALAN'S UNITED AUTO PTE LTD (SIN MING) BLOCK 7, SIN MING INDUSTRIAL ESTATE, #01-76 SINGAPORE 575642		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,443.20
Revised Amount	:S\$	2,056.80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,056.80
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 May 2018		15 May 2018 15:17 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	OVERSEAS RESOURCES PTE LTD, Co. Reg. No.: 197800760Z		
Main Claimant:	NG YOONG BOON, ID: S6907009D		
Vehicle Reg. No.:	SJU2868X	Date of Loss:	08/05/2018 13:00 - :59 [57 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 558260	Policy/Cover Note No.:	28720181MKC (Comprehensive) Coverage: 30/04/2018 - 29/04/2019
Vehicle Reg. No. (Insured):	GBC1180S	Policy No. (Claimant):	
		Excess:	S\$1,000.00
Repairer:	Alan's United Auto Pte Ltd (SIN MING) BLOCK 7, SIN MING INDUSTRIAL ESTATE, #01-76, 575642 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/05/2018]		
Adj Asg. Remarks:	LIABILITY NOT CLEAR OI NON REPORTING To let LKK Auto Consultants Pte Ltd Mr. Kenneth Kong to SURVEY		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Eileen Goh

From: Woon Choo Kwok
Sent: Monday, 14 May, 2018 12:58 PM
To: Elaine Ngu; Eileen Goh
Cc: Foo Ai Ngoh; Jason Sim
Subject: FW: ATTACHED SJU2868X REPAIR ESTIMATE,GIA REPORT TO REQUEST JOINT EXPERT SURVEYOR LIST FOR CONDUCT PRE REPAIR SURVEY
Attachments: SKM_284e18051411060.pdf
Follow Up Flag: Follow up
Flag Status: Flagged

Dear Officers

fya

Best Regards

Kwok Woon Choo
Senior Admin Officer, Claims Services
Tel : 6643 1330 Fax: 6225 7402 | woonchoo_kwok@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Agnes Lee
Sent: Monday, May 14, 2018 11:44 AM
To: Woon Choo Kwok <WoonChoo_Kwok@sg.msig-asia.com>
Subject: FW: ATTACHED SJU2868X REPAIR ESTIMATE,GIA REPORT TO REQUEST JOINT EXPERT SURVEYOR LIST FOR CONDUCT PRE REPAIR SURVEY

From: kennychan@alanutd.com [<mailto:kennychan@alanutd.com>]
Sent: 14 May 2018 11:10
To: Claims <claims@sg.msig-asia.com>
Subject: ATTACHED SJU2868X REPAIR ESTIMATE,GIA REPORT TO REQUEST JOINT EXPERT SURVEYOR LIST FOR CONDUCT PRE REPAIR SURVEY

Dear Motor Claims Dept.

Attached our client vehicle SJU2868X repair estimate , GIA report , police report to request joint expert surveyor list for conduct pre repair survey ,claiming your insured vehicle GBC1180S accident on 08-05-2018 HIT N RUN ,thank you .

Regards
Kenny

Alan's United Auto Pte Ltd
64538686

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Annex A

Transaction ref 20170227111905050994

The owner and vehicle particulars for Vehicle No. SJU2868X as at 27 Feb 2017 are as follows:

1. Name	: NG YOONG BOON
2. Identification No. Type	: Singapore NRIC
3. Identification No.	: S6907009D
4. Place Of Passport Issue	: -
5. Vehicle No.	: SJU2868X
6. Previous Vehicle No.	: -
7. Effective Date of Ownership	: 27 Feb 2017
8. Original Registration Date	: 25 Jul 2013
9. First Registration Date	: 25 Jul 2013
10. Vehicle Type	: P10 - Passenger Motor Car
11. Vehicle Scheme	: Normal
12. Attachment 1	: No Attachment
13. Attachment 2	: -
14. Attachment 3	: -
15. Vehicle Make	: SUBARU
16. Vehicle Model	: IMPREZA 4D 1.6I-S AWD CVT
17. Year of Manufacture	: 2012
18. Primary Colour	: Silver
19. Secondary Colour	: -
20. Passenger Capacity	: 4
21. Chassis/Trailer Chassis No.	: JF1GJ3KC5CG004245 / -
22. Propellant	: Petrol
23. Engine No./Motor No.	: FB16R356344 / -
24. Engine Capacity(cc)/Power Rating(kW)	: 1600 / -
25. Maximum Power Output(kW/bhp)	: 84.0 / 112
26. Unladen Weight(kg)	: 1360

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05782

Vehicle Insured : GBC1180S

Accident Date : 08-May-2018

Date : 14-May-2018

Our Ref : 218086 (MSIG) / CHAN

PAGE : 1

NG YOONG BOON
9 LOR. 26 GEYLANG
#05-13
Singapore 398484

*Not with work
1/10/18
Re-survey After Paint
4 days*

ESTIMATED COST OF REPAIR FOR SUBARU IMPREZA 1.6 SJU2868X

1 pc O/s headlamp
1 pc Front o/s fender
1 pc Front o/s fender lamp
1 pc Front o/s fender inner shield

Gr	900.00	✓
B	350.00	✓
B	46.00	✓
Ln	108.00	X
	1,404.00	
Less 20% :	280.80	

30/5/18

1,123.20

1 pc To rewire damaged parts and refocus
headlamp beam.

20.00 ✓

To putty and spray replaced parts

700.00 *600*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

600.00 *400*

Total : S\$ 2,443.20

Singapore Dollars Two Thousand Four Hundred and
Forty Three and Cents Twenty Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal circulation(s) is allowed
- Supplier(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by: _____
Signature: _____
Date: _____

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18008811/KVD3N2

Date: 08/06/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28720181MKC
Claimant Vehicle No :	SJU2868X	Insured Vehicle No :	GBC1180S
Date of Loss:	08/05/2018	Nature of Claim:	TP
		Claim No:	558260

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU2868X	Engine No:	FB16R356344
Make & Model:	SUBARU IMPREZA, 1.6 (A)	Chassis No:	JF1GJ3KC5CG004245
Reg. Date:	25/07/2013 (Man. Year: 2012)	Odometer:	81437 km
Colour:	Metallic Silver		
Engine Capacity:	1600 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,123.20	1,036.80	86.40	7.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,320.00	1,020.00	300.00	22.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,443.20	2,056.80	386.40	15.82
Approved Total (Overridden) (S\$)		1,600.00		
(S\$)	2,443.20	1,600.00	843.20	34.51
+ GST 7.00/7.00% (S\$)	171.02	112.00	59.02	34.51
Nett Amount (S\$)	2,614.22	1,712.00	902.22	34.51

INSPECTION

Date of Assignment: 15/05/2018

Date Inspected: 25/05/2018 Inspected At:

Alan's United Auto Pte Ltd (SIN MING)
BLOCK 7, SIN MING INDUSTRIAL
ESTATE, #01-76
Singapore 575642

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Jun 2018)
Parts:	143	SUBARU IMPREZA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJU2868X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S HEADLAMP	Cut	900.00 FL	*900.00 FL
2	1		*FRONT O/S FENDER	Bent	350.00 FL	*350.00 FL
3	1		*FRONT O/S FENDER LAMP	Broken	46.00 FL	*46.00 FL
4	1		*FRONT O/S FENDER INNER SHIELD	Serviceable	108.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	1,404.00	1,296.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	280.80	259.20
Total Parts (\$\$)	1,123.20	1,036.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REWIRE DAMAGED PARTS AND REFOCUS HEADLAMP BEAM	New	20.00	20.00
2	TO PUTTY AND SPRAY REPLACED PARTS	New	700.00	600.00
3	TO REMOVE,CUT-OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ABOVE PARTS	New	600.00	400.00
Gross Labour Cost (\$\$)			1,320.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >