

CHUNNI MOTOR WORK PTE LTD

To supply by (LKK)

REPAIR ESTIMATE*

VEHICLE NO : SHA 3891A

DATE : 11.05.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039 FWD

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper <i>Dented</i>			\$ 603.60	✓
	Rear Bumper Clip 10 pcs <i>H/C</i>			\$ 22.00	✓
	Tail Lamp (LH) <i>H/C</i>			\$ 565.60	✓
	Rear Fender With Housing (LH) <i>Dented</i>			\$ 4,736.80	✓
	Rear Fender Inner Lining (LH) <i>deformed</i>			\$ 164.40	✓
	Rear Fender Air-Duct <i>SVL</i>			\$ 51.60	×
	Rear Windscreen Moulding <i>H/C</i>			\$ 60.00	✓
	Fuel Lid Cover <i>NH</i>			\$ 98.50	×
	Rear Door (LH) <i>Dented</i>			\$ 1,351.10	✓
	Rear Door Gear/Regulator (LH) <i>NH</i>			\$ 785.50	×
	Rear Door Power Motor (LH) <i>NH</i>			\$ 530.50	×
	Front Door (LH) <i>Dented</i>			\$ 1,403.05	✓
	Front Door Gear / Regulator (LH) <i>NH</i>			\$ 785.50	×
	Front Door Power Motor <i>NH</i>			\$ 950.90	×
	Door Centre Pillar Outer (LH) <i>NH Dented</i>			\$ 1,786.20	✗ ✓
	Rocker Panel Outer Garnish (LH) <i>Dented</i>			\$ 483.60	✓
	Rear Tyre Rim (LH) <i>2 V&T</i>			\$ 351.90	2 ✓
	Rear Wheel Hup-Cap (LH) <i>cut</i>			\$ 150.70	✓
	Rear Wheelbearing ING & Hub <i>2 distanced</i>			\$ 401.40	2 ✓
	Rear Trailing Arm (LH) <i>2 distanced</i>			\$ 120.00	2 ✓
	Rear Assist (LH) <i>2 distanced</i>			\$ 120.00	2 ✓
	Rear Shock Absorber (LH) <i>2 distanced</i>			\$ 342.20	2 ✓
	Rear Shock Absorber Mounting (LH) <i>NH</i>			\$ 57.70	×
	Rear Crossmember <i>2 distanced</i>			\$ 1,190.00	2 ✓
	Stabilizer Bar <i>2 distanced</i>			\$ 204.60	2 ✓
	Stabilizer Link <i>2 distanced</i>			\$ 68.15	2 ✓
	Rear Upper Arm (LH) <i>2 distanced</i>			\$ 335.75	2 ✓
	Rear Lower Arm (LH) <i>2 distanced</i>			\$ 204.35	2 ✓
	Rear Knuckle Arm (LH) <i>2 distanced</i>			\$ 574.80	2 ✓
				SUB TOTAL	
				\$ 18,500.40	
				LESS 20%	
				\$ 3,700.08	
				DISCOUNTED TOTAL	
				\$ 14,800.32	
	Rear Bumper Reverse Sensor <i>NH</i>			\$ 135.70	Nett ✗
	Rear Bumper Advertisement Logo <i>H/C</i>			\$ 50.00	Nett ✓
	Rear Bumper Rubber Mat <i>H/C</i>			\$ 50.00	Nett ✓
	Rear Windscreen Sealant <i>H/C</i>			\$ 46.00	Nett ✓
	Rear Door Advertisement Logo (LH) <i>H/C</i>			\$ 100.00	Nett ✓
	Rear Door Comfortdelgro & Apps Sticker (LH) <i>H/C</i>			\$ 80.00	Nett ✓
	Front Door Coloured Comfort Logo (LH) <i>H/C</i>			\$ 75.00	Nett ✓
	Front Door Advertisement Logo (LH) <i>H/C</i>			\$ 100.00	Nett ✓
	Rear Tyre (LH) <i>SVL</i>			\$ 216.00	Nett ✗
				\$ 852.70	

SHA 3891A

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,600.00 1000/-
	Spray Painting Charge			\$ 1,000.00 800/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 80.00 40/-
	Towing Charge			\$ 50.00 22
	Remove/Refix Cushion & Upholstery Rear			\$ 80.00 80/-
	Remove/Refix Rear Windscreen Glass			\$ 100.00 80/-
	Transfer of Door		\$ 80.00	\$ 160.00 120/-
	Remove/Refix Undercarriage (RR)			\$ 190.00 150/-
	Rear Wheel Alignment			\$ 80.00 60/-
	TOTAL LABOUR			\$ 3,390.00
	ESTIMATE TOTAL			\$ 19,043.02
	<p>14/05/2018 @ 1315 hrs HAT Antenna 4/5mm 7 days. LKK Auto</p>			
				
				
	<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: _____ Date: _____</p>			
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				