



Your Ref : S8M00GKU

Date: 14<sup>th</sup> December 2018

Our Ref : CC4/ASM18008837/T1ja3s2

**M/s AXA Insurance Pte Ltd**  
8 Shenton Way #24-01  
AXA Tower  
Singapore 068811  
(The Motor Claims Department)

Attn: Richard Ang

Dear Sir/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE NO  
SJC 3932G ACCIDENT ON 09/05/2018 INSURED PC 3156J**

Instruction was received to inspect the vehicle Reg. No. SJC 3932G. The inspection was conducted on 15/05/2018 at the premises of M/s Ethoz Group Ltd, 30 Bukit Batok Crescent Singapore 658075.

The following information were recorded: -


Registration Number	: SJC 3932G
Make & Model	: Mitsubishi Colt 1.5A
Year of Registration	: 2008
Engine Capacity	: 1499 cc
Body Colour	: Silver
Chassis Number	: JMYXSZ23A8Z000101

The vehicle sustained damages at the front and rear portion. (Details see photographs enclosed).

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **"Total Loss"**.

Market Value	S\$	29,000.00
Less: LTA Reimbursement Value (RV)	(S\$	20,013.00)
Nett Liability	S\$	8,987.00
		=====

Vehicle Inspected By:



MOHAMAD TAUFIKH  
M.MATAI, AMSAE-A  
Automotive Assessor



K.K.LAU  
MSc(Eng M), B Eng(Hons), Peng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCIAd, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.