

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

China Taiping - (CLS)

TS

VEHICLE NO : SHD 4312H

DATE 14/5/2018 10:43

MAKE :

LKK - Calvin

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper <i>X Rep. 2</i>			\$ 578.40	
	Rear Bumper Protector (RH) <i>X Rep</i>			\$ 38.00	
	Tail Lamp (RH) <i>✓</i>			\$ 344.00	
	Rear Fender (RH) <i>X Rep</i>			\$ 1,935.90	
	Rear Fender Inner Lining (RH) <i>X</i>			\$ 74.10	
	Rear Windscreen Moulding <i>X</i>			\$ 60.00	
	Rear Wheel Hub Cap, RH <i>✓</i>			\$ 145.00	
	SUB TOTAL			\$ 3,175.40	
	LESS 20%			\$ 635.08	
	DISCOUNTED TOTAL			\$ 2,540.32	
	Rear Bumper Rubber Mat <i>X</i>			\$ 50.00	Nett
	Rear Windscreen Sealant <i>X</i>			\$ 46.00	Nett
				\$ 96.00	
	Labour Charge				
	Panel Beating			\$ 850.00 <i>400</i>	
	Spray Painting Charge			\$ 400.00	360
	Wiring Charge			\$ 50.00	20
	Tuff Kote			\$ 50.00	X
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	30
	Remove/Refix Rear Windscreen Glass			\$ 120.00	X
	Remove/Refix Reverse Sensor			\$ 120.00	X
	Rear Wheel Alignment			\$ 80.00	X
	TOTAL LABOUR			\$ 1,820.00	
	ESTIMATE TOTAL			\$ 4,456.32	
<i>Kalvin LKK</i> <i>14/5/18 1125hrs</i> <i>3 Rep.</i> <i>CLS</i> <i>After Repair</i>					
Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					