

REPAIR ESTIMATE*

VEHICLE NO : SHC 3273Z

MAKE

MODEL : HYUNDAI i40

Arg Asia - 4sum

DATE 14/5/2018 10:52

TS

LKK - Kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 562.30
	Front Bumper Bracket Top (LH) ?			\$ 22.40
	Front Bumper Bracket (LH) ?			\$ 24.60
	Front Fender (LH) ✓			\$ 619.00
	Front Fender Shield (LH) ?			\$ 169.80
	Front Fender Retainer ?			\$ 9.20
	Frt Wheel Hub Cap, LH ✓			\$ 150.70
	SUB TOTAL			\$ 1,558.00
	LESS 20%			\$ 311.60
	DISCOUNTED TOTAL			\$ 1,246.40
	Labour Charge			300
	Panel Beating			\$ 560.00
	Spray Painting Charge			\$ 400.00 360
	Tuff Kote			\$ 50.00 20
	Frt Wheel Alignment			\$ 80.00 x
	TOTAL LABOUR			\$ 1,090.00
	ESTIMATE TOTAL			\$ 2,336.40
<div style="display: flex; justify-content: space-between; align-items: flex-start;"> <div style="width: 40%;"> <p>Kalvin</p> <p>14/5/18 11:00h</p> <p>2 days</p> <p>4/5</p> <p>After Repair p.k.</p> </div> <div style="width: 50%; border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div> </div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				