

Our Ref : CI/FCI18008868/N

11 May 2018

M/s First Capital Insurance Limited

36 Robinson Road #16-01

City House

Singapore 068877

TECHNICAL INVESTIGATION REPORT OF FIRE INCIDENT INVOLVING THE INSURED VEHICLE SHB 6366A ON 25 APRIL 2018

1. We refer to your letter dated 7 May 2018 and the instructions therein.
2. Our analysis, comments and opinions with respect to the cause of fire to the insured vehicle SHB 6366A (herein referred to as "**Insured Vehicle**") are set out below.

Inspection of the Insured Vehicle

3. The Insured Vehicle was physically inspected on 9 May 2018 at the premises of ComfortDelGro Engineering Pte. Ltd. (herein referred to as "**CDGE**") located 59 Loyang Drive, Singapore 508969. A static inspection was carried out to the Insured Vehicle where the following general information was recorded:-

Vehicle Registration No.	: SHB 6366A
Make / Model	: HYUNDAI I40 1.7L CRDI AT ABS AIRBAG 4DR
Chassis No	: KMHLB41UMDU042111
Year of Registration	: October 2013
Mileage	: N.A. (battery melted)

4. The Insured Vehicle was noted to have sustained fire damage that was confined to its front portion. The entire engine compartment of the Insured Vehicle was observed to be severely burnt while the interior compartment was observed to be significantly affected by the fire.
5. The fire had resulted in the body parts at the front portion of the Insured Vehicle to be burnt. This had included its front bumper, front bonnet, front support panel, front grille, front headlamps, front windscreen, front rims and front tyres amongst others. See photos 1 – 5 below.