

ASS. REC. BY:

REF:

CS / ICS18008870 / Attnz

Special Instruction:

SUIVALOY

Adrian

## ASSIGNMENT (Office)

mschman

From (Person):

Janice Goh

of

ICS

Date/Time:

16052018 927am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 3011Y

Insured:

SJM 8126G

at Workshop m/s

Modern Automotive

Tel:

6748 4422.

of

Blk 3023A Ubi Rd 1 #01-61

Policy No:

Claim No:

DMPC1800189H/CT

Sum Insured:

Excess:

Make of Veh:

D.O.A.

13052018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

H.O.D. Endorsement:

Date/Time:

16052018 10-16am

Person Contacted:

Grace

Vehicle IN/OUT

Date/Time

Action/Instruction ( ✓ ) Estimate

SKW 3011Y - X

SJM 8126G - NSA / ALH16007311 / TI

DOA: 20042015

Lump Sum \$76501. (Red: 7552.64.497.)

REF:

ASS. REC. BY: Adrian Ling

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SKW 30114 Yr Regn: 2015, MarchType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda CX5 c.c. 2488Colour: White A/C: Insured / Std / NI / NASp. Reading: 48716 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JM6KE1031F0279728Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/55R19R: 225/55R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 16/05/18Survey held at ModernDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time \_\_\_\_\_ Action / Instruction

TP ECICS.

RECEIVED 13 JUN 2018

RECEIVED 13 JUN 2018

Date/Time, File Pass to?

13/6 Typist

Date/Time, File Return to?

2)

Report Format :

Lump Sum / k.B.I. (\$) 7650☐ : Preli. Report☒ : Final ReportDays Of Repair: 8Resurvey No. of Trip: —Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

\_\_\_\_ \$ + RS. \_\_\_\_ SI

Photos

Others

TOTAL

450

10

460

## Denise Tay (LKKAuto)

---

**From:** ASM - Jaclyn <jaclynlai@asmauto.com.sg>  
**Sent:** Wednesday, 13 June 2018 3:03 PM  
**To:** SUR  
**Subject:** MSIG - TP claim : XE2291C (DOA: 23.03.18)  
**Attachments:** IMG\_20180611\_105128.jpg; IMG\_20180611\_105140.jpg; IMG\_20180611\_105209.jpg; IMG\_20180611\_105223.jpg; IMG\_20180611\_105307.jpg; 20180323\_155342.jpg

Dear Taufikh,

Attached before paint & round mirror' s photos for your reference.

COR part-by-part \$5,723.98 & 3 days. please confirm.

Thank you

Best Regards,

*Jaclyn Lai*

*Customer Service & Motor Claims Executive*

**ASM Automotive Services Pte Ltd**

No. 2 Kwong Min Road, Singapore 628705

Hp: 9236 8218 | Tel: 6265 0980 | Fax: 6265 6068

Web: [www.asmauto.com.sg](http://www.asmauto.com.sg)



## Catherine Chong (LKK Auto)

---

**From:** ECICS Claims <claims@ecics.com.sg>  
**Sent:** Wednesday, 16 May, 2018 9:27 AM  
**To:** Chin; ASSIGNMENTS@LKKAUTO.COM  
**Cc:** ECICS Claims  
**Subject:** RE: TP SKW3011Y & SJM8126G

Without Prejudice

Dear Grace

Thank you for your email.

We will appoint LKK for the PRS.

Pursuant to the Motor Claim Framework (MCF), we will settle your client's property claim 100% base on BOLA s28.

Aside to LKK

Please assist to arrange TP PRS.

Thank you.

Regards,  
Janice Goh  
**Claims Division**  
DID: +65 6303 0182  
FAX: +65 6338 9267

**ECICS Limited**  
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

**WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to [motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg) directly.**

***\*\*Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.\*\****

---

**From:** Chin [mailto:chin@modernautomotive.com.sg]  
**Sent:** Monday, 14 May, 2018 4:46 PM  
**To:** ECICS Claims  
**Subject:** RE: TP SKW3011Y & SJM8126G

Dear Janice

We choose LKK to survey our client vehicle.

Please also advise liability.

Thank you

Regards,  
Grace Chin  
Modern Automotive Pte Ltd  
Blk 3023-A, Ubi Road 1 #01-61  
Singapore 408717

Tel: 6748 4422  
Fax: 6747 6720

---

**From:** ECICS Claims [<mailto:claims@ecics.com.sg>]  
**Sent:** Monday, 14 May, 2018 3:33 PM  
**To:** Chin <[chin@modernautomotive.com.sg](mailto:chin@modernautomotive.com.sg)>; ECICS Claims <[claims@ecics.com.sg](mailto:claims@ecics.com.sg)>  
**Subject:** RE: TP SKW3011Y & SJM8126G

**Without prejudice**

Dear Grace

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. LKK
2. JP knight
3. Formteam
4. Appraisal Associates
5. Autoprobe
6. Raleigh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Thank you.

Regards,  
Janice Goh  
**Claims Division**  
DID: +65 6303 0182  
FAX: +65 6338 9267

**ECICS Limited**  
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

**WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to [motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg) directly.**

***\*\*Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.\*\****

---

**From:** Chin [<mailto:chin@modernautomotive.com.sg>]  
**Sent:** Monday, 14 May, 2018 3:13 PM  
**To:** ECICS Claims  
**Subject:** Re: TP SKW3011Y & SJM8126G

Dear Sir / Mdm

We refer to the above matter.

Kindly appoint surveyor and advise liability as follow:

Your Insured: SJM8126G

Our Insured: SKW3011Y

DOA: 13.05.2018

We enclosed herewith our client report for your perusal .

Please reply asap.

Thank you

Regards,  
Grace Chin  
Modern Automotive Pte Ltd  
Blk 3023-A, Ubi Road 1 #01-61  
Singapore 408717

Tel: 6748 4422

Fax: 6747 6720

follow us on  facebook  follow us on twitter  visit our website [ecics.com.sg](http://ecics.com.sg) 

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

MODERN AUTOMOTIVE PTE LTD  
BLK 3023A UBI ROAD 1 #01-61  
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

ECICS Limited  
7 Temasek Boulevard  
#10-01 Suntec Tower One  
Singapore 038987  
Tel : 6337 4779  
Fax : 6338 9267

*Design*

Quotation

DATE : 15.05.2018  
VEH NO : SKW3011Y  
MODEL : Mazda CX5  
D O A : 13.05.2018  
YR REF : SJM8126G

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SKW3011Y (MAZDA CX5)

Item	Description	Qty	Amnt
<b>NO</b>	<b>LIST ITEMS</b>		
1	Front Number Plate Holder <i>behind</i>	1	63.00 ✓
2	Front Bumper <i>behind</i>	1	904.70 ✓
3	Front Bumper Clips <i>new</i>	1 set	30.00 ✓
4	Front Bumper Side Holder - LH & RH <i>new</i>	2	77.80 ✓
5	Front Bumper Sponge <i>behind</i>	1	105.40 ✓
6	Front Bumper Reinforcement <i>new</i>	1	524.40 ✓
7	Front Bumper Reinforcement Cover <i>cracked</i>	1	124.10 ✓
8	Front Grille <i>cracked</i>	1	634.00 ✓
9	Front Grille Logo <i>new</i>	1	72.50 ✓
10	Front Grille Clips <i>new</i>	1 set	15.00 ✓
11	Headlamp - LH & RH <i>RH cracked</i>	2	<del>4814.00</del> 2307 ✓
12	Rear Bumper <i>distorted</i>	1	1218.00 ✓
13	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
14	Rear Bumper Side Holder - LH & RH <i>new</i>	2	64.80 ✓
15	Rear Bumper Tow Cover <i>missing</i>	1	15.90 ✓
16	Rear Bumper Reflector - LH & RH <i>new</i>	2	187.80 ✓
17	Rear Bumper Reinforcement <i>best</i>	1	543.00 ✓
18	Rear Bumper Reinforcement Bracket - LH & RH <i>best</i>	2	48.20 ✓
19	Reverse Sensor <i>best</i>	4	720.00 ✓
20	Rear End Panel <i>dented</i>	1	519.00 ✓
21	Rear End Panel Top Garnish <i>new</i>	1	170.50 ✓
22	Rear End Panel Sensor <i>cracked</i>	1	82.40 ✓
23	Tailgate <i>repair</i>	1	1321.40 ✓
24	Tailgate Lock <i>new</i>	1	238.00 ✓
25	Tailgate Weatherstripe <i>new</i>	1	174.50 ✓
26	Mazda Logo	1	48.00 ✓
27	CX5 Wording <i>new</i>	1	45.30 ✓
28	Skyactiv Emblem	1	71.60 ✓
29	Tailgate Glass Moulding <i>new</i>	1	185.00 ✓

RE: ESTIMATE FOR ACCIDENT REPAIR SKW3011Y (MAZDA CX5)

30	Rear Exhaust Pipe	Best	1	1260.00	✓
31	Rear Exhaust Mounting	He New	1	45.00	x
		899970			
		719976			
		Less 20%		14,153.30	
				(2,830.66)	
				\$ 11,322.64	

S/NETT ITEMS

1	Front Number Plate	Best	1	30.00	✓
2	Rear End Panel Sealant	He New	1	60.00	✓
3	Tailgate Glass Sealant	He New	1	60.00	x
		70			
	Total Parts			\$ 11,472.64	

LABOUR CHARGE

1	To knocking & pull out front & rear portion & renew above parts	\$ 1,500.00	1000
2	To putty & spray up paint works	\$ 1,400.00	1000
3	To check wiring	\$ 100.00	60
4	To remove reverse sensor	\$ 100.00	60
5	To remove upholstery	\$ 150.00	80
6	To remove tailgate glass	\$ 180.00	x
7	To transfer tailgate fittings	\$ 150.00	x
8	To remove exhaust pipe	\$ 150.00	80
		\$ 3,730.00	

Grand Total

\$ 15,202.64

GST Will be reflected in the final bills

NOTE: -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN

THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY  
WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE  
FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

- To resurvey both sides
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 9569.76

r/s: 7650

08 Days



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18008870/ATBN2

Date: 19/06/2018

## REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SKW3011Y	Insured Vehicle No :	SJM8126G
Date of Loss:	13/05/2018	Nature of Claim:	TP
		Claim No:	DMPC1800189H/CT

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SKW3011Y	Engine No:	PY20482004
Make & Model:	MAZDA CX-5, 2.5 (A)	Chassis No:	JM6KE1031F0279728
Reg. Date:	24/03/2015 (Man. Year: 2014)	Odometer:	48716 km
Colour:	White		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	225/55R19	Rear Tyre Size:	225/55R19
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	11,472.64	7,289.76	4,182.88	36.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,730.00	2,280.00	1,450.00	38.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,202.64</b>	<b>9,569.76</b>	<b>5,632.88</b>	<b>37.05</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,650.00</b>		
(S\$)	15,202.64	7,650.00	7,552.64	49.68
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,064.18</b>	<b>535.50</b>	<b>528.68</b>	<b>49.68</b>
<b>Nett Amount (S\$)</b>	<b>16,266.82</b>	<b>8,185.50</b>	<b>8,081.32</b>	<b>49.68</b>

## INSPECTION

Date of Assignment: 16/05/2018

Date Inspected: 16/05/2018 Inspected At:

Modern Automotive Pte Ltd (HQ)  
Blk 3023A Ubi Road 1, #01-61 & #01-58  
Singapore 408717

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 19 Jun 2018)	
<b>Parts:</b> M1-SUV	MAZDA CX-5 2.5 (A) (Catalogue:Merimen Singapore 1.0)	
<b>Labour:</b> Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b>	(Unsubmitted, no print-code for SKW3011Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE HOLDER	Deformed	63.00 FL	*63.00 FL
2	1		*FRONT BUMPER	Deformed	904.70 FL	*904.70 FL
3	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
4	2		*FRONT BUMPER SIDE HOLDER-LH & RH	Necessary	77.80 FL	*77.80 FL
5	1		*FRONT BUMPER SPONGE	Deformed	105.40 FL	*105.40 FL
6	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	524.40 FL	*- FL
7	1		*FRONT BUMPER REINFORCEMENT COVER	Cracked	124.10 FL	*124.10 FL
8	1		*FRONT GRILLE	Cracked	634.00 FL	*634.00 FL
9	1		*FRONT GRILLE LOGO	Necessary	72.50 FL	*72.50 FL
10	1		*SET FRONT GRILLE CLIPS	Necessary	15.00 FL	*15.00 FL
11	1		*HEADLAMP-LH & RH	O/s Cracked	4,614.00 FL	*2,307.00 FL
12	1		*REAR BUMPER	Distorted	1,218.00 FL	*1,218.00 FL
13	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
14	2		*REAR BUMPER SIDE HOLDER-LH & RH	Necessary	64.80 FL	*64.80 FL
15	1		*REAR BUMPER TOW COVER	Missing	15.90 FL	*15.90 FL
16	2		*REAR BUMPER REFLECTOR-LH & RH	Not Necessary	187.80 FL	*- FL
17	1		*REAR BUMPER REINFORCEMENT	Bent	543.00 FL	*543.00 FL
18	2		*REAR BUMPER REINFORCEMENT BRACKET-LH & RH	Bent	48.20 FL	*48.20 FL
19	4		*REVERSE SENSOR	Bent	720.00 FL	*720.00 FL
20	1		*REAR END PANEL	Dented	519.00 FL	*519.00 FL
21	1		*REAR END PANEL TOP GARNISH	Not Necessary	170.50 FL	*- FL
22	1		*REAR END PANEL SENSOR	Cracked	82.40 FL	*82.40 FL
23	1		*TAILGATE	Repair	1,321.40 FL	*- FL
24	1		*TAILGATE LOCK	Not Necessary	238.00 FL	*- FL
25	1		*TAILGATE WEATHERSTRIPE	Not Necessary	174.50 FL	*- FL
26	1		*MAZDA LOGO	Necessary	48.00 FL	*48.00 FL
27	1		*CX5 WORDING	Necessary	45.30 FL	*45.30 FL
28	1		*SKYACTIV EMBLEM	Necessary	71.60 FL	*71.60 FL
29	1		*TAILGATE GLASS MOULDING	Not Necessary	185.00 FL	*- FL
30	1		*REAR EXHAUST PIPE	Bent	1,260.00 FL	*1,260.00 FL
31	1		*REAR EXHAUST MOUNTING	Not Necessary	45.00 FL	*- FL
32	1		*FRONT NUMBER PLATE	Bent	30.00 FS	*30.00 FS
33	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
34	1		*TAILGATE GLASS SEALANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (S\$)	14,303.30	9,089.70
				- List Item Discount on L Items 20.00/20.00% (S\$)	2,830.66	1,799.94
				Total Parts (S\$)	11,472.64	7,289.76

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO KNOCKING & PULL OUT FRONT & REAR PORTION & RENEW ABOVE PARTS	New	1,500.00	1,000.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	1,400.00	1,000.00
3	TO CHECK WIRING	New	100.00	60.00
4	TO REMOVE REVERSE SENSOR	New	100.00	60.00
5	TO REMOVE UPHOLSTERY	New	150.00	80.00
6	TO REMOVE TAILGATE GLASS	New	180.00	-
7	TO TRANSFER TAILGATE FITTINGS	New	150.00	-
8	TO REMOVE EXHAUST PIPE	New	150.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,730.00</b>	<b>2,280.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >