

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18008911/KEA3Q2

Date: 25/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : GBE3252U **Insured Vehicle No :** SLW4121U

Date of Loss: 08/05/2018 **Nature of Claim:** TP **Claim No:** 4633766648SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE3252U		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEA01BR2SDEB (CBU) (M)	Engine No:	4P10B87427
Reg. Date:	26/10/2015 (Man. Year: 2015)	Chassis No:	FEA01BA10193
Colour:	White	Odometer:	190109 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/70 R15	Rear Tyre Size:	195/70 R15 (D)
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 2/2 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 2/2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,657.99	16,259.96	2,398.03	12.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,340.00	3,260.00	1,080.00	24.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	22,997.99	19,519.96	3,478.03	15.12
Approved Total (Overridden) (\$\$)		15,600.00		
(\$\$)	22,997.99	15,600.00	7,397.99	32.17
+ GST 7.00/7.00% (\$\$)	1,609.86	1,092.00	517.86	32.17
Nett Amount (\$\$)	24,607.85	16,692.00	7,915.85	32.17
+ Car Rental (14.0 x S\$120.00/day) (\$\$)		1,680.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		18,374.00		
Global Sum Settlement (\$\$)		17,500.00		

INSPECTION

Date of Assignment: 14/05/2018

Date Inspected: 14/05/2018 Inspected At:

Alan's United Auto Pte Ltd (HQ)
Blk 7 Sin Ming Industrial Estate, #01-76
Singapore 575642

Estimated Period of Repair: 10.0 days

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S TAILLAMP	Scratched	228.74 FL	*228.74 FL
2	1		*REAR END PANEL	Repair	2,293.55 FL	*- FL
3	1		*O/S SIDE GATE REAR LOCK HOOK	Bent	178.03 FL	*178.03 FL
4	1		*O/S CORNER STOPPER	Cut	28.59 FL	*28.59 FL
5	1		*REAR O/S FENDER	Cracked	207.92 FL	*207.92 FL
6	2		*REAR ABSORBER	Punctured	360.00 FL	*360.00 FL
7	2		*REAR SUSPENSION SPRING	O/S Bent / N/S Distorted	3,048.72 FL	*3,048.72 FL
8	2		*REAR O/S SPRING HOOK	Bent	332.26 FL	*332.26 FL
9	1		*REAR AXLE HOUSING	Bent	4,273.79 FL	*4,273.79 FL
10	2		*REAR AXLE SHAFT	Bent	1,363.80 FL	*1,363.80 FL
11	1		*CENTRE PROPELLA SHAFT	Bent	3,114.66 FL	*3,114.66 FL
12	1		*CENTRE PROPELLA SHAFT COUPLING	Necessary	337.37 FL	*337.37 FL
13	1		*FRONT WINDSCREEN GLASS	Cracked	680.97 FL	*680.97 FL
14	1		*REAR W/S GLASS RUBBER	Dented	208.00 FL	*208.00 FL
15	1		*FRONT WIPER GARNISH	Cracked	670.67 FL	*670.67 FL
16	1		*N/S WIPER LINKAGE	Serviceable	349.18 FL	*- FL
17	1		*FRONT BODY PANEL	Bent	1,130.60 FL	*1,130.60 FL
18	1		*BODY PANEL FUSO EMBLEM	Necessary	137.24 FL	*137.24 FL
19	1		*RADIATOR GRILLE	Cracked	979.92 FL	*979.92 FL
20	1		*RADIATOR GRILLE LOGO	Necessary	77.12 FL	*77.12 FL
21	1		*RADIATOR GRILLE CANTER EMBLEM	Necessary	78.81 FL	*78.81 FL
22	1		*AIR CON BLOWER ASSY	Cracked	2,593.18 FL	*2,593.18 FL
23	1		*N/S HEAD LAMP	Serviceable	554.65 FL	*- FL
24	1		*N/S SIGNAL LAMP	Mtg Cracked	294.64 FL	*294.64 FL
25	1		*ERP IU BRACKET	Necessary	26.00 FS	*26.00 FS
26	4		*AXLE OIL	Necessary	48.00 FS	*48.00 FS
27	2		*BRAKE OIL	Necessary	20.00 FS	*20.00 FS
28	1		*FRONT WIPER PANEL	Bent	1,229.58 FL	*1,229.58 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	24,845.99	21,648.61
- List Item Discount on L Items 25.00/25.00% (\$\$)	6,188.00	5,388.65
Total Parts (\$\$)	18,657.99	16,259.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REWIRE DAMAGED PARTS AND REFOCUS HEADLAMP BEAM	New	20.00	20.00
2	TO REMOVE & RENEW FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	150.00	80.00
3	TO REMOVE AIR CON CONDENSER ,PIPES AND DRIER ,VACUUM AND TO RECHARGE GAS	New	120.00	100.00
4	TO APPLY UNDERSEALING	New	60.00	30.00
5	TO REMOVE FRONT INSTRUMENT PANEL ASSY AND REWIRING	New	180.00	180.00
6	TO DISMANTLE AND LOWER REAR UNDERCARRIAGE	New	300.00	240.00
7	TO REMOVE AND REFIX EXHAUST SILENCER BOX	New	60.00	60.00
8	TO PUTTY AND SPRAY REPLACED PARTS	New	1,400.00	1,100.00
9	TO REMOVE,CUT-OUT DAMAGED PARTS,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ABOVE PARTS	New	1,800.00	1,200.00
10	LABOUR TO CUT OUT FRONT WIPER PANEL	New	150.00	150.00
11	TO PUTTY AND SPRAY FRONT WIPER PANEL	New	100.00	100.00
Gross Labour Cost (\$\$)			4,340.00	3,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >