

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: AEMD/105/009/2017/119

Date: 21st May 2018

Our Ref: CS1/SPF18008938/K1vbs2

M/s Automotive Engineering & MGT Division

Accident Claim Section
(Singapore Police Force)

1 Mount Pleasant Road
Blk 8 Old Police Academy
Singapore 298333
(The Motor Claims Department)

Attn: Abdul Rahman

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SHC 2728K INSURED VEHICLE: QX 219J ACCIDENT DATE: 16/08/2017

We thank you for your instruction on 14/05/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SHC 2728K from M/s Vicom Ltd.
- b) Colour damaged vehicle photographs of SHC 2728K.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

| 1 | ilar i | In | forma | tion | Record | led | - |
|---|--------|----|---------|------|-----------|-----|---|
| | | | LULLING | uvii | ILLUCTION | | |

Registration Number

: SHC 2728K

Make & Model

: Hyundai Sonata

Year of Registration

: 2011

Chassis Number

: KMHET41VMAA803571

Engine Capacity

: 1991 cc

- We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
- We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.