

Catherine Chong (LKK Auto)

From: Abdul Rahman MOHAMAD SALIM (SPF)
<Abdul_Rahman_Mohamad_Salim@spf.gov.sg>
Sent: Monday, 14 May, 2018 3:18 PM
To: Catherine Chong (LKK Auto)
Cc: 'Olivia Lau'; Rosalyn TAN (SPF); Frankie THAY (SPF)
Subject: SHA9799U - Request Paper Survey
Attachments: SHA9799U LOD of CDGE.pdf

Your Ref: SHA9799U
Our Ref : AEMD/105/009/2017/171

Dear Cath,

Your preceding mail and our assignment on 13 Dec 2017 have reference.

Attached as requested.

Regards

Abdul Rahman (Mr)
Accident Claims Officer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4840 | FAX: (65) 6478 4848



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Saturday, 12 May 2018 3:30 PM
To: Abdul Rahman MOHAMAD SALIM (SPF) <Abdul_Rahman_Mohamad_Salim@spf.gov.sg>
Subject: Request Paper Survey

Dear Mr Abdul Rahman,

Kindly refer to the attachment.

Please assist provide us the LOD for all vehicle for us conduct Paper Survey.

Best Regards,

Catherine Chong | Admin
LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



SINGAPORE POLICE FORCE

SPF Accidents Claims Section
Automotive Engg & Mgmt Div
Police Logistics Department
No. 1 Mount Pleasant Road
Block 8 Old Police Academy
#02-12 Singapore 298333

Your Ref: SHA9799U

Our Ref: AEMD/105/009/2017/171

Date: 13 December 2017

Tel: 64784840

Fax: 64784848

LKK Auto Consultants Pte Ltd
Paya Ubi Industrial Park
51 Ubi Avenue 1 #01/02-25
Singapore 408933

Via Fax only: 62564315

Dear Sir,

ACCIDENT INVOLVING GOVT VEHICLE GBB7948K AND OTHER VEHICLE SHA9799U ON 22 NOVEMBER 2017

We refer to the above matter.

- 2 Please arrange for a **Paper Survey Inspection** of vehicle no. **SHA9799U** which has been repaired at **Messrs ComfortDelgro Engr Pte Ltd** of **205 Braddell Road, Singapore 579701**.
- 3 Estimates were provided by the workshop.
- 4 Thank you.

Yours faithfully,

Abdul Rahman
Accident Claims Officer
for Assistant Director

A FORCE FOR THE NATION

COMFORTDELGRO ENGINEERING PTE LTD
 #205 Braddell Road
 Blk C Ext 1 3rd Level
 Singapore 579701



VICOM LTD
 385 Sin Ming Drive Singapore 575718

Mainline (65) 6458 4555
 Facsimile (65) 6458 1040

www.vicom.com.sg
 Company Registration No: 198100320K

SURVEY REPORT

GENERAL INFORMATION			
VAC Ref. No.	: 518780	Claim No.	: 305091778
Accident Date	: 22/11/2017	Claim Type	: THIRD PARTY
Assignment Date	: 24/11/2017	Policy No.	:
Survey Date	: 24/11/2017	Finalised Dt.:	
Survey Report Date	: 01/12/2017		
VEHICLE PARTICULARS			
Vehicle No.	: SHA9799U	Chassis No.	: WDD2120022A758753
Registration Date	: 25/07/2013	Engine No.	: OBSCURED
Make	: MERCEDES BENZ	Engine Cap.	: 2143 CC
Model	: E220 CDI (E5)	Transmission	: AUTO
		Colour	: WHITE
CONDITION OF VEHICLE DURING SURVEY (VISUAL and STATIC TEST ONLY)			
Foot Brake	: SERVICEABLE	Steering	: SERVICEABLE
Hand Brake	: SERVICEABLE	Modification	: NONE
Mileage	: 622782		
<u>TYRES</u>	<u>SIZE</u>	<u>MAKE</u>	<u>BALANCE (mm)</u>
FRONT RH	205/60R16	BRIDGESTONE	6
FRONT LH	205/60R16	BRIDGESTONE	6
REAR RH	205/60R16	BRIDGESTONE	6
REAR LH	205/60R16	BRIDGESTONE	6
SURVEY CONDUCTED AT			
ComfortDelGro Engineering Pte Ltd, 59 Loyang Drive Singapore 508969. Assignment given by: MVA Limts (C.D.G.E.)			
REMARKS			
[1]Workshop Estimate : S\$ 3,936.80 [2]Our Adjustment : S\$ 1,400.00 [3]Repair Period : 2 days [4]We have not authorised repairs. This survey was carried out on without prejudice basis.			

VICOM LTD

SURVEY REPORT

Annex A: Adjustment on Spare Parts

#	Qty	Vehicle Parts Description	Condition follow	Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	1	Rear Bumper	Deformed	1510.00	1510.00
2	1	Rear Bumper Reinforcement	Reuse	1151.00	0.00
3	2	Rear Bumper Bracket Lower Rh/Lh	Reuse	270.00	0.00
4	2	Rear Bumper Bracket Top Rh/Lh	Reuse	250.00	0.00
5	2	Rear Bumper Retainer Mounting Rh/Lh	Reuse	230.00	0.00
			Subtotal	:	3411.00
			Less 20 %		682.20
			TOTAL	:	2728.80
SPECIAL NETT ITEM					
1	1	Rear Bumper Reverse Sensor	Reuse	388.00	0.00
			TOTAL	:	388.00
			TOTAL FOR SPARE PARTS	:	3116.80
					1208.00

VICOM LTD

SURVEY REPORT

Annex B: Adjustment on Labour and Spray Painting

#	Job Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	Panel beating	400.00	280.00 ²⁰⁰
2	Spray painting	250.00	200.00
3	Wiring charges	50.00	20.00 ^X
4	Remove/ refix reverse sensor	120.00	60.00 ²⁰
TOTAL FOR LABOUR AND SPRAY PAINTING		: 820.00	560.00

Summary

Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
TOTAL FOR SPARE PARTS	: 3116.80	1208.00
TOTAL FOR LABOUR AND SPRAY PAINTING	: 820.00	560.00
TOTAL REPAIR COST	: 3936.80	1768.00

SURVEY REPORT

Annex C: Conclusion

ASSESSOR'S REPORT

At the place of inspection, we saw this vehicle sustained rear damage.

The damages seen during our survey were at rear bumper and surrounding areas. A fuller detailed description of the damages is in Annex A of this survey report.

ASSESSOR'S RECOMMENDATION

Comfortdelgro Engineering Pte Ltd (Loyang) estimated a repair cost of S\$3,936.80. We adjusted it to S\$1,768.00 on a part-by-part basis.

As this vehicle was more than 4 years old during the accident, we assess repairs on a lumpsum basis is appropriate. By applying the market discount of 20% from the part-by-part repairs, the re-adjusted repair cost on lumpsum basis is S\$1,414.40, round upto S\$1,410.00 .

Accordingly, we recommend repairs to this vehicle be carried out on a lumpsum basis at S\$1,400.00.

The repairs would require a period of 2 working days.



Kamarudin Abdul Kadir
for VICOM Ltd



Your Ref: AEMD/105/009/2017/171

Date: 21st May 2018

Our Ref: CS1/SPF18008939/K1vbs2

M/s Automotive Engineering & MGT Division

Accident Claim Section

(Singapore Police Force)

1 Mount Pleasant Road

Blk 8 Old Police Academy

Singapore 298333

(The Motor Claims Department)

Attn: Abdul Rahman

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SHA 9799U INSURED VEHICLE: GBB 7948K ACCIDENT DATE: 22/11/2017**

We thank you for your instruction on 14/05/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SHA 9799U from M/s Vicom Ltd.
- b) Colour damaged vehicle photographs of SHA 9799U.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SHA 9799U
Make & Model	: Mercedes Benz E220 CDI (E5)
Year of Registration	: 2013
Chassis Number	: WDD2120022A758753
Engine Capacity	: 2143 cc
2. We recommend that the repairs of the entire damage require about 2 (Two) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 9799U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	1,510.00	1,510.00
1	REAR BUMPER REINFORCEMENT	REUSE	1,151.00	-
2	REAR BUMPER BRACKET LOWER RH/LH	REUSE	270.00	-
2	REAR BUMPER BRACKET TOP RH/LH	REUSE	250.00	-
2	REAR BUMPER RETAINER MOUNTING RH/LH	REUSE	230.00	-
	LESS 20% DISCOUNT		-682.20	-302.00
			2,728.80	1,208.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER REVERSE SENSOR (SN)	REUSE	388.00	-
			388.00	-
	<u>LABOUR</u>			
	PANEL BEATING.		400.00	200.00
	SPRAY PAINTING.		250.00	200.00
	WIRING CHARGES.	NOT NECESSARY	50.00	-
	REMOVE / REFIX REVERSE SENSOR.		120.00	20.00
			820.00	420.00
	GRAND TOTAL		3,936.80	1,628.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,300.00

Report Ref No. CS1/SPF18008939/K1vbs2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.