C. S. ONG AUTO PTE. LTD.

Business.Reg.No.: 201408916W GST Reg.No.: 201408916W

(10, Ang Mo Kio Ind. Park 2A, #04-01 AMK Autopoint, Singapore (568047).

Tel: 6484 1933 Fax: 6484 1922 E-Mail: csongauto@yahoo.com.sg

o: Motor Claims Department, FWD SINGAPORE PTE LTD Date: 14-05-2018

Accident Involving Vehicles SJV8049Z & SJW4521Y [Your Insured] on 09/05/2018 @ 2100hrs along TRAFFIC LIGHT JUNCTION OF AMK AVE 1 & LI HWAN DRIVE

Estimated Repair Costs For SJV8049Z [M/Benz E200]			
1Pc Rear Bumper	Det -	\$	1,314.00
2Pcs Rear Bumper LH & RH Metal Brackets	Holders @ \$23.00 Each	\$	46.00
1Pc Rear Bumper Centre Top Bracket	anc	\$ >	
2Pcs Rear Bumper LH & RH Side Retainers	@ \$107.00 Each	\$ -	214.00
1Pc Rear Bumper Tow-Hook Cover	any	\$	74.00
1Pc Rear Bumper RH Chrome Moulding @	\$130.00 Each ~~	\$	1,300.00
1Pc Rear Bumper LH Chrome Moulding @	\$130.00 Each wa	\$	130.00
1Pc Rear Bumper Centre Chrome Moulding	uz ==	\$	182.00
1Pc Rear Bumper Reinforcement	GNC.X	\$	558.00
Tre real bamps removed	Parts Sum:	\$	3,833.00
	Parts Less 10%:	\$	383.30
	Parts Total:	\$	3,449.70
Labour & MISC Charges	1997.0		
Labour & Misc Charges	6	5	SU.
* To supply 1Set Rear Reverse Sensor.	2300/2	\$	500.00
Cen	hant vaniage navy parts	\$	1000 00
* To remove all rear damaged panels, panel beat, replace new parts refit and to realign all of the above, replaced and transferred parts.		Ψ	2000.00
refit and to realign all of the above, replace	ed and transferred parts.		- 671
		φ,	1,000.00
* To putty and re-spray new paintwork on a	ill rear affected areas.	\$	1,000.00
u di contra an all affected areas		¢ /	100.00
* To conduct a check on all wiring systems	on all affected areas.	7 6	100.00
	ffected areas	\$	×80.00
* To apply anti-rust agent & coating on all a	Habarra & MICC Chargos Total:	\$	2,680.00
	Labour & MISC Charges Total:		3,449.70
	Parts Total:	\$ \$	2,680.00
	Labour & MISC Charges Total:	4	6,129.70
	Grand Total:	Þ	0,123.70