"Flankline"		REF: C31 /SPF1	8008941 /Klv	652	Special Instruction;	
	Object Oak	ASSIG	NMENT (OR	ice)	furt by fart : \$ 3	1024.60
rom (Person);	HOULL KUMMUN	of SPF	Date/Time: 14	J52018	Third Parties:	
Estimated Cost:		Bill to:			Claimant:	
OD/FP Palmen	ection / Evaluation	_ \			Surveyor: Vil	
Fo Inspect Vehic	1000	SHC 7948J	0 4 0-2000 (20-20 4 0)	(2× 1021 a	Workshop: (000	fort Delgro
	(omt	· · · · · · · · · · · · · · · · · · ·		(3x 10263	<u> </u>)
of		cyang Dike	Tel:			
Policy No:		U	Claim No.	AEMD/105/00	A /2018/NOS	
Sum Insured:			Excess:	18110/100/00	17 00107 000	
Make of Veh:			D.O.A.	11.01.2018		
Client's Record)					Do Not Fine	170
Vingo or or or or or or or or				H	O.D. Endorsement/Date	
Date/Time:		Person Contacted:	Vel	aicle IN/OUT		
Date/Time:	Confirm	ned withFi	inal Fig	,days (Red	\$/_%; O	riginal_2_da
Date/Time: _].	TISUS Submit	Final Fig \$ 886.	Jo, Ldays (Red \$ 138-40/	₹_%; Original	_days)
	Action/Instruction	X				
	AC THEJ -	(S/FOLI 6008858)	Althaul		DUA : 05052011	0
	XX (A)PZ - (T/TPD18007343	/DU .		DUA: 11-01-2015)
3				41	21/1	2/5018
1						
Para(1) : Pa	rts found not	replaced (To b	ighlight P	or IID ID	E(a)	
Para(1): Pa	erts found not	replaced (To b	nighlight R	or UB, LR	, Etc)	
					- 1	
					- 1	
		onsistency of dan	nages (Parts		- 1	
		onsistency of dan	nages (Parts		- 1	
			nages (Parts		- 1	
		onsistency of dan	nages (Parts		- 1	
Para(2) : Co	omments on co	onsistency of dan	nages (Parts		- 1	
Para(2) : Co	omments on co	onsistency of dan	nages (Parts)		- 1	Date:
Para(2) : Co	ett Value Market Value	RECEIVED 2	nages (Parts)	Not Consister	ree Charged: Basic & Add	Date:
Para(2) : Co	omments on co	RECEIVED 2	nages (Parts)	Not Consister	Fee Charged: Basic & Add Transport	Date:
Para(2) : Co	ett Value Market Value Salvage Value	RECEIVED 2	nages (Parts)	Not Consister	Fee Charged: Basic & Add Transport Photos Others	Date:
Para(2) : Co	ett Value Market Value Salvage Value Nett Value	RECEIVED 2	Inspected/Evaluated b	Not Consister	Fee Charged: Basic & Add Transport Photos Others Total	Date:
Para(2) : Co	ett Value Market Value Salvage Value Nett Value	RECEIVED 2	Inspected/Evaluated b	Not Consister	Fee Charged: Basic & Add Transport Photos Others Total File Return to	Date:
Para(2) : Co	Market Value Salvage Value Nett Value 15- typistrii	RECEIVED 2	Inspected/Evaluated b	Not Consister	Fee Charged: Basic & Add Transport Photos Others Total	Date:

Catherine Chong (LKK Auto)

From: Abdul Rahman MOHAMAD SALIM (SPF)

<Abdul_Rahman_Mohamad_Salim@spf.gov.sg>

Sent: Monday, 14 May, 2018 3:23 PM

To: Catherine Chong (LKK Auto)

Cc: 'Olivia Lau'; Rosalyn TAN (SPF); Frankie THAY (SPF)

Subject: SHC7948J - Request Paper Survey
Attachments: SHC7948J LOD of CDGE.pdf

Your Ref: SHC7948J

Our Ref : AEMD/105/009/2018/005

Dear Cath,

Your preceding mail and our assignment on 29 Jan 2018 have reference.

Attached as requested.

Regards

Abdul Rahman (Mr)
Accident Claims Officer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4840 | FAX: (65) 6478 4848



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]

Sent: Saturday, 12 May 2018 3:30 PM

To: Abdul Rahman MOHAMAD SALIM (SPF) < Abdul_Rahman_Mohamad_Salim@spf.gov.sg>

Subject: Request Paper Survey

Dear Mr Abdul Rahman,

Kindly refer to the attachment.

Please assist provide us the LOD for all vehicle for us conduct Paper Survey.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51; Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Your Ref:

SHC7948J

Our Ref :

AEMD/105/009/2018/005

Date :

29 January 2018

SPF Accidents Claims Section Automotive Engg & Mgmt Div Police Logistics Department No. 1 Mount Pleasant Road Block 8 Old Police Academy #02-12 Singapore 298333

Tel: 64784840

Fax: 64784848

M/s LKK Auto Consultants Pte Ltd Paya Ubi Industrial Park 51 Ubi Avenue 1 #01/02-25 Singapore 408933

Via Fax only: 62564315

Dear Sir/Madam,

ACCIDENT ON 11 JANUARY 2018 INVOLVING GOVT VEH QX1026S AND OTHER VEH SHC7948J

We refer to the above matter.

- 2 Kindly arrange for a Pre-Repair Inspection of vehicle no. SHC7948J at M/s Comfort Delgro Engrg Pte Ltd of 205 Braddell Road, Singapore 579701.
- For appointment kindly contact Tel: 63836280/62148374.
- 4 Estimates were provided by the workshop.
- 5 Thank you.

Yours faithfully,

Abdul Rahman

Accident Claims Officer for ASST DIRECTOR

A FORCE FOR THE NATION

COMFORTDELGRO ENGINEERING PTE LTD #205 Braddell Road Blk C Ext 1 3rd Level

Singapore 579701



VICOM LTD

385 Sin Ming Drive Singapore 575718

Mainline (65) 6458 4555 Facsimile (65) 6458 1040

SURVEY REPORT

. www.vicom.com.sg Company Regi

GENERAL INFORMATION

VAC Ref. No. : 520950 Claim No.

: 305106038 Accident Date : 11/01/2018 Claim Type : THIRD PARTY

Assignment Date : 12/01/2018 Policy No. Survey Date : 12/01/2018 Finalised Dt .:

Survey Report Date : 16/01/2018

VEHICLE PARTICULARS

Vehicle No. : SHC7948J Chassis No. : KMHLB41UMFU068351

Registration Date : 16/04/2015 Engine No. : OBSCURED Make : HYUNDAI Engine Cap. : 1685 CC Model : I-40 Transmission: AUTO

> Colour : YELLOW

CONDITION OF VEHICLE DURING SURVEY (VISUAL and STATIC TEST ONLY)

Foot Brake : SERVICEABLE Steering : SERVICEABLE

Hand Brake : SERVICEABLE Modification: NONE

Mileage : 467451

TYRES	SIZE	MAKE	BALANCE (mm)
FRONT RH	205/60R16	HANKOOK	6
FRONT LH	205/60R16	HANKOOK	6
REAR RH	205/60R16	HANKOOK	6
REAR LH	205/60R16	HANKOOK	6

SURVEY CONDUCTED AT

ComfortDelGro Engineering Pte Ltd, 59 Loyang Drive Singapore 508969.

Assignment given by: MVA Limts (C.D.G.E.)

REMARKS

[1] Workshop Estimate : S\$ 2,450.30

[2] Our Adjustment : S\$ 2,024.60

[3] Repair Period : 2 days

[4] We have not authorised repairs. This survey was carried out on without

prejudice basis.

VICOM LTD SURVEY REPORT

Annex A: Adjustment on Spare Parts

#	Qty	Vehicle Parts Description	Condition		Workshop Estimate (S\$)	VAC Adjustmen (S\$)
_			Follow		,	
1	1	Rear Bumper	Deformed		603.00	603.00
2	1	Rear Bumper Reinforcement	Snapped		504.35	504.35
3	2	Rear Bumper Reinforcement Bracket Rh/Lh	Dented		360.00	360.00
4	2	Rear Bumper Side Bracket (Rh/Lh) X No Parage	Necessary		98.00	98.00
5	10	Rear Bumper Clips	Necessary		22.00	22.00
6	1	Rear Bumper Sponge	Snapped		143.40	143.40
7	1	Rear Bumper Under Cover	Snapped		225.00	225.00
			Subtotal	:	1955.75	1955.75
		Less 20 %			391.15	391.15
			TOTAL	:	1564.60	1564.60
		SPECIAL NETT ITEM				
1	1	Rear Bumper Reverse Sensor	Reuse		135.70	0.00
			TOTAL	:	135.70	0.00
		TOTAL FOR SPARE PARTS	5	:	1700.30	1564.60

VICOM LTD SURVEY REPORT

Annex B: Adjustment on Labour and Spray Painting

#	Job Desc	cription		Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	Panel beat	ing		380.00	200.00
2	Spray pain	iltng		200.00	180.00
3	Wiring cha	rges		50.00	20.00 > 60.00 2
4	Remove/ r	efix reverse sensor		120.00	60.00 2
		TOTAL FOR LABOUR AND SPRAY PAINTING	:	750.00	460.00
s	ummary				
		Description		Workshop Estimate (S\$)	VAC Adjstment (S\$)
		TOTAL FOR SPARE PARTS	:	1700.30	1564.60
		TOTAL FOR SPARE PARTS TOTAL FOR LABOUR AND SPRAY PAINTING	:	1700.30 750.00	1564.60 460.00

VICOM LTD SURVEY REPORT

Annex C: Conclusion

ASSESSOR'S REPORT

At the place of inspection, we saw this vehicle sustained rear damage.

The damages seen during our survey were at rear bumper and surrounding areas. A fuller detailed description of the damages is in Annex A of this survey report.

ASSESSOR'S RECOMMENDATION

Comfortdelgro Engineering Pte Ltd (Loyang) estimated a repair cost of S\$2,450.30. We adjusted it to S\$2,024.60 on a part-by-part basis.

Accordingly, we recommend repairs to this vehicle be carried out on a part-by-part basis at S\$2,024.60.

The repairs would require a period of 2 working days.

Kamarudin Abdul Kadir

for VICOM Ltd



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: AEMD/105/009/2018/005

Date: 21st May 2018

Our Ref: CS1/SPF18008941/K1vbs2

M/s Automotive Engineering & MGT Division

Accident Claim Section (Singapore Police Force) 1 Mount Pleasant Road Blk 8 Old Police Academy Singapore 298333 (The Motor Claims Department)

Attn: Abdul Rahman

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SHC 7948J INSURED VEHICLE: QX 1026S ACCIDENT DATE: 11/01/2018

We thank you for your instruction on 14/05/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SHC 7948J from M/s Vicom Ltd.
- b) Colour damaged vehicle photographs of SHC 7948J.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number

: SHC 7948J

Make & Model

: Hyundai I-40

Year of Registration : 2015

Chassis Number

: KMHLB41UMFU068351

Engine Capacity

: 1685 cc

- 2. We recommend that the repairs of the entire damage require about 2 (Two) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7948J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	603.00	603.00
1	REAR BUMPER REINFORCEMENT	SNAPPED	504.35	504.35
2	REAR BUMPER REINFORCEMENT BRACKET RH/LH	DENTED	360.00	360.00
2	REAR BUMPER SIDE BRACKET (RH/LH)	NO DAMAGE	98.00	
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER SPONGE	SNAPPED	143.40	143.40
1	REAR BUMPER UNDER COVER	SNAPPED	225.00	225.00
	LESS 20% DISCOUNT	0.2003790000200	-391.15	-371.55
			1,564.60	1,486.20
	SPECIAL NETT ITEMS			
া	REAR BUMPER REVERSE SENSOR (SN)	REUSE	135.70	
			135.70	
	LABOUR			
	PANEL BEATING.		380.00	200.00
	SPRAY PAINTING.		200.00	180.00
	WIRING CHARGES.	NOT NECESSARY	50.00	
	REMOVE / REFIX REVERSE SENSOR.		120.00	20.00
			750.00	400.00
	GRAND TOTAL		2,450.30	1,886.20

RECOMMENDED COST OF REPAIRS

Report Ref No. CS1/SPF18008941/K1vbs2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.