



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### OPINION ON REPAIR COST FOR VEHICLE NO. SLS 7567T

Qty	Description of Parts	Condition	Recommended (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>		
2	GROMMET	NECESSARY	4.46
1	COMPANY SIGN	NECESSARY	57.72
1	LEFT FOGLAMP COVER	NOT NECESSARY	-
1	IMPACT ABSORBER	NOT NECESSARY	-
1	FRT BUMPER	DEFORMED	1,146.15
1	LHF INTERMEDIATE LAYER	NOT NECESSARY	-
1	LH FRT FENDER	TO REPAIR SEE LABOUR	-
1	LH HEADLAMP UNIT	NOT NECESSARY	-
1	SUPPORT ENG. LOWER COVER	NOT NECESSARY	-
1	DISTANCE SENSOR	DISTORTED	172.07
1	SPACER RING	NECESSARY	6.42
	LESS 10% DISCOUNT		-138.68
			1,248.14
	<b><u>LABOUR</u></b>		
	USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT, RESET MEMORY TO IDEN. STD.		380.00
	TO REMOVE, REPLACE HEADLAMP WITH FOCUS.		96.00
	DISASSEMBLE & REPLACE FRT BUMPER, LHF FENDER. INCLUSIVE OF THE REPAIR OF LH FRT FENDER.		1,008.00
	RESPRAY ON FRT BUMPER, LHF FENDER.		1,200.00
			2,684.00
<b>GRAND TOTAL</b>			<b>3,932.14</b>
<b>RECOMMENDED COST OF REPAIRS</b>			<b>3,932.14</b>

Report Ref No. CS1/SPF18008947/T1rbs2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.