

ASS. REC. BY:

REF CS3/MSG18008955/R/24d3^{SV} Special Instruction:Surveyor
Menmen

Rasul

ASSIGNMENT (Office)

From (Person):

Muhd Ashik

of

MSIG

Date/Time:

17/5/18 @ 9:34am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

XD 80072

Insured:

YP 6819 K

at Workshop n/s

Thong Huat Brothers

Tel:

6367 0772

of

4 Sungai Kadut Avenue

Policy No:

B28999728 MKC

Claim No:

558239

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

12/05/2018

CA / REV / REP. / REV 24 HRS

lwp

R.O.D. Endorsement:

Date/Time:

10:51am @ 17/5/18

Person Contacted:

Mrs. Teo

Vehicle (IN) OUT

Date/Time	Action/Instruction (X) Estimate
	XD 80072-X
	YP 6819K-X

Rpm

REF: MSIG

ASSIGNMENT

From: Date: 17/05/2018

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: XD 8007 Z
at Workshop m/s Thong Huat Brothers
of 4 Sungai Kadut Avenue

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh: 6367 0772 @ Mrs. Teo

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR. Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS / wp

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: XD 80072 Yr Regn: 10 / 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MITSUBISHI

C.C. 12892

Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 421790

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: FV51JJA10204

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 295/80R22.5

R: 1. DP

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or ANNAITE

Front

Rear

R/Bal. 8 mm R/Bal. 8/8 mm

L/Bal. 8 mm L/Bal. 8/8 mm

D.O.A. 12/05/18 D.O.I. 17/05/18

Survey held at Thong Huat

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/D Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Estimated repair range \$7,500 - \$9,500

21/6/18 Submit P.R.S Report

[Signature]
20/6/2018

Date/Time File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS. \$

) Photos

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG18008955/R1z4d3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 17-05-2018	
		Code : MSG	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	YP 6819K	Veh. Inspected	XD 8007Z
Policy No.	B28999728MKC	Coverage (\$)	0.00
Claim No.	558239	Excess (\$)	0.00
Assign From	MERIMEN (MUHD ASHIK)	Assign Date	17/05/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	12/05/2018	Inspection Date	17/05/2018
Survey held at	-		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 May 2018		17 May 2018 09:34 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	THL FOUNDATION EQUIPMENT PTE LTD, Co. Reg. No.: 200408545C		
Main Claimant:	THONG HUAT BROTHERS (PTE) LTD, Co. Reg. No.: 197201236H		
Vehicle Reg. No.:	XD8007Z	Date of Loss:	12/05/2018 11:00 - :59 [54 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 558239	Policy/Cover Note No.:	B28999728MKC (Comprehensive) Coverage: 01/08/2017 - 31/07/2018
Vehicle Reg. No. (Insured):	YP6819K	Policy No. (Claimant):	
		Excess:	
Repairer:	Thong Huat Brothers (pte) Ltd (HQ) 4 Sungei Kadut Avenue, 729641 Sungei Kadut - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 18/05/2018]		
Driver/Custodian (Insured):	TEO CHIN ANN (), NRIC: S1642172C, Tel: +6598300942		
Adj Asg. Remarks:	Liability 100% Disagree on SJE - assign LKK W/S contact : 6367 0772		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 May 2018		17 May 2018 09:34 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	THL FOUNDATION EQUIPMENT PTE LTD, Co. Reg. No.: 200408545C		
Main Claimant:	THONG HUAT BROTHERS (PTE) LTD, Co. Reg. No.: 197201236H		
Vehicle Reg. No.:	XD8007Z	Date of Loss:	12/05/2018 11:00 - :59 [54 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 558239	Policy/Cover Note No.:	B28999728MKC (Comprehensive) Coverage: 01/08/2017 - 31/07/2018
Vehicle Reg. No. (Insured):	YP6819K	Policy No. (Claimant):	
		Excess:	
Repairer:	Thong Huat Brothers (pte) Ltd (HQ) 4 Sungei Kadut Avenue, 729641 Sungei Kadut - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 18/05/2018]		
Driver/Custodian (Insured):	TEO CHIN ANN (), NRIC: S1642172C, Tel: +6598300942		
Adj Asg. Remarks:	Liability 100% Disagree on SJE - assign LKK W/S contact : 6367 0772		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***XD8007Z (558239)**
[YP6819K]
TP
THONG HUAT BROTHERS (PTE) LTD
May 12 2018 11:00AM
[THL FOUNDATION EQUIPMENT PTE LTD]
Thong Huat Brothers (pte) Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

Assessment Reports

1 per page
 ☒

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/05/18 17:43	Accident Statement From: SC - Reg. No: YP6819K, Claimant: THL FOUNDATION EQUIPMENT PTE LTD	 Load HTM	☒

Photos/Images

3 per page
 ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/05/18 17:36	General View	 Load JPG	☒
2	18/05/18 17:36	General View	 Load JPG	☒
3	18/05/18 17:36	General View	 Load JPG	☒
4	18/05/18 17:36	General View	 Load JPG	☒
5	18/05/18 17:36	General View	 Load JPG	☒
6	18/05/18 17:36	General View	 Load JPG	☒
7	18/05/18 17:36	General View	 Load JPG	☒
8	18/05/18 17:36	General View	 Load JPG	☒
9	18/05/18 17:36	General View	 Load JPG	☒
10	18/05/18 17:36	General View	 Load JPG	☒
11	18/05/18 17:36	General View	 Load JPG	☒
12	18/05/18 17:36	General View	 Load JPG	☒
13	18/05/18 17:36	General View	 Load JPG	☒
14	18/05/18 17:36	General View	 Load JPG	☒
15	18/05/18 17:36	General View	 Load JPG	☒
16	18/05/18 17:36	General View	 Load JPG	☒
17	18/05/18 17:36	General View	 Load JPG	☒
18	18/05/18 17:36	General View	 Load JPG	☒
19	18/05/18 17:36	General View	 Load JPG	☒
20	18/05/18 17:36	General View	 Load JPG	☒
21	18/05/18 17:36	General View	 Load JPG	☒
22	18/05/18 17:36	General View	 Load JPG	☒
23	18/05/18 17:36	General View	 Load JPG	☒
24	18/05/18 17:36	General View	 Load JPG	☒
25	18/05/18 17:36	General View	 Load JPG	☒
26	18/05/18 17:36	General View	 Load JPG	☒
27	18/05/18 17:36	General View	 Load JPG	☒
28	18/05/18 17:36	General View	 Load JPG	☒
29	18/05/18 17:36	General View	 Load JPG	☒
30	18/05/18 17:36	General View	 Load JPG	☒
31	18/05/18 17:36	General View	 Load JPG	☒

Assessment Reports				✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	18/05/18 17:36	General View	 Load JPG	✓
33	18/05/18 17:36	General View	 Load JPG	✓
34	18/05/18 17:36	General View	 Load JPG	✓
35	18/05/18 17:36	General View	 Load JPG	✓
36	18/05/18 17:36	General View	 Load JPG	✓
Documentation			1 per page	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/05/18 17:43	TP ACCIDENT REPORT - XD8007Z From: SC - Reg. No: YP6819K, Claimant: THL FOUNDATION EQUIPMENT PTE LTD	 Load PDF	
2	16/05/18 17:49	PRI from KSCGP	 Load PDF	
3	16/05/18 18:12	Survey Disagree on SJE - assign LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18008955/R1Z4D3S2
Date: 22/06/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: B28999728MKC
Claimant Vehicle No: XD8007Z Insured Vehicle No: YP6819K
Date of Loss: 12/05/2018 Nature of Claim: TP Claim No: 558239

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XD8007Z
Make & Model: MITSUBISHI FV51JJD4RDEA, 12.9 D (M) Engine No: 6M70457866
Reg. Date: 23/10/2013 (Man. Year: 2013) Chassis No: FV51JJA10204
Colour: Blue Odometer: 421790 km
Engine Capacity: 12882 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5(D)
Front Left Side: ANNAITE 8 mm Rear Left Side: ANNAITE 8/8 mm
Front Right Side: ANNAITE 8 mm Rear Right Side: ANNAITE 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 17/05/2018
Date Inspected: 17/05/2018 Inspected At: Thong Huat Brothers (pte) Ltd (HQ)
4 Sungei Kadut Avenue
Singapore 729641
Estimated Period of Repair: 0.0 days

Adjuster: MOHD RASUL

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,500.00 - \$9,500.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 22 Jun 2018)

Parts: N/A MITSUBISHI FV51JJD4RDEA 12.9 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for XD8007Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >