

Enc

cc 4-LPC 9041 / D ha3sz

LKK:
FMA

ABT

DOE

16/5/18

Date / Time :

15/5/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

SJY 1537L

Name of Insured :

Org Born Hays (Mary Wany)

Insured Tel No. :

HP:

Claim No. :

1718181VPOS1020610

Policy No. :

217VPOS014783

Make / Model :

2 nos

Excess Sec II :SS

D.O.A: 13/5/18

Place of Accident :

Jinny East St 74

Is driver the owner?

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

Org Chanon

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

96646428

(V/L: YES / NO)

Insured Liability :

%

Final ? Yes / No

SHA 1369E



INSRS:

WSP:

Tel:

Liability:

RMKS:

Chunni



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

13/6
nk

SHA 1369E - NO (AT 13000363/11/vn) on 13/6/18
SJY 1537L - cut LRP 1700K-88 / 11/23/18; 14/3/18

STAGE DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

Check whether OI has reported his vehicle?? No damage seen in his

GIA rpt??

RECEIVED 3 SEP 2018

FINALISED

Jinny 45 26,650 - 14 days 2

25/5/18

25/06/18

PRG 20180605. OUI WATKING TURN FROM MINOR ROAD.

TYPE REPORT WHILE PENDING TP LOD.

ORIGINAL TP LOD WITH LPC.

REPORT DONE.

RECEIVED 27 JUN 2018

BOOK WARRANTS TO LPC BY EMAIL

LPC APPROVED WARRANTS. SEND JTC OFFER TO TP.

TP ACCEPTED OFFER. ALL POOS IN ORDER.

10/08/18

16/08/18

06/09/18

PRELIMINARY ADVICE

Date/Time:

17/6

Sent By:

hnu

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

L16

SS

26,650.00 / 14 days Reduction: 30 %

Email

Call

FINAL SETTLEMENT

Date/Time:

24/08/18

Confirm with

WILLIAM

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. :

9

If NO or B 28, Ass. Lia :

Repair Cost:

(w/650)

SS

28,515.50

COID FROM MINOR ROAD

Loss of Rental (LOR):

SS

2,882.60 / 19 days X 125.40

Loss of Use (LOU):

SS

950.00 x 50 x 19 days

Loss of Income (LOI):

SS

— (\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

"ORIGINAL LOD WITH LPC"

GIA/LTA Search

SS

2.00

Medical:

SS

—

1) Claim status: Normal/Reject/Private Settle

Disbursement:

SS

—

(e.g. Tow/ Independent)

2) Report Format:

Legal Cost

SS

—

3) Survey fee:

\$450.00

Total:

SS

31,850.10

Global Sum SS:

31,850.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

31,850.00

Name 1:

CHUNNI MOTOR WORK PTE LTD

Payee 2: (Strike if N.A.)

SS

—

Name 2:

Payee 3: (Strike if N.A.)

SS

—

Name 3:

31/8/18

Surveyor:

ASSIGNMENT

COE June 2025

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or No

Lum Sum: 109,847 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SHA 1369E

Yr Regn:

2017 June

Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

C.C.

1798

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

125951

T/Radio:

Insured / Std / NI / NA

Eng/No:

22R3048322

C/No:

5TDK33FU203558767

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / ☒ R/Rim / STD A/Rim or

Tyre Size:

F:

195/65 R15

R:

— 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

13/05/2018

D.O.I.

16/05/2018

Survey held at

Chunni AMIC

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Front 7 N/S Body 7 N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

25/06/18 Longpac 854 1537L
Jnapu 1/2 26,600/- with 14 days & rev
(CRSD: \$ 11,804.92 / 30%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC4/LPC18009041/Dha3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 18-05-2018	
LPC		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJY 1537L	Veh. Inspected	SHA 1369E
Policy No.	Z17VP05014783	Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020610	Excess (\$)	0.00
Assign From		Assign Date	18/05/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Storing	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Wear	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	13/05/2018	Survey Date	16/05/2018
Survey held at	CHUNNI MOTOR WORK PTE L BLK 10 ANG MO KIO IND. PARK, A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS WE HAVE NOT AUTHORIZED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 17/18/18/VP05/020610
Our ref: CC4/LPC18009041/Dha3

Date: 17.05.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHA 1369E


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 16/05/2018 at the premises of M/s Chunni Motor Work Pte Ltd have the following to report:-

Workshop Estimate Amount	: S\$	38,454.92
Revised Estimate Amount	: S\$	31,289.88
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	31,289.88
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
N/S front, N/S body and N/S rear



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 9.0 day

Yours faithfully,

ANG BRYAN TANI
Licensed Appraiser

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE

VEHICLE NO: SHA 1369E

MAKE :

MODEL : TOYOTA PRIUS

Go Suresh CLKK

LONPAC

DATE : 14.05.2018

TEL NO : 6542 5119

FAX NO : 6542 6039

16/5/18
 Attn: Gary
 Co Page 3

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
FRONT BUMPER COVER Left Crack / cut			\$ 490.50
BRACKET, FRONT BUMPER SIDE, LH S/L			\$ 77.00
UNIT ASSY, HEADLAMP, LH (LED) not Crack / mounting			\$ 3,413.40
FENDER SUB-ASSY, FRONT LH Demol			\$ 933.10
FRONT FENDER SHIELD, LH damaged			\$ 198.50
FRONT FENDER SHIELD CLIP new			\$ 14.90
FRONT FENDER HYBRID EMBLEM, LH new			\$ 86.50
PANEL SUB-ASSY, FRONT DOOR, LH new			\$ 1,238.50
FRONT DOOR INNER LOCK, LH new Distorted			\$ 688.80
FRONT DOOR CHECK, LH new Distorted			\$ 153.52
FRONT DOOR TRIMBOARD, LH new Distorted			\$ 725.00
FRONT DOOR HANDLE BASE, LH new Distorted			\$ 287.70
MOTOR ASSY, POWER WINDOW REGULATOR, FRT, LH new Distorted			\$ 768.90
REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH new Distorted			\$ 228.40
MIRROR ASSY, OUTER REAR VIEW, LH new Crack			\$ 1,374.00
FRONT WINDSCREEN GLASS MOULDING new Distorted new			\$ 208.60
FRONT WINDSCREEN GLASS PILLAR, LH new Distorted			\$ 339.56
FRONT WHEEL RIM (LH) new			\$ 1,570.55
FRONT WHEEL HUB BEARING (LH) new Distorted			\$ 559.94
FRONT SUSPENSION LOWER ARM (LH) new Distorted			\$ 631.90
FRONT SHOCK ABSORBER (LH) new Distorted			\$ 398.20
ABSORBER TOP MOUNTING, LH new Distorted			\$ 196.20
FRONT DRIVE SHAFT (LH) new Distorted			\$ 1,764.00
RACK & PINION ASSY new Distorted			\$ 1,621.30
BAR, STABILIZER new Distorted			\$ 352.40
LINK ASSY, FRONT STABILIZER, LH new Distorted			\$ 196.80
KNUCKLE, STEERING, LH new Distorted			\$ 580.80
END SUB-ASSY, TIE ROD, LH new Distorted			\$ 159.30
ENGINE UNDER COVER new Distorted			\$ 457.20
ENGINE CROSS MEMBER new Distorted			\$ 2,504.40
FRONT BRAKE ABS SENSOR ONLY, LH new Distorted			\$ 450.70
SUB TOTAL			\$ 22,670.57
LESS 20% 75%			\$ 4,534.11
DISCOUNTED TOTAL			\$ 18,136.46
FRONT DOOR COMFORT LOGO, LH new			\$ 75.00
FRONT WINDSCREEN SEALANT new new			\$ 46.00
FRONT TYRE (LH) S/L			\$ 216.00
			\$ 337.00

21659.97

16244.97

75/-

NETT ✓
 NETT ✗
 NETT ✗

SHA 1369E

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
REAR FENDER, LH Dental			\$ 817.50	✓
REAR FENDER INNER PANEL, LH 4N			\$ 728.00	✓
REAR FENDER OUTER PANEL, LH 4N Dental			\$ 486.00	✓
REAR FENDER PANEL, ROOF SIDE OUTER, LH 4N monthy make			\$ 311.00	✓
REAR FENDER SHEILD (LH) 4N cut			\$ 134.20	✓
REAR FENDER SHEILD (RH) 4N			\$ 134.20	✓
REAR FENDER TRIMBOARD (LH) 4N			\$ 725.00	✓
REAR FENDER TOP COVER (BLACK COLOR) (LH) 4N monthy make			\$ 301.10	✓
PANEL SUB-ASSY, REAR DOOR, LH Buc			\$ 1,227.00	✓
REAR DOOR HINGE LOWER, LH 4N by			\$ 82.30	✓
REAR DOOR CHECK, LH 4N distorted			\$ 153.00	✓
REAR DOOR TRIMBOARD, LH 4N			\$ 725.00	✓
REAR DOOR INNER LOCK, LH 4N Dam			\$ 644.70	✓
MOTOR ASSY, POWER WINDOW REGULATOR REAR, LH 4N Dam			\$ 768.90	✓
REGULATOR SUB-ASSY, REAR DOOR WINDOW, LH 4N by			\$ 228.40	✓
REINFORCE SUB-ASSY, ROCKER, OUTER LH Dental			\$ 519.80	✓
CENTRE ROCKER PANEL (GARNISH), LH 4N black			\$ 576.00	✓
REAR TYRE RIM (LH) cut			\$ 1,555.00	✓
REAR WHEEL BEARING IN & HUB 4N Dam			\$ 493.00	✓
REAR CROSS MEMBER 4N distorted			\$ 2,179.40	✓
REAR SHOCK ABSORBER, LH 4N distorted			\$ 116.00	✓
REAR SHOCK ABSORBER MOUNTING, LH 4N distorted			\$ 125.30	✓
REAR LOWER ARM, LH 4N distorted			\$ 345.70	✓
REAR UPPER ARM, LH 4N distorted			\$ 348.80	✓
REAR KNUCKLE ARM, LH 4N distorted			\$ 800.73	✓
REAR BRAKE ABS SENSOR (WIRE) 4N Dam			\$ 78.80	✓
REAR STABILIZER BAR 4N distorted			\$ 311.50	✓
REAR STABILIZER LINK, LH 4N distorted			\$ 147.90	✓
REAR TRAILING ARM, LH 4N distorted			\$ 262.90	✓
REAR ASSIST ARM, LH 4N distorted			\$ 342.20	✓
Rear door hinge Upper LH \$82.30 4N ✓				
SUB TOTAL			\$ 15,669.33	
LESS 20% 25%			\$ 3,133.87	
DISCOUNTED TOTAL			\$ 12,535.46	
REAR DOOR COMFORT & APPS STICKER, LH Nec			\$ 80.00	NETT ✓
REAR TYRE (LH) 2/L			\$ 216.00	NETT X
			\$ 296.00	

13128.43

9846.32

801-

SHA 1369E

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
LABOUR CHARGE			
Panel Beating			\$ 2,600.00 1400/-
Spray Painting Charge			\$ 2,000.00 1200/-
Wiring Charge			\$ 100.00 40/-
Tuff Kote			\$ 150.00 60/-
Towing Charge			\$ 60.00 4x
Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
Remove/Refix Reverse Sensor			\$ 120.00 4x
Remove/Refix Undertarringe (RR)			\$ 400.00 180/-
Remove/Refix Fuel Tank			\$ 150.00 4x
Transfer of Door		\$ 120.00	\$ 240.00 120/-
Remove/Refix Undertarringe (FRT)			\$ 400.00 180/-
Four Wheel Alignment			\$ 120.00 60/-
Remove/Refix Dashboard			\$ 450.00 4x
Remove/Refix Front Windscreen Glass			\$ 120.00 4x
Remove/Refix Cushion & Upholstery Front			\$ 20.00 50/-
			3370/-
TOTAL LABOUR			\$ 7,150.00
ESTIMATE TOTAL			\$ 38,454.92
			29616.29
			10%
			71826.650/-
			38520.76

11/05/2018 @ 1430m
 P/P Not Androm 12/14
 4/2018 & days
 Ryan
 LKK Andro

Q

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHA 1369 E

Technician:

Mileage: 125953

Time Printed 16.5.18 6:06 PM

TOYOTA PRIUS

Front : Left

Actual	BEFORE	Specified Range
6°53'		-1°20' 0°10'
3°16'		2°25' 3°55'
24°57'		-0°06' 0°06'
7°38'		11°50' 13°20'
14°30'		10°30' 13°30'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
2°29'		-1°20' 0°10'
4°11'		2°25' 3°55'
0°28'		-0°06' 0°06'
6°47'		11°50' 13°20'
9°16'		10°30' 13°30'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
4°24'		-0°45' 0°45'
-0°56'		-0°45' 0°45'
0°50'		-0°45' 0°45'
25°25'		-0°12' 0°12'

Rear : Left

Actual	BEFORE	Specified Range
5°43'		-2°00' -1°00'
23°13'		0°02' 0°17'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
2°00'		-2°00' -1°00'
0°13'		0°02' 0°17'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
3°43'		-0°30' 0°30'
23°26'		0°03' 0°33'
11°30'		

Nivitha (LKK Auto)

From: ERIC WOO JUN KIAT <ericwoo@lonpac.com>
Sent: Tuesday, 15 May 2018 3:03 PM
To: assignments@lkkauto.com
Cc: chunnimotor@gmail.com; MT_Claim_SG
Subject: FW: Our Ref: 17/18/18/VP05/020610 Accident involving SJY1537L & SHA1369E along Jurong East Ave 1 on 13/5/18
Attachments: 15052018145744.pdf

3.16pm @ 15/5/2018
Vehicle In
person @ Lynn
arrange on 16/05/18

Dear Catherine / Nivitha,

Kindly refer to our attachment.

Please proceed to appoint Wilson Teo conduct a survey of the vehicle SHA 1369E on without Prejudice Basis.

We look forward to receiving your report soon.

Thank you.

Best Regards,
Eric Woo
Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

From: Chunni Motor [mailto:chunnimotor@gmail.com]
Sent: Tuesday, 15 May, 2018 2:52 PM
To: ERIC WOO JUN KIAT
Cc: MT_Claim_SG
Subject: Re: Our Ref: 17/18/18/VP05/020610 Accident involving SJY1537L & SHA1369E along Jurong East Ave 1 on 13/5/18

Dear Sir,

We agree to appoint Wilson Teo.

Thank you

Regards,
Chunni Motor Work P/L

On Tue, May 15, 2018 at 2:46 PM, ERIC WOO JUN KIAT <ericwoo@lonpac.com> wrote:

Dear Ms Lynn,

We refer to your fax of 15 May 2018.

We will proceed to conduct a pre-repair survey of the damage to your client's vehicle jointly with your workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert. (Please see attached).

Please let us know within 2 working days whether you are agreeable to the appointment of any of the motor surveyors provided to you as a single joint expert. You may select one of the listed motor surveyors.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6279 9253 | Fax: (65) 6296 3767

CHUNNI MOTOR WORK
PTE LTD



Date : 15.05.18

To : Lonpac Insurance Bhd

No of Pages : 13

Re : Accident involving veh no: SHA 1369E & SJY 1537L Along
Jurong East Ave 1 / Jurong East St 21 on 13.05.18

We refer to the above mention matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly arrange to survey at AMK Autopoint, Soon Hock Motor, #01-05/06,

Tel : 6483 6016.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 65427162. Email : chunnimotor@gmail.com

Thank you for your kind assistance.

Nivitha (LKK Auto)

From: ERIC WOO JUN KIAT <ericwoo@lonpac.com>
Sent: Tuesday, 15 May 2018 3:03 PM
To: assignments@lkkauto.com
Cc: chunnimotor@gmail.com; MT_Claim_SG
Subject: FW: Our Ref: 17/18/18/VP05/020610 Accident involving SJY1537L & SHA1369E along Jurong East Ave 1 on 13/5/18
Attachments: 15052018145744.pdf

16/05/2018 @ 3.30pm
vehicle in
person @ hisy
sur @ Bryan

Dear Catherine / Nivitha,

Kindly refer to our attachment.

Please proceed to appoint Wilson Teo conduct a survey of the vehicle SHA 1369E on without Prejudice Basis.

We look forward to receiving your report soon.

Thank you.

Best Regards,
Eric Woo
Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

From: Chunni Motor [mailto:chunnimotor@gmail.com]
Sent: Tuesday, 15 May, 2018 2:52 PM
To: ERIC WOO JUN KIAT
Cc: MT_Claim_SG
Subject: Re: Our Ref: 17/18/18/VP05/020610 Accident involving SJY1537L & SHA1369E along Jurong East Ave 1 on 13/5/18

Dear Sir,

We agree to appoint Wilson Teo.

Thank you

Regards,
Chunni Motor Work P/L

On Tue, May 15, 2018 at 2:46 PM, ERIC WOO JUN KIAT <ericwoo@lonpac.com> wrote:

Dear Ms Lynn,

We refer to your fax of 15 May 2018.

We will proceed to conduct a pre-repair survey of the damage to your client's vehicle jointly with your workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert. (Please see attached).

Please let us know within 2 working days whether you are agreeable to the appointment of any of the motor surveyors provided to you as a single joint expert. You may select one of the listed motor surveyors.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6279 9253 | Fax: (65) 6296 3767



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18009041/Dha3s2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 04-09-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJY 1537L	Veh. Inspected	SHA 1369E
Policy No.	Z17VP05014783	Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020610	Excess (\$)	0.00
Assign From	ERIC WOO	Assign Date	15/05/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU203558767	Colour	BLUE
Odometer	125951	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65R15	WEST LAKE	6 mm
L/H Front Tyre	195/65R15	WEST LAKE	6 mm
R/H Rear Tyre	195/65R15	WEST LAKE	6 mm
L/H Rear Tyre	195/65R15	WEST LAKE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION, N/S BODY AND N/S REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/05/2018	Inspection Date	16/05/2018
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 14 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 1369E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER COVER	CRACKED / CUT	490.50	490.50
1	BACKET, FRONT BUMPER SIDELH	SERVICEABLE	77.00	-
1	UNIT ASSY, HEADLAMP, LH (LED)	MTG CRACKED	3,413.40	3,413.40
1	FENDER SUB-ASSY, FRONT LH	DENTED	933.10	933.10
1	FRONT FENDER SHIELD, LH	DEFORMED	198.50	198.50
1	FRONT FENDER SHIELD CLIP	NECESSARY	14.90	14.90
1	FRONT FENDER HYBRID EMBLEM, LH	NECESSARY	86.50	86.50
1	PANEL SUB-ASSY, FRONT DOOR, LH	BUCKLED	1,238.50	1,238.50
1	FRONT DOOR INNER LOCK, LH	DAMAGED	688.80	688.80
1	FRONT DOOR CHECK LH	DISTORTED	153.52	153.52
1	FRONT DOOR TRIMBOARD, LH	NOT NECESSARY	725.00	-
1	FRONT DOOR HANDLE BASE, LH	DAMAGED	287.70	287.70
1	MOTOR ASSY, POWER WINDOW REGULATOR, FRT, LH	DAMAGED	768.90	768.90
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH	BENT	228.40	228.40
1	MIRROR ASSY, OUTER REAR VIEW, LH	CRACKED	1,374.00	1,374.00
1	FRONT WINDSCREEN GLASS MOULDING	NOT NECESSARY	208.60	-
1	FRONT WINDSCREEN GLASS PILLAR LH	DENTED	339.56	339.56
1	FRONT WHEEL RIM (LH)	CUT	1,570.55	1,570.55
1	FRONT WHEEL HUB BEARING (LH)	DAMAGED	559.94	559.94
1	FRONT SUSPENSION LOWER ARM (LH)	DISTORTED	631.90	631.90
1	FRONT SHOCK ABSORBER (LH)	DISTORTED	398.20	398.20
1	ABSORBER TOP MOUNTING, LH	DISTORTED	196.20	196.20
1	FRONT DRIVE SHAFT (LH)	DISTORTED	1,764.00	1,764.00
1	RACK & PINION ASSY	DISTORTED	1,621.30	1,621.30
1	BAR STABILIZER	DISTORTED	352.40	352.40
1	LINK ASSY, FRONT STABILIZER, LH	DISTORTED	196.80	196.80
1	KNUCKLE, STEERING, LH	DISTORTED	580.80	580.80
1	END SUB-ASSY, TIE ROD, LH	DISTORTED	159.30	159.30
1	ENGINE UNDER COVER	DEFORMED	457.20	457.20
1	ENGINE CROSS MEMBER	DISTORTED	2,504.40	2,504.40
1	FRONT BRAKE ABS SENSOR ONLY, LH	DAMAGED	450.70	450.70

Report Ref No. CC4/LPC18009041/Dha3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER, LH	DENTED	817.50	817.50
1	REAR FENDER INNER PANEL, LH	NOT NECESSARY	728.00	-
1	REAR FENDER OUTER PANEL, LH	DENTED	486.00	486.00
1	REAR FENDER PANEL, ROOF SIDE OUTER, LH	SERVICEABLE	311.00	-
1	REAR FENDER SHIELD (LH)	CUT	134.20	134.20
1	REAR FENDER SHIELD (RH)	NOT NECESSARY	134.20	-
1	REAR FENDER TRIMBOARD (LH)	NOT NECESSARY	725.00	-
1	REAR FENDER TOP COVER (BLACK COLOR) (LH)	MTG CRACKED	301.10	301.10
1	PANEL SUB-ASSY, REAR DOOR, LH	BUCKLED	1,227.00	1,227.00
1	REAR DOOR HINGE LOWER, LH	BENT	82.30	82.30
1	REAR DOOR CHECK, LH	DISTORTED	153.00	153.00
1	REAR DOOR TRIMBOARD, LH	NOT NECESSARY	725.00	-
1	REAR DOOR INNER LOCK, LH	DAMAGED	644.70	644.70
1	MOTOR ASSY, POWER WINDOW REGULATOR REAR LH	DAMAGED	768.90	768.90
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, LH	BENT	228.40	228.40
1	REINFORCE SUB-ASSY, ROCKER OUTER LH	DENTED	519.80	519.80
1	CENTRE ROCKER PANEL (GARNISH), LH	CRACKED	576.00	576.00
1	REAR TYRE RIM (LH)	CUT	1,555.00	1,555.00
1	REAR WHEEL BEARING ING & HUB	DAMAGED	493.00	493.00
1	REAR CROSS MEMBER	DISTORTED	2,179.40	2,179.40
1	REAR SHOCK ABSORBER LH	DISTORTED	116.00	116.00
1	REAR SHOCK ABSORBER MOUNTING, LH	DISTORTED	125.30	125.30
1	REAR LOWER ARM, LH	DISTORTED	345.70	345.70
1	REAR UPPER ARM, LH	DISTORTED	348.80	348.80
1	REAR KNUCKLE ARM, LH	DISTORTED	800.73	800.73
1	REAR BRAKE ABS SENSOR (WIRE)	DAMAGED	78.80	78.80
1	REAR STABILIZER BAR	DISTORTED	311.50	311.50
1	REAR STABILIZER LINK, LH	DISTORTED	147.90	147.90
1	REAR TRAILING ARM, LH	DISTORTED	262.90	262.90
1	REAR ASSIST ARM LH	DISTORTED	342.20	342.20
1	REAR DOOR HINGE UPPER LH	BENT	82.30	82.30
	LESS 20% DISCOUNT		-7,684.44	-

Report Ref No. CC4/LPC18009041/Dha3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-	-8,697.10
			30,737.76	26,091.30
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT DOOR COMFORT LOGO, LH (SN)	NECESSARY	75.00	75.00
1	FRONT WINDSCREEN SEALANT (SN)	NOT NECESSARY	46.00	-
1	FRONT TYRE (LH) (SN)	SERVICEABLE	216.00	-
1	REAR DOOR COMFORT & APPS STICKER, LH (SN)	NECESSARY	80.00	80.00
1	REAR TYRE (LH) (SN)	SERVICEABLE	216.00	-
			633.00	155.00
	<u>LABOUR</u>			
	PANEL BEATING.		2,600.00	1,400.00
	SPRAY PAINTING CHARGE.		2,000.00	1,200.00
	WIRING CHARGE.		100.00	40.00
	TUFF KOTE.		150.00	60.00
	TOWING CHARGE.	NOT NECESSARY	60.00	-
	REMOVE / REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE / REFIX REVERSE SENSOR.	NOT NECESSARY	120.00	-
	REMOVE / REFIX UNDERCARRIAGE (RR)		400.00	180.00
	REMOVE / REFIX FUEL TANK.	NOT NECESSARY	150.00	-
	TRANSFER OF DOOR.		240.00	120.00
	REMOVE / REFIX UNDERCARRIAGE (FRT)		400.00	180.00
	FOUR WHEEL ALIGNMENT.		120.00	60.00
	REMOVE / REFIX DASHBOARD.	NOT NECESSARY	450.00	-
	REMOVE / REFIX FRONT WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	REMOVE / REFIX CUSHION & UPHOLSTERY FRONT.		90.00	50.00
			-	-
			-	-
			-	-
			7,150.00	3,370.00
	GRAND TOTAL		38,520.76	29,616.30

Report Ref No. CC4/LPC18009041/Dha3s2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			26,650.00
---	--	--	-----------

Report Ref No. CC4/LPC18009041/Dha3s2

ANG BRYAN TANI

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.