Adjuster Report Page 1 of 3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18009047/KEA3Q2

Date: 04/05/2020

REFERENCE

Price:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant YN40P Insured Vehicle No: SLF7422X

Date of Loss: 19/03/2018 Nature of Claim: TP Claim No: 0358244928SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YN40P

Make & Model: ISUZU NPR75UH5A, 5.2 D (M) Engine No: 4HK1726434

Reg. Date: 04/03/2009 (Man. Year: 2009) Chassis No: JAANPR75H97101460

Colour: Silver Odometer: 270615 km

Engine Capacity: 5193 cc
Market Value/New Car
N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/75 R17.5 Rear Tyre Size: 215/75 R17.5 (D)
Front Left Side: Double Coin 6 mm Rear Left Side: Aeolus 8/8 mm
Front Right Side: Double Coin 6 mm Rear Right Side: Aeolus 8/8 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|------------|------------|------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

Date of Assignment: 25/08/2018

Date Inspected: 25/08/2018 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun

Industrial Park A Singapore 768761

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Recommended Parts

| No. | Qty Part No. | Particulars | Condition | Repairer's | Amount |
|-------|---------------|------------------------|-------------------|------------|--------|
| 1 | 1 | *LH SIDE GUARD | Bent | 0.00 F | *- F |
| 2 | 2 | *LH SIDE GUARD BRACKET | Bent | 0.00 F | *- F |
| 3 | 2 | *BATTERY | Bent | 0.00 F | *- F |
| 4 | 1 | *BATTERY SUPPORT | Bent | 0.00 F | *- F |
| 5 | 1 | *BATTERY SUPPORT BOLT | Bent | 0.00 F | *- F |
| 6 | 1 | *REAR LH WHEEL COVER | Distorted | 0.00 F | *- F |
| F=Fra | anchise part. | | _ | | |
| | | | Total Parts (S\$) | 0.00 | 0.00 |
| | | | | | |

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >