

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18009049/GEA3Q2

Date: 04/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100421043

Claimant
Vehicle No : FT8871Z **Insured Vehicle No :** SKC140H

Date of Loss: 10/05/2018 **Nature of Claim:** TP **Claim No:** 9604974323SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FT8871Z		
Make & Model:	HONDA CB400SFYJ, 399cc	Engine No:	NC23E2022924
Reg. Date:	12/09/2001 (Man. Year: 2001)	Chassis No:	NC391022918
Colour:	Green	Odometer:	247964 km
Engine Capacity:	399 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/60Z R17	Rear Tyre Size:	150/60Z R17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,682.00	4,213.80	468.20	10.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	495.00	290.00	205.00	41.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	5,177.00	4,503.80	673.20	13.00
+ Loss of Use (3.0 x S\$30.00/day) (S\$)		90.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,601.25		
Global Sum Settlement (S\$)		4,600.00		

INSPECTION

Date of Assignment: 16/05/2018

Date Inspected: 17/05/2018 Inspected At: Ahm Performance (HQ)
1 KAKI BUKIT AVENUE 6 #02-46
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BRAKE LEVER	Cut	85.00 F	*85.00 FL
2	1		*MIRROR	Cut	70.00 F	*70.00 FL
3	2		*INNER FORK TUBE L&R	Bent	660.00 F	*660.00 FL
4	2		*FORK OIL SEAL L&R	Necessary	98.00 F	*98.00 FL
5	2		*FORK OIL	Necessary	56.00 F	*56.00 FL
6	1		*STEERING STREM	Bent	390.00 F	*390.00 FL
7	1		*STEERING CONE	Necessary	120.00 F	*120.00 FL
8	1		*EXHAUST HEADER	Bent	1,350.00 F	*1,350.00 FL
9	4		*EXHAUST HEADER GASKET	Necessary	40.00 F	*40.00 FL
10	1		*MUFFLER	Cut	1,150.00 F	*1,150.00 FL
11	1		*FRAME SLIDER	Cut	160.00 F	*160.00 FL
12	1		*BRAKE PEDAL	Cut	90.00 F	*90.00 FL
13	1		*FRONT FOOTREST R	Cut	95.00 F	*95.00 FL
14	1		*REAR PILLION FOOTREST R	Cut	75.00 F	*75.00 FL
15	1		*FOOTREST BRACKET R	Bent	195.00 F	*195.00 FL
16	1		*CLUTCH LEVER	Broken	48.00 F	*48.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	4,682.00	4,682.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	468.20
Total Parts (S\$)	4,682.00	4,213.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOW	New	45.00	40.00
2	LABOUR	New	450.00	250.00
Gross Labour Cost (\$)			495.00	290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >