

ASS. REC. BY:

REF: CS/FCI18009060/R1td3ⁿ²

Special Instruction:

Surveyor

Rasul

ASSIGNMENT (Office)

CWS

From (Person):

Aung Yin Min

of

FCI

Date/Time:

18/05/18 @ 8:59am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBE 951 E

Insured:

SHC 0785H

at Workshop no/3

SG 98 Motor

Tel:

64524898

of

BLK 4001, AMK Ind. Park 1 # 01-21

Policy No:

Claim No:

D18003955 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/05/2018

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement:

Date/Time:

9:01am @ 18/5/18

Person Contacted:

Rose

Vehicle:

IN / OUT

Date/Time	Action/Instruction (✓) Estimate	
	FBE 951 E - CS / FCI 17010652 / 8/h3k2	DOA: 29/5/17
	SHC 0785H - CS / AIG 16003527 / H1jg3g2	DOA: 20/2/16
	lump sum \$2400 - Cred: 2441.60, 50%	

Form

REF: FCI

1354C

LOG XEROX 2019/11/01

ASSIGNMENT

From: Date: 18/15/18

Estimated Cost:

OD TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBE 951 E
at Workshop m/s SG 98 Motor

of

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS^{lup}

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: FBE 951 E Yr Regn: 2009 NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: YAMAHA YZF-R1S C.C. 150

Colour: RED A/C: Insured / Std / NI / NA

Sp. Reading: 608123 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: ME120 P01192019883

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 90/80-17

R: 110/80-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 4 mm

L/Bal. mm

D.O.A. 15/05/18 D.O.I. 18/05/18

Survey held at SG 98 Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 27 NOV 2018

Date/Time: File Pass to? ☐ : Preli. Report

1) 24/11 Typist ☒ : Final Report

Date/Time: File Return to?

2) -

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + RS \$

) Photos:

) Others:

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TP 24007

135

50

105

290

MOTOR SURVEY ASSIGNMENT

Date	17-05-2018	Our Ref No.	D18003955MFSH
Accident Date	15-05-2018	Claim Type.	Third Party
Insured Vehicle	SHC0785H	Third Party Vehicle.	FBE951E
Survey Location	BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21		
Contact Person.	ROSE		
Contact No.	64524898/ 91711655	Fax No.	64524868
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED;		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SG 98 MOTOR PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	AUNGYM		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/240464)



PRI Documents



Close



PRI Header Details

Claim No	D18003955MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & SG 98 MC
Workshop Name	SG 98 MOTOR PTE LTD (Contact Person : ROSE)	Survey Location & Contact Details	BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 Mobile: 91711655 , Phone: 64524898 , Fax: 64524861 EmailId: SG_MOTOR_ENTERPRISE@YAHOO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0785H	TP Vehicle No	FBE951E
PRI Recieved Date	17-05-2018 06:57:58 PM	Surveyor Appointed Date	18-05-2018 08:57:50 AM	Surveyor Accept Date	18-05-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	18-05-2018	Upload Survey Report *:	Choose File
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Dear Mr. Rasul - fax on 08/11 @ 0930

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 21 May 2018

To : LKK

By Fax: 6256-4315

Attn : Rasul

Tel : 90010068

VEHICLE NO : FBE 951E

Yamaha R15

ACCIDENT DATE: 15 May 2018

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Fork Tube	1 set	320.00 X suc
2 Head Cowling	1	250.00 suc
3 Head Lamp	1	380.00 X suc
4 Handle Bar RH	1	75 105.00 RH
5 Side Fairing Outer RH	1	115 180.00 suc
6 Inner Fairing RH	1	145.00 cut
7 RH Signal	1	50 75.00 suc
8 Fuel Tank	1	480.00 RH
9 Throttle Grip	1	75 165.00 cut
10 Brake Lever	1	40 78.00 suc
11 Footrest RH	1	45 68.00 suc
12 Footrest Bracket LH	1	95.00 X suc
13 Exhaust Pipe	1	550.00 suc
14 Rear Tail Cover RH/LH	2	165.00 CRB
15 Front LH Signal	1	50 75.00 CRB
16 Front Fairing Outer LH	1	175.00 CRB
17 Seat	1	185.00 X old damage (ny)
18 Rear Footrest RH	1	68.00 X suc
19 Footrest Bracket RH	1	95.00 RH
20 Rear Rim	1	320.00 suc
21 Rear Tyre	1	250.00 X suc
Sub-Total		4,224.00 2630
Less 10%		422.40 10%
Sub-Total		3,801.60 2367

①

VEHICLE NO : FBE 951E

Yamaha R15

Nett items

1 Towing fee	40.00	
2 Remove & replace necessary parts, align & etc	280.00 200	} 640
3 Remove & replace fork tube & top up fork oil	150.00 X 4	
4 Putty & respray paint & decal sticker	420.00 300	
5 Remove & Replace Rear Rim & tyre & swing Arm	150.00 100	
Sub-Total	1,040.00	
Nett Total	4,841.60	

NB. This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
Thank you

SG 98 MOTOR PTE LTD

LG

Paul
Hp 90010068
4 days
4/5
18/05/18 @ 1545

2367
640
3007
202
2405.60
41 - 2,400
4 days

2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18009060/R1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 29-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 785H	Veh. Inspected	FBE 951E	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18003955MFSH	Excess (\$)	0.00	
Assign From	AUNGYM	Assign Date	18/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA YZF-R15	c.c	150	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	ME120P01192019883	Colour	RED	
Odometer	8123	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	90/80-17	BRIDGESTONE	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	110/80-17	BRIDGESTONE	4 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/05/2018	Inspection Date	18/05/2018	
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBE 951E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SET FORK TUBE	SERVICEABLE	320.00	-
1	HEAD COWLING	SCRATCHED	250.00	250.00
1	HEAD LAMP	SERVICEABLE	380.00	-
1	HANDLE BAR RH	BENT	105.00	75.00
1	SIDE FAIRING OUTER RH	SCRATCHED	180.00	115.00
1	INNER FAIRING RH	CUT	145.00	145.00
1	RH SIGNAL	SCRATCHED	75.00	50.00
1	FUEL TANK	BENT	480.00	480.00
1	THROTTLE GRIP	CUT	165.00	75.00
1	BRAKE LEVER	SCRATCHED	78.00	40.00
1	FOOTREST RH	SCRATCHED	68.00	45.00
1	FOOTREST BRACKET LH	SERVICEABLE	95.00	-
1	EXHAUST PIPE	SCRATCHED	550.00	550.00
2	REAR TAIL COVER RH/LH	CRACKED	165.00	165.00
1	FRONT LH SIGNAL	CRACKED	75.00	50.00
1	FRONT FAIRING OUTER LH	CRACKED	175.00	175.00
1	SEAT (NOT NECESSARY)	OLD DAMAGED	185.00	-
1	REAR FOOTREST RH	SERVICEABLE	68.00	-
1	FOOTREST BRACKET RH	BENT	95.00	95.00
1	REAR RIM	SCRATCHED	320.00	320.00
1	REAR TYRE	SERVICEABLE	250.00	-
	LESS 10% DISCOUNT		-422.40	-263.00
			3,801.60	2,367.00
LABOUR				
	TOWING FEE.		40.00	40.00
	REMOVE & REPLACE NECESSARY PARTS,ALIGN & ETC.		280.00	200.00
	REMOVE & REPLACE FORK TUBE & TOP UP FORK OIL.	NOT NECESSARY	150.00	-
	PUTTY & RESPRAY PAINT & DECAL STICKER.		420.00	300.00
	REMOVE & REPLACE REAR RIM & TYRE & SWING ARM.		150.00	100.00
			1,040.00	640.00

Report Ref No. CS/FCI18009060/R1td3n2



GRAND TOTAL		4,841.60	3,007.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,400.00

Report Ref No. CS/FCI18009060/R1td3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.