

ASS. REC. BY:

REF:

CS/FCI18009063/Atd3

n2

Special Instruction:

Surveyor:

CWS

Adnan

ASSIGNMENT (Office)

From (Person):

Lurene jaw

of

FCI

Date/Time:

18/05/18 @ 11:16am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

CB 7160 D

Insured:

SHB 3999T

at Workshop m/s

Huei Meng Spray

Tel:

67465519

of

1 kaki bukit Ave 6 Blk C # 01-61

Policy No:

Claim No:

D18003838 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

11/05/2018

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

2:18pm @ 18/5/18

Person Contacted:

June

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

CB 7160 D-X

SHB 3999T-003/119 17003620/Hlpb3p2

DOA: 16/02/2017

lump sum \$1500 (Red. 3552.17 : 70%)

REF:

ASS. REC. BY: Adrian Ling**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its
repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: CB7160D Yr Regn: 2013 AprilType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or Mini BusMake: Toyota Hiace c.c. 2882Colour: Silver A/C: Insured / Std / Nil / NASp. Reading: 92492 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: JTFST22P80095956Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16R: 205/55R16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /TOYO / YOKO or

Front		Rear	
R/Bal. <u>06</u>	mm	R/Bal. <u>06</u>	mm
L/Bal. <u>06</u>	mm	L/Bal. <u>06</u>	mm
D.O.A.		D.O.I. <u>30/05/18</u>	

Survey held at Hua MengDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orFront O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP 1st Cap</u>
	<u>Door Repair</u>

RECEIVED 05 SEP 2018

Date/Time, File Pass to?

☐ : Preli. Report☒ : Final Report1) 519 Typist

Date/Time, File Return to?

2) _____

Days Of Repair: 2Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____) S + RS. \$ _____☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)Report Format : TPLump Sum / I.B.I. (\$) 1500/-

Survey Fee:

Transportation:

Photos

Others

TOTAL

140503016256



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18009063/Atd3

36 ROBINSON ROAD

#16-01 CITY HOUSES SINGAPORE 068877

Date : 18-05-2018

Code : FCI2



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 3999T	Veh. Inspected	CB 7160D
Policy No.		Coverage (\$)	0.00
Claim No.	D18003838MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	18/05/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	11/05/2018	Inspection Date
Survey held at	HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

MOTOR SURVEY ASSIGNMENT

Date	14-05-2018	Our Ref No. D18003838MFSH
Accident Date	11-05-2018	Claim Type. Third Party
Insured Vehicle	SHB3999T	Third Party Vehicle. CB7160D
Survey Location	AUTOBAY@KAKIBUKIT 1 KAKI BUKIT AVENUE 6BLK C #01-61/01-34	
Contact Person.	JUNE	
Contact No.	67478064/ 67465519	Fax No. 67434896
Survey Type	WITHOUT PREJUDICE: PENDING VF TO DETERMINE LIABILITY	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUA MENG SPRAY PAINTING WORKSHOP	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/240438)



PRI Documents



Close



PRI Header Details

Claim No	D18003838MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & HUA MEN WORKSHOP
Workshop Name	HUA MENG SPRAY PAINTING WORKSHOP (Contact Person : JUNE)	Survey Location & Contact Details	AUTOBAY@KAKIBUKIT 1 KAKI BUKIT AVENUE 6BLK C # Mobile: 67465519 , Phone: 67478064 , Fax: 67434891 EmailId: HUAMENG@LIVE.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: PENDING VF TO DETERMINE LIAI		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB3999T	TP Vehicle No	CB7160D
PRI Recieved Date	16-05-2018 10:19:38 PM	Surveyor Appointed Date	18-05-2018 11:15:23 AM	Surveyor Accept Date	18-05-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	18-05-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Accident Sketch Plan Pg. 1

LETTER OF UNDERTAKING

I/We, Elite Transport Services, the owner of vehicle no. C821600

My/Our Insurance is under M/s AXA Insurance Singapore Pte Ltd, I/we shall decide whether to claim under my/our Policy or against the Third Party and if the former shall submit such a claim to M/s AXA Insurance Singapore Pte Ltd with all relevant facts and documents within 14(fourteen) days of occurrence or discovery of damage.

My/Our Third Party claim is handle by my/our preferred workshop, Hua meng
Spring Painting Workshop

Signed and Acknowledge by:

53033981N 倪桂芳
Nric no. and signature of policyholder



Company Stamp

14/5/18
Date

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

JTFST22P800015556

Elite Transport Services
Blk 246 Serangoon Ave 3
#05-204
S550246

TP 1st Cap
Dorise

Date : 30.06.2018
Vehicle no : CB 7160D
Make/Model : Toyota Hiace
Accident date : 11.05.2018

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Front bumper <i>schud</i>	1	\$ 535.8 ✓
2	Front bumper side holder @ \$164.00 <i>for 2nd</i>	2	\$ 328 164.
3	Front bumper clips (1set) <i>New</i>	1	\$ 60 30
4	Front RH head lamp <i>lt</i>	1	\$ 758.6 ✓
5	Front RH door <i>Repair</i>	1	\$ 1973.4 ×
6	Front RH door top hinge <i>green</i>	1	\$ 93.7 ×
7	Front RH door lower hinge	1	\$ 93.7 ×
8	Front RH door stopper <i>green</i>	1	\$ 152 ×
9	Front RH door inner rubber	1	\$ 44.6 ×
10	Front EH step panel garnish <i>int</i>	1	\$ 163.1 ✓
			\$ 4202.9
Less 25% Disc			\$ 1050.73
Total			\$ 3152.17
<u>Labour Cost</u>			
1	Remove, replace & repair consistent to the accident	650	\$ 1000 <i>400</i>
2	Respray painting		\$ 900 <i>250</i>
Total			\$ 1900
Grand Total			\$ 5052.17

total: 1888.62

h/s: 1.5K

02 days

1.5K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FC118009063/Atd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 06-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3999T	Veh. Inspected	CB 7160D	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18003838MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	18/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	JTFST22P800015956	Colour	SILVER	
Odometer	92492	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	DUNLOP	6 mm	
L/H Front Tyre	205/55 R16	DUNLOP	6 mm	
R/H Rear Tyre	205/55 R16	DUNLOP	6 mm	
L/H Rear Tyre	205/55 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/05/2018	Inspection Date	30/05/2018	
Survey held at	HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. CB 7160D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	535.80	535.80
2	FRONT BUMPER SIDE HOLDER @\$164.00	O/S DAMAGED	328.00	164.00
1	SET FRONT BUMPER CLIPS	NECESSARY	60.00	30.00
1	FRONT RH HEAD LAMP	CUT	758.60	758.60
1	FRONT RH DOOR	TO REPAIR SEE LABOUR	1,973.40	-
1	FRONT RH DOOR TOP HINGE	NOT NECESSARY	93.70	-
1	FRONT RH DOOR LOWER HINGE	NOT NECESSARY	93.70	-
1	FRONT RH DOOR STOPPER	NOT NECESSARY	152.00	-
1	FRONT RH DOOR INNER RUBBER	NOT NECESSARY	44.60	-
1	FRONT EH STEP PANEL GARNISH	CUT	163.10	163.10
	LESS 25% DISCOUNT		-1,050.73	-412.88
			3,152.17	1,238.62
	<u>LABOUR</u>			
	REMOVE, REPLACE & REPAIR CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT RH DOOR.		1,000.00	400.00
	RESPRAY PAINTING.		900.00	250.00
			1,900.00	650.00
	GRAND TOTAL		5,052.17	1,888.62
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,500.00

Report Ref No. CS/FCI18009063/Atd3n2

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.