

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

Ang Asia CIP *TS*

VEHICLE NO : SHA 7706B

DATE 17/5/2018

MAKE :

MODEL : HYUNDAI i40

LKK - Kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>Defunct</i>			\$ 603.60
	Rear Bumper Clips <i>new</i>			\$ 22.00
	SUB TOTAL			\$ 625.60
	LESS 20%			\$ 125.12
	DISCOUNTED TOTAL			\$ 500.48
	Labour Charge			
	Panel Beating			\$ 280.00 <i>200</i>
	Spray Painting Charge			\$ 200.00 <i>180</i>
	Wiring Charge			\$ 50.00 <i>X 11</i>
	R/Refix Reverse Sensor			\$ 120.00 <i>20</i>
	TOTAL LABOUR			\$ 650.00
	ESTIMATE TOTAL			\$ 1,150.48
<p><i>Kalvin</i> <i>17/5/13 1505h</i> <i>200</i> <i>PIP</i> <i>Before Part pld</i></p> <div data-bbox="909 1621 1420 2016" data-label="Text"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>				
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				