

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

AXA

VEHICLE NO : SHC 3103G

DATE 17/5/2018 11:12

MAKE :

DOA: 17.05.18 LS

MODEL : MERCEDES

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bumper Assy, Frt <i>X 1 pair</i>			\$ 1,890.50
	Bumper Reinforcement, Frt <i>X 2</i>			\$ 1,158.00
	Bumper Sponge, Frt/Centre <i>X 2</i>			\$ 285.00
	Bumper Inner Clip, Frt <i>X 2</i>			\$ 22.00
	License Plate Trim Cover, Frt <i>1 ea</i>			\$ 155.00
	SUB TOTAL			\$ 3,510.50
	LESS 20%			\$ 702.10
	DISCOUNTED TOTAL			\$ 2,808.40
	Number Plate, Frt (Merc Taxi) <i>1 ea</i>			\$ 50.00 Nett
	Labour Charge			<i>100</i>
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 250.00 <i>200</i>
	TOTAL LABOUR			\$ 600.00
	ESTIMATE TOTAL			\$ 3,458.40

Kaluz (11/14)
18/5/18 1030 hrs.
2 hrs.
LS
After Repair photo.

Larry Ng

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.