



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : GBG8432Z

Date of Accident : 18 May 2018

Miss Lim Chwee Yee

Date : 18 May 2018

Estimate To Repair SLW9086E - Honda Jazz 1.3 CVT (A)
Chassis No : JHMGK3850JX213065

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	tailgate lid <i>sed/600</i>	\$ 0.00
02	1 pc	tailgate lid lock <i>7m, 1/2m</i>	\$ 0.00
03	1 pc	tailgate lid lock stricker <i>11 X</i>	\$ 0.00
04	1 pc	tailgate lid weatherstrip <i>7m, 1/2m</i>	\$ 0.00
05	1 pc	tailgate lid inner trimboard	\$ 0.00
06	2 ps	tailgate lid rubber stoppers @ \$.00	\$ 0.00
07	1 pc	tailgate lid inner closing handle garnish	\$ 0.00
08	2 ps	tailgate lid hinge top @ \$.00 <i>11 X</i>	\$ 0.00
09	2 ps	tailgate lid reflector garnish @ \$.00	\$ 0.00
10	1 pc	tailgate lid outer garnish <i>3m</i>	\$ 0.00
11	1 pc	tailgate lid outer garnish "H" badge <i>1m</i>	\$ 0.00
12	1 pc	tailgate lid Jazz badge <i>1m</i>	\$ 0.00
13	1 pc	tailgate lid opening lever/handle outer	\$ 0.00
14	2 ps	tailgate lid damper stays @ \$.00 <i>11 X</i>	\$ 0.00
15	2 ps	tailgate lid drainage grommet @ \$.00 <i>11 X</i>	\$ 0.00
16	1 pc	rear windscreen glass <i>5m, 1/2m</i>	\$ 0.00
17	1 pc	rear wiper motor <i>11 X</i>	\$ 0.00
18	1 pc	rear wiper arm <i>11 X</i>	\$ 0.00
19	1 pc	rear wiper blade <i>11 X</i>	\$ 0.00
20	1 pc	rear wiper arm cover <i>11 X</i>	\$ 0.00
21	2 ps	rear licence plate lamps @ \$.00 <i>11 X</i>	\$ 0.00
22	1 pc	rear end panel inner <i>25 X</i>	\$ 0.00
23	1 pc	rear end panel outer <i>3.4m</i>	\$ 0.00
24	1 pc	rear end panel inner trim <i>7m</i>	\$ 0.00
25	2 ps	rear lamps @ \$.00 <i>1m</i>	\$ 0.00
26	1 pc	left rear lamp panel	\$ 0.00
27	4 ps	left rear lamp panel clip holders @ \$.00 <i>11 X</i>	\$ 0.00
28	1 pc	rear luggage floor panel	\$ 0.00
29	1 pc	rear luggage floor tools compartment foam <i>2m/10m</i>	\$ 0.00
30	1 pc	rear bumper <i>Dis</i>	\$ 0.00
31	2 ps	rear bumper side retainers @ \$.00 <i>3/4 1/5 1 pc</i>	\$ 0.00
32	2 ps	rear bumper side holder @ \$.00	\$ 0.00
33	2 ps	rear bumper screw spacer @ \$.00	\$ 0.00
34	2 ps	rear bumper fog lamp garnish @ \$.00 <i>25 X</i>	\$ 0.00
35	1 pc	rear bumper centre garnish	\$ 0.00
36	8 ps	rear bumper clips @ \$.00 <i>1m</i>	\$ 0.00
37	2 ps	rear bumper splashshield cover @ \$.00	\$ 0.00
38	1 pc	left rear fender <i>2 X</i>	\$ 0.00
39	1 pc	left rear fender inner liner <i>11 X</i>	\$ 0.00



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : GBG8432Z

Date of Accident : 18 May 2018

Miss Lim Chwee Yee

Date : 18 May 2018

Estimate To Repair SLW9086E - Honda Jazz 1.3 CVT (A)

Chassis No : JHMGK3850JX213065

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
40	8 ps	left rear fender inner liner clips @ \$.00 11X	\$ 0.00
41	2 ps	rear fender air vent @ \$.00 11X	\$ 0.00
42	1 pc	speaker shelf board ?	\$ 0.00
43	2 ps	rear fender inner top garnish @ \$.00 ?	\$ 0.00
44	1 pc	bonnet	\$ 0.00
45	2 ps	bonnet hinges @ \$.00 7m ✓	\$ 0.00
46	1 pc	bonnet lock 7m ✓	\$ 0.00
47	1 pc	bonnet lock cable 11X	\$ 0.00
48	1 pc	bonnet insulator Dis ✓	\$ 0.00
49	6 ps	bonnet insulator clips @ \$.00 11m ✓	\$ 0.00
50	1 pc	right bonnet underseal weatherstrip 11m ✓	\$ 0.00
51	1 pc	left bonnet underseal weatherstrip 11m ✓	\$ 0.00
52	1 pc	left bonnet underseal weatherstrip inner 11X	\$ 0.00
53	1 pc	right bonnet underseal weatherstrip inner 11X	\$ 0.00
54	2 ps	bonnet rubber stoppers @ \$.00 11X	\$ 0.00
55	1 pc	front support panel 34c ✓	\$ 0.00
56	2 ps	headlamps @ \$.00 11m/320 ✓	\$ 0.00
57	2 ps	headlamp lower brackets @ \$.00 ?	\$ 0.00
58	1 pc	front bumper Dis ✓	\$ 0.00
59	1 pc	front bumper reinforcement 11m ✓	\$ 0.00
60	2 ps	front bumper air guide @ \$.00 ?	\$ 0.00
61	4 ps	front bumper air guide clips @ \$.00 ?	\$ 0.00
62	1 pc	front bumper lower centre air grille ?	\$ 0.00
63	2 ps	front bumper lower centre air grille side garnish @ \$.00 ?	\$ 0.00
64	2 ps	front bumper spot lamp garnish @ \$.00 11X	\$ 0.00
65	10 ps	front bumper clips @ \$.00 11m ✓	\$ 0.00
66	1 pc	front bumper tow cover 71.1 ✓	\$ 0.00
67	2 ps	front bumper side retainers @ \$.00 34c ✓	\$ 0.00
68	2 ps	front fenders @ \$.00 11X	\$ 0.00
69	2 ps	front fender inner liner @ \$.00 11X	\$ 0.00
70	8 ps	front fender inner liner clips @ \$.00 11X	\$ 0.00
71	1 pc	windscreen washer tank ?	\$ 0.00
72	1 pc	windscreen washer tank motor front ?	\$ 0.00
73	1 pc	windscreen washer tank motor rear 11m X	\$ 0.00
74	2 ps	windscreen washer tank motor pipe @ \$.00 11X	\$ 0.00
75	1 pc	wiper grille 11X	\$ 0.00
76	1 pc	radiator assy ?	\$ 0.00
77	1 pc	radiator expansion tank ?	\$ 0.00
78	1 pc	radiator expansion tank bracket ?	\$ 0.00



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : GBG8432Z

Date of Accident : 18 May 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Miss Lim Chwee Yee

Date : 18 May 2018

Estimate To Repair SLW9086E - Honda Jazz 1.3 CVT (A)

Chassis No : JHMGK3850JX213065

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
79	1 pc	radiator grille <i>me ✓</i>	\$ 0.00
80	1 pc	radiator grille outer chrome garnish <i>CM ✓</i>	\$ 0.00
81	1 pc	radiator grille emblem badge <i>MIS ✓</i>	\$ 0.00
82	3 ps	radiator grille emblem badge clips @ \$.00 <i>11X</i>	\$ 0.00
83	1 pc	radiator grille emblem badge base/holder <i>?</i>	\$ 0.00
84	1 pc	radiator grille chrome moulding <i>CM ✓</i>	\$ 0.00
85	6 ps	radiator grille clips @ \$.00 <i>11X</i>	\$ 0.00
86	2 ps	radiator top mount bush @ \$.00 <i>11X</i>	\$ 0.00
87	1 pc	radiator fan shroud <i>?</i>	\$ 0.00
88	1 pc	radiator fan blade <i>?</i>	\$ 0.00
89	1 pc	radiator fan motor <i>?</i>	\$ 0.00
90	1 pc	radiator top hose <i>?</i>	\$ 0.00
91	1 pc	radiator bottom hose <i>?</i>	\$ 0.00
92	2 ps	radiator bottom mount bush @ \$.00 <i>?</i>	\$ 0.00
93	1 pc	radiator expansion tank hose	\$ 0.00
94	1 pc	inlet manifold assy <i>svx</i>	\$ 0.00
95	1 pc	inlet manifold rubber hose <i>11X</i>	\$ 0.00
96	1 pc	inlet manifold rubber hose cliop holder <i>11X</i>	\$ 0.00
97	1 pc	air cleaner tank - intake duct <i>twi ✓</i>	\$ 0.00
98	2 ps	air cleaner tank - intake duct clips @ \$.00 <i>me ✓</i>	\$ 0.00
99	1 pc	air cleaner tank - intake hose <i>?</i>	\$ 0.00
100	1 pc	aircon condenser <i>pan/Bul ✓</i>	\$ 0.00
101	1 pc	aircon fan blade <i>?</i>	\$ 0.00
102	1 pc	aircon fan motor <i>?</i>	\$ 0.00
103	1 pc	aircon fan shroud <i>?</i>	\$ 0.00
104	1 pc	aircon pipe condenser to compressor <i>11X</i>	\$ 0.00
105	1 pc	aircon hose compressor to evaporator <i>11X</i>	\$ 0.00
106	1 pc	battery cover <i>me ✓</i>	\$ 0.00
107	1 pc	battery tray	\$ 0.00
108	1 pc	battery support panel <i>11X</i>	\$ 0.00
109	12 ps	roof-gutter moulding clips @ \$.00 <i>11X</i>	\$ 0.00
		Less 20 %	\$ 0.00
			\$ 0.00
		<u>SPECIAL NETT ITEMS</u>	
110	1 set	sundries and clips <i>11X</i>	\$ 100.00
111	1 pc	rear windscreen glass sealant <i>me</i>	\$ 180.00
112	1 pc	rear windscreen glass sponge seal <i>me</i>	\$ 100.00
113	1 pc	rear windscreen glass solat film <i>me</i>	\$ 500.00

x
40
30
200



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : GBG8432Z

Date of Accident : 18 May 2018

Miss Lim Chwee Yee

Date : 18 May 2018

Estimate To Repair SLW9086E - Honda Jazz 1.3 CVT (A)

Chassis No : JHMGK3850JX213065

S/No	Quantity	Description	Amount
		<u>SPECIAL NETT ITEMS</u>	
114	1 pc	rear licence plate <i>Ref</i>	\$ 50.00
115	1 pc	backoff camera with night vision	\$ 550.00
116	1 pc	rear luggage floor panel insulator	\$ 250.00
117	1 set	rear bumper parking sensor <i>shard 200</i>	\$ 500.00
118	1 pc	front licence plate <i>Ref</i>	\$ 80.00
119	1 tin	radiator coolant <i>new</i>	\$ 80.00
120	1 pc	battery	\$ 200.00
			\$ 2,590.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To place vehicle on jig bench to obtain cross and parallel measurement and correct to manufacturer specification with hydraulic pneumatic jack.	\$ 850.00
02		To rust-proofing of the affected areas.	\$ 350.00
03		To apply panel protection system and shines	\$ 450.00
04		To remove and refit rear windscreen glass and vaccum shattered broken glass	\$ 250.00
05		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 180.00
06		To reinstall of rear bumper parking sensor.	\$ 200.00
07		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 250.00
08		To remove backoff camera and settings.	\$ 120.00
09		To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.	\$ 300.00
10		To check electrical lighting concerned.	\$ 80.00
11		Labour to remove and renew inlet manifold assy and front chassis.	\$ 1,250.00
12		To conduct diagnostic check and recall error codes and settings.	\$ 500.00
13		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 3,800.00
14		Putty and spray painting of the affected portion.	\$ 2,500.00
			\$ 10,080.00
		Total	\$ 12,670.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

40
?
?
200
40
30
?
280
120
?
120
60
50
100
30
x
x
1800
1700