

ASS. REC. BY:

REF:

CS/SPF18009218/Alber

Special Instruction:

Major

Rasul

ASSIGNMENT (Office)

From (Person):

Perry He

of

SPF

Date/Time:

17/05/2018 4:12pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

TP94H

Insured:

at Workshop m/s

Ben Hock Hin

Tel:

6281 6520

of

Blk 6 Defu Lane 4

Policy No:

Claim No:

HOMSPFETQ17300218

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

CA / REV / REP. / REV 24 HRS

21.05.2018

H.O.D. Endorsement:

Date/Time:

18/05/2018 2:40pm

Person Contacted:

Raymond

Vehicle IN/OUT

Date/Time

Action/Instruction ( ✓ ) Estimate

7/6/18

TP 94H - X  
Robert to Perry

Sunny 6286 0815

Mike 63822763

4/7/2018

Call Perry to check; He said on hold first.

Surveyor: *Faruq*

REF:

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: TP 94H

at Workshop m/s Bar Hock HW

of 6, Perumangudi 4

Insured: SPF

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rport: \_\_\_\_\_ Consistent?: **Yes** or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: **Yes** or No

Est. Repairs: \_\_\_\_\_ days Res.: **Yes** or No

Lum Sum: \_\_\_\_\_ % 3 Val.: **Yes** or No

CA /  REV / REP. / 24 HRS

Vehicle: **IN / OUT**

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: TP 94H Yr Regn: \_\_\_\_\_ /

Type: **M.Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: YAMAHA XS 900P c.c. \_\_\_\_\_

Colour: MULTI A/C: **Insured** / Std / NI / NA

Sp. Reading: 06876 T/Radio: **Insured** / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: 344KM00000127632

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: **Inorder** / Jammed / Leaked / Burnt or

Brake: **Inorder** / Jammed / Leaked / Burnt or

Modi: **Nil** / S/Rim / STD A/Rim or

Tyre Size: F: 120/70ZR17

R: 150/70ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **METZELER**

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. \_\_\_\_\_ mm L/Bal. \_\_\_\_\_ mm

D.O.A. \_\_\_\_\_ D.O.I. 21/05/18

Survey held at Bar Hock HW

Des. of Damages: **Frt** / Rear / O/S / **N/S** / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Submit Parts \$14,740.10 Man-Hour 31.90 hour
	check Parts \$1,529.10
RECEIVED 13 NOV 2018	

Date/Time, File Pass to?

1) typist

Date/Time, File Return to?

2) \_\_\_\_\_

: Preli. Report

: Final Report

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: 200

Transportation: \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL

200

Report Format : 01

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Add Fee: : Site Insp (\$ \_\_\_\_\_) S + RS, SI

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

## Catherine Chong (LKK Auto)

---

**From:** Perry HE (SPF) <Perry\_HE@spf.gov.sg>  
**Sent:** Thursday, 17 May, 2018 4:12 PM  
**To:** assignments  
**Cc:** Wei Yea LIM (SPF); Kwee Huat TAN (SPF); Kim Pang CHAY (SPF); Ai Phing (LKKAuto); Shiau Chan (LKKAuto); Veron Chen (LKKAuto)  
**Subject:** Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ17300218 - TP94H

Hi Catherine and Ashley,

Please provide Appraisal Service (Parts and Labour-man hours) for the following SPF vehicle at BHH.

**Vehicle No: TP94H**

**Parts:**

- 1.1 BOX DOCUMENT
- 1.2 BOX SIDE LH
- 1.3 BOX SIDE RH
- 1.4 STICKER SIDE BOX LH - SUPPLY BY AEMD
- 1.5 STICKER SIDE BOX RH - SUPPLY BY AEMD
- 1.6 LATCH (#20-J) WITH LOCK - S/STEEL
- 1.7 BRACKET FOOTREST REAR LH
- 1.8 LIGHT LED (JL) 4 LED BLUE - CLEAR LENS
- 1.9 LIGHT LED (JL) 4 LED RED - CLEAR LENS
- 1.10 COVER LED LIGHT (FOR 4 LED)
- 1.11 BRACKET LED LIGHT (50 MM)
- 1.12 BRACKET SIDE BOX
- 1.13 BRACKET SIGNAL LAMP REAR LH
- 1.14 BOLT REAR SIGNAL LAMP
- 1.15 CRASH BAR FRONT
- 1.16 CRASH BAR REAR LH
- 1.17 CRASH BAR REAR RH
- 1.18 FOOTREST FRONT LH
- 1.19 FOOTREST FRONT RH
- 1.20 RUBBER FOOTREST
- 1.21 PROTECTOR FRONT (LH -STK 21958) WITH SPRAY PAINTING  
POLICE LIVERY LINING
- 1.22 STAY COWLING FRONT
- 1.23 MID NUT PLASTIC (WINDSHIELD)
- 1.24 RIVET
- 1.25 SCREW (VISOR)
- 1.26 SIREN (CR)
- 1.27 STAND MAIN
- 1.28 STOPPER MAINSTAND
- 1.29 STAND SIDE
  
- 2.1 RIM SPORT FRONT
- 2.2 SEAL DUST FORK
- 2.3 SEAL OIL (25X40X5) SWINGING ARM
- 2.4 SEAL OIL (40X53X8) FORK
- 2.5 SHAFT PIVOT
- 2.6 SHAFT PIVOT
- 2.7 T-JOINT

- 2.8 TUBE INNER FORK
- 2.9 VALVE RIM
- 2.10 WASHER PLATE
- 2.11 OIL FORK (UNICORN) MR-15(M)
- 2.12 MIRROR LH
- 2.13 COLLAR
- 2.14 COLLAR
- 2.15 BRACKET UNDER FORK
- 2.16 BUSH FORK INNER (LOWER)
- 2.17 BUSH FORK INNER (UPPER)
- 2.18 CLIP TUBE INNER FORK
- 2.19 AXLE WHEEL FRONT
- 2.20 BALANCER HANDLE
- 2.21 BEARING
- 2.22 BEARING (B6203) WHEEL FRONT
- 2.23 BEARING STEERING CONE LOWER
- 2.24 BEARING STEERING CONE UPPER
- 2.25 BEARING STEERING CONE UPPER
- 2.26 GASKET SILENCER
- 2.27 LEVER CLUTCH
- 2.28 PLATE DISC BRAKE FRONT
- 2.29 PLATE NUMBER REAR (TP)
- 2.30 BOLT PLATE DISC BRAKE
- 2.31 BOLT
- 2.32 BOLT FLANGE
- 2.33 BOLT FLANGE
- 2.34 GROMMET
- 2.35 LENS SIGNAL FRONT LH
- 2.36 MID RUBBER PEDAL GEAR
- 2.37 MOLE 4
- 2.38 MUFFLER LH
- 2.39 PANEL INNER
- 2.40 PEDAL GEAR

**Labour:**

- REPLACE ITEMS 1.1 - 1.5 hr
- REPLACE ITEMS 1.2 - 1.5 hr
- REPLACE ITEMS 1.3 - 1.5 hr
- REPLACE ITEMS 1.7 - 0.7 hr
- REPLACE ITEMS 1.8 - 1 hr
- REPLACE ITEMS 1.9 - 1 hr
- REPLACE ITEMS 1.11 - 1 hr
- REPLACE ITEMS 1.12 - 1 hr
- REPLACE ITEMS 1.13 - 2 hr
- REPLACE ITEMS 1.15 - 1.5 hr
- REPLACE ITEMS 1.16 - 0.5 hr
- REPLACE ITEMS 1.17 - 0.5 hr
- REPLACE ITEMS 1.18 - 0.5 hr
- REPLACE ITEMS 1.19 - 0.5 hr
- REPLACE ITEMS 1.21 - 1.5 hr
- REPLACE ITEMS 1.22 - 25 - 4 hr
- REPLACE ITEMS 1.26 - 0.5 hr
- REPLACE ITEMS 1.27 - 1.28 - 1 hr
- REPLACE ITEMS 1.29 - 0.5 hr

Thank you.

Perry He Junyun  
Contract Management Engineer  
Automotive Engineering & Management Division  
Police Logistics Department  
Singapore Police Force  
DID: (65) 6478 4869 | HP: (65) 9191 5725



**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
<b>1</b>	<b>MATERIALS</b>					
1.1	BOX DOCUMENT	1	BENT	\$814.20	\$814.20	
1.2	BOX SIDE LH	1	CRACKED	\$2,006.00	\$2,006.00	
1.3	BOX SIDE RH	1	SCRATCHED	\$2,006.00	\$2,006.00	
1.4	STICKER SIDE BOX LH- SUPPLY BY AEMD	1	NECESSARY	\$0.00	\$0.00	
1.5	STICKER SIDE BOX RH- SUPPLY BY AEMD	1	NECESSARY	\$0.00	\$0.00	
1.6	LATCH(#20-J) WITH LOCK-S/STELL	4	UNCONFIRM	\$54.28	\$217.12	
1.7	BRACKET FOOTREST REAR LH	1	BROKEN	\$82.60	\$82.60	
1.8	LIGHT LED (JL)4 LED BLUE- CLEAR LENS	1	CRACKED	\$306.80	\$306.80	
1.9	LIGHT LED (JL)4 LED RED- CLEAR LENS	1	NOT NECESSARY	\$306.80		
1.10	COVER LED LIGHT (FOR 4 LED)	2	SCRATCHED	\$92.04	\$184.08	
1.11	BRACKET LED LIGHT (50MM)	2	NECESSARY	\$17.70	\$35.40	
1.12	BRACKET SIDE BOX	1	BENT	\$363.44	\$363.44	
1.13	BRACKET SIGNAL LAMP REAR LH	1	CRACKED	\$228.21	\$228.21	
1.14	BOLT REAR SIGNAL LAMP	2	NECESSARY	\$56.64	\$113.28	
1.15	CRASH BAR FRONT	1	BENT	\$649.00	\$649.00	
1.16	CRASH BAR REAR LH	1	MISSING	\$169.92	\$169.92	
1.17	CRASH BAR REAR RH	1	BENT	\$169.92	\$169.92	
1.18	FOOTREST FRONT LH	1	BROKEN	\$20.06	\$20.06	
1.19	FOOTREST FRONT RH	1	SCRATCHED	\$20.06	\$20.06	
1.20	RUBBER FOOTREST	1	MISSING	\$15.34	\$15.34	
1.21	PROTECTOR FRONT(LH-STK21958) WITH SPRAY PAINTING	1	SCRATCHED	\$450.76	\$450.76	
1.22	StAY COWLING FRONT	1	BENT	\$401.20	\$401.20	
1.23	MID NUT PLASTIC(WINDSHIELD)	6	NECESSARY	\$6.14	\$36.84	
1.24	RIVET	6	NECESSARY	\$2.36	\$14.16	
1.25	SCREW(VISOR)	6	NECESSARY	\$3.54	\$21.24	
1.26	SIREN(CR)	1	CRACKED	\$3,953.00	\$3,953.00	
1.27	STAND MAIN	1	REPAIR	\$350.40		
1.28	STOPPER MAINSTAND	1	MISSING	\$6.14	\$6.14	
1.29	STAND SIDE	1	BENT	\$106.20	\$106.20	
<b>2</b>	<b>ADDITIONAL SERVICES</b>					
2.1	RIM SPORT FRONT	1	BENT	\$939.28	\$939.28	
2.2	SEAL DUST FORK	2	LEAK	\$16.52	\$33.04	
2.3	SEAL OIL(25X40X5) SWINGING ARM	2	NECESSARY	\$4.72	\$9.44	
2.4	SEAL OIL(40X53X8) FORK	2	NECESSARY	\$15.34	\$30.68	
2.5	SHAFT PIVOT	1	UNCONFIRM	\$22.07	\$22.07	
2.6	SHAFT PIVOT	1	UNCONFIRM	\$20.89	\$20.89	
2.7	T-JOINT	1	UNCONFIRM	\$149.74	\$149.74	
2.8	TUBE INNER FORK	2	UNCONFIRM	\$263.14	\$526.28	
2.90	VALVE RIM	1	NECESSARY	\$10.62	\$10.62	
2.10	WASHER PLATE	6	UNCONFIRM	\$2.36	\$14.16	
2.11	OIL FORK(UNICORN) MR-15(M)	1	NECESSARY	\$8.85	\$8.85	
2.12	MIRROR LH	1	SCRATCHED	\$162.84	\$162.84	
2.13	COLLAR	4	UNCONFIRM	\$0.63	\$2.52	
2.14	COLLAR	2	UNCONFIRM	\$6.73	\$13.46	
2.15	BRACKET UNDER FORK	1	UNCONFIRM	\$300.90	\$300.90	
2.16	BUSH FORK INNER (LOWER)	2	UNCONFIRM	\$18.88	\$37.76	
2.17	BUSH FORK INNER (UPPER)	2	UNCONFIRM	\$14.75	\$29.50	
2.18	CLIP TUBE INNER FORK	2	UNCONFIRM	\$3.54	\$7.08	
2.19	AXLE WHEEL FRONT	1	NECESSARY	\$49.56	\$49.56	
2.20	BALANCE HANDLE	1	SCRATCHED	\$24.78	\$24.78	
2.21	BEARING	2	UNCONFIRM	\$27.14	\$54.28	
2.22	BEARING(B6203) WHEEL FRONT	2	UNCONFIRM	\$23.60	\$47.20	
2.23	BEARING STEERING CONE LOWER	1	UNCONFIRM	\$68.44	\$68.44	
2.24	GASKET SILENCER	1	NECESSARY	\$56.64	\$56.64	
2.25	LEVER CLUTCH	1	SCRATCHED	\$16.52	\$16.52	
2.26	PLATE DISC BRAKE FRONT	1	SCRATCHED	\$24.78	\$24.78	
2.27	PLATE NUMBER REAR(TP)	1	BENT	\$263.14	\$263.14	
2.28	BOLT PLATE DISC BRAKE	1	NECESSARY	\$21.24	\$21.24	
2.29	BOLT	6	NECESSARY	\$3.07	\$18.42	
2.3	BOLT FLANGE	2	NECESSARY	\$44.87	\$89.74	
2.31	BOLT FLANGE	1	NECESSARY	\$3.54	\$3.54	
2.32	GROMMET	2	NECESSARY	\$3.54	\$7.08	
2.33	LENS SIGNAL FRONT LH	4	SCRATCHED	\$10.01	\$40.04	
2.34	MID RUBBER PEDAL GEAR	1	CUT	\$9.79	\$9.79	
2.35	MOLE 4	1	UNCONFIRM	\$17.70	\$17.70	
2.36	MUFFLER LH	1	BENT	\$624.69	\$624.69	
2.37	PANEL INNER	1	SCRATCHED	\$69.62	\$69.62	
2.38	PEDAL GEAR	1	BENT	\$51.92	\$51.92	



S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
<b>1</b>	<b>MATERIALS</b>					
1.1	BOX DOCUMENT	1	BENT	\$814.20	\$814.20	
1.2	BOX SIDE LH	1	CRACKED	\$2,006.00	\$2,006.00	
1.3	BOX SIDE RH	1	SCRATCHED	\$2,006.00	\$2,006.00	
1.4	STICKER SIDE BOX LH- SUPPLY BY AEMD	1	NECESSARY	\$0.00	\$0.00	
1.5	STICKER SIDE BOX RH- SUPPLY BY AEMD	1	NECESSARY	\$0.00	\$0.00	
1.6	LATCH(#20-J) WITH LOCK-S/STELL	4	UNCONFIRM	\$54.28	\$217.12	
1.7	BRACKET FOOTREST REAR LH	1	BROKEN	\$82.60	\$82.60	
1.8	LIGHT LED (JL)4 LED BLUE- CLEAR LENS	1	CRACKED	\$306.80	\$306.80	
1.9	LIGHT LED (JL)4 LED RED- CLEAR LENS	1	NOT NECESSARY	\$306.80		
1.10	COVER LED LIGHT (FOR 4 LED)	2	SCRATCHED	\$92.04	\$184.08	
1.11	BRACKET LED LIGHT (50MM)	2	NECESSARY	\$17.70	\$35.40	
1.12	BRACKET SIDE BOX	1	BENT	\$363.44	\$363.44	
1.13	BRACKET SIGNAL LAMP REAR LH	1	CRACKED	\$228.21	\$228.21	
1.14	BOLT REAR SIGNAL LAMP	2	NECESSARY	\$56.64	\$113.28	
1.15	CRASH BAR FRONT	1	BENT	\$649.00	\$649.00	
1.16	CRASH BAR REAR LH	1	MISSING	\$169.92	\$169.92	
1.17	CRASH BAR REAR RH	1	BENT	\$169.92	\$169.92	
1.18	FOOTREST FRONT LH	1	BROKEN	\$20.06	\$20.06	
1.19	FOOTREST FRONT RH	1	SCRATCHED	\$20.06	\$20.06	
1.20	RUBBER FOOTREST	1	MISSING	\$15.34	\$15.34	
1.21	PROTECTOR FRONT(LH-STK21958) WITH SPRAY PAINTING	1	SCRATCHED	\$450.76	\$450.76	
1.22	SLAY COWLING FRONT	1	BENT	\$401.20	\$401.20	
1.23	MID NUT PLASTIC(WINDSHIELD)	6	NECESSARY	\$6.14	\$36.84	
1.24	RIVET	6	NECESSARY	\$2.36	\$14.16	
1.25	SCREW(VISOR)	6	NECESSARY	\$3.54	\$21.24	
1.26	SIREN(CR)	1	CRACKED	\$3,953.00	\$3,953.00	
1.27	STAND MAIN	1	REPAIR	\$350.40		
1.28	STOPPER MAINSTAND	1	MISSING	\$6.14	\$6.14	
1.29	STAND SIDE	1	BENT	\$106.20	\$106.20	
<b>2</b>	<b>ADDITIONAL SERVICES</b>					
2.1	RIM SPORT FRONT	1	BENT			
2.2	SEAL DUST FORK	2	LEAK			
2.3	SEAL OIL(25X40X5) SWINGING ARM	2	NECESSARY			
2.4	SEAL OIL(40X53X8) FORK	2	NECESSARY			
2.5	SHAFT PIVOT	1	UNCONFIRM			
2.6	SHAFT PIVOT	1	UNCONFIRM			
2.7	T-JOINT	1	UNCONFIRM			
2.8	TUBE INNER FORK	2	UNCONFIRM			
2.90	VALVE RIM	1	NECESSARY			
2.10	WASHER PLATE	6	UNCONFIRM			
2.11	OIL FORK(UNICORN) MR-15(M)	1	NECESSARY			
2.12	MIRROR LH	1	SCRATCHED			
2.13	COLLAR	4	UNCONFIRM			
2.14	COLLAR	2	UNCONFIRM			
2.15	BRACKET UNDER FORK	1	UNCONFIRM			
2.16	BUSH FORK INNER (LOWER)	2	UNCONFIRM			
2.17	BUSH FORK INNER (UPPER)	2	UNCONFIRM			
2.18	CLIP TUBE INNER FORK	2	UNCONFIRM			
2.19	AXLE WHEEL FRONT	1	NECESSARY			
2.20	BALANCE HANDLE	1	SCRATCHED			
2.21	BEARING	2	UNCONFIRM			
2.22	BEARING(B6203) WHEEL FRONT	2	UNCONFIRM			
2.23	BEARING STEERING CONE LOWER	1	UNCONFIRM			
2.24	BEARING STEERING CONE UPPER	2	UNCONFIRM			
2.25	BEARING STEERING CONE UPPER	1	UNCONFIRM			
2.26	GASKET SILENCER	1	NECESSARY			
2.27	LEVER CLUTCH	1	SCRATCHED			
2.28	PLATE DISC BRAKE FRONT	2	SCRATCHED			
2.29	PLATE NUMBER REAR(TP)	1	BENT			
2.30	BOLT PLATE DISC BRAKE	6	NECESSARY			
2.31	BOLT	2	NECESSARY			
2.32	BOLT FLANGE	1	NECESSARY			
2.33	BOLT FLANGE	2	NECESSARY			
2.34	GROMMET	4	NECESSARY			
2.35	LENS SIGNAL FRONT LH	1	SCRATCHED			
2.36	MID RUBBER PEDAL GEAR	1	CLUT			
2.37	MOLE 4	1	UNCONFIRM			
2.38	MUFFLER LH	1	BENT			
2.39	PANEL INNER	1	SCRATCHED			
2.40	PEDAL GEAR	1	BENT			

2	SCOPE OF REPAIRS					
	REPLACE ITEM 1.1					1.5
	REPLACE ITEM 1.2					1.5
	REPLACE ITEM 1.3					1.5
	REPLACE ITEM 1.7					0.7
	REPLACE ITEM 1.8					1
	REPLACE ITEM 1.9					
	REPLACE ITEM 1.11					1
	REPLACE ITEM 1.12					1
	REPLACE ITEM 1.13					2
	REPLACE ITEM 1.15					1.5
	REPLACE ITEM 1.16					0.5
	REPLACE ITEM 1.17					
	REPLACE ITEM 1.18					0.5
	REPLACE ITEM 1.19					
	REPLACE ITEM 1.21					1.5
	REPLACE ITEM 1.22 - 1.25					4
	REPLACE ITEM 1.26					0.5
	REPLACE ITEM 1.27 - 1.28					0.5
	REPLACE ITEM 1.29					0.5
COSTING		TOTAL PARTS COST			\$12,390.97	
		TOTAL MAN-HOUR				19.7

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
<b>1</b>	<b>MATERIALS</b>					
1.1	BOX DOCUMENT	1	BENT	\$814.20	\$814.20	
1.2	BOX SIDE LH	1	CRACKED	\$2,006.00	\$2,006.00	
1.3	BOX SIDE RH	1	SCRATCHED	\$2,006.00	\$2,006.00	
1.4	STICKER SIDE BOX LH- SUPPLY BY AEMD	1	NECESSARY	\$0.00	\$0.00	
1.5	STICKER SIDE BOX RH- SUPPLY BY AEMD	1	NECESSARY	\$0.00	\$0.00	
1.6	LATCH(#20-J) WITH LOCK-S/STELL	4	UNCONFIRM	\$54.28		
1.7	BRACKET FOOTREST REAR LH	1	BROKEN	\$82.60	\$82.60	
1.8	LIGHT LED (JL)4 LED BLUE- CLEAR LENS	1	CRACKED	\$306.80	\$306.80	
1.9	LIGHT LED (JL)4 LED RED- CLEAR LENS	1	NOT NECESSARY	\$306.80		
1.10	COVER LED LIGHT (FOR 4 LED)	2	SCRATCHED	\$92.04	\$184.08	
1.11	BRACKET LED LIGHT (50MM)	2	NECESSARY	\$17.70	\$35.40	
1.12	BRACKET SIDE BOX	1	UNCONFIRM	\$363.44	\$363.44	
1.13	BRACKET SIGNAL LAMP REAR LH	1	UNCONFIRM	\$228.21	\$228.21	
1.14	BOLT REAR SIGNAL LAMP	2	UNCONFIRM	\$56.64	\$113.28	
1.15	CRASH BAR FRONT	1	BENT	\$649.00	\$649.00	
1.16	CRASH BAR REAR LH	1	MISSING	\$169.92	\$169.92	
1.17	CRASH BAR REAR RH	1	NOT NECESSARY	\$169.92		
1.18	FOOTREST FRONT LH	1	BROKEN	\$20.06	\$20.06	
1.19	FOOTREST FRONT RH	1	NOT NECESSARY	\$20.06		
1.20	RUBBER FOOTREST	1	MISSING	\$15.34	\$15.34	
1.21	PROTECTOR FRONT(LH-STK21958) WITH SPRAY PAINTING	1	SCRATCHED	\$450.76	\$450.76	
1.22	SLAY COWLING FRONT	1	UNCONFIRM	\$401.20	\$401.20	
1.23	MID NUT PLASTIC(WINDSHIELD)	6	NECESSARY	\$6.14	\$36.84	
1.24	RIVET	6	NECESSARY	\$2.36	\$14.16	
1.25	SCREW(VISOR)	6	NECESSARY	\$3.54	\$21.24	
1.26	SIREN(CR)	1	CRACKED	\$3,953.00	\$3,953.00	
1.27	STAND MAIN	1	REPAIR	\$350.40		
1.28	STOPPER MAINSTAND	1	MISSING	\$6.14	\$6.14	
1.29	STAND SIDE	1	BENT	\$106.20	\$106.20	
<b>2</b>	<b>ADDITIONAL SERVICES</b>					
2.1	RIM SPORT FRONT	1	UNCONFIRM			
2.2	SEAL DUST FORK	2	UNCONFIRM			
2.3	SEAL OIL(25X40X5) SWINGING ARM	2	UNCONFIRM			
2.4	SEAL OIL(40X53X8) FORK	2	UNCONFIRM			
2.5	SHAFT PIVOT	1	UNCONFIRM			
2.6	SHAFT PIVOT	1	UNCONFIRM			
2.7	T-JOINT	1	UNCONFIRM			
2.8	TUBE INNER FORK	2	UNCONFIRM			
2.90	VALVE RIM	1	UNCONFIRM			
2.10	WASHER PLATE	6	UNCONFIRM			
2.11	OIL FORK(UNICORN) MR-15(M)	1	UNCONFIRM			
2.12	MIRROR LH	1	UNCONFIRM			
2.13	COLLAR	4	UNCONFIRM			
2.14	COLLAR	2	UNCONFIRM			
2.15	BRACKET UNDER FORK	1	UNCONFIRM			
2.16	BUSH FORK INNER (LOWER)	2	UNCONFIRM			
2.17	BUSH FORK INNER (UPPER)	2	UNCONFIRM			
2.18	CLIP TUBE INNER FORK	2	UNCONFIRM			
2.19	AXLE WHEEL FRONT	1	UNCONFIRM			
2.20	BALANCE HANDLE	1	UNCONFIRM			
2.21	BEARING	2	UNCONFIRM			
2.22	BEARING(B6203) WHEEL FRONT	2	UNCONFIRM			
2.23	BEARING STEERING CONE LOWER	1	UNCONFIRM			
2.24	BEARING STEERING CONE UPPER	2	UNCONFIRM			
2.25	BEARING STEERING CONE UPPER	1	UNCONFIRM			
2.26	GASKET SILENCER	1	UNCONFIRM			
2.27	LEVER CLUTCH	1	UNCONFIRM			
2.28	PLATE DISC BRAKE FRONT	4	UNCONFIRM			
2.29	PLATE NUMBER REAR(TP)	1	UNCONFIRM			
2.30	BOLT PLATE DISC BRAKE	6	UNCONFIRM			
2.31	BOLT	2	UNCONFIRM			
2.32	BOLT FLANGE	1	UNCONFIRM			
2.33	BOLT FLANGE	2	UNCONFIRM			
2.34	GROMMET	4	UNCONFIRM			
2.35	LENS SIGNAL FRONT LH	1	UNCONFIRM			
2.36	MID RUBBER PEDAL GEAR	1	UNCONFIRM			
2.37	MOLE 4	1	UNCONFIRM			
2.38	MUFFLER LH	1	UNCONFIRM			
2.39	PANEL INNER	1	UNCONFIRM			
2.40	PEDAL GEAR	1	UNCONFIRM			

2	<b>SCOPE OF REPAIRS</b>				
	REPLACE ITEM 1.1				1.5
	REPLACE ITEM 1.2				1.5
	REPLACE ITEM 1.3				1.5
	REPLACE ITEM 1.7				0.7
	REPLACE ITEM 1.8				1
	REPLACE ITEM 1.9				
	REPLACE ITEM 1.11				1
	REPLACE ITEM 1.12				1
	REPLACE ITEM 1.13				2
	REPLACE ITEM 1.15				1.5
	REPLACE ITEM 1.16				0.5
	REPLACE ITEM 1.17				
	REPLACE ITEM 1.18				0.5
	REPLACE ITEM 1.19				
	REPLACE ITEM 1.21				1.5
	REPLACE ITEM 1.22 - 1.25				4
	REPLACE ITEM 1.26				0.5
	REPLACE ITEM 1.27 - 1.28				0.5
	REPLACE ITEM 1.29				0.5
<b>COSTING</b>		<b>TOTAL PARTS COST</b>			\$11,983.87
		<b>TOTAL MAN-HOUR</b>			19.7

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
<b>1</b>	<b>MATERIALS</b>					
1.1	BOX DOCUMENT	1	BENT	\$814.20	\$814.20	
1.2	BOX SIDE LH	1	CRACKED	\$2,006.00	\$2,006.00	
1.3	BOX SIDE RH	1	SCRATCHED	\$2,006.00	\$2,006.00	
1.4	STICKER SIDE BOX LH- SUPPLY BY AEMD	1	NECESSARY	\$0.00	\$0.00	
1.5	STICKER SIDE BOX RH- SUPPLY BY AEMD	1	NECESSARY	\$0.00	\$0.00	
1.6	LATCH(#20-J) WITH LOCK-S/STELL	4	UNCONFIRM	\$54.28		
1.7	BRACKET FOOTREST REAR LH	1	BROKEN	\$82.60	\$82.60	
1.8	LIGHT LED (1/4) LED BLUE- CLEAR LENS	1	CRACKED	\$306.80	\$306.80	
1.9	LIGHT LED (1/4) LED RED- CLEAR LENS	1	NOT NECESSARY	\$306.80		
1.10	COVER LED LIGHT (FOR 4 LED)	2	SCRATCHED	\$92.04	\$184.08	
1.11	BRACKET LED LIGHT (50MM)	2	NECESSARY	\$17.70	\$35.40	
1.12	BRACKET SIDE BOX	1	UNCONFIRM	\$363.44	\$363.44	PH
1.13	BRACKET SIGNAL LAMP REAR LH	1	UNCONFIRM	\$228.21	\$228.21	CPA
1.14	BOLT REAR SIGNAL LAMP	2	UNCONFIRM	\$56.64	\$113.28	PH
1.15	CRASH BAR FRONT	1	BENT	\$649.00	\$649.00	
1.16	CRASH BAR REAR LH	1	MISSING	\$169.92	\$169.92	
1.17	CRASH BAR REAR RH	1	NOT NECESSARY	\$169.92		
1.18	FOOTREST FRONT LH	1	BROKEN	\$20.06	\$20.06	
1.19	FOOTREST FRONT RH	1	NOT NECESSARY	\$20.06		
1.20	RUBBER FOOTREST	1	MISSING	\$15.34	\$15.34	
1.21	PROTECTOR FRONT(LH-STK21958) WITH SPRAY PAINTING	1	SCRATCHED	\$450.76	\$450.76	
1.22	SKAY COWLING FRONT	1	UNCONFIRM	\$401.20	\$401.20	PH
1.23	MID NUT PLASTIC(WINDSHIELD)	6	NECESSARY	\$6.14	\$36.84	
1.24	RIVET	6	NECESSARY	\$2.36	\$14.16	
1.25	SCREW(VISOR)	6	NECESSARY	\$3.54	\$21.24	
1.26	SIREN(CR)	1	CRACKED	\$3,953.00	\$3,953.00	
1.27	STAND MAIN	1	REPAIR	\$350.40		
1.28	STOPPER MAINSTAND	1	MISSING	\$6.14	\$6.14	
1.29	STAND SIDE	1	BENT	\$106.20	\$106.20	

scratches

broken required to replace  
bent required to replace  
bent required to replace

bent required to replace

scratches

bent required to replace







Scope Of Work  
Home Team Agency

SCOPE OF WORK

1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR :	Indeco Engineers Pte Ltd	VEH TYPE :	UNIT :	TP
VEH NO :	TP94H	MC	REPAIR TYPE:	ACCIDENT
VEH MAKE/MODEL:	YAMAHA XJ900P(M)		Mileage:	


Reference No.
MHA/SPF/2018/05-0022 1100004968

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)	
<b>Scope Of Repairs</b>							
1.1	BOX DOCUMENT	690.00	1	18%	814.20	814.20	
1.2	BOX SIDE LH	1700.00	1	18%	2006.00	2006.00	
1.3	BOX SIDE RH	1700.00	1	18%	2006.00	2006.00	
1.4	STICKER SIDE BOX LH - SUPPLY BY AEMD		1	18%	0.00	0.00	
1.5	STICKER SIDE BOX RH - SUPPLY BY AEMD		1	18%	0.00	0.00	
1.6	LATCH (#20-J) WITH LOCK - S/STEEL	46.00	4	18%	54.28	217.12	
1.7	BRACKET FOOTREST REAR LH	70.00	1	18%	82.60	82.60	
1.8	LIGHT LED (JL) 4 LED BLUE - CLEAR LENS	260.00	1	18%	306.80	306.80	
1.9	LIGHT LED (JL) 4 LED RED - CLEAR LENS	260.00	1	18%	306.80	306.80	
1.10	COVER LED LIGHT (FOR 4 LED)	78.00	2	18%	92.04	184.08	
1.11	BRACKET LED LIGHT (50 MM)	15.00	2	18%	17.70	35.40	
1.12	BRACKET SIDE BOX	308.00	1	18%	363.44	363.44	
1.13	BRACKET SIGNAL LAMP REAR LH	193.40	1	18%	228.21	228.21	
1.14	BOLT REAR SIGNAL LAMP	48.00	2	18%	56.64	113.28	
1.15	CRASH BAR FRONT	550.00	1	18%	649.00	649.00	
1.16	CRASH BAR REAR LH	144.00	1	18%	169.92	169.92	
1.17	CRASH BAR REAR RH	144.00	1	18%	169.92	169.92	
1.18	FOOTREST FRONT LH	17.00	1	18%	20.06	20.06	
1.19	FOOTREST FRONT RH	17.00	1	18%	20.06	20.06	
1.20	RUBBER FOOTREST	13.00	1	18%	15.34	15.34	
1.21	PROTECTOR FRONT (LH -STK 21958) WITH SPRAY PAINTING	382.00	1	18%	450.76	450.76	
	POLICE LIVERY LINING			18%			
1.22	STAY COWLING FRONT	340.00	1	18%	401.20	401.20	
1.23	MID NUT PLASTIC (WINDSHIELD)	5.20	6	18%	6.14	36.82	
1.24	RIVET	2.00	6	18%	2.36	14.16	
1.25	SCREW (VISOR)	3.00	6	18%	3.54	21.24	
1.26	SIREN (CR)	3350.00	1	18%	3953.00	3953.00	
1.27	STAND MAIN	297.00	1	18%	350.46	350.46	
1.28	STOPPER MAINSTAND	5.20	1	18%	6.14	6.14	
1.29	STAND SIDE	90.00	1	18%	106.20	106.20	
<b>Additional Services</b>							
2.1	RIM SPORT FRONT		1				
2.2	SEAL DUST FORK		2				
2.3	SEAL OIL (25X40X5) SWINGING ARM		2				
2.4	SEAL OIL (40X53X8) FORK		2				
2.5	SHAFT PIVOT		1				
2.6	SHAFT PIVOT		1				
2.7	T-JOINT		1				
2.8	TUBE INNER FORK		2				
2.9	VALVE RIM		1				
2.10	WASHER PLATE		6				
2.11	OIL FORK (UNICORN) MR-15(M)		1				
2.12	MIRROR LH		1				
2.13	COLLAR		4				
2.14	COLLAR		2				
2.15	BRACKET UNDER FORK		1				
2.16	BUSH FORK INNER (LOWER)		2				
2.17	BUSH FORK INNER (UPPER)		2				
2.18	CLIP TUBE INNER FORK		2				
2.19	AXLE WHEEL FRONT		1				
2.20	BALANCER HANDLE		1				
2.21	BEARING		2				
2.22	BEARING (B6203) WHEEL FRONT		2				
2.23	BEARING STEERING CONE LOWER		1				
2.24	BEARING STEERING CONE UPPER		2				
2.25	BEARING STEERING CONE UPPER		1				
2.26	GASKET SILENCER		1				
2.27	LEVER CLUTCH		1				
2.28	PLATE DISC BRAKE FRONT		1				
2.29	PLATE NUMBER REAR (TP)		1				
2.30	BOLT PLATE DISC BRAKE		6				
2.31	BOLT		2				
2.32	BOLT FLANGE		1				
2.33	BOLT FLANGE		2				
2.34	GROMMET		4				
2.35	LENS SIGNAL FRONT LH		1				
2.36	MID RUBBER PEDAL GEAR		1				
2.37	MOLE 4		1				
2.38	MUFFLER LH		1				
2.39	PANEL INNER		1				
2.40	PEDAL GEAR		1				
<b>Remarks:</b>					<b>Parts Total:</b>	<b>\$</b>	<b>13,048.20</b>

20/11/2017

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
1	<b>Scope Of Repairs</b>			
1.1	REPLACE ITEMS 1.1	53.80	1.5	80.70
	REPLACE ITEMS 1.2	53.80	1.5	80.70
	REPLACE ITEMS 1.3	53.80	1.5	80.70
	REPLACE ITEMS 1.7	53.80	0.7	37.66
	REPLACE ITEMS 1.8	53.80	1	53.80
	REPLACE ITEMS 1.9	53.80	1 X	53.80
	REPLACE ITEMS 1.11	53.80	1	53.80
	REPLACE ITEMS 1.12	53.80	1	53.80
	REPLACE ITEMS 1.13	53.80	2	107.60
	REPLACE ITEMS 1.15	53.80	1.5	80.70
	REPLACE ITEMS 1.16	53.80	0.5	26.90
	REPLACE ITEMS 1.17	53.80	0.5 X	26.90
	REPLACE ITEMS 1.18	53.80	0.5	26.90
	REPLACE ITEMS 1.19	53.80	0.5 X	26.90
	REPLACE ITEMS 1.21	53.80	1.5	80.70
	REPLACE ITEMS 1.22 - 25	53.80	4	215.20
	REPLACE ITEMS 1.26	53.80	0.5	26.90
	REPLACE ITEMS 1.27 - 1.28	53.80	0.5	26.90
	REPLACE ITEMS 1.29	53.80	0.5	26.90
			19.7	
2	<b>Additional Services</b>			
2.1	TRANSPORT CHARGES (SOR 8) (BILL UNDER MONTH END SOR BILLING)		2	
			<b>Labour Total:</b>	<b>\$ 1,194.36</b>
			<b>GRAND TOTAL :</b>	<b>\$ 14,242.56</b>

Contractor shall complete the entire repair within 4 working days upon quotation approved date.

Verification of Scope of Work					
Contractor QC		Vetted By:		Approved By:	
Name:	<b>Gan Hup Tiong</b>	Name:		Name:	
Date:	<b>17/5/18</b>	Date:		Date:	
Sign:		Sign:		Sign:	
Verification of Completed Repairs					
Contractor QC		Home Team QC / Fleet Manager / Appointed Surveyor		Home Team Contract / Fleet Manager	
Name:		Name:		Name:	
Date:		Date:		Date:	
Sign:		Sign:		Sign:	

All completed repairs must be verified by Home Team Contract Manager / Fleet Manager before payment can be made

*Rahul*  
*Hp 90010068*  
*3 days*  
*21/05/18 @ 1350*  
*Revert*  
*Resurvey by paint*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Scope Of Work  
Home Team Agency

SCOPE OF WORK


1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR :	Indeco Engineers Pte Ltd	VEH TYPE :	UNIT :	TP	Reference No. MHA/SPF/2018/05-0022A 1100004968
VEH NO :	TP94H	MC	REPAIR TYPE:	ACCIDENT	
VEH MAKE/MODEL:	YAMAHA XJ900P(M)		Mileage:		

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)	
<b>1 Scope Of Repairs</b>							
1.1	BOX DOCUMENT	690.00	1	18%	814.20	814.20	
1.2	BOX SIDE LH	1700.00	1	18%	2006.00	2006.00	
1.3	BOX SIDE RH	1700.00	1	18%	2006.00	2006.00	
1.4	STICKER SIDE BOX LH - SUPPLY BY AEMD		1	18%	0.00	0.00	
1.5	STICKER SIDE BOX RH - SUPPLY BY AEMD		1	18%	0.00	0.00	
1.6	LATCH (#20-J) WITH LOCK - S/STEEL	46.00	4	18%	54.28	217.12	
1.7	BRACKET FOOTREST REAR LH	70.00	1	18%	82.60	82.60	
1.8	LIGHT LED (L) 4 LED BLUE - CLEAR LENS	260.00	1	18%	306.80	306.80	
1.9	LIGHT LED (L) 4 LED RED - CLEAR LENS	260.00	1	18%	306.80	306.80	
1.10	COVER LED LIGHT (FOR 4 LED)	78.00	2	18%	92.04	184.08	
1.11	BRACKET LED LIGHT (50 MM)	15.00	2	18%	17.70	35.40	
1.12	BRACKET SIDE BOX	308.00	1	18%	363.44	363.44	
1.13	BRACKET SIGNAL LAMP REAR LH	193.40	1	18%	228.21	228.21	
1.14	BOLT REAR SIGNAL LAMP	48.00	2	18%	56.64	113.28	
1.15	CRASH BAR FRONT	550.00	1	18%	649.00	649.00	
1.16	CRASH BAR REAR LH	144.00	1	18%	169.92	169.92	
1.17	CRASH BAR REAR RH	144.00	1	18%	169.92	169.92	
1.18	FOOTREST FRONT LH	17.00	1	18%	20.06	20.06	
1.19	FOOTREST FRONT RH	17.00	1	18%	20.06	20.06	
1.20	RUBBER FOOTREST	13.00	1	18%	15.34	15.34	
1.21	PROTECTOR FRONT (LH -STK 21958) WITH SPRAY PAINTING POLICE LIVERY LINING	382.00	1	18%	450.76	450.76	
1.22	STAY COWLING FRONT	340.00	1	18%	401.20	401.20	
1.23	MID NUT PLASTIC (WINDSHIELD)	5.20	6	18%	6.14	36.82	
1.24	RIVET	2.00	6	18%	2.36	14.16	
1.25	SCREW (VISOR)	3.00	6	18%	3.54	21.24	
1.26	SIREN (CR)	3350.00	1	18%	3953.00	3953.00	
1.27	STAND MAIN	297.00	1	18%	350.46	350.46	
1.28	STOPPER MAINSTAND	5.20	1	18%	6.14	6.14	
1.29	STAND SIDE	90.00	1	18%	106.20	106.20	
<b>2 Additional Services</b>							
2.1	RIM SPORT FRONT	796.00	1	18%	939.28	939.28	
2.2	SEAL DUST FORK	14.00	2	18%	16.52	33.04	
2.3	SEAL OIL (25X40X5) SWINGING ARM	4.00	2	18%	4.72	9.44	
2.4	SEAL OIL (40X53X8) FORK	13.00	2	18%	15.34	30.68	
2.5	SHAFT PIVOT	18.70	1	18%	22.07	22.07	
2.6	SHAFT PIVOT	17.70	1	18%	20.89	20.89	
2.7	T-JOINT	126.90	1	18%	149.74	149.74	
2.8	TUBE INNER FORK	223.00	2	18%	263.14	526.28	
2.9	VALVE RIM	9.00	1	18%	10.62	10.62	
2.10	WASHER PLATE	2.00	6	18%	2.36	14.16	
2.11	OIL FORK (UNICORN) MR-15(M)	7.50	1	18%	8.85	8.85	
2.12	MIRROR LH	138.00	1	18%	162.84	162.84	
2.13	COLLAR	0.53	4	18%	0.63	2.50	
2.14	COLLAR	5.70	2	18%	6.73	13.45	
2.15	BRACKET UNDER FORK	255.00	1	18%	300.90	300.90	
2.16	BUSH FORK INNER (LOWER)	16.00	2	18%	18.88	37.76	
2.17	BUSH FORK INNER (UPPER)	12.50	2	18%	14.75	29.50	
2.18	CLIP TUBE INNER FORK	3.00	2	18%	3.54	7.08	
2.19	AXLE WHEEL FRONT	42.00	1	18%	49.56	49.56	
2.20	BALANCER HANDLE	21.00	1	18%	24.78	24.78	
2.21	BEARING	23.00	2	18%	27.14	54.28	
2.22	BEARING (B6203) WHEEL FRONT	20.00	2	18%	23.60	47.20	
2.23	BEARING STEERING CONE LOWER	58.00	1	18%	68.44	68.44	
2.24	BEARING STEERING CONE UPPER	48.00	1	18%	56.64	56.64	
2.25	GASKET SILENCER	14.00	1	18%	16.52	16.52	
2.26	LEVER CLUTCH	21.00	1	18%	24.78	24.78	
2.27	PLATE DISC BRAKE FRONT	223.00	1	18%	263.14	263.14	
2.28	PLATE NUMBER REAR (TP)	18.00	1	18%	21.24	21.24	
2.29	BOLT PLATE DISC BRAKE	2.60	6	18%	3.07	18.41	
2.30	BOLT	38.00	2	18%	44.84	89.68	
2.31	BOLT FLANGE	3.00	1	18%	3.54	3.54	
2.32	BOLT FLANGE	3.00	2	18%	3.54	7.08	
2.33	GROMMET	8.48	4	18%	10.01	40.03	
2.34	LENS SIGNAL FRONT LH	8.30	1	18%	9.79	9.79	
2.35	MOLE 4	15.00	1	18%	17.70	17.70	
2.36	MUFFLER LH	529.40	1	18%	624.69	624.69	
2.37	PANEL INNER	59.00	1	18%	69.62	69.62	
2.38	PEDAL GEAR (Include Mid Rubber Pedal Gear)	44.00	1	18%	51.92	51.92	
Remarks:					SPARE PARTS SUBJECT TO AVAILABILITY	Parts Total: \$	16,926.32

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
<b>1</b> Scope Of Repairs				
1.1	REPLACE ITEMS 1.1	53.80	1.5	80.70
1.2	REPLACE ITEMS 1.2	53.80	1.5	80.70
1.3	REPLACE ITEMS 1.3	53.80	1.5	80.70
1.4	REPLACE ITEMS 1.7	53.80	0.7	37.66
1.5	REPLACE ITEMS 1.8	53.80	1	53.80
1.6	REPLACE ITEMS 1.9	53.80	1	53.80
1.7	REPLACE ITEMS 1.11	53.80	1	53.80
1.8	REPLACE ITEMS 1.12	53.80	1	53.80
1.9	REPLACE ITEMS 1.13	53.80	2	107.60
1.10	REPLACE ITEMS 1.15	53.80	1.5	80.70
1.11	REPLACE ITEMS 1.16	53.80	0.5	26.90
1.12	REPLACE ITEMS 1.17	53.80	0.5	26.90
1.13	REPLACE ITEMS 1.18	53.80	0.5	26.90
1.14	REPLACE ITEMS 1.19	53.80	0.5	26.90
1.15	REPLACE ITEMS 1.21	53.80	1.5	80.70
1.16	REPLACE ITEMS 1.22 - 25	53.80	4	215.20
1.17	REPLACE ITEMS 1.26	53.80	0.5	26.90
1.18	REPLACE ITEMS 1.27 - 1.28	53.80	1	53.80
1.19	REPLACE ITEMS 1.29	53.80	0.5	26.90
<b>2</b> Additional Services				
2.1	TRANSPORT CHARGES (SOR 8) (BILL UNDER MONTH END SOR BILLING)		2	
2.2	REPLACE ITEMS 2.23	53.80	3	161.40
2.3	REPLACE ITEMS 2.26	53.80	0.5	26.90
2.4	REPLACE ITEMS 2.36	53.80	1	53.80
2.5	REPLACE ITEMS 2.37	53.80	2	107.60
2.6	REPLACE ITEMS 2.38	53.80	0.5	26.90
2.7	REPLACE ITEMS 2.27	53.80	0.7	37.66
2.8	REPLACE ITEMS 2.28	53.80	0.5	26.90
2.9	REPLACE ITEMS 2.1	53.80	1	53.80
2.10	REPLACE ITEMS 2.8	53.80	3	161.40
			Labour Total:	\$ 1,850.72
			<b>GRAND TOTAL :</b>	<b>\$ 18,777.04</b>

Contractor shall complete the entire repair within 6 working days upon quotation approved date.

Verification of Scope of Work					
Contractor QC		Vetted By:		Approved By:	
Name:	<b>Gan Hup Tiong</b>	Name:		Name:	
Date:	<b>16/9/19</b>	Date:		Date:	
Sign:		Sign:		Sign:	
Verification of Completed Repairs					
Contractor QC		Home Team QC / Fleet Manager / Appointed Surveyor		Home Team Contract / Fleet Manager	
Name:		Name:		Name:	
Date:		Date:		Date:	
Sign:		Sign:		Sign:	

All completed repairs must be verified by Home Team Contract Manager / Fleet Manager before payment can be made



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION Ref : CS/SPF18009218/R1rbe2

CONTRACT MANAGEMENT SECTION  
(SINGAPORE POLICE FORCE) 1 MOUNT  
PLEASANT ROAD BLK 8 OLD POLICE  
ACADEMYSINGAPORE 298333

Date : 03-12-2018



ATTN : PERRY HE

Code : SPF3

### 1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	TP 94H
Policy No.		Coverage (\$)	0.00
Claim No.	HOMSPFETQ17300218	Excess (\$)	0.00
Assign From	PERRY HE	Assign Date	17/05/2018

### 2. Vehicle Particulars & Condition

Make & Model	YAMAHA XJ900P (M)	c.c	892
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JYA4KM00000127632	Colour	MULTI COLOUR
Odometer	6876	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	120/70Z R17	METZELER	4 mm
L/H Front Tyre			mm
R/H Rear Tyre	150/70Z R17	METZELER	4 mm
L/H Rear Tyre			mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date		Inspection Date	21/05/2018
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410		

### 5a. Remarks

--



**Registration No. TP 94H**

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
<b>1</b>	<b>MATERIALS</b>					
1.1	BOX DOCUMENT	1	BENT	\$814.20	\$814.20	
1.2	BOX SIDE LH	1	CRACKED	\$2,006.00	\$2,006.00	
1.3	BOX SIDE RH	1	SCRATCHED	\$2,006.00	\$2,006.00	
1.4	STICKER SIDE BOX LH- SUPPLY BY AEMD	1	NECESSARY	\$0.00	\$0.00	
1.5	STICKER SIDE BOX RH- SUPPLY BY AEMD	1	NECESSARY	\$0.00	\$0.00	
1.6	LATCH(#20-J) WITH LOCK-S/STELL	4	UNCONFIRM	\$54.28	\$217.12	
1.7	BRACKET FOOTREST REAR LH	1	BROKEN	\$82.60	\$82.60	
1.8	LIGHT LED (JL)4 LED BLUE- CLEAR LENS	1	CRACKED	\$306.80	\$306.80	
1.9	LIGHT LED (JL)4 LED RED- CLEAR LENS	1	NOT NECESSARY	\$306.80		
1.10	COVER LED LIGHT (FOR 4 LED)	2	SCRATCHED	\$92.04	\$184.08	
1.11	BRACKET LED LIGHT (50MM)	2	NECESSARY	\$17.70	\$35.40	
1.12	BRACKET SIDE BOX	1	BENT	\$363.44	\$363.44	
1.13	BRACKET SIGNAL LAMP REAR LH	1	CRACKED	\$228.21	\$228.21	
1.14	BOLT REAR SIGNAL LAMP	2	NECESSARY	\$56.64	\$113.28	
1.15	CRASH BAR FRONT	1	BENT	\$649.00	\$649.00	
1.16	CRASH BAR REAR LH	1	MISSING	\$169.92	\$169.92	
1.17	CRASH BAR REAR RH	1	BENT	\$169.92	\$169.92	
1.18	FOOTREST FRONT LH	1	BROKEN	\$20.06	\$20.06	
1.19	FOOTREST FRONT RH	1	SCRATCHED	\$20.06	\$20.06	
1.20	RUBBER FOOTREST	1	MISSING	\$15.34	\$15.34	
1.21	PROTECTOR FRONT(LH-STK21958) WITH SPRAY PAINTING	1	SCRATCHED	\$450.76	\$450.76	
1.22	StAY COWLING FRONT	1	BENT	\$401.20	\$401.20	
1.23	MID NUT PLASTIC(WINDSHIELD)	6	NECESSARY	\$6.14	\$36.84	
1.24	RIVET	6	NECESSARY	\$2.36	\$14.16	
1.25	SCREW(VISOR)	6	NECESSARY	\$3.54	\$21.24	
1.26	SIREN(CR)	1	CRACKED	\$3,953.00	\$3,953.00	
1.27	STAND MAIN	1	REPAIR	\$350.40		

1.28	STOPPER MAINSTAND	1	MISSING	\$6.14	\$6.14	
1.29	STAND SIDE	1	BENT	\$106.20	\$106.20	
2	<b>ADDITIONAL SERVICES</b>					
2.1	RIM SPORT FRONT	1	BENT	\$939.28	\$939.28	
2.2	SEAL DUST FORK	2	LEAK	\$16.52	\$33.04	
2.3	SEAL OIL(25X40X5) SWINGING ARM	2	NECESSARY	\$4.72	\$9.44	
2.4	SEAL OIL(40X53X8) FORK	2	NECESSARY	\$15.34	\$30.68	
2.5	SHAFT PIVOT	1	UNCONFIRM	\$22.07	\$22.07	
2.6	SHAFT PIVOT	1	UNCONFIRM	\$20.89	\$20.89	
2.7	T-JOINT	1	UNCONFIRM	\$149.74	\$149.74	
2.8	TUBE INNER FORK	2	UNCONFIRM	\$263.14	\$526.28	
2.90	VALVE RIM	1	NECESSARY	\$10.62	\$10.62	
2.10	WASHER PLATE	6	UNCONFIRM	\$2.36	\$14.16	
2.11	OIL FORK(UNICORN) MR-15(M)	1	NECESSARY	\$8.85	\$8.85	
2.12	MIRROR LH	1	SCRATCHED	\$162.84	\$162.84	
2.13	COLLAR	4	UNCONFIRM	\$0.63	\$2.52	
2.14	COLLAR	2	UNCONFIRM	\$6.73	\$13.46	
2.15	BRACKET UNDER FORK	1	UNCONFIRM	\$300.90	\$300.90	
2.16	BUSH FORK INNER (LOWER)	2	UNCONFIRM	\$18.88	\$37.76	
2.17	BUSH FORK INNER (UPPER)	2	UNCONFIRM	\$14.75	\$29.50	
2.18	CLIP TUBE INNER FORK	2	UNCONFIRM	\$3.54	\$7.08	
2.19	AXLE WHEEL FRONT	1	NECESSARY	\$49.56	\$49.56	
2.20	BALANCE HANDLE	1	SCRATCHED	\$24.78	\$24.78	
2.21	BEARING	2	UNCONFIRM	\$27.14	\$54.28	
2.22	BEARING(B6203) WHEEL FRONT	2	UNCONFIRM	\$23.60	\$47.20	
2.23	BEARING STEERING CONE LOWER	1	UNCONFIRM	\$68.44	\$68.44	
2.24	GASKET SILENCER	1	NECESSARY	\$56.64	\$56.64	
2.25	LEVER CLUTCH	1	SCRATCHED	\$16.52	\$16.52	
2.26	PLATE DISC BRAKE FRONT	1	SCRATCHED	\$24.78	\$24.78	
2.27	PLATE NUMBER REAR(TP)	1	BENT	\$263.14	\$263.14	
2.28	BOLT PLATE DISC BRAKE	1	NECESSARY	\$21.24	\$21.24	
2.29	BOLT	6	NECESSARY	\$3.07	\$18.42	
2.3	BOLT FLANGE	2	NECESSARY	\$44.87	\$89.74	
2.31	BOLT FLANGE	1	NECESSARY	\$3.54	\$3.54	
2.32	GROMMET	2	NECESSARY	\$3.54	\$7.08	
2.33	LENS SIGNAL FRONT LH	4	SCRATCHED	\$10.01	\$40.04	
2.34	MID RUBBER PEDAL GEAR	1	CUT	\$9.79	\$9.79	
2.35	MOLE 4	1	UNCONFIRM	\$17.70	\$17.70	
2.36	MUFFLER LH	1	BENT	\$624.69	\$624.69	

2.37	PANEL INNER	1	SCRATCHED	\$69.62	\$69.62	
2.38	PEDAL GEAR	1	BENT	\$51.92	\$51.92	
<b>2</b>						
	REPLACE ITEM 1.1					1.5
	REPLACE ITEM 1.2					1.5
	REPLACE ITEM 1.3					1.5
	REPLACE ITEM 1.7					0.7
	REPLACE ITEM 1.8					1
	REPLACE ITEM 1.9					
	REPLACE ITEM 1.11					1
	REPLACE ITEM 1.12					1
	REPLACE ITEM 1.13					2
	REPLACE ITEM 1.15					1.5
	REPLACE ITEM 1.16					0.5
	REPLACE ITEM 1.17					
	REPLACE ITEM 1.18					0.5
	REPLACE ITEM 1.19					
	REPLACE ITEM 1.21					1.5
	REPLACE ITEM 1.22 - 1.25					4
	REPLACE ITEM 1.26					0.5
	REPLACE ITEM 1.27 - 1.28					0.5
	REPLACE ITEM 1.29					0.5
	REPLACE ITEM 2.23					3
	REPLACE ITEM 2.26					0.5
	REPLACE ITEM 2.36					1
	REPLACE ITEM 2.37					2
	REPLACE ITEM 2.38					0.5
	REPLACE ITEM 2.27					0.7
	REPLACE ITEM 2.28					0.5
	REPLACE ITEM 2.10					1
	REPLACE ITEM 2.80					3
<b>COSTING</b>		<b>TOTAL PARTS COST</b>			\$16,269.20	
		<b>TOTAL MAN-HOUR</b>				<b>31.9</b>

Registration No. TP 94H

**Registration No. TP 94H**

Vehicle Inspected By

**MOHD. RASUL BIN MOHD YUNUS**  
*AMSOE, AMIRTE, AMSAE-A, M.MATAI*  
*Automotive Assessor*

**ADRIAN LING WAI PING**  
*B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI*  
*Licensed Appraiser*

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.