

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YM 5565P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SET FRONT CABIN ASSY }	DISTORTED	45,873.80	45,873.80
1	FRONT BUMPER	DISTORTED	1,836.44	1,836.44
1	AIRCON CONDENSER	BENT / PUNCTURE	586.70	586.70
1	AIRCON BLOWER ASSY }		1,171.91	-
1	AIRCON EVAPORATOR UNIT }		1,485.99	-
1	AIRCON COOLING COIL ASSY }		641.90	-
1	PASSENGER SEAT LH }		1,899.72	-
1	PASSENGER CENTRE SEAT }		877.25	-
1	FRONT NUMBER PLATE	TO REPAIR SEE LABOUR	30.00	-
	LESS 25% DISCOUNT		-13,600.93	-12,074.24
			40,802.78	36,222.70
	<u>LABOUR</u>			
	TOWING CHARGE.		150.00	120.00
	LABOUR TO DISMANTLE & RENEW CABIN & ALL AFFECTED AREA. TO DISMANTLE & REPAIR FRONT PORTION OF AFFECTED AREA. INCLUSIVE OF THE REPAIR OF FRONT NUMBER PLATE.		4,500.00	3,000.00
	LABOUR TO RENEW CARGO BOX, FRONT SIDE PANEL.		1,500.00	1,200.00
	LABOUR TO REMOVE & REFIT AIRCON PARTS & TOP UP AIRCON GAS.		280.00	100.00
	LABOUR TO DISMANTLE & RENEW ALL WIRING & REFOCUS.		120.00	30.00
	LABOUR TO REMOVE & REFIT IU BRACKET.		30.00	20.00
	TO SPRAY & PAINTING WHOLE CABIN & BOX PANEL & ALL ACCIDENT AFFECTED DENTED PARTS.		2,000.00	1,100.00
			8,580.00	5,570.00
	GRAND TOTAL		49,382.78	41,792.70

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		28,000.00
LESS EXCESS		-3,000.00
NETT LIABILITY		25,000.00

Report Ref No. CS/EQI18009220/Usbe2





Report Ref No. CS/EQI18009220/Usbe2

CHUA KANG SENG
Licensed Appraiser