

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG18009226/T1PB3S2**Date:** 12/12/2018REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100479286
Claimant Vehicle No :	PA5859L	Insured Vehicle No :	SLF3592P
Date of Loss:	16/05/2018	Nature of Claim:	TP
		Claim No:	1711162906SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PA5859L	Engine No:	2KD1380381
Make & Model:	TOYOTA HIACE, 2.0 (M)	Chassis No:	KDH2220011174
Reg. Date:	13/01/2006 (Man. Year: 2005)	Odometer:	544202 km
Colour:	Grey		
Engine Capacity:	2500 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,716.25	6,560.72	4,155.53	38.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,900.00	1,660.00	1,240.00	42.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,616.25	8,220.72	5,395.53	39.63
Approved Total (Overridden) (S\$)		6,550.00		
Nett Amount (S\$)	13,616.25	6,550.00	7,066.25	51.90
+ Loss of Use (8.0 x S\$130.00/day) (S\$)		1,040.00		
Nett Liability (S\$)		7,590.00		

INSPECTION

Date of Assignment:	21/05/2018	
Date Inspected:	21/05/2018 Inspected At:	Sin Hup Lee Service Co (HQ) Blk 1005 Bukit Merah Lane 2, #01-209 Alexandra Village Industrial Estate Singapore 159761
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEAD LAMP LH	Cracked	479.80 FL	*479.80 FL
2	1		*HEAD LAMP CLIP	Necessary	21.30 FL	*21.30 FL
3	1		*FRONT GRILLE	Cracked	398.50 FL	*398.50 FL
4	1		*FRONT GRILLE CLIP 8pcs	Necessary	40.60 FL	*40.60 FL
5	1		*BONNET	Bent	553.20 FL	*553.20 FL
6	1		*FRONT BUMPER	Cracked	513.20 FL	*513.20 FL
7	1		*FRONT BUMPER TOW COVER	Missing	43.60 FL	*43.60 FL
8	1		*FRONT BUMPER REINFORCEMENT	Bent	474.20 FL	*474.20 FL
9	1		*FRONT BUMPER BRACKET L+R	N/s Cracked/O/s Not Necessary	197.40 FL	*98.70 FL
10	1		*FRONT BUMPER FOG LIGHT COVER LH	Cracked	85.50 FL	*85.50 FL
11	10		*FRONT BUMPER CLIP	Necessary	40.80 FL	*40.80 FL
12	1		*FRONT BUMPER SIDE BRACKET LH	Distorted	171.20 FL	*171.20 FL
13	1		*RADIATOR	Bent	1,377.60 FL	*1,377.60 FL
14	1		*RADIATOR LOWER BRACKET	Bent	263.70 FL	*263.70 FL
15	1		*RADIATOR FAN ASSY	Cracked	578.20 FL	*578.20 FL
16	1		*WIRE HARNESS ASSEMBLY }	Torn	3,169.50 FL	*1,500.00 FL
17	1		*WIRE HARNESS LH DOOR }		2,976.10 FL	*- FL
18	1		*FRONT DOOR LH	Bent	1,574.20 FL	*1,574.20 FL
19	1		*FRONT PILLAR LH	Repair	796.40 FL	*- FL
20	1		*FRONT BUMPER CHROME LH	Cracked	200.00 FS	*200.00 FS
21	1		*FRONT BUMPER SENSOR	Cracked	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	14,155.00	8,614.30
- List Item Discount on L Items 25.00/25.00% (S\$)	3,438.75	2,053.58
Total Parts (S\$)	10,716.25	6,560.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT-WELD FRONT DOOR PILLAR LH. TO REPAIR FRONT PANEL LH, FLOOR PANEL LH, STEP PANEL LH, REMOVE AND RE-FIX DAMAGED PARTS, STRAIGHTEN AND REALIGN AFFECTED AREAS.	New	1,120.00	700.00
2	TO SPRAY AFFECTED AREAS.	New	900.00	600.00
3	TO REMOVE AND RE-FIX REAR DASHBOARD SIDE COVER, GLOVE BOX AND OTHER ATTACHMENT PARTS.	New	200.00	0.00
4	TO REMOVE AND RE-FIX DOOR MECHANISM. CHECK & TEST POWER WINDOW AND CENTRE LOCKING SYSTEM.	New	100.00	60.00
5	TO REMOVE AND RE-FIX WIRE HARNESS CLAIM CLIP AND OTHER ATTACHMENT PARTS.	New	200.00	100.00
6	TO REMOVE AND RE-FIX RADIATOR ELECTRICAL FORM & HOSE PIPE.	New	100.00	60.00
7	TO RUSTPROOF AFFECTED AREAS.	New	80.00	40.00
8	TO CHECK BODY STRUCTURE AND CHASSIS ALIGNMENT.	New	200.00	100.00
			Gross Labour Cost (\$)	2,900.00
				1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >