

新合利服務公司

**Sin Hup Lee Service Co.**

Block 1005 Bukit Merah Lane2 #01-20

Singapore 159761

Tel: 6278 2482 Fax: 6271 9802

Email: sinhuplee@gmail.com

Reg. No. 083995/00E

Attn: Motor Claim Department  
AIG Asia Pacific Insurance Pte. Ltd  
AIG Building  
78 Shenton Way #07-16  
Singapore 079120

Ng Say Choo  
c/o Sin Hup Lee Service Co.  
Block 1005 Bukit Merah Lane 2 #01-20  
Singapore 159761

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

20 May 2018  
Caprienne 62563561  
Tanjilur 97445749  
21/5/18 @ 115 pm.  
- WP.  
Cunpsam  
Resurvey after paint  
sur @ lkkauto.com  
6 days

Dear Sir/Ms,

**Re: Road Traffic on 16 May 2018 along Bukit Batok West Ave 8, involving vehicle SLF3592P / PA5859L**

**Quotation for Repair Vehicle No: PA5859L, Toyota Hiace (Third Party Claim)**

Quantity	List Item	Price
1	Head Lamp LH	\$ car 479.80
1	Head Lamp Clip	\$ rec 21.30
1	Front Grille	\$ car 398.50
1	Front Grille Clip	\$ rec 40.60
8	Front Grille Clip	\$ bt 553.20
1	Bonnet	\$ car 513.20
1	Front Bumper	\$ mis 43.60
1	Front Bumper Tow Cover	\$ bt 474.20
1	Front Bumper Reinforcement	\$ 197.40
2	Front Bumper Bracket L+R	\$ car 85.50
1	Front Bumper Fog Light Cover LH	\$ car 40.80
10	Front Bumper Clip	\$ dis 171.20
1	Front Bumper Side Bracket LH	\$ bt 1,377.60
1	Radiator	

1	Radiator Lower Bracket	\$	bt	263.70
1	Radiator Fan Assy <i>&lt;7 photo</i>	\$	?	578.20
1	Wire Harness Assembly	\$	1500	3,169.50
1	Wire Harness LH Door	\$		2,976.10
1	Front Door LH	\$	bt	1,574.20
1	Front Pillar LH	\$	Ry	796.40
		\$		13,755.00
		\$		3,438.75
		\$		10,316.25

Less 25%

	<b>NETT ITEM</b>			
1	Front Bumper <i>Chrome</i> LH	\$	cr	200.00
1	Front Bumper Sensor	\$	cr	200.00

**Labour**

1	To cut-weld Front Door Pillar LH. To repair Front Panel LH, Floor Panel LH, Step Panel LH, remove and re-fix damaged parts, straighten and realign affected areas.	\$	700	1,120.00
2	To spray affected areas	\$	600	900.00
3	To remove and re-fix Rear Dashboard Side Cover, Glove Box and other attachment parts	\$	photo ?	200.00
4	To remove and re-fix Door Mechanism. Check & test Power Window and Centre Locking System	\$	60	100.00
5	To remove and re-fix Wire Harness Claim Clip and other attachment parts	\$	100	200.00
6	To remove and re-fix Radiator Electric Form & Hose Pipe	\$	60	100.00
7	To rustproof affected areas	\$	40	80.00
8	To check body structure and chassis alignment	\$	100	200.00

**Total Amount** \$ 13,616.25

Kindly arrange your surveyor to survey my vehicle.  
 We look forward to hear from you soon.  
 Thank you.

Yours Faithfully  
 Mr Wong  
 81122116