

SS REC BY: REF: (53/SPFI 7019 246 / T110-1) Pre: \$ 2800 (LS)

ASSIGNMENT (Office)

From (Person): Abdul Rahman of SPF Date/Time: 21/06/2018

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJS 9788 H Insured: QX 555M

at Workshop m/s: One Zone Autocare Tel: 62520118 / 92308294

of 7 Soon Lee Street #01-05 I space Building (G27 608)

Policy No: Claim No: AEMD/105/009/2017/QX 555M

Sum Insured: Excess:

Make of Veh: D.O.A 29/09/17

(Client's Record):

CA / REV / REP. / REV 24 HRS 'wp'

Date/Time: 6/10/17 12:33 pm Person Contacted: Mr. ERIC Vehicle: IN OUT

Date/Time	Action/Instruction	Estimate	Do Not Finalize
	Eric say vehicle already start repair, will arrange survey after repair.		
	SJS 9788 H-X		
	QX 555M-009/AIG 11022356/1724XX-D.O.A: 29/10/11		

25/5/18 Submit LS \$ 1050, 2 days
(Red 1750, 6390)

\$ 1500 - \$ 2500.

URGENT

RECEIVED 25 MAY 2018

14/12/19 To re-open indicate upper range

Upper Range \$1500 - \$3500 (EST)

[Signature]
25/5/2018

27/2/19 Pls pass to typist

28/2/19 1st doc 1/6/18, reopen ref only

Survey report 280

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bel. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / FR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum. Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SJS 9788H

Yr Regn: 2009 / Sep

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mitsubishi Lancer 1.6 CC 1584

Colour: Black A/C: Insured / Std / NI / NA

Sp Reading: A T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JMY3NC S3 A94 004735.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / STD / STD A/Rim or

Tyre Size: F: 18 225/45R17

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

6

mm

Rear

6

mm

R/Bal:

R/Bal:

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

D.O.I.

9/10/17 5.52pm

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

F + N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11/5.

Submit PRS report.

RECEIVED 11 MAY 2018

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

S + PRS, SI

Photos

Other

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

PRS

Lump Sum / I.B.I. (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 9788H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER ASSY	GRAZED / WARPED	695.00	695.00
1	FRONT BUMPER LEFT BRACKET	BENT / NECESSARY	58.00	58.00
1	FRONT BUMPER LEFT RETAINER	BENT / NECESSARY	59.00	59.00
1	FRONT LEFT HEADLAMP	NOT NECESSARY	619.00	-
2	FRONT GRILLE ASSY	NOT NECESSARY	215.00	-
1	FRONT GRILLE EMBLEM	NOT NECESSARY	48.00	-
1	FRONT BONNET ASSY	TO REPAIR SEE LABOUR	789.00	-
	LESS 10% DISCOUNT		-248.30	-81.20
			2,234.70	730.80
SPECIAL NETT ITEMS				
10	FRONT BUMPER CLIPS (SN)	WARPED	50.00	30.00
1	FRONT BUMPER LOWER SPOILER (SN)	TO REPAIR SEE LABOUR	680.00	-
10	FRONT BUMPER LOWER SPOILER CLIPS (SN)	NECESSARY	40.00	30.00
1	FRONT BUMPER LOWER SPOILER SEALANT (SN)	NECESSARY	60.00	40.00
			830.00	100.00
LABOUR				
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN FRONT LEFT AND FRONT PORTION AND REPLACE FRONT LEFT AND FRONT DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT BONNET ASSY AND FRONT BUMPER LOWER SPOILER.		600.00	250.00
	TO PUTTY AND SPRAY PAINTING FRONT LEFT AND FRONT PORTION.		600.00	250.00
	TO CHECK WIRING AND FOCUS FRONT HEADLAMP.		50.00	20.00
	TO APPLY ANTI RUST PROOFING TO FRONT LEFT AFFECTED AREA.	NOT NECESSARY	100.00	-
			-	-
			-	-
			-	-
			1,350.00	520.00
GRAND TOTAL			4,414.70	1,350.80



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,050.00
---	--	--	----------

Report Ref No. CS3/SPF17019246/T1vbs2-1

THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500.00 - \$2,500.00 (EST)

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.