SS REC BY	A 1	24
	ASSIGNMENT (Office)	0
rom (Person)	a) About Rahman of SPF Date/Time 31062018	
stimated Cos	Bill to:	-
o Inspect Ve	STIP RESTOR RESTEVATING MYTCS  Wehicle No. SJS 9788 H Insured: QX 655 M	
a Workshop i	on he strut # 01-05 I space Building (627 608)	94
Policy No:	Claim No AEMD/105/009/2017/Qx555	M
Sum Insured	Excess:	-
Make of Veh.		
2000 A 2 1110 A		
El Control	6/10/17 12.33 pm Person Contacted Mr. GRIC Volume 12:00T	
	Action/Instruction ( ) Estimate Ou Not Findize	
El Control		
8	Eric Say vehicle aready start repair, will arrange survey after repair.	
8	Action/Instruction ( X) Estimate Do Not Principle  Eric Say vibrate aready start repair, will arrange survey after repoir.  SJS 9788 H X  QX 555M-cc7/AIG 11622356/MIMXX-6-0-A; 28/10/11	
Date/Time	Action/Instruction ( X) Estimate On Not Findize  Eric Say vibrate aready stant repair, will arrange survey after repoir.  S15 9788 H.X	NT

RECEIVED 2 5 MAY 2018

52/2/2018.

Surey report 280

# ASSIGNMENT

From: Date:		Velt No.	8.75	778871	Yr Regn:	2009	Sep
Estimated Cost		0			erry / Taxi / Prim	e Mover /	
OD / TP / WS / TP RES / OD RES / EVA / INV / MV			/Trailer or				
To Inspect Vehicle No:		Make:	4. Kubis	hi Lauce	w 1.6	cc / 1	184
at Workshop m/s		Colour	Blac			red / Std / !	14
of		Sp Reading	P		T/Radio: Insu	red / Std /	NI/NA
Insured		Eng/No:					
Policy No.		C/No:	Time	43NCS	3 494 C	00 47	30
Claims No.		Table 1	/	Poor / Burnt	The state of the s		7.
Sum Insured Excess:			~	ed / Leaked /			
(Client's Record)		The same of the same of	0	ned / Leaked /			
Make of Veh:		SACROPHICS CONS.	V -	TD A/Rim or			
		Tyre Size:	F:	410	noly	mor	-
(Palicy Condition)	M	The one	R:	109	2 -	, ,	
Remark: The veh had commenced its	N/S O/S	PS DINTE		V / ES / 1 17 A	MIC / OHTSU /	PIR / SHM	
repair at the time of inspection.		TOYOTYO		TITOTLEM	and rolling	. IIV JOIN	
Bal. or Market Value:		Front			Rear		
IDAC Accident Rport: Consistent? : Yes	or No	R/Bal.	6	mm	R/Bal.	6	mm
GIA / PR Seen: Consistent? : Yes		L/Bal.	6	mm	UBal.	6-	mm
Est Repairs: days Res.: Yes		D.O.A.			D.O.I.	9/10/1	1.
Lum Sum: % 3 Val. Yes		Survey held	at			1.11	5.52p
Lan Garage		E-Volumet Change	_	Rear / O/S	I N/S / U/C / F	Roofton or	
CA / REV / REP. / 24 HRS	Vehicle: IN / OUT	010.010011	agoo, rite r	e+N		in derived	
Date: Person Contacted:	Venicle: III / COT	The U/C	/ Chassis I	1 1 1	y Structure affer	cted due to	collision.
Date / Time   Action / Instruction   LILS .	IAY 2018						
Date/Time, File Pass to? : Preli. Report		Days Of Re	pair:				
1) : Final Report Date/Time, File Return to?		Resurvey N			Survey Fee Transportation		D
3	Add Fee	: Site	Insp (\$		)S+RS	SI	
	-	Inter	rview (\$		) Photos		
Report Format : PRS	To the second	Tec	n. Inys (\$		) Others		
Lump Sum / I.B.I: (S	)	T Wei	ekend (\$		,		
					TOTAL		

#### Catherine Chong (LKK Auto)

From: Abdul Rahman MOHAMAD SALIM (SPF)

<Abdul\_Rahman\_Mohamad\_Salim@spf.gov.sg>

Sent: Monday, 21 May, 2018 2:42 PM
To: Catherine Chong (LKK Auto)

Cc: 'Olivia Lau'; Rosalyn TAN (SPF)

Subject: FW: PENDING REPORT OF SJS9788H ASSIGNED ON 5 OCT 2017

Attachments: SJS9788H - Appraisal & Photos.pdf

Our Ref: AEMD/105/009/2017/136

Dear Cath,

We spoke earlier wrt Invoice CS3/SPF17019246/T1bs2 dated 16 May 2018 which is incomplete.

As requested, please see attached independent appraisal and photos for your reference.

Regards.

NB: URGENT basis.

Abdul Rahman (Mr)
Accident Claims Officer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4840 | FAX: (65) 6478 4848



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Abdul Rahman MOHAMAD SALIM (SPF)

Sent: Tuesday, 3 April 2018 10:05 AM

To: olivialau@lkkauto.com

Cc: Rosalyn TAN (SPF) <Rosalyn\_TAN@spf.gov.sg>; Frankie THAY (SPF) <Frankie\_THAY@spf.gov.sg>

Subject: PENDING REPORT OF SJS9788H ASSIGNED ON 5 OCT 2017

Our Ref: AEMD/105/009/2017/136

Dear Olivia,

We refer to your assignment of 5 OCT 2017 which is still pending. (Attached refer).

Please expedite as Solicitors has reminded ACS on proposal for settlement.

#### Regards

Abdul Rahman (Mr)
Accident Claims Officer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4840 | FAX: (65) 6478 4848





WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



# VEHICLE DAMAGE INSPECTION REPORT

Our Ref:

581/TP/2017

Date: 20/10/2017

REFERENCE

Date of loss:

29/9/2017

Claimant:

Lim Chin Thong Sean

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SJS9788H

17/9/2009

Reg date: Colour:

Type:

Black

Type of Claims:

Motor Car

Third Party

Make &

Model

Engine No:

JMYSNCS3A9U004733 Chassis No: Odometer No: N.A

Engine Cap:

1584cc

Mitsubishi

Lancer 1.6 GLX

4G18KC7167

CONDITION OF VEHICLE AT THE TIME OF SURVEY

(STATIC ONLY)

General Condition: Good

Steering:

Good

Engine Modification: Nil

Paint work:

Good

Handbrake: Footbrake:

Good Good Pre-accident

Damage:

Nil

CONDITION OF TYRES

Front Left Size:

Continental 195/60R15 70%

Front Right Size: Rear Right Size:

Continental 195/60R15 70% Continental 195/60R15 70%

Continental 195/60R15 70% Rear Left Size: The above percentages represent the remaining life of the twe threads

COST OF REPAIRS

Parts

Labour

Calculated Cost (S\$):

Repairer SS

Adjuster S\$

2,354.60 3,064.70 S 1,110.00 1.350.00 3,464.60 4,414.70

Recommended Lump Sum Repair Cost (SS):

Date of Assignment:

2/10/2017

Date Inspected:

Est. repair Period:

2/10/2017 05 days

2,800.00

Inspected At: One Zone Autocare

No 7 Soon Lee Street

Ispace Building #01-05 Singapore 627608


SINCERE APPRAISAL SERVICES Co.Reg no. 53159958B

S

60 Paya Lebar Road #07-41 Paya Lebar Square Singapore 409051 Tel: 6636-4628 Fax: 6636-4638 E-mail: sincereappraisal@gmail.com

### POINT OF IMPACT

Damaged at the left hand front portion



## BRIEF CIRCUMSTANCES OF ACCIDENT

The Insured's vehicle collided onto the Third Party's vehicle at the car park of Bedok North Street 3, Block 539.

# GENERAL DESCRIPTION OF DAMAGES

Our visual inspection of the vehicle revealed that the damages noted are at the left hand front portion.

### SPECIAL REMARKS

We have inspected the actual damages found on the vehicle and recommend the replacement of parts and repairs accordingly. The estimated repair cost is \$4,414.70. The repairer has agreed to undertake the repairs at our adjusted lump sum amount of \$2,800.

We have not authorised the repair. Under normal circumstances, estimated 05 working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.



Automotive Appraiser: Dave Chang

Please note that this report is solely based on our findings at the time and place of inspection. This inspection has been carried out to our best knowledge and ability. Any other liability is hereby excluded.

## ANNEX A

## REPAIR DETAILS

Recommended	Parts
Recommended	Lauts

1000		nucu rans	Condition		pairer's mount		ljuster's Amount
No	Qty	Description	grazed/warped	S	695.00	\$	695.00 ~
1	1	Front bumper assy	bent/necessary	5	58.00	5	58.00~
2	1	Front bumper left bracket	J. C.	S	59.00	S	59.00
3	1	Front bumper left retainer	bent/necessary	5	619.00	S	619.00 XUB NA
4	1	Front left headlamp	bent	\$	215.00	S	215.00 XMB NA
5	2	Front grille assy	necessary	2	48.00	S	48.00 MB NA
6	1	Front grille emblem	necessary	5	789.00	S	
7	1	Front bonnet assy	repair	5	2,483.00	S	1,694.00
			8/2	9	248.30	\$	169.40
		Less 10%	730.80	\$	2,234.70	\$	1.524.60
		Special Nett Items				2007	*0.00.20
1	10	Front bumper clips	warped	\$	50.00	\$	50.00 30
2	1	Front bumper lower spoiler	warped/necessary	S	680.00	\$	680.00 ₹≫
	10		necessary	\$	40.00	5	40.00 30
3	1.	Front bumper lower spoiler sealant	necessary	S	60.00	\$	60.00 40
		Trom camper to the		\$	830.00	\$	830.00
		Total parts		s	3,064.70	s	2,354.60

### ANNEX B

### REPAIR DETAILS

Recommended Labour

			Repairer's Amount		djuster's Amount
No	Description  Description from left and	5	600.00	8	500.00 250
	Labour for panel beating, cut, weld, straighten front left and front portion and replace front left and front damaged parts.	\$	600.00	\$	500.00 250
2	To putty and spray painting front left and front portion.	5	50.00	\$	30.00 20
3	To check wiring and focus front headlamp.  To apply anti rust proofing to front left affected area.	S	100.00	\$	80.00 × ~ ∽
+	Total labour:	S	1,350.00	S	1,110.00 520

#### ANNEX C

1/5\$ 1050

## REPAIR DETAILS

Adjusted Repair Cost

		epairer's Amount	Adjuster's Amount		
Total parts :	S	3,064.70	S	2,354.60	
Total labour :		1,350.00	S	1,110.00	
Total repair cost :		4,414.70	S	3,464.60	

	5	2,800.00
	3	2,000.00
Adjusted Repair Cost (Lump Sum Repair)		



#### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des	Experts En Automobile
---	-----------------------

Ref: CS3/SPF17019246/T1vbs2-1 AUTOMOTIVE ENGINEERING & MGT DIVISION

ACCIDENT CLAIM SECTION (SINGAPORE POLICE

FORCE)1 MOUNT PLEASANT ROAD BLK 8 OLD Date: 25-05-2018



		NGAPORE 298333	Code: SPF	1 11 11 11 11 11 11 11 11 11 11 11 11 1
	N: ABDUL RAHMA		500000000000000000000000000000000000000	
1.			:- THIRD PARTY CLA	
	Insured Veh.	QX 555M	Veh. Inspected	SJS 9788H
	Policy No.		Coverage (\$)	0.00
	Claim No.	AEMD/105/009/2017/QX555M	Excess (\$)	0.00
	Assign From	ABDUL RAHMAN	Assign Date	21/05/2018
2.		Vehicle Parti	iculars & Condition	
	Make & Model	MITSUBISHI LANCER 1.6	c.c	1584
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	JMYSNCS3A9U004733	Colour	BLACK
	Odometer	5	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD	3.10	
3.		Condit	ions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	225/45R17	BRIDGESTONE	6 mm
	L/H Front Tyre	225/45R17	BRIDGESTONE	6 mm
	R/H Rear Tyre	225/45R17	BRIDGESTONE	6 mm
	L/H Rear Tyre	225/45R17	BRIDGESTONE	6 mm
4.		Descript	ion of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE FR	T N/S PORTION.	
	DAMAGES SEE D	ETAILS		
5.			al Information	
	Accident Date	29/09/2017	Inspection Date	09/10/2017
	Survey held at	ONE ZONE AUTOCARE	Management of the last	TANKA PARENCE SECTION AND ADMINISTRATION AND ADMINI
	TO CONTRACT OF A PROPERTY OF A	7 SOON LEE STREET #01-05	ISPACE BUILDING SING	APORE 627608
5a.			Remarks	
	A)THE INSPECTION	ON WAS CONDUCTED ON A"WI	THOUT PREJUDICE" BAS	SIS. SED REPAIRS.
5b.		Estimate	Days of Repair	t de la companya de l
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	2 Working Da	ys



#### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

#### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 9788H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS		200 30040	05-95
1	FRONT BUMPER ASSY	GRAZED / WARPED	695.00	695.00
1	FRONT BUMPER LEFT BRACKET	BENT / NECESSARY	58.00	58.00
1	FRONT BUMPER LEFT RETAINER	BENT / NECESSARY	59.00	59.00
1	FRONT LEFT HEADLAMP	NOT NECESSARY	619.00	0.
2	FRONT GRILLE ASSY	NOT NECESSARY	215.00	8
1	FRONT GRILLE EMBLEM	NOT NECESSARY	48.00	123
1	FRONT BONNET ASSY	TO REPAIR SEE LABOUR	789.00	15
	LESS 10% DISCOUNT		-248.30	-81.20
	10.0 miles		2,234.70	730.80
	SPECIAL NETT ITEMS	1		
10	FRONT BUMPER CLIPS (SN)	WARPED	50.00	30.00
1	FRONT BUMPER LOWER SPOILER (SN)	TO REPAIR SEE	680.00	19
10	FRONT BUMPER LOWER SPOILER CLIPS (SN)	NECESSARY	40.00	30.00
1	FRONT BUMPER LOWER SPOILER SEALANT (SN)	NECESSARY	60.00	40.00
			830.00	100.00
	LABOUR	1		
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN FRONT LEFT AND FRONT PORTION AND REPLACE FRONT LEFT AND FRONT DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT BONNET ASSY AND FRONT BUMPER LOWER SPOILER.		600.00	250.00
	TO PUTTY AND SPRAY PAINTING FRONT LEFT AND FRONT PORTION.		600.00	250.00
	TO CHECK WIRING AND FOCUS FRONT HEADLAMP.		50.00	20.00
	TO APPLY ANTI RUST PROOFING TO FRONT LEFT AFFECTED AREA.	NOT NECESSARY	100.00	33
			100	199
			85	
				59
			1,350.00	200409,04501
	GRAND TOTAL		4,414.70	1,350.80



Page No.: 2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	1,	050.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS3/SPF17019246/T1vbs2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

**Automotive Assessor** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.