

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III18009252/REA3Q2**Date:** 25/02/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	M485742/02
<b>Claimant Vehicle No :</b>	SJL9923X	<b>Insured Vehicle No :</b>	PC3989Y
Date of Loss:	16/05/2018	Nature of Claim:	TP
		Claim No:	MC2018/2414

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJL9923X</b>	Engine No:	R18A12805832
Make & Model:	HONDA STREAM, 1.8 L (A)	Chassis No:	JHMRN68408S205833
Reg. Date:	18/12/2008 (Man. Year: 2008)	Odometer:	263326 km
Colour:	Grey		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Falken 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Falken 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,803.50	96.00	1,707.50	94.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	720.00	1,180.00	62.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,703.50</b>	<b>816.00</b>	<b>2,887.50</b>	<b>77.97</b>
<b>+ GST 7.00/7.00% (S\$)</b>	259.25	57.12	202.13	77.97
<b>Nett Amount (S\$)</b>	<b>3,962.75</b>	<b>873.12</b>	<b>3,089.63</b>	<b>77.97</b>
<b>+ Loss of Use (3.0 x S\$65.00/day) (S\$)</b>		195.00		
		(S\$)	1,068.12	
<b>Liabe Amount (50.00%) (S\$)</b>		<b>534.06</b>		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>541.51</b>		
<b>Global Sum Settlement (S\$)</b>		<b>550.00</b>		

INSPECTION

Date of Assignment:	21/05/2018		
Date Inspected:	21/05/2018	Inspected At:	Allswell Motor Traders (HQ) 25 Defu Lane 9 Singapore 539266
Estimated Period of Repair:	3.0 days		

**Adjuster:** MOHD RASUL**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 30 Mar 2021)
<b>Parts:</b>	M1-MPV	HONDA STREAM 1.8 L (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJL9923X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,098.00 F	*- FL
2	1		*LH SIDE FENDER	Repair	591.00 F	*- FL
3	1		*LH HEADLAMP BOTTOM BRACKET	Cracked	59.60 F	*59.60 FL
4	1		*LH RETAINER	Cracked	32.90 F	*32.90 FL
5	2		*CLIPS	Necessary	22.00 FS	*22.00 FS
					<b>Sub Total (\$\$)</b>	<b>1,803.50</b>
					<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>	<b>0.00</b>
					<b>Total Parts (\$\$)</b>	<b>1,803.50</b>
						<b>96.00</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	DISMANTLE /ASSEMBLY FRONT BUMPER LH FENDER	New	160.00	0.00
2	ADJUST AND BUSH OUT LH HEADLAMP IN POSITION	New	160.00	30.00
3	PUTTY /SAND PAPER/GUIND OF FRONT BUMPER /LH FENDER	New	460.00	40.00
4	SPRAY PAINTING OF FRONT BUMPER /LH FENDER	New	660.00	400.00
5	PANEL BEATING OF LH FENDER FRONT BUMPER	New	460.00	250.00
<b>Gross Labour Cost (\$)</b>			<b>1,900.00</b>	<b>720.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >