

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05783

Vehicle Insured : YP2593L
Accident Date : 14-May-2018

Date : 18-May-2018

Our Ref : 218087 (AXA) / CHAN

PAGE : 1

FUDA FOOD PTE LTD
9 TAGORE LANE
Singapore 787472

*Not Notarised
L1 Survy @?
Blowing After Paint
4 days*

ESTIMATED COST OF REPAIR FOR TOYOTA HIACE GBC3902M

1 pc Bonnet
1 pc Bonnet logo
1 pc N/s corner panel
1 pc N/s headlamp
1 pc Radiator grille
1 pc Front bumper fascia
1 pc Front n/s bumper side retainer

<i>R1</i>	756.60	✓
<i>Mr</i>	66.10	✓
<i>Bu</i>	220.20	✓
<i>Spr</i>	689.60	✓
	464.10	✓
<i>R1</i>	425.10	✓
<i>D.1</i>	149.70	✓

2,771.40

Less 25% : 692.85

2,078.55

To rewire damaged parts and refocus
headlamp beam.

20.00 ✓

To putty and spray replaced parts

500.00 *450*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

600.00 *480*

Total : S\$ 3,198.55

Singapore Dollars Three Thousand One Hundred
and Ninety Eight and Cents Fifty Five Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: