



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 6610G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	TO REPAIR SEE LABOUR	1,206.36	-
1	FRONT GRILLE	TWISTED / CRACKED	509.37	509.37
1	FRONT GRILLE LOGO	NECESSARY	78.50	78.50
1	FRONT BUMPER	DISTORTED	1,169.88	1,169.88
1	FRONT BUMPER CENTRE GRILLE	TWISTED	239.45	239.45
1	FRONT BUMPER NOZZLE COVER N/S	TWISTED	62.00	62.00
1	FRONT BUMPER NOZZLE SPRAY N/S	CRACKED	178.51	178.51
2	FRONT BUMPER PDC SENSORS N/S @\$166.02	SHORTED	332.04	332.04
1	FRONT BUMPER FOG LAMP N/S	BROKEN	322.05	322.05
1	FRONT BUMPER FOG LAMP COVER N/S	TWISTED	166.50	166.50
1	FRONT BUMPER LOWER COVER	CRACKED	299.42	299.42
1	FRONT BUMPER CHROME MOULDING CENTRE	NECESSARY	115.00	115.00
2	FRONT BUMPER CHROME MOULDING SIDES @\$92.00	NECESSARY	184.00	184.00
1	FRONT BUMPER SPONGE	TORN	105.22	105.22
1	FRONT BUMPER REINFORCEMENT BRACKET N/S	BENT	145.00	145.00
1	FRONT BUMPER SIDE HOLDER N/S	CRACKED	48.50	48.50
1	SET FRONT BUMPER CLIPS	NECESSARY	45.00	45.00
1	HEADLAMP HID N/S	CRACKED	2,959.71	2,959.71
1	FRONT SUPPORT PANEL	CRACKED	482.35	482.35
1	FRONT FENDER N/S	BUCKLED	381.69	381.69
1	FRONT FENDER INNER SHIELD N/S	TORN	171.96	171.96
1	SET FRONT FENDER INNER SHIELD CLIPS N/S	NECESSARY	50.00	50.00
1	WIPER WASHER TANK	DISTORTED	158.30	158.30
1	WIPER WASHER TANK MOTOR	DAMAGED	125.00	125.00
1	HEADLAMP TOP PANEL N/S	TO REPAIR SEE LABOUR	86.11	-
1	FRONT KNUCKLE ARM N/S	BENT	690.31	690.31
1	FRONT KNUCKLE ARM BEARING N/S	NECESSARY	400.10	400.10
1	FRONT FENDER INNER PANEL N/S	TO REPAIR SEE LABOUR	821.15	-
	LESS 5% DISCOUNT		-	-470.99
			11,533.48	8,948.87



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TOWING CHARGE KING ROLLER.		150.00	120.00
	TO CHECK WIRING.		80.00	30.00
	TO SPRAY RUST PROOFING.		150.00	50.00
	TO DISMANTLE & REPLACING PDC SENSOR.		80.00	50.00
	TO CONDUCT WHEEL ALIGNMENT.		120.00	120.00
	TO DISMANTLE & REPLACING FRONT UNDERCARRIAGE.		200.00	150.00
	TO REFILL AIR CON GAS.		150.00	100.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF BONNET,HEADLAMP TOP PANEL N/S AND FRONT FENDER INNER PANEL N/S.		1,080.00	800.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	1,000.00
			3,510.00	2,420.00
	GRAND TOTAL		15,043.48	11,368.87
RECOMMENDED COST OF REPAIR SUM				10,200.00

Report Ref No. CS/TP18009268/Utn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.