

ASS. REC. BY:

REF: CS/FCI18009272/Drd3

n2

Special Instruction:

Surveyor:

CWS

Bryen

ASSIGNMENT (Office)

From (Person):

Srfheura

of

FCI

Date/Time:

22/5/18 @ 11:17am

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 1054C

Insured:

SHA 8742P

at Workshop m/s

Chunni Motor

Tel:

6542 5119

of

Blk 10, AMK Ind. park 2A #03-19

Policy No:

Claim No:

D18004020MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

17/05/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:18pm @ 22/5/18

Person Contacted:

Irene

Vehicle:

IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SHC 1054C - CS3 / III 15012236 / Fbk3	DoA: 18/7/15
	SHA 8742P - CC3 / AK10010495 / Dfgl	DoA: 25/5/2016
	Report thru email.	

Surveyor

REF:

ASSIGNMENT

CoE Dec 2024

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 876 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 1054C Yr Regn: 2016 / Dec
 Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) Prime Mover /
 Truck / Trailer or
 Make: Hyundai I40 C.C. 1685
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 251278 T/Radio: Insured / Std / NI / NA
 Eng/No: D4FDGUT00034
 C/No: KMHLB41UMHU097724
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Good / Jammed / Leaked / Burnt or
 Brake: Good / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/60 R16
 R: - 11 -
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Hankook
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 17/05/2018 D.O.I. 22/05/2018
 Survey held at Chunni AMK
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S Front
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>02/07/18</u>	<u>First cap SHC 8742P</u>
	<u>Invoice 2/5 8500/- with 8 days of rep</u>
	<u>Red: \$5833.36, 41%.</u>
RECEIVED 02 JUL 2018	

Date/Time, File Pass to? ☐ : Prel. Report

1) typist ☒ : Final Report

Date/Time, File Return to?

2)

Report Format: TP

Lump Sum / 121 (\$) 8500

Days Of Repair: 81

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos OSP

Others 2/1/18

TOTAL

4x15= 60

170+ 60

50

50+50

100

480



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18009272/Drd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 22-05-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 8742P	Veh. Inspected	SHC 1054C
Policy No.		Coverage (\$)	0.00
Claim No.	D18004020MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	22/05/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	17/05/2018	Inspection Date	22/05/2018
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004020MFSH

Our Ref: CS/FCI18009272/Drd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 1054C .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 21.05.2018 at the premises of M/s CHUNNI MOTORWORK PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ 14,333.36 .
Revised Estimate Amount	: S\$ 10,727.24 .
"Check" Items Amount	: S\$.
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages
at o/s front portion.



Yours faithfully
BRYAN ANG
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	18-05-2018	Our Ref No. D18004020MFSH
Accident Date	17-05-2018	Claim Type. Third Party
Insured Vehicle	SHA8742P	Third Party Vehicle. SHC1054C
Survey Location	BLK 10 ANG MO KIO INDUSTRIAL PARK 2AAMK AUTOPOINT #03-19	
Contact Person.	LYNN OR IRENE	
Contact No.	65427162/ 65425119	Fax No. 65426039
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/240544)



PRI Documents



Close



PRI Header Details

Claim No	D18004020MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & CHUNNI M
Workshop Name	CHUNNI MOTOR WORK PTE LTD (Contact Person : LYNN OR IRENE)	Survey Location & Contact Details	BLK 10 ANG MO KIO INDUSTRIAL PARK 2AAMK AUTOPO Mobile: 65425119 , Phone: 65427162 , Fax: 6542603! EmailId: CHUNNIMOTOR@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA8742P	TP Vehicle No	SHC1054C
PRI Recieved Date	21-05-2018 05:15:58 PM	Surveyor Appointed Date	22-05-2018 11:16:39 AM	Surveyor Accept Date	22-05-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	22-05-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

NAME
ADDRESS

Home Tel.:
VIN:
Registration: SHC 1054 C
Technician:
Mileage: 251278
Time Printed 21.5.18 3:56 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°40'		-3°00' 3°00'
3°48'		-0°19' 5°41'
-0°40'		-1°30' 1°30'
18°42'		
18°02'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
3°05'		-3°00' 3°00'
4°07'		-0°19' 5°41'
22°59'		-1°30' 1°30'
10°42'		
13°46'		

Front

	Actual	BEFORE	Specified Range
Cross Camber	-3°44'		-3°00' 3°00'
Cross Caster	-0°19'		-3°00' 3°00'
Cross SAI	8°00'		-3°00' 3°00'
Total Toe	22°19'		-3°00' 3°00'
Cross Turn Diff.			

Rear : Left

Actual	BEFORE	Specified Range
-1°55'		-3°30' 2°30'
-0°06'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-1°47'		-3°30' 2°30'
0°17'		-1°30' 1°30'

Rear

	Actual	BEFORE	Specified Range
Cross Camber	-0°08'		-3°00' 3°00'
Total Toe	0°11'		-3°00' 3°00'
Thrust Angle	-0°12'		-3°00' 3°00'

FCI

11671.55
9337.24

SHC 1054C

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			S 1,600.00 600/-
	Spray Painting Charge			S 500.00 400/-
	Wiring Charge			S 50.00 30/-
	Tuff Kote			S 50.00 40/-
	Towing Charge			S 50.00 40/-
	Remove/Refix Undercarriage (FRT)			S 400.00 180/-
	FRT Wheel Alignment			S 120.00 60/-
	Remove/Refix Aircon & Refill Gas			S 150.00 80/-
			1390/-	
	TOTAL LABOUR			S 2,920.00
	ESTIMATE TOTAL			S 14,333.36
				10727.24
				458500/-
	21/05/2018 @ 1500m HRT Antenna L/SAM 8 Rym LKK Auto			
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18009272/Drd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 04-07-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8742P	Veh. Inspected	SHC 1054C	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18004020MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	22/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KMHLB41UMHU097724	Colour	BLUE	
Odometer	251278	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	HANKOOK	6 mm	
L/H Front Tyre	205/60 R16	HANKOOK	6 mm	
R/H Rear Tyre	205/60 R16	HANKOOK	6 mm	
L/H Rear Tyre	205/60 R16	HANKOOK	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/05/2018	Inspection Date	22/05/2018	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1054C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER COVER	CUT / CRACKED	1,052.20	1,052.20
1	FRONT BUMPER SPONGE	NOT NECESSARY	142.20	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	526.10	-
1	FRONT BUMPER BRACKET TOP (RH)	NOT NECESSARY	22.40	-
1	FRONT BUMPER RETAINER MOUNTING	NOT NECESSARY	9.20	-
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN	1,067.50	1,067.50
1	HEADLAMP (RH)	CRACKED	1,388.00	1,388.00
1	FRONT FENDER (RH)	DENTED	619.00	619.00
1	FRONT FENDER APRON PANEL (RH)	DENTED	1,575.50	1,575.50
1	FRONT FENDER SHIELD (RH)	NOT NECESSARY	169.80	-
1	FRONT FENDER RETAINER	NOT NECESSARY	9.20	-
1	FRONT DOOR MIRROR (RH)	BROKEN	980.50	980.50
1	FRONT WHEEL RIM (RH)	BENT	351.90	351.90
1	FRONT WHEEL HUB CAP (RH)	CRACKED	150.70	150.70
1	FRONT WHEEL BEARING	DAMAGED	258.50	258.50
1	FRONT SHOCK ABSORBER (ASSY)(RH)	DISTORTED	342.20	342.20
1	FRONT SHOCK ABSORBER MOUNTING (RH)	NOT NECESSARY	75.10	-
1	FRONT DRIVE SHAFT (RH)	NOT NECESSARY	1,069.55	-
1	RACK & PINION ASSY	DISTORTED	2,184.00	2,184.00
1	STG TIE END	DISTORTED	69.50	69.50
1	STABILIZER BAR	DISTORTED	252.30	252.30
1	STABILIZER BAR BUSH (RH)	NOT NECESSARY	16.10	-
1	STABILIZER BAR LINK	DISTORTED	81.70	81.70
1	STABILIZER BRACKET	NOT NECESSARY	24.00	-
1	FRONT SUSPENSION LOWER ARM (RH)	DISTORTED	715.10	715.10
1	KNUCKLE ARM (RH)	DISTORTED	582.95	582.95
1	ABS SENSOR	NOT NECESSARY	261.50	-
	LESS 20% DISCOUNT		-2,799.34	-2,334.31
			11,197.36	9,337.24

Report Ref No. CS/FC118009272/Drd3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	FRONT TYRE (RH)(SN)	SERVICEABLE	216.00	-
			216.00	-
	LABOUR			
	PANEL BEATING.		1,600.00	600.00
	SPRAY PAINTING CHARGE.		500.00	400.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.		50.00	40.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX UNDERCARRIAGE (FRT).		400.00	180.00
	FRT WHEEL ALIGNMENT.		120.00	60.00
	REMOVE/REFIX AIRCON & REFILL GAS.		150.00	80.00
			2,920.00	1,390.00
	GRAND TOTAL		14,333.36	10,727.24
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,500.00

Report Ref No. CS/FCI18009272/Drd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.