COMFORTDELGRO ENGINEERING 45 Pandan Road S (609286)

ACCIDENT REPAIR ESTIMATES

Our Ref:				
Type of Claim : X Own Damag	ge	Vehicle No.	:	GBD1199J
3rd Party		Make & Model	:	NISSAN / NV350 2.5 5AT
Windscreer	7	Year of Manufacture	:	2014
		Chassis No.	:	JN1MC2E26Z0002072
Ins Company : QBE	INS	Engine No.	:	YD25348855A
Excess :TE	BA	Policy No.	:	8-V0015362-MVA
Date of Accident : 14.05	.2018	Time of Accident	:	16.30
Suggested Days of Repair :	15 DAY	In-house Vehicle Asses	sor	
Repair Estimates		Name	:	Wong Chee Wei
Parts (a) Cost / List Price Items	\$19,234.00	Signature	:	· · · · · · · · · · · · · · · · · · ·
		Contact No	:	68676919
Plus/Less 15 % _	\$2,885.10			HP : 97239882
(b) Nett Price Items		LKK Auto Consu the Repairer of t	iltan	ts hence notify
Less %		 To resurvey before 	e/arrer	spra, _ainting
		To display damage Parts prices are su	t ect	rtrs) di giresurvey to oci firmation
(c) Special Nett Items	\$501.00	 Third party survey 	is on	a "V thout Prejuditie" basis
Total Parts Cost (Appendix A)	\$22,620.10	 No illegal modificat Supplementary iter 	m(s; r	mus' esurves and
Labour (Appendix B)	\$3,760.00	is subject to final a	рргэу	ral fru insurance impany
Total Repair Cost	\$26,380.10	Acknowledged by Re	epaire	er
The above total will be subjected to 7%	6 G.S.T.	Signature:		
Name of Surveyor		Tautill 974	19e	5749
Company	·	LKN.		
Survey conducted on	23 <	at	12	<i>></i> 0.
Remarks By Surveyor	ľ			
(a) The repair of this vehicle is autho	orized / is not authori	ized until further notice.		
(b) Recommended Days of Repair	:	day(s)	mp.	yum.
(c) Resurvey	: Required / No	t Required 🎎	uiv	ug often repair.
(d) Excess	:\$_ 500	Revent, N	10+	
(e) Signature of surveyor	:	Date:		23/5/18

ACCIDENT REPAIR ESTIMATES/F3

COMFORTDELGRO ENGINEERING PTE LTD

Appendix B

45 Pandan Road S (609386) Tel: 68676919 Fax: 62626950,68676903

ı	а	h	റ	11	r
_	-0	_	u	•	

Vehicle No.	:	GBD1199J	Submit By :	:	Wong Chee Wei
Make & Model	:	NISSAN	Year of Manufacture:	_	2014

wake	nake a Model Tear of Manufacture :		2014			
S/No	Labour Description	Esimated Price	Adjusted Price			
1	TO REMOVE / REPLACE / STRIAGHTEN /PANEL BEAT, CUT,					
	WELD :FRONT BUMPER,FR PANEL CORNER PANEL,A PILLE					
	,B PILLE ,DOOR LHF ,WHEEL HOUSE PANEL ,DAMAGED AREA	\$1,600.00	1200.			
2	TO PUTTY,RESPRAY :FR BUMPER,FR PANEL,CORNER PANEL					
	LHF ,DOOR LHF AND DAMAGED AREA	\$1,200.00	900			
3	TO CHECK WIRE	\$60.00	30.			
4	TO REMOVE / REPLACE / RE FIT A/CON CONDENSER					
	OIL COLLER ASSY	\$200.00	100.			
5	TO VACUUM , RE FILL AIR CON GAS	\$150.00	100			
6	TO REMOVE / RE FIT DASHBOARDS TO FACILITATE TO REPAIR	\$300.00	200? phato			
7	TO REMOVE / RE FIT SEAT CUSHION TO FACILITATE TO REPAIR	\$100.00	60			
8	TO REMOVE / TRANSFER DOOR MECHANISM LOCK TO NEW DOOR	\$150.00	60			
		- 10-				
		I				

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

COMFORTDELGRO ENGINEERING PTE LTD

Appendix A

45 Pandna Road S (609286) Tel: 68676919 Fax: 62626950

Spare Pai	rts	
-----------	-----	--

Vehicle No. :	G	BD1199J	Submit By	:	Wong Chee Wei
Make & Model:	NISSAN	NV350 2.5 5AT	Year Manufacture :		2014
Chassis No. :	JN1M	C2E26Z0002072	Engine No.	: _	YD25348855A
					OD

rdo u

	S/Order :								
S/No	Part Description	Qty	Cost	Nett	List	S- Nett	Diposition By		
	EDONE BANEN		Price	Price	Price	Price	Surveyor		
	FRONT PANEL	1	\$720.00		•		RY		
	CORNER PANEL LH	1	\$280.00			<u> </u>	RX dd~		
3	CORNER PANEL RH	1	\$280.00				ad-		
4	A PILLE PANEL ASSY COMPLETE	1	\$850.00				3		
5	A PIILE INNER COVER LHF	1	\$90.00				i e		
6	WHEEL HOUSE PANEL LHF	1	\$950.00				7		
7	WHEEL HOUSE PANEL TOP COVER LHF	1	\$150.00				•		
8	B PILLE PANEL LHF	1					Ry		
9	FR BUMPER	1	\$380.00				de's		
	FR BUMPER CLIPS	10	\$20.00				nei		
11	FR BUMPER SIDE RETAINER RH	1	\$85.00				nei-		
12	FR BUMPER SIDE RETAINER LH	1	\$85.00		•		nes/		
13	FR BUMPER REINFORCEMENT	1	\$350.00				btu		
14	FR NO.PLATE	1				\$45.00	6t - 30		
15	FOG LAMP RH	1	\$250.00				7		
16	FOG LAMP LH	1	\$250.00				dis		
17	DOOR LHF	1	\$750.00				510		
18	DR HINGE TOP LHF	1	\$45.00				61-		
19	DR HNGE LWR LHF	1	\$45.00						
20	DR CHECK LHF	1	\$48.00				67- dis/		
21	DR TRIM COVER LHF	1	\$450.00				?		
22	DR WEATHERSTRIP LHF	1	\$120.00				ent/		
23	DR LOCK LHF	1	\$165.00				~		
24	DR LOCK STIKER LHF	1	\$25.00				?		
	WINDOW GLASS RUN CHANNEL	1	\$65.00				7		
	WINDOW GLASS MOULDING OUTER LHF	1	\$98.00				cut/		
	WINDOW GLASS MOULDING INNER LHF	1	\$45.00				7		
	WINDOW GLASS LHF	1	\$450.00				7		
29	WINDOW REGULATOR LHF	1	\$150.00				٦		
	WINDOW REGULATOR MOTOR LHF	1	\$250.00				7		

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

S	oa	re	Pa	rts	

Vehicle No. :	G	BD1199J	Submit By	:	Wong Chee Wei
Make & Model:	NISSAN	NV350 2.5 5AT	Year Manufacture	:	2014
Chassis No. :	JN1M	1C2E26Z0002072	Engine No.	:	YD25348855A

Pages							
S/No	Part Description		Cost	Nett	List	S- Nett	Disposition By
		Qty	Price	Price	Price	Price	Surveyor
31	SIDE MIRRIR ASSY LHF	1	\$350.00				bus
32	SPEAKER LHF	1	\$250.00				?
33	OIL COLLER ASSY	1	\$500.00				mis-
34	OIL COLLER HOSE INLET	1	\$55.00				ms/
35	OIL COLLER HOSE OULET	11	\$60.00				mis
36	OIL COLLER PIPE	1	\$180.00				bt-
37	OIL COLLER BRACKET	1	\$85.00				bt/
38	OIL COLLER COWLING	1	\$90.00				cno
39	AIR CON CONDENSER	1	\$1,300.00				. ?.
40	AIR CON CONDENSER PIPE INLET	1	\$290.00				7
41	AIR CON CONDENSER PIPE OULET	1	\$158.00				Ç
42	AIR CON CONDENSER FAN COWLING	1	\$150.00		,		· ·
43	AIR CON CONDENSER FAN BLADE	1	\$85.00				?
	AIR CON CONDENSER FAN MOTOR	1	\$260.00				?
45	AIR CON CONDENSER UNDER COVER	1	\$115.00				7
46	STEEL RIM LHF	1	\$250.00				6t_
47	TYRE B/STONE 195R15 8PR R623	1				\$350.00	puched - 30
48	UPPER ARM LHF	1	\$220.00				2
49	LOWER ARM LHF	1	\$165.00				?
50	KNUCKLE ARM LHF	1	\$330.00				61/
51	KNUCKLE BEARING LHF	1	\$120.00				bナー
52	WHEEL HUB LHF	1	\$350.00				61-
53	SHOCK ABSORBER LHF	1	\$120.00				41
54	STABILIZER BAR	1	\$280.00				?
55	STABILIZER BAR SIDE LINKAGE LH	1	\$45.00				7
56	STREEING RACK & PINION ASSY	1	\$1,680.00				?
57	STEERING RACK ROD	1	\$90.00)
58	STEERING TIE ROD END	1	\$80.00				7
<u>.</u> د	MUDFLAP FR LHF	1	\$85.00				1
60	CROSS MEMBER FRONT	1	\$450.00				?
61	AIR INTER COLLER ASSY	. 1	\$1,650.00				7
62	DOOR RHF	1	\$750.00				RV
63	SIDE STEP GARNISH LHF	1	\$150.00				de_
64	SIDE STEP PANEL LHF	1	\$85.00				61

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts					
Vehicle No. :	G	BD1199J	Submit By	:	Wong Chee Wei
Make & Model:	NISSAN	NV350 2.5 5AT	Year Manufacture	:	2014
Chassis No.	INIANA	100E007000070			

					Pages 3		
S/No	Part Description	Qty	Cost	Nett	List	S- Nett	Disposition By
			Price	Price	Price	Price	Surveyor
65	FR WINDSCREEN	1	\$850.00				×
66	FR WINDSCREEN MOULDING	1	\$110.00				ye.
67	FR WINDSCREEN SEALANT	2				\$40.00	ARE
68	I U BRACKET	1				\$26.00	X
69	INNER SEAL TAPE	1				\$40.00	~ ~ ~
70							
71							
72							
73							
74						:	
75				_			
76							
77							
							
79							
80							
81							
82							
83							
84							
85							
86							
87							
88							
89							
90							
91							
92				-			
93							
94							
95							
96							
97							
98							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.